

DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
029 1982 033 0 8211290767 179463 10/09/82

DOCKET:029 YANKEE ROWE TYPE:PWR
REGION: 1. NSSS:WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: YANKEE ATOMIC ELECTRIC CO.
SYMBOL: YAE

ABSTRACT

THE REFUELING NUCLEAR CHANNELS WERE INADVERTENTLY DE-ENERGIZED FOR APPROXIMATELY 10 MINUTES. THIS IS CONTRARY TO TECH SPEC 3.9.2. THE CHANNELS WERE IMMEDIATELY RESTORED UPON DISCOVERY OF THEIR LOSS. THIS IS THE FIRST REPORTED OCCURRENCE OF THIS NATURE. THE CAUSE WAS THE ACCIDENTAL BREAKER OPERATION AS THE RESULT OF BEING BUMPED BY THE WOODEN HANDLE OF A JOHNSON BAR USED TO SET NEW NEARBY EQUIPMENT. THE BREAKER WAS CLOSED AND THE CABINET DOOR SECURELY CLOSED. PERSONNEL WERE INSTRUCTED TO BE MORE ATTENTIVE.



FORM

2

LER SCSS DATA

08-30-91

DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
206 1981 020 0 8109230562 168829 09/03/81

DOCKET:206 SAN ONOFRE 1. TYPE:PWR
REGION: 5 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS


WATCH 975 - SINGLE COMPONENT FAILURE CAUSED MULTIPLE INSTRUMENT FAILURES.
COMMON CAUSE FAILURE OF SAFETY INJECTION VALVES-FAILURE TO OPEN.

WATCH-LIST CODES FOR THIS LER ARE:

975 POSSIBLE SIGNIFICANT EVENT

ABSTRACT

SAFETY INJECTION VALVES HV.851 FAILED TO OPEN UPON A VALID SAFETY
INJECTION SYSTEM (SIS) SIGNAL. THE FAILURE OF THESE TWO VALVES
RESULTED IN BOTH SIS TRAINS BEING INOPERABLE. SI WAS NOT REQUIRED.
ENGINEERING TESTS HAVE CONFIRMED THAT THESE VALVES WILL NOT OPEN WITH
THE DESIGN DELTA P. INSPECTION OF THE VALVE INTERNALS SHOWED ONLY
NORMAL WEAR. TESTS ARE BEING PERFORMED TO DETERMINE VALVE OPERABILITY
UNDER VARYING CONDITIONS. DESIGN CHANGES ARE BEING CONSIDERED.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
206 1981. 021 0 8109230575 168830 09/03/81

DOCKET:206 SAN ONOFRE 1. TYPE:PWR
REGION: 5 NSSS:WE
ARCHITECTURAL:ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

REFERENCE LERS:
1.206/81-020

ABSTRACT

A FAILURE OF THE NUMBER 1 TWINCO VOLTAGE REGULATOR FILTER CHOKE CAUSED A DEGRADATION OF 115 VAC POWER RESULTING IN ERRATIC FEEDWATER CONTROL AND STEAM GENERATOR LEVEL CONTROL. SUBSEQUENT RCS COOLDOWN AND DEPRESSURIZATION CAUSED INITIATION OF SAFETY INJECTION (REFER TO LER NO. 81-020). VOLTAGE REGULATOR FILTER CHOKE FAILED TO GROUND. REGULATOR WAS TEMPORARILY JUMPERED FOR POWER CONTINUITY, AND HAS SUBSEQUENTLY BEEN REPAIRED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
206 1989 020 0 8908310129 215105 07/23/89

DOCKET:206 SAN ONOFRE 1 TYPE:PWR
REGION: 5 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:

10 10 CFR 50.73(a)(2)(i): Shutdowns or technical
specification violations.

ABSTRACT

POWER LEVEL - 075%. AT APPROX. 0500 ON 7/23/89, WITH UNIT 1 AT 75% POWER, DURING PERFORMANCE OF THE MONTHLY EMERGENCY SIREN FUSE BLOCK REMOVAL VERIFICATION, IN ACCORDANCE WITH TECH SPEC (TS) 4.1.1, THE FUSE BLOCKS FOR BOTH BREAKER 8-1145 AND BREAKER 8-1293A, WERE FOUND INSTALLED. SINCE THE TS SURVEILLANCE REQUIRES THAT ONE FUSE BE REMOVED, THIS WAS A CONDITION PROHIBITED BY TS. THE FUSE BLOCK TO BREAKER 8-1293A WAS IMMEDIATELY REMOVED. THERE IS NO SAFETY SIGNIFICANCE TO THIS EVENT SINCE DURING THE TIME THE FUSE BLOCKS FOR BOTH BREAKERS 8-1145 AND 81293A WERE INSTALLED, BREAKER 8-1293A REMAINED OPEN. THE ROOT CAUSE OF THIS EVENT WAS DETERMINED TO BE THE FAILURE TO DOCUMENT THE MANIPULATION AND VERIFICATION OF SAFETY RELATED EQUIPMENT, AS REQUIRED PER PROCEDURES. INVESTIGATION DETERMINED THAT THE FUSE BLOCK TO BREAKER 8-1293A HAD BEEN INAPPROPRIATELY LEFT INSTALLED FOLLOWING MAINTENANCE ON THE FUSE BLOCK FOR BREAKER 8-1145 ON 7/10/89. PRIOR TO THE MAINTENANCE ON 7/10/89, PROPER DOCUMENTATION FOR THE REMOVAL OF THE FUSE BLOCK HAD NOT BEEN IMPLEMENTED. THEREFORE, UPON COMPLETION OF THE MAINTENANCE, THE CONTROL OPERATOR (CO) ONLY PROVIDED GENERAL SYSTEM RESTORATION GUIDANCE TO THE PLANT EQUIPMENT OPERATOR (PEO). THE CO DID NOT SPECIFY THE SEQUENCE OF STEPS FOR THE PEO TO PERFORM IN ORDER TO ENSURE PROPER SYSTEM RESTORATION. THIS RESULTED IN THE PEO LEAVING THE FUSE BLOCK FOR BREAKER 8-8908310129.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
213 1986 025 0 8607180300 199893 06/19/86

DOCKET:213 CONNECTICUT YANKEE TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: CONN. YANKEE ATOMIC POWER CO.
SYMBOL: CYA

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. WITH THE PLANT IN MODE 2 AT 0% POWER A REACTOR TRIP OCCURRED WHILE REPAIRING A POWER RANGE CHANNEL IN THE NUCLEAR INSTRUMENTATION SYSTEM. FUSE REPLACEMENT IN THE FAILED NIS CHANNEL DRAWER POWER SUPPLY GENERATED A VOLTAGE DIP ON THE VITAL BUS. THE END RESULT OF THIS VOLTAGE DIP WAS THE REACTOR TRIP. A CONTRIBUTING FACTOR TO FAILURE OF THIS POWER SUPPLY MAY HAVE BEEN ELEVATED CONTROL ROOM TEMPERATURE DUE TO MAINTENANCE IN PROGRESS. ADMINISTRATIVE CONTROL PROCEDURE WILL BE DEVELOPED FOR PLANT OPERATION AT ELEVATED CONTROL ROOM TEMPERATURE BY OCTOBER 1986. IN THE INTERIM THE DUTY OFFICERS AND SHIFT PERSONNEL HAVE BEEN GIVEN INSTRUCTION BY MEMORANDUM. A MAINTENANCE UPGRADE OF NIS EQUIPMENT IS TO BE COMPLETED BY NOVEMBER 1986, AND REPLACEMENT OF NIS IS PLANNED FOR THE 1988-89 REFUELING OUTAGE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
219 1982 002 0 8203050431. 172606 01/18/82


DOCKET: 219 OYSTER CREEK TYPE: BWR
REGION: 1 NSSS: GE
ARCHITECTURAL ENGINEER: BNRO
FACILITY OPERATOR: GENERAL PUBLIC UTILITIES CORP.
SYMBOL: GPU

COMMENTS

STEP 3: COMP MEI - TIP INSERT/WITHDRAW MACHINE.

ABSTRACT

INSTALLATION OF A MODIFICATION COULD HAVE LED TO A POSSIBLE FAILURE TO MAINTAIN PRIMARY CONTAINMENT INTEGRITY. THIS CONDITION WAS DUE TO THE INSTALLATION OF UNDERVOLTAGE TRIP BREAKERS TO NO. 3 AND NO. 4 TIP MACHINE DRIVE MOTOR CIRCUITS. THIS WOULD HAVE RENDERED THE AUTOMATIC RETRACT AND SUBSEQUENT TIP BALL VALVE CLOSURE FEATURES INOPERABLE. THE CAUSE IS AN INADEQUATE SAFETY REVIEW. IT SHOULD BE NOTED THAT THE PLANT OPERATIONS REVIEW COMMITTEE IDENTIFIED THE DEFICIENCY, BUT STILL APPROVED THE MODIFICATION WITH THE PROVISIO THAT THE UNDERVOLTAGE TRIP BREAKERS BE DELETED. SUBSEQUENTLY, THE DIRECTOR - STATION OPERATIONS, BASED UPON THE PORC RECOMMENDATIONS, APPROVED THE MODIFICATIONS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
220 1989 002 0 8904190199 213633 03/08/89

DOCKET:220 NINE MILE POINT 1 TYPE:BWR
REGION: 1, NSSS:GE
ARCHITECTURAL ENGINEER: NMP
FACILITY OPERATOR: NIAGRA MOHAWK POWER CORP.
SYMBOL: NMP

COMMENTS

STEPS 1-29: MARCH 8 EVENT. STEPS 30-41: MARCH 11 EVENT. STEP 2: ISYS HS -
RESERVE TRANSFORMER HEATING. STEPS 3,4: PSYS HS - RESERVE TRANSFORMER
HEATING. STEPS 5,6: COMP RLX - SUDDEN FAULT PRESSURE RELAY.

WATCH-LIST CODES FOR THIS LER ARE:

941 REPORT ASSOCIATED WITH 10 CFR 50.72
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1.220/86-008

ABSTRACT

POWER LEVEL - 000%. ON MARCH 8, 1989, WITH THE MODE SWITCH IN
"SHUTDOWN" AND NINE MILE POINT UNIT 1 IN AN EXTENDED REFUELING OUTAGE
WITH THE CORE OFF-LOADED, THE REACTOR BUILDING EMERGENCY VENTILATION
SYSTEM (RBEVS) WAS INITIATED DUE TO A MOMENTARY LOSS OF POWER TO THE
INSTRUMENT AND CONTROL (I&C) BUS 130. THIS LOSS OF POWER TRIPPED THE
REFUEL FLOOR HIGH RADIATION MONITOR, AND WITH THE KEYLOCK SWITCH FOR
THE MONITOR IN THE "REFUEL" POSITION, THIS RESULTED IN RBEVS
INITIATING AS DESIGNED. ON MARCH 11, 1989 THE RBEVS WAS AGAIN
INITIATED WHEN THE REFUEL FLOOR RADIATION MONITOR TRIPPED DUE TO A
MOMENTARY LOSS OF POWER TO THE I&C BUS 130. THE ROOT CAUSE FOR THE
MARCH 8 EVENT WAS EQUIPMENT FAILURE DUE TO PROCEDURAL DEFICIENCY.
THIS LED TO A SPURIOUS ALARM FOR RESERVE TRANSFORMER 101N, AND
ULTIMATELY A LOSS OF POWER DURING OPERATIONAL EFFORTS TO REMOVE THE
TRANSFORMER FROM SERVICE. ROOT CAUSE FOR THE MARCH 11 EVENT IS
PERSONNEL ERROR DUE TO COGNITIVE ERROR AND PROCEDURAL DEFICIENCY. IN
RETURNING THE 101N RESERVE TRANSFORMER TO SERVICE, AFTER THE MARCH 8
EVENT, THE CONTROL ROOM OPERATORS INADVERTENTLY INITIATED A LOSS OF
POWER DURING THEIR CONTROL ROOM SWITCHING OPERATIONS. IMMEDIATE
CORRECTIVE ACTIONS TAKEN AS A RESULT OF THE MARCH 8 AND MARCH 11
AUTO-INITIATION OF RBEVS CONSISTED OF RESETTING THE 86-16 LOCKOUT
DEVICE AND RESTORING POWER TO POWERBOARD 16B.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
220 1989 013 0 8911090290 215812 09/29/89

DOCKET:220 NINE MILE POINT 1 TYPE:BWR
REGION: 1, NSSS:GE
ARCHITECTURAL ENGINEER: NMP
FACILITY OPERATOR: NIAGRA MOHAWK POWER CORP.
SYMBOL: NMP

WATCH-LIST CODES FOR THIS LER ARE:

31 ACCIDENTAL ACTION
35 HUMAN ERROR
941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 220/89-012

ABSTRACT

POWER LEVEL - 000%. ON 9/29/89, NINE MILE POINT UNIT 1 (NMP1) WAS IN A REFUELING OUTAGE WITH THE MODE SWITCH IN "SHUTDOWN", AND THE CORE OFFLOADED. AT 1315 HOURS NMP1 EXPERIENCED A FULL REACTOR SCRAM DUE TO A MOMENTARY DROP IN VOLTAGE ON REACTOR PROTECTION SYSTEM (RPS) BUS 11. THE VOLTAGE DROP IN RPS BUS 11 WAS DUE TO A LEAD WIRE BEING SHORTED TO GROUND DURING REPLACEMENT OF A POWER SUPPLY ON THE ROD POSITION INDICATION SYSTEM (RPIS). IMMEDIATE CORRECTIVE ACTION WAS TAKEN BY OPERATIONS PERSONNEL BY RESETTING THE SCRAM AT 1317 HOURS. THE ROOT CAUSE FOR THIS EVENT WAS A FAILURE TO PROPERLY PLAN AND EVALUATE THE WORK PRIOR TO STARTING PHYSICAL WORK ACTIVITIES IN THE FIELD. 10CFR50.72(B)(2)(II) NOTIFICATION WAS MADE AT 1355 HOURS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
237 1985 034 0 8509180539 196523 08/16/85

DOCKET:237 DRESDEN 2 TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

WATCH LIST 932: IE INFORMATION NOTICE 85-77; WATCH LIST 975,990: LOSS OF
OFFSITE POWER ACCOMPANIED BY SEVERAL OTHER FAILURES; STEP 10: COMPONENT COM
- TELEPHONES; STEP 17: COMPONENT MEI - RADIO REPEATER STATION; STEP 18:
COMPONENT COM - RADIOS; STEP 33: EFFECT LX - FAILURE TO RESET; STEP 38:
COMPONENT RLX - CONTROL RELAY; STEP 49: EFFECT LX - FAILURE TO RESET.

WATCH-LIST CODES FOR THIS LER ARE:


975 POSSIBLE SIGNIFICANT EVENT
990 COMPLEX EVENT
900 POST EVENT DATA AVAILABILITY
932 RESULT OF IE BULLETINS, ORDERS, ETC.(IEB 81-7)
943 ALERT

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 070%. DURING NORMAL UNIT OPERATION, ON 8-16-85 AT 0021,
DRESDEN UNIT 2 SCRAMMED DUE TO LOW REACTOR WATER LEVEL. THE SCRAM
RESULTED FROM LOSS OF OFFSITE POWER DUE TO A FAULT ON THE SECONDARY
SIDE OF UNIT 1 RESERVE AUX TRANSFORMER, TR12. TRANSFORMER 12 PRIMARY
SIDE WAS BEING POWERED FROM THE SAME 138 KV POWER SOURCE AS THE UNIT 2
RESERVE AUX TRANSFORMER, TR22. WHEN PROTECTIVE RELAYING SENSED THE
FAULT, THE UNIT 2 OFFSITE POWER SOURCE WAS ISOLATED AND POWER TO TR22
WAS LOST. 4 KV BUSES 22 AND 24 DID NOT AUTOMATICALLY TRANSFER POWER.
ONE OF TWO RUNNING REACTOR FEEDPUMPS POWERED FROM BUS 22 TRIPPED ON
BUS UNDERVOLTAGE AND THE STANDBY REACTOR FEEDPUMP ALSO POWERED FROM
BUS 22 FAILED TO AUTOMATICALLY START BECAUSE OF THE BUS UNDERVOLTAGE.
THE LOW WATER LEVEL SCRAM AND COMPLETE LOSS OF POWER TO THE UNIT
RESULTED. BOTH EMERGENCY DG'S AUTOMATICALLY STARTED AND THE UNIT WAS
PLACED INTO A SAFE SHUTDOWN CONDITION. INVESTIGATION OF THE 4 KV
BREAKER CONTROL CIRCUITRY HAS SHOWN THAT UNDER THE CONDITION THAT
PREVAILED, RESERVE FEED BREAKERS FOR BUSES 22 AND 24 WERE NOT
DESIGNED TO AUTOMATICALLY TRANSFER POWER FEED TO THE UNIT AUX
TRANSFORMER, TR21. THE CIRCUITRY HAS BEEN MODIFIED AND FUNCTIONALLY
TESTED TO ENSURE THAT THIS EVENT DOES NOT RECUR. THE SAFETY
SIGNIFICANCE OF THIS EVENT WAS MINIMIZED BY THE FACT THAT ALL SAFETY
SYSTEMS FUNCTIONED AS DESIGNED AND THE UNIT WAS PLACED IN A SAFE
SHUTDOWN CONDITION.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
244 1985 014 0 8507110262 194975 06/06/85

DOCKET:244 GINNA TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: ROCHESTER GAS & ELECTRIC CORP.
SYMBOL: RGE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON JUNE 6, 1985 WHILE OPERATING AT 99.8% REACTOR POWER, AN AUTOMATIC REACTOR TRIP AND SUBSEQUENT TURBINE TRIP OCCURRED WHEN THE "OVERPOWER DELTA TEMPERATURE" REACTOR TRIP ACTUATED. AT THE TIME OF THE TRIP, INSTRUMENTATION AND CONTROL PERSONNEL WERE REPAIRING THE EXCORE NUCLEAR POWER RANGE CHANNEL N-41 OPERATION SELECTOR SWITCH. COINCIDENT WITH THE REPAIR, AN UNDERVOLTAGE CONDITION OCCURRED FOR ONE CYCLE ON INSTRUMENT BUS 1D. THE CAUSE OF THE EVENT WAS ATTRIBUTED TO THE GROUNDING OF THE DEFEATED CHANNEL'S OPERATION SELECTOR SWITCH POWER WIRE THROUGH USE OF A SOLDERING IRON. THE GROUND CAUSED AN UNDERVOLTAGE SPIKE ON INSTRUMENT BUS 1D. THE UNDERVOLTAGE CAUSED AN OVERPOWER DELTA TEMPERATURE BISTABLE TO DE-ENERGIZE ON THE REACTOR PROTECTION CHANNEL #4 DUE TO THE WIRING CONFIGURATION OF THE EXCORE NUCLEAR POWER CHANNELS. THIS CONDITION INITIATED A TWO OUT OF FOUR LOGIC WHICH CAUSED AN AUTOMATIC REACTOR TRIP ON OVERPOWER DELTA TEMPERATURE. ALL SYSTEMS OPERATED AS DESIGNED AND THE REACTOR WAS STABILIZED AT HOT SHUTDOWN CONDITIONS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
247 1985 006 0 8506040027 194976 04/16/85

DOCKET: 247 INDIAN POINT 2 TYPE: PWR
REGION: 1 NSSS: WE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: CONSOLIDATED EDISON CO.
SYMBOL: CEC

COMMENTS

STEP 3: COMP MSC - FEEDWATER TURBINE OVERSPEED, MANUAL AND BEARING OIL
FAILURE TRIP. MECHANISM; STEP 4: COMP MSC - CONTROL OIL SYSTEM ORIFICE BLOCK
AND CHECK VALVE ASSEMBLY. STEP 12: COMP RLX - FLOW SWITCH AUXILIARY RELAY.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 247/85-005.

ABSTRACT

POWER LEVEL - 100%. ON APRIL 16, 1985 AT 12:20 A.M., WHILE THE PLANT
WAS FULL POWER, THE LOSS OF ONE OF THE TWO MAIN BOILER FEEDWATER
PUMPS, #22 INITIATED A SEQUENCE OF EVENTS LEADING TO A REACTOR TRIP.
THE EVENT OCCURRED WHEN THE OPERATOR REDUCED LOAD. THE LEVEL IN ALL
FOUR (4) STEAM GENERATORS FELL AND THE REACTOR TRIP OCCURRED ON A
LOW-LOW LEVEL SIGNAL FROM STEAM GENERATOR #24. THE REACTOR PROTECTION
SYSTEM FUNCTIONED IN ACCORDANCE WITH THE DESIGN. THE CAUSE OF THE
MAIN BOILER FEEDWATER PUMP TRIP WAS SUBSEQUENTLY DETERMINED TO BE A
MALFUNCTION IN THE CONTROL OIL SYSTEM.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
249 1989 001 1 8907250110 214841 03/25/89

DOCKET:249 DRESDEN 3 TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 2: MODEL 362 GA 63-20C. STEP 24: TYPE HFA. STEP 27: COMP MSC-BREAKER LINKAGE. STEP 56: COMP MSC-MOTOR BRUSHES. STEP 61: COMP MEI-MULTIPLEXOR. STEP 62: PSYS PX-SECURITY. STEP 65: CAUSE HX-ANALYZER COOLED DOWN FOLLOWING SHORT TIME W/O POWER. STEPS 8,9: MODEL AMH-16-350-IH. STEP 28: MODEL AK-2-25-2. STEP 63: MODEL 35V12300. STEP 51: MODEL 12IAV69A1A. STEP 57: MODEL 5CD14D19A111620. STEP 68: DI X-10. STEPS 75,76: DI X-11. WATCH 990 - MULTIPLE EQUIPMENT FAILURES FOLLOWING INITIATING EVENT CONTRIBUTED TO EVENT.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE
941 REPORT ASSOCIATED WITH 10 CFR 50.72
990 COMPLEX EVENT

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 237/84-012 2 237/85-034 3 249/87-010

ABSTRACT

POWER LEVEL - 089%. AT APPROX. 0133 HOURS ON 3/25/89, A FAULT OCCURRED WITHIN 345 KV SWITCHYARD POWER CIRCUIT BREAKER (PCB) 8-15. LOCAL BREAKER BACKUP LOGIC CIRCUITRY THEN AUTOMATICALLY ISOLATED PCB 8-15; THIS DE-ENERGIZED UNIT 3 RESERVE AUX. TRANSFORMER (TR) 32, CAUSING A LOSS OF OFFSITE POWER (LOOP) TO UNIT 3. THE AUTOMATIC TRANSFER OF 4 KV BUS 32 FROM TR 32 TO UNIT 3 AUXILIARY TR 31 DID NOT OCCUR QUICKLY ENOUGH TO PREVENT UNDERVOLTAGE TRIPS OF THE 3B REACTOR FEED PUMP (RFP) AND THE 3B REACTOR RECIRCULATION PUMP. WHEN THE STANDBY 3C RFP STARTED, REACTOR WATER LEVEL ROSE TO THE MAIN TURBINE AND RFP TRIP SETPOINT AND A REACTOR SCRAM ON TURBINE STOP VALVE CLOSURE RESULTED. THE MAIN STEAM ISOLATION VALVES (MSIVS) WERE MANUALLY CLOSED TO CONSERVE REACTOR INVENTORY AND THE ISOLATION CONDENSER WAS USED FOR REACTOR PRESSURE CONTROL. MILDLY CONTAMINATED CONDENSATE WAS INITIALLY USED TO SUPPLY THE ISOLATION CONDENSER SHELL SIDE BECAUSE THE CLEAN DEMINERALIZED WATER SUPPLY VALVE WAS UNAVAILABLE. THIS RESULTED IN LOW LEVEL CONTAMINATION TO THE AREA SURROUNDING THE ISOLATION CONDENSER VENT. COLD SHUTDOWN CONDITIONS WERE ACHIEVED BY 2230 HOURS ON 3/25/89. CORRECTIVE ACTIONS INCLUDED INSPECTION, TESTING AND REPAIR OF VARIOUS BREAKERS AND LOGIC CIRCUITS AND SURVEYS/CLEANUP OF THE AREAS AFFECTED BY THE ISOLATION CONDENSER VENT. SIMILAR EVENT: 237/85-034.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
250 1984 021 0 8408200273 191043 07/14/84


DOCKET:250 TURKEY POINT 3 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 251/84-014

ABSTRACT

POWER LEVEL - 000%. ON JUL 14, 1984, UNIT 3 EXPERIENCED A REACTOR TRIP FROM A SUBCRITICAL CONDITION. THE REACTOR TRIP SIGNAL WAS CAUSED BY A POWER INTERRUPTION OF THE SOURCE RANGE NUCLEAR INSTRUMENTATION CONTROL POWER WHILE MAINTENANCE PERSONNEL WERE TROUBLESHOOTING THE CIRCUITRY. ALL EQUIPMENT FUNCTIONED AS DESIGNED ON INITIATION OF THE ENGINEERED SAFETY FEATURE ACTUATION SIGNAL (ESFAS). IMMEDIATE ACTIONS INCLUDED: 1) VERIFICATION THAT AN ACTUAL REACTOR POWER EXCURSION HAD NOT OCCURRED VIA THE OTHER SOURCE RANGE CHANNEL N-31 AND, INTERMEDIATE RANGE CHANNELS N-35 AND N-36. 2) VERIFICATION THAT A POWER INTERRUPTION OF THE N-32 CIRCUITRY HAD OCCURRED BY MAINTENANCE PERSONNEL TROUBLESHOOTING THE EQUIPMENT. 3) PERFORMED OFF-NORMAL OPERATING PROCEDURE 208.1 FOR REACTOR TRIP. 4) IN ACCORDANCE WITH 10 CFR 50.72(B)(2)(II), NOTIFICATION OF A SIGNIFICANT EVENT WAS MADE TO THE NRCOC AND THE RESIDENT INSPECTOR. IMMEDIATE CORRECTIVE ACTION WAS TO COUNSEL MAINTENANCE PERSONNEL ON THE NEED TO EXERCISE CAUTION WHEN TROUBLESHOOTING THE NUCLEAR INSTRUMENTATION WITH THE REACTOR PROTECTION EQUIPMENT IN SERVICE. SIMILAR OCCURRENCES: 251-84-14.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
250 1984 026 0 8411190312 192024 10/09/84


DOCKET:250 TURKEY POINT 3 TYPE:PHR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 251/84-011 2 251/84-022

ABSTRACT

POWER LEVEL - 100%. AT 2:37 AM, ON 10-9-84, WHILE UNIT 3 WAS AT 100% POWER, A TURBINE RUNBACK TO 70% REACTOR POWER OCCURRED. DURING AN INVESTIGATION FOR A GROUND ON AN INVERTER OF UNIT 4, A TEMPORARY LOSS OF POWER OCCURRED ON THE 120V AC INSTRUMENT BUS SUPPLYING POWER TO THE UNIT 3 VITAL PANEL 3P07. THIS CAUSED NUCLEAR INSTRUMENTATION SYSTEM CHANNEL N-42 TO GENERATE AN "NIS ROD DROP" SIGNAL CAUSING A TURBINE RUNBACK TO 70% POWER. 30 SECONDS AFTER THE RUNBACK SIGNAL, THE POWER TO 3P07 RETURNED AND THE N-42 POWER RANGE CHANNEL RETURNED TO NORMAL INDICATION LEVELS. AN INADVERTENT TRANSFER OF POWER FOR PANEL 3P07 FROM THE NORMAL 3A INVERTER TO THE SPARE AS INVERTER, WHICH IS SHARED WITH UNIT 4, IS BELIEVED TO BE THE CAUSE OF THE LOSS OF POWER. JUST PRIOR TO THIS UNIT 3 EVENT, THE AS INVERTER HAD BEEN MADE INOPERABLE BY A BLOWN FUSE AS THE RESULT OF AN UNRELATED EVENT ON UNIT 4 (LER 251-84-022). A THOROUGH INVESTIGATION INVOLVING EQUIPMENT TESTS, FAILED TO REVEAL ANY EQUIPMENT RELATED CAUSE FOR THIS TEMPORARY LOSS OF POWER. CORRECTIVE ACTIONS WERE TO STABILIZE UNIT 3 AT 70% REACTOR POWER. AFTER A 12 HR INVESTIGATION FAILED TO REVEAL ANY EQUIPMENT FAILURES, PREPARATIONS WERE BEGUN ON 10-9-84 TO RETURN UNIT 3 TO FULL POWER. CORRECTIVE ACTIONS INCLUDED TRAINING ON INVERTER SWITCHING FOR THE PERSONNEL ON-SHIFT DURING THE EVENT. THE EVENT WILL BE DISCUSSED IN OPERATOR REQUALIFICATION CLASSES VIA THE OPERATING EXPERIENCE FEEDBACK PROGRAM.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
250 1985 023 0 8509090269 196668 08/01/85

DOCKET:250 TURKEY POINT 3 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL


REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 250/84-003	2 250/84-014	3 250/84-026	4 250/85-018
5 251/84-011	6 251/84-021	7 251/84-012	8 251/85-013
9 251/85-017	10 251/85-019		

ABSTRACT

POWER LEVEL - 030%. ON 8-1-85, UNIT 3 EXPERIENCED A REACTOR TRIP FOLLOWED BY A SAFETY INJECTION SYSTEM ACTUATION. THE BS INVERTER THAT WAS IN SERVICE SUPPLYING POWER TO THE 120 VOLT VITAL INSTRUMENT PANEL 3P08, TRIPPED. THE LOSS OF 3P08 CAUSED THE 'A' SG LEVEL CONTROL CHANNEL III TO FAIL LOW. THIS GAVE A DEMAND SIGNAL TO THE 'A' SG MAIN FEEDWATER CONTROL VALVE TO GO FULLY OPEN. THIS RESULTED IN THE 'A' SG LEVEL INCREASING UNTIL IT REACHED THE HI-HI LEVEL SETPOINT (80%) WHICH TRIPPED THE TURBINE AND BOTH SG FEEDWATER PUMPS. THE REACTOR TRIPPED AS A RESULT OF THE TURBINE TRIP. THE LOSS OF POWER TO STEAM FLOW PROTECTION CHANNEL III IN PANEL 3P08 COMPLETED HALF THE LOGIC FOR SI AND WHEN T-AVG FOR LOOP A DECREASED TO BELOW THE SETPOINT OF 543 DEGREES F, THE LOGIC FOR SI WAS COMPLETED. THIS RESULTED IN CONTAINMENT PHASE 'A' ISOLATION AND CLOSURE OF THE MSIV'S. THE SI PUMPS STARTED, HOWEVER, NO SI FLOW WAS DELIVERED TO THE RCS. POWER TO 3P08 WAS RESTORED USING A CONSTANT VOLTAGE TRANSFORMER (CVT) IN ACCORDANCE WITH PLANT PROCEDURES. THE UNIT WAS STABILIZED IN A HOT STANDBY CONDITION, AND SAFEGUARDS EQUIPMENT WERE PROCEDURALLY RETURNED TO THEIR NORMAL OPERATING STATUS. THE REASON FOR THE BS INVERTER TRIP WAS DUE TO THE FAILURE OF THE OSCILLATOR AND LOGIC POWER SUPPLY MODULE. THE VOLTAGE REGULATOR AND SYNCHRONIZER, DWELL ANGLE CONTROL AND OSCILLATOR AND LOGIC POWER SUPPLY MODULES WERE REPLACED. FUSE F6 WAS FOUND BLOWN AND REPLACED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
250 1985 025 0 8510080333 198157 08/30/85

DOCKET:250 TURKEY POINT 3 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

COMMENTS


STEP 2: EFF XX-REQUIRE PROTECTION. STEPS 13 AND 15: COMP XS- ISOLATION SWITCH.

REPORTABILITY CODES FOR THIS LER ARE:

14 10 CFR 50.73(a)(2)(v): Event that could have prevented fulfillment of a safety function.

ABSTRACT

POWER LEVEL - 100%. ON 8-27 AND 8-30-85 FPL MADE ADVANCED NOTIFICATION TO THE NRC-NRR AND IE REGION II ON THE PRELIMINARY RESULTS OF A REVIEW OF THE COMPLETED TURKEY POINT 3 APPENDIX 'R' SAFE SHUTDOWN ANALYSIS, WHICH WAS ORIGINALLY COMPLETED IN 1983. A REVIEW WAS INITIATED IN SEPT 1984 TO ENHANCE THE DOCUMENTATION PACKAGES DEVELOPED FOR THE ORIGINAL APPENDIX 'R' FIRE PROTECTION ANALYSIS, AND ON 9-20-85, FPL COMPLETED THE REVIEW OF THE ORIGINAL APPENDIX 'R' SAFE SHUTDOWN ANALYSIS. THE RESULTS OF THIS REVIEW IDENTIFIED ADDITIONAL CIRCUITS THAT MAY REQUIRE PROTECTION, REROUTING, OR CIRCUIT MODIFICATIONS. ADDITIONAL NRC GUIDANCE, PREPARATION FOR THE FPL ST. LUCIE APPENDIX 'R' AUDIT, APPENDIX 'R' DESIGN EVOLUTION, AND ADDED ENGINEERING PERSONNEL EXPERIENCE, INDICATED THE NEED TO UPGRADE THE ORIGINAL DOCUMENTATION PACKAGES FOR THE SAFE SHUTDOWN ANALYSIS. ALTHOUGH THE REVIEW WAS INITIATED TO ENHANCE THE DOCUMENTATION OF THE ORIGINAL APPENDIX 'R' ANALYSES, IT RESULTED IN THE IDENTIFICATION OF ADDITIONAL CIRCUITS WHICH MAY NEED TO BE PROTECTED. THE FOLLOWING CORRECTIVE ACTIONS HAVE BEEN COMPLETED OR WILL BE INITIATED: 1) THE AFFECTED CIRCUITS WERE LOCATED WITHIN FIRE ZONES THAT WERE INCLUDED IN ROVING FIRE WATCH PATROLS, INITIATED AS A COMPENSATORY MEASURE IN SUPPORT OF APPENDIX 'R' SCHEDULAR EXEMPTIONS. 2) THE PRELIMINARY ENGINEERING EVALUATION INDICATES THAT SECTIONS OF CONDUIT RANGING FROM 2' TO 120' AND PULL BOXES REQUIRE PROTECTION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
250 1989 005 0 8903210386 213268 02/15/89

DOCKET:250 TURKEY POINT 3 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL


WATCH-LIST CODES FOR THIS LER ARE:
37 MANUFACTURING ERROR OR INADEQUACY

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1.250/87-001.

ABSTRACT

POWER LEVEL - 000%. ON 2/15/89, AT 0210, WITH UNIT 3 CRITICAL AT 0% POWER (APPROXIMATELY 1E -7 AMPS IN THE INTERMEDIATE RANGE), UPON ATTEMPTING TO START THE 3B STEAM GENERATOR FEEDWATER PUMP (SGFP), AUXILIARY FEEDWATER (AFW) FLOW WAS AUTOMATICALLY INITIATED. AT THIS TIME, THE 3A SGFP WAS NOT RUNNING, AND THE 3A STANDBY SGFP WAS SUPPLYING WATER TO THE UNIT 3 STEAM GENERATORS. THE AFW AUTO-START LOGIC IS ENABLED WHEN 1) BOTH SGFP BREAKERS ARE OPEN, AND 2) AT LEAST ONE OF THESE SGFP BREAKERS IS IN A TRIPPED CONDITION. THE CAUSE OF THIS EVENT WAS A WIRING ERROR ON A STARTING CIRCUIT RELAY IN THE 3B BREAKER CUBICLE. THE WIRING ERROR HAS BEEN CORRECTED, AND THE 3B SGFP CONTROL CIRCUIT HAS BEEN VERIFIED TO FUNCTION PROPERLY. THE 4B SGFP BREAKER WAS SUPPLIED BY THE SAME MANUFACTURER AND WAS FOUND TO HAVE THE SAME WIRING ERROR; THE ERROR WILL BE CORRECTED BY MARCH 19, 1989.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
251 1984 011 0 8407130079 190542 06/10/84

DOCKET: 251, TURKEY POINT 4 TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

COMMENTS

STEP 1: EFFECT IX - ELECTRICAL TRANSIENT.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 250/84-009 2 250/84-013 3 250/84-015

ABSTRACT

POWER LEVEL - 100%. ON JUNE 10, 1984, AT 12:18 A.M., A TURBINE RUNBACK TO APPROXIMATELY 510 MEGAWATTS OCCURRED. THE ROOT CAUSE WAS DETERMINED TO STEM FROM AN ELECTRICAL TRANSIENT IN THE "NORMAL" (4A) STATIC INVERTER (4Y01) THAT WAS IN SERVICE SUPPLYING POWER TO A VITAL 120 VOLT (A.C.) INSTRUMENT POWER BUS (PANEL 4P07). THIS RESULTED IN A MOMENTARY LOSS OF POWER TO VITAL PANEL 4P07 AND ITS FEEDS TO THE NUCLEAR INSTRUMENTATION SYSTEM (NIS) CHANNEL N-42 POWER RANGE NUCLEAR INSTRUMENTATION. A MOMENTARY LOSS OF NIS CHANNEL N-42 DETECTOR VOLTAGE RESULTED AND INITIATED AN "NIS ROD DROP" SIGNAL WHICH GENERATED THE TURBINE RUNBACK. IMMEDIATE CORRECTIVE ACTIONS INCLUDED STABILIZING THE UNIT, SWAPPING THE VITAL PANEL ONTO THE "STANDBY" (AS) STATIC INVERTER (3Y04) AND COMPLETION OF SATISFACTORY LOGIC CIRCUIT TESTING AND LOAD TESTING OF THE 4A INVERTER WITH A RESISTIVE LOAD OF 53 AMPS PERFORMED WITH LINE DISTURBANCE MONITORING EQUIPMENT WHICH DID NOT RECORD ANY ABNORMAL FLUCTUATIONS. THE 4A INVERTER WAS RETURNED TO SERVICE AND LICENSED OPERATORS WERE REQUESTED TO MAINTAIN AN AWARENESS OF THE INVERTERS STATUS. SIMILAR OCCURRENCES: LER 250-84-009, LER 250-84-013, AND LER 250-84-015.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
251 1984 022 0 8411190596 192026 10/09/84


DOCKET:251 TURKEY POINT 4 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 251/84-011 2 251/84-021 3 250/84-009 4 250/84-013
5 250/84-026

ABSTRACT

POWER LEVEL - 000%. ON 10-9-84, WHILE UNIT 4 WAS HEATING UP FROM COLD SHUTDOWN TO HOT SHUTDOWN, A REACTOR TRIP OCCURRED. THE ROOT CAUSE OF THE REACTOR TRIP WAS A BLOWN FUSE IN THE NORMAL 4A STATIC INVERTER (4Y01) THAT WAS SUPPLYING 120V AC INSTRUMENT POWER TO VITAL PANEL 4P07, WHICH CAUSED THE NUCLEAR INSTRUMENTATION BISTABLES FOR CHANNELS N-32 (SOURCE RANGE) AND N-36 TO DEENERGIZE, GENERATING REACTOR TRIP SIGNALS. IN ADDITION, THE LOSS OF POWER TO PANEL 4P07 INITIATED THE CLOSURE OF THE LETDOWN LINE PRESSURE CONTROL VALVE (PCV-4-145), WHICH WAS OPERATING IN THE AUTOMATIC MODE. THE LOSS OF POWER TO THE OVERPRESSURE MITIGATING SYSTEM ON PANEL 4P07 OPENED THE PRESSURIZER POWER OPERATED RELIEF VALVE (PORV-V-4-455C) WHEN THE TEMPERATURE INPUTS FAILED LOW RESULTING IN THE RCS PRESSURE DROPPING TO 50 PSIG. CORRECTIVE ACTIONS WERE TO PLACE VALVE PCV-4-145 IN THE MANUAL MODE TO REESTABLISH LETDOWN PRESSURE CONTROL, CLOSE THE PORV, COOL DOWN AND STABILIZE THE RCS AND REENERGIZE THE VITAL PANEL 4P07 USING THE SPARE AS INVERTER. INVESTIGATIONS BY MAINTENANCE PERSONNEL REVEALED A WIRING ERROR IN THE DC INPUT FILTER SECTION OF THE 4A INVERTER WHICH ALLOWED THE CIRCUIT TO BE MORE SUSCEPTIBLE TO DC BUS PROBLEMS. THE INVERTER WAS REWIRED AND SATISFACTORILY TESTED IN ACCORDANCE WITH THE MANUFACTURER'S PROCEDURES. CORRECTIVE ACTIONS WILL BE TO REPLACE THE INVERTERS TO ENSURE A MORE RELIABLE POWER SUPPLY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
251 1985 019 0 8500000000 197718 07/17/85

DOCKET: 251. TURKEY POINT 4 TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: FLORIDA POWER & LIGHT CO.
SYMBOL: FPL

COMMENTS

STEP 13: EFFECT AX - LOSS OF MANUAL CONTROL; STEP 7: EFFECT KX - ABNORMAL
RUNBACK WITH TURBINE POWER CONTINUOUSLY DECREASED AT 200 PERCENT PER
MINUTE.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 250/84-003	2 250/84-014	3 250/84-026	4 250/85-018
5 251/84-011	6 251/84-021	7 251/84-022	8 251/85-012
9 251/85-013	10 251/85-017		

ABSTRACT

POWER LEVEL - 100%. ON 7-17-85 A REACTOR TRIP OCCURRED FOLLOWED BY SAFEGUARDS EQUIPMENT ACTUATION DUE TO THE LOSS OF VITAL INSTRUMENT POWER FROM THE 4D INVERTER. THE LOSS OF POWER TO THE 4P09 PANEL DE-ENERGIZED A TURBINE RUNBACK RELAY WHICH INITIATED A TURBINE RUNBACK. THIS COMBINED WITH A FAILURE OF A RUNBACK TIMER RELAY RESULTED IN A CONTINUOUS 200% PER MIN TURBINE RUNBACK. THE RAPID TURBINE RUNBACK COMBINED WITH LETDOWN FLOW ISOLATION RESULTED IN THE PRIMARY SYSTEM PRESSURE RISING TO THE PRESSURIZER HI-PRESSURE SETPOINT, WHICH INITIATED A REACTOR TRIP AND A SUBSEQUENT TURBINE TRIP. THE LOSS OF POWER TO 1. STEAM FLOW PROTECTION CHANNEL IN PANEL 4P09 FOR EACH SG COMPLETED HALF THE LOGIC FOR SAFEGUARDS INITIATION. T-AVG WAS MOMENTARILY REDUCED BELOW THE SAFEGUARDS INITIATION SETPOINT OF 543 F AS A RESULT OF OPEN CONDENSER STEAM DUMPS. THIS COINCIDENCE COMPLETED THE ESF'S LOGIC ACTUATING SAFETY INJECTION AND CONTAINMENT PHASE 'A' ISOLATION. ALTHOUGH THE SAFETY INJECTION PUMPS STARTED, NO RESULTANT SAFETY INJECTION FLOW WAS DELIVERED TO THE RCS. THE UNIT WAS SUBSEQUENTLY STABILIZED IN HOT SHUTDOWN CONDITIONS. THE CAUSE OF THE TURBINE RUNBACK, FOLLOWED BY THE REACTOR AND TURBINE TRIPS, AND SAFEGUARDS EQUIPMENT ACTUATION WAS DUE TO THE FAILURE OF A CURRENT LIMITING CARD IN THE 4D INVERTER. CORRECTIVE ACTIONS WERE TAKEN.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
259 1985 032 1 8509040362 198437 06/20/85

DOCKET:259 BROWNS FERRY 1 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: TVAX
FACILITY OPERATOR: TENNESSEE VALLEY AUTHORITY
SYMBOL: TVA

WATCH-LIST CODES FOR THIS LER ARE:


913 UPDATE NEEDED

REPORTABILITY CODES FOR THIS LER ARE:

11 10 CFR 50.73(a)(2)(ii): Unanalyzed conditions.

ABSTRACT

POWER LEVEL - 000%. BASED ON ANALYTICAL CALCULATIONS BY TVA'S OFFICE OF ENGINEERING, THE POSSIBILITY EXISTS FOR THE 250 VDC MAIN BATTERY TERMINAL VOLTAGE TO DROP BELOW THE FINAL SAFETY ANALYSIS REPORT (FSAR) SECTION 8.6.2 SPECIFIED FINAL VALUE OF 210 VDC FOR A SHORT TRANSIENT CONDITION FOLLOWING POSTULATED ACCIDENTS. THE CALCULATED TRANSIENT VALUE IS 207 VDC. THIS SHORT TRANSIENT COULD CAUSE AN INADVERTENT TRIP OF THE STATION INVERTERS WHICH POWER THE WIDE RANGE TORUS TEMPERATURE MONITORS AND THE TOPAZ INVERTERS WHICH POWER THE HIGH PRESSURE COOLANT INJECTION CONTROLLER CIRCUITRY. CORRECTIVE ACTION, PENDING FURTHER EVALUATION, IS TO LOWER THE UNDERVOLTAGE TRIP SETTING ON THE INVERTERS.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
263 1984 028 0 8410290031 191625 09/14/84

DOCKET:263 MONTICELLO TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: NORTHERN STATES POWER CO.
SYMBOL: NSP

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. THE OVERLOAD/OVERTEMPERATURE RELAY FOR THE 'B' REACTOR PROTECTION SYSTEM MOTOR GENERATOR SET OPEN-CIRCUITED. THIS RESULTED IN SHUTDOWN OF THE MOTOR, LOSS OF POWER TO BUS 'B' LOADS, AND INITIATION OF SECONDARY CONTAINMENT AND GROUP 2 ISOLATIONS. POWER WAS RESTORED TO BUS 'B' FROM THE ALTERNATE SOURCE UNTIL THE RELAY WAS REPLACED. AFTER REPLACEMENT OF THE RELAY, THE MG SET WAS RETURNED TO SERVICE. SUBSEQUENTLY, THE COMPARABLE RELAY IN 'A' RPS-MG SET WAS REPLACED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
263 1987 006 0 8703250226 203504 02/16/87

DOCKET:263 MONTICELLO TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: NORTHERN STATES POWER CO.
SYMBOL: NSP

COMMENTS

STEP 2: COMP XFMR - INVERTER OUTPUT FEEDBACK CONTROL TRANSFORMER; PART NO.
991-182-90. STEP 16: PART NO. 130LA20A. STEP 17: PART NO. 03572130-002.

WATCH-LIST CODES FOR THIS LER ARE:


20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ELECTRICAL DISTURBANCE ON THE DIVISION I
UNINTERRUPTIBLE POWER SUPPLY, UPS, INITIALLY CAUSED LOCKUP OF
FEEDWATER REGULATING VALVES, AND TRANSFER OF THE DIVISION I UPS TO ITS
ALTERNATE SOURCE. TWO MINUTES LATER A SECOND ELECTRICAL DISTURBANCE
RESULTED IN TRIP OF THE DIVISION I REACTOR PROTECTION SYSTEM LEVEL
INSTRUMENTATION INITIATING A REACTOR SCRAM, PRIMARY CONTAINMENT
ISOLATIONS, AUTOMATIC INITIATION OF THE STANDBY GAS TREATMENT SYSTEM
AND TRIP OF BOTH REACTOR RECIRCULATION PUMPS. FOLLOWING REACTOR SCRAM,
REACTOR BUILDING VENT CHANNEL A WIDE RANGE GAS MONITOR, WRGM, FAILED.
REACTOR PRESSURE WAS AUTOMATICALLY CONTROLLED BY THE LOW-LOW SET
ACTUATION OF ONE SAFETY RELIEF VALVE. PLANT CONDITIONS WERE STABILIZED
USING NORMAL SCRAM RECOVERY PROCEDURES. A FAILED FEEDBACK CONTROL
TRANSFORMER AND BLOWN FUSE WERE DISCOVERED ON THE DIVISION I UPS
INVERTER AND ARE THOUGHT TO BE THE ROOT CAUSE OF THE EVENT. A FAILED
METAL OXIDE VARISTOR, PROCESSOR UNIT AND BLOWN FUSE WERE FOUND IN THE
CHANNEL A WRGM FOLLOWING THE EVENT. THE FAILED COMPONENTS WERE
REPLACED AND FUNCTIONAL TESTING OF ALL AFFECTED WAS SATISFACTORILY
PERFORMED. THE POWER SOURCES FOR THE REACTOR WATER LEVEL
INSTRUMENTATION WILL BE CHANGED TO PREVENT A REACTOR SCRAM AND PRIMARY
CONTAINMENT ISOLATIONS DUE TO A LOSS OF ONE UPS DIVISION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
263 1987 013 0 8707140436 205202 06/07/87

DOCKET:263 MONTICELLO TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: NORTHERN STATES POWER CO.
SYMBOL: NSP

COMMENTS

WATCH 975: POTENTIAL COMMON CAUSE FAILURE MODE. STEP 96: MODEL 5K404AK981A.
STEP 97: SERIAL # 7929AR.

WATCH-LIST CODES FOR THIS LER ARE:


34 DESIGN ERROR OR INADEQUACY
975 POSSIBLE SIGNIFICANT EVENT
942 UNUSUAL EVENT

REPORTABILITY CODES FOR THIS LER ARE:

14 10 CFR 50.73(a)(2)(v): Event that could have prevented
fulfillment of a safety function.
15 10 CFR 50.73(a)(2)(vii): Single failure criteria.

ABSTRACT

POWER LEVEL - 100%. THREE EVENTS OCCURRED RELATED TO BREAKER/FUSE MISCOORDINATION. THE FIRST TWO INVOLVED TRIP OF AN ESSENTIAL DIVISION II MCC. OPERATORS ACTED TO COMPLY WITH TECH SPEC LCO STATEMENTS BASED ON THE INOPERABLE 480V LOADS. NUE'S WERE DECLARED AND NORMAL SHUTDOWNS INITIATED. EQUIPMENT WAS MEGGARED AND NO FAULT FOUND. LOADS WERE RESTORED AND THE NUE'S TERMINATED. THIRD EVENT WAS DECLARED WHEN BREAKER/FUSE MISCOORDINATION WAS FOUND AND DETERMINED TO PROVIDE POTENTIAL FOR EVENTS THAT MIGHT CAUSE REDUNDANT 480V MCC SOURCES TO BE TRIPPED. AN NUE WAS DECLARED AND NORMAL SHUTDOWN INITIATED. CAUSE OF THE MISCOORDINATION CONDITION WAS PERSONNEL ERROR AND PROCEDURAL INADEQUACY THAT ALLOWED BREAKER TRIP DEVICE INSTALLATION WITH INADEQUATE REVIEW. CAUSE OF THE BREAKER TRIPS WAS INTERMITTENT GROUND FAULTS IN WIRING FOR A DRYWELL COOLER FAN. TRIP DEVICE GROUND FAULT DETECTION FEATURE WAS JUMPERED, LEAVING OVERCURRENT PROTECTION FEATURES INSTALLED. THE NUE WAS TERMINATED. APPROPRIATE PERSONNEL HAVE BEEN NOTIFIED OF THE EVENTS AND HOW TO PREVENT FUTURE INADEQUACY. REVIEWS OF PLANT CHANGES WERE PERFORMED WITH NO SIMILAR PROBLEM FOUND. FURTHER REVIEW OF ELECTRICAL COORDINATION AND ADMINISTRATIVE PROCESSES ARE BEING PERFORMED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
265 1985 011 0 8506170398 194936 05/07/85

DOCKET: 265 QUAD CITIES 2 TYPE: BWR
REGION: 3 NSSS: GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CHE

COMMENTS

STEP 3: EFFECT IX - DAMAGED.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.
15 10 CFR 50.73(a)(2)(vii): Single failure criteria.

REFERENCE LERS:

1 265/77-037

ABSTRACT

POWER LEVEL - 090%. ON MAY 7, 1985, UNIT 1 WAS IN THE RUN MODE AT APPROXIMATELY 90 PERCENT OF RATED CORE THERMAL POWER. UNIT 2 WAS IN COLD SHUTDOWN. AT 1517 HOURS, CONTRACTOR PERSONNEL WORKING ON ROOF REPAIRS WERE ATTEMPTING TO CONNECT A POWER CORD FOR A DRILL TO AN AC OUTLET LOCATED NEAR THE GROUND BELOW. WHILE LOWERING THE CORD FROM THE ROOF, A SUDDEN 'A' PHASE TO GROUND FAULT OCCURRED. THIS FAULT OPENED OIL CIRCUIT BREAKERS (OCB) 8-9 AND 9-10, WHICH CAUSED A LOSS OF NORMAL AUXILIARY POWER TO UNIT 2. DIESEL GENERATOR 1/2 AUTO-STARTED AND CLOSED-IN TO BUS 23-1 ON A BUS 23-1 UNDERVOLTAGE SIGNAL. UNIT 2 REMAINED STABLE. THE ELECTRICAL TRANSIENT IN THE 345 KV SWITCHYARD CAUSED A TRANSIENT ON THE UNIT 1 ELECTRICAL SYSTEM. THE TRANSIENT CAUSED A LOSS OF 'A' REACTOR PROTECTION SYSTEM BUS AND A LOCK-UP OF A FEEDWATER REGULATING VALVE. THE LOCKED-UP FEEDWATER REGULATING VALVE RESULTED IN A HIGH REACTOR WATER LEVEL CONDITION WHICH RESULTED IN A TURBINE TRIP AND REACTOR SCRAM. THIS OCCURRED SIX MINUTES AFTER THE ELECTRICAL TRANSIENT, AT 1523 HOURS. SUBSEQUENTLY, A NORMAL SCRAM RECOVERY WAS PERFORMED AND ALL ELECTRICAL SYSTEMS WERE RETURNED TO NORMAL. ALL SYSTEMS AND EQUIPMENT FUNCTIONED AS DESIGNED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
269 1985 007 0 8506120047 195503 04/25/85

DOCKET:269 OCONEE 1 TYPE:PWR
REGION: 2 NSSS:BW
ARCHITECTURAL ENGINEER: DKBE
FACILITY OPERATOR: DUKE POWER CO.
SYMBOL: DPC

COMMENTS


STEP 7: MODEL 120/9.3 F1; STEP 5: COMP MSC - TRANSISTOR; STEP 6: COMPONENT
XS - STATIC TRANSFER SWITCH.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 094%. ON 4-25-85 AT 0533 HRS, OCONEE 1 TRIPPED FROM FULL POWER WHEN BOTH MAIN FEEDWATER PUMPS TRIPPED ON HIGH DISCHARGE PRESSURE. THE TRIP OCCURRED DUE TO A CHAIN OF EVENTS WHICH BEGAN WITH CONSECUTIVE FAILURES OF A STATIC INVERTER AND A RELATED STATIC TRANSFER SWITCH. MOST OF THE UNIT 1 CONTROL ROOM STATALARM PANELBOARDS AND CHART RECORDERS WERE DISABLED BY THE FAILURES, AND THIS RESULTED IN AN 'ALERT' CONDITION BEING DECLARED FOR THE FACILITY AT 0512 HRS. THE POWER SYSTEM FAILURES ALSO CAUSED A LOSS OF POWER TO THE MAIN FEEDWATER PUMP TURBINE CONTROLS. WHEN POWER WAS RESTORED, FEEDWATER FLOW OSCILLATIONS DEVELOPED, DUE TO INTEGRATED CONTROL SYSTEM ACTION, AND THE FEEDWATER PUMPS TRIPPED SHORTLY THEREAFTER CAUSING THE ANTICIPATORY REACTOR TRIP. THE CORRECTIVE ACTIONS ENSURED THAT THE UNIT WAS STABILIZED AT HOT SHUTDOWN CONDITIONS. THE PROBLEM WAS INVESTIGATED, AND THE FAILED COMPONENTS WERE IDENTIFIED AND REPAIRED. THE REACTOR WAS CRITICAL AGAIN AT 0851 HRS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
271 1984 020 0 8410170244 191682 09/08/84

DOCKET:271 VERMONT YANKEE TYPE:BWR
REGION: 1 NSSS:GE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: VERMONT YANKEE NUCLEAR POWER CORP.
SYMBOL: VYC

COMMENTS


STEP 2: MODEL CR120J22001.

REPORTABILITY CODES FOR THIS LER ARE:

14 10 CFR 50.73(a)(2)(v): Event that could have prevented
fulfillment of a safety function.

ABSTRACT

POWER LEVEL - 087%. ON 9/8/84 DURING NORMAL STEADY STATE OPERATION, A
RCIC VALVE OVERLOAD ALARM WAS RECEIVED AND INDICATION WAS LOST FOR THE
RCIC INBOARD STEAM SUPPLY VALVE, RCIC-15. THE OUTBOARD STEAM SUPPLY
VALVE, RCIC-16, WAS SHUT AS REQUIRED BY TECH SPEC 3.7.D.2 AND
ALTERNATE TESTING WAS COMMENCED AS REQUIRED BY TECH SPEC SECTION
4.5.G.2. FAILURE WAS FOUND TO BE DUE TO SHORTING OF AN ANNUNCIATOR
RELAY WHICH CAUSED THE CENTRAL POWER FUSE TO BLOW. THE RELAY WAS
REPLACED AND VALVE OPERABILITY WAS SATISFACTORILY DEMONSTRATED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
271 1990 009 0 9007030031 218701 06/01/90

DOCKET:271. VERMONT YANKEE TYPE:BWR
REGION: 1 NSSS:GE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: VERMONT YANKEE NUCLEAR POWER CORP.
SYMBOL: VYC

COMMENTS

STEP 4: CAUSE IX - INTERMITTENT FAULT. STEP 6: EFF IX - TRANSFER TO
ALTERNATE POWER SOURCE.

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
941. REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON 06/01/90, AT 1353 HOURS, WITH THE REACTOR AT
100% POWER, A CONTRACT ELECTRICIAN WORKING ON A NORMAL/EMERGENCY
LIGHTING PANEL ALLOWED A GROUND WIRE TO COME IN CONTACT WITH A LIVE
BUS. THE RESULTING SHORT CIRCUIT CAUSED THE VITAL AC MOTOR GENERATOR
SET (EIIS=EF) TO LOSE THE FIELD EXCITATION AND SUBSEQUENTLY A LOSS OF
GENERATOR OUTPUT. ON THE LOSS OF GENERATOR OUTPUT, THE VITAL AC BUS
TRANSFERRED TO ITS ALTERNATE SOURCE. THIS CAUSED A PRESSURE TRANSIENT
IN THE REACTOR COOLANT SYSTEM DUE TO THE TRANSFER FROM THE ELECTRIC
PRESSURE REGULATOR TO THE MECHANICAL PRESSURE REGULATOR, RESULTING IN
A REACTOR SCRAM. ON 06/03/90, AT 0103 HOURS, THE REACTOR MODE SWITCH
WAS RETURNED TO THE RUN POSITION AND THE IN GENERATOR PHASED TO THE
GRID. THE ROOT CAUSE OF THIS EVENT WAS PERSONNEL ERROR DUE TO A LACK
OF MENTAL ATTENTION. CORRECTIVE ACTIONS WILL INCLUDE ELECTRICAL
CONTRACTOR RETRAINING AND INCREASED EMPHASIS SAFETY AND ATTENTION TO
DETAIL. AN EVALUATION WILL BE PERFORMED ON THE VITAL AC MG SET TO
DETERMINE IF COLLAPSE OF THE GENERATOR FIELD AS A RESULT OF THE FAULT
WAS THE APPROPRIATE EQUIPMENT RESPONSE. A PLANT OPERATIONAL REVIEW
SUB-COMMITTEE WILL EVALUATE THE NEED FOR A FORMAL GUIDELINE GOVERNING
WORK IN ENERGIZED ELECTRICAL EQUIPMENT. NO OTHER INCIDENTS INVOLVING
A FAULT ON THE VITAL AC CAUSING A REACTOR SCRAM HAVE OCCURRED IN THE
LAST FIVE YEARS.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
275 1985 016 0 8506280144 194938 05/20/85

DOCKET:275 DIABLO CANYON-1 TYPE:PWR
REGION: 5 NSSS:WE
ARCHITECTURAL ENGINEER: PGEC
FACILITY OPERATOR: PACIFIC GAS & ELECTRIC CO.
SYMBOL: PGE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. AT 1540 PDT, MAY 20, 1985, WITH UNIT 1 IN MODE 3 (HOT STANDBY), AN AUTOMATIC REACTOR TRIP OCCURRED. ALL AUTOMATIC EQUIPMENT FUNCTIONED AS DESIGNED. THE REACTOR TRIP BREAKERS WERE RESET AND UNIT STARTUP CONTINUED. WHILE INSTRUMENT BUS IV-1-2 (EE)(BU) WAS BEING TRANSFERRED FROM BACK-UP TO NORMAL POWER, A VOLTAGE TRANSIENT CAUSED BISTABLES FOR SOURCE RANGE CHANNEL 32 (JC)(RI) TO DEENERGIZE AND CAUSED A HIGH SOURCE RANGE REACTOR TRIP. THE SWITCH IS DESIGNED TO PRODUCE A MOMENTARY DEENERGIZATION OF THE ASSOCIATED INSTRUMENT AC BUS WHENEVER THE INVERTER POWER SOURCE IS CHANGED. THIS DESIGN IS NECESSARY TO PREVENT PARALLELING NON-SYNCHRONIZED POWER SOURCES. TO PREVENT RECURRENCE, THE APPLICABLE OPERATIONAL PROCEDURE HAS BEEN REVISED TO PROHIBIT TRANSFERRING INSTRUMENT AC BUS POWER TO BACK-UP SOURCES WITH THE PLANT AT POWER ABOVE P-8 OR WITH THE REACTOR TRIP BREAKERS (JC)(BKR) CLOSED AND THE REACTOR POWER LEVEL LESS THAN THE P-10 INTERLOCK. IN ADDITION THE EVENT HAS BEEN REVIEWED WITH ALL APPLICABLE PERSONNEL.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
280 1980 029 0 8007070229 159240 06/03/80

DOCKET: 280 SURRY 1; TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: VIRGINIA ELECTRIC POWER CO.
SYMBOL: VEP

ABSTRACT

POWER LEVEL - 100%. CAUSE - FIRE IN VITAL BUS. VITAL BUS IV SOLA
FAILED, INITIATING AN AUTOMATIC TURBINE RUNBACK. THE REACTOR TRIPPED
ON STEAM GENERATOR LO LEVEL WITH FEED WATER MISMATCH. A SAFETY
INJECTION WAS INITIATED ON HI STEAM LINE FLOW WITH LO TAVE. A SECOND
SAFETY INJECTION WAS INITIATED DUE TO AN UNSUCCESSFUL CROSS CONNECT
ATTEMPT TO REENERGIZE VITAL BUS IV IN WHICH VITAL BUS II WAS LOST. A
FILTERING CAPACITOR IN THE SOLA-TRANSFORMER FAILED AND CAUGHT FIRE
DAMAGING THE SOLA AND CAUSING LOSS OF POWER TO VITAL BUS IV. THE VITAL
BUS WAS RE-ENERGIZED AND THE TRANSFORMER REPLACED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
280 1984 025 0 8501100434 192485 12/03/84

DOCKET:280 SURRY 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: VIRGINIA ELECTRIC POWER CO.
SYMBOL: VEP

COMMENTS


STEP 3: EFFECT IX - VOLTAGE TRANSIENT.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. AT 0859 ON 12-3-84, DURING A REFUELING OUTAGE, UNIT 1 WAS AT COLD SHUTDOWN WHEN A SOURCE RANGE AND INTERMEDIATE RANGE REACTOR TRIP SIGNAL WAS EXPERIENCED. PLANT PARAMETERS DID NOT INDICATE A VALID HIGH FLUX TRIP. THE REACTOR TRIP SIGNAL DID NOT RESULT IN THE ACTUATION OF ANY COMPONENT BECAUSE THE REACTOR TRIP BREAKERS WERE ALREADY OPEN. THE REACTOR TRIP SIGNAL WAS GENERATED AS A RESULT OF A VOLTAGE TRANSIENT THAT WAS INDUCED UPON VITAL BUS 2 DURING THE REPLACEMENT OF A KEY SWITCH ON A BORIC ACID FLOW TRANSMITTER. THE KEY SWITCH WAS BEING REPLACED WITH THE CIRCUIT ENERGIZED. DURING THE REPLACEMENT OF THE SWITCH, AN ENERGIZED LEAD MOMENTARILY SHORTED TO GROUND CREATING A VOLTAGE TRANSIENT ON THE VITAL BUS. THE VOLTAGE SPIKE DID NOT RESULT IN THE LOSS OF POWER TO ANY SAFETY RELATED COMPONENT. ADDITIONAL ADMINISTRATIVE CONTROLS FOR WORK ON ENERGIZED COMPONENTS WILL BE INITIATED WHICH INCLUDE (1) DETERMINING THE STATUS OF INSTRUMENT AND CONTROLS POWERED FROM REDUNDANT VITAL BUSES AND (2) THE EVALUATION OF THE CONSEQUENCES OF WORKING ON ENERGIZED CIRCUITS.




DOCKET YEAR LER NUMBER- REVISION DCS NUMBER NSIC EVENT DATE
285 1986 001 0 8608130523 200618 07/02/86

DOCKET:285 FT. CALHOUN 1 TYPE:PWR
REGION: 4 NSSS:CE
ARCHITECTURAL ENGINEER: GIBB
FACILITY OPERATOR: OMAHA PUBLIC POWER DISTRICT
SYMBOL: OPP

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON JULY 2, 1986, AT 0534, WHILE THE PLANT WAS OPERATING AT 100% POWER, THE REACTOR AND TURBINE GENERATOR WERE AUTOMATICALLY TRIPPED ON LOW STEAM GENERATOR LEVEL AFTER THE FAILURE OF A SAFETY RELATED INSTRUMENT INVERTER. THE TRIP WAS INITIATED BY A CLOSURE OF THE TURBINE CONTROL VALVES WHICH WAS CAUSED BY THE LOSS OF 120 VAC INSTRUMENT POWER TO THE ELECTROHYDRAULIC CONTROL UNIT. OTHER CONSEQUENCES OF THE LOSS OF POWER INCLUDED INOPERABILITY OF THE STEAM DUMP AND BYPASS VALVES AND FAILURE OF THE FEEDWATER VALVE RAMPDOWN CIRCUITRY. THESE FAILURES COMBINED TO CAUSE AN ABNORMAL POST-TRIP PRESSURE TRANSIENT IN THE REACTOR COOLANT SYSTEM. ALTERNATE POWER WAS QUICKLY RESTORED TO THE FAILED INSTRUMENT BUS AND, WITHIN A FEW MINUTES, THE PLANT WAS PLACED IN A NORMAL HOT SHUTDOWN CONDITION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
286 1984 014 0 8411190141 192034 10/13/84

DOCKET:286 INDIAN POINT 3 TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: POWER AUTHORITY OF THE STATE OF NY
SYMBOL: PNY

COMMENTS

STEP 2: EFFECT IX.- CURRENT SURGES. STEP 1: COMP RLX - PERMISSIVE RELAY.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1.286/84-002

ABSTRACT

POWER LEVEL - 000%. ON OCTOBER 13, 1984, WITH THE REACTOR SUBCRITICAL AT HOT ZERO POWER (HWP), A TRIP SIGNAL WAS INITIATED AT 0136 HOURS, AS THE RESULT OF A BLOWN CONTROL POWER FUSE ON CHANNEL 35 INTERMEDIATE RANGE. THE PLANT HAD RECENTLY BEEN BROUGHT TO HWP MAINTENANCE/INSPECTION OUTAGE. THE TRIP SIGNAL RESULTED IN THE AUTOMATIC INSERTION OF THE SHUTDOWN AND CONTROL ROD BANKS, WHICH WERE BEING GRADUALLY INSERTED AS PART OF THE SHUTDOWN/COOLDOWN PROCEDURES. THE FUSE (BUSSMAN, 5 AMP, SLOW BLOW) ON INTERMEDIATE RANGE 35 WAS REPLACED BY 0143 HOURS.




DOCKET YEAR LER NUMBER. REVISION DCS NUMBER NSIC EVENT DATE
286 1985 012 0 8601090599 198164 11/30/85

DOCKET:286 INDIAN POINT.3 / TYPE:PWR
REGION: 1. NSSS:WE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: POWER AUTHORITY OF THE STATE OF NY
SYMBOL: PNY

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 286/85-011.

ABSTRACT
POWER LEVEL - 000%. IMMEDIATELY AFTER A UNIT TRIP ON 11-30-85,
(REPORTED IN LER 286/85-011) SOURCE RANGE NUCLEAR INSTRUMENTATION
CHANNEL 31 FAILED TO RE-ENERGIZE WHEN THE REACTOR NEUTRON FLUX HAD
DROPPED BELOW THE P-6 PERMISSIVE SETPOINT. REDUNDANT SR CHANNEL 32
RE-ENERGIZED AS REQUIRED. I&C TECHNICIANS WERE INSTRUCTED TO
INVESTIGATE AND CORRECT THE MALFUNCTION OF CHANNEL 31. WHILE IN THE
PROCESS OF INVESTIGATING THE PROBLEM, THE TECHNICIANS REMOVED THE
CONTROL POWER FUSES FROM SR CHANNEL 31, DE-ENERGIZING REACTOR TRIP
RELAY 31D-X, THEREBY CAUSING A REACTOR TRIP. AT THE TIME OF THE TRIP,
THE REACTOR WAS SUBCRITICAL WITH SHUTDOWN ROD BANKS WITHDRAWN. THE
FAILURE TO RE-ENERGIZE WAS TRACED TO A LOOSE CONNECTION IN SR CHANNEL
31 WHICH WAS REPAIRED.



DOCKET YEAR LER NUMBER. REVISION DCS NUMBER NSIC EVENT DATE
286 1987 002 0 8703180279 203467 02/11/87

DOCKET:286 INDIAN POINT 3 TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: POWER AUTHORITY OF THE STATE OF NY
SYMBOL: PNY

COMMENTS

STEP 20: CAUSE RC - LOSS OF CIRC. WATER PUMP SEAL WATER. STEP 30: COMP MSC
- RETAINING PIN, ASSOCIATED WITH SPINDLE LIFT NUT. STEP 36: EFF IX -
VOLTAGE FLUCTUATION. STEP 2: ASCO NO. X8308-100. STEPS 3,35: NO. 125 CT.


WATCH-LIST CODES FOR THIS LER ARE:
20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1.286/85-001.

ABSTRACT

POWER LEVEL - 100%. ON FEBRUARY 11, 1987, NO. 34 STATIC INVERTER
TRIPPED DUE TO AN OVERCURRENT CONDITION CAUSED BY A SHORT-CIRCUITED
SOLENOID VALVE. THIS RESULTED IN A RUNBACK OF BOTH MAIN BOILER
FEEDWATER PUMP SPEED CONTROLLERS (THESE CONTROLLERS ARE POWERED FROM
NO. 34 STATIC INVERTER) AND A SUBSEQUENT REACTOR TRIP ON STEAM FLOW/
FEEDWATER FLOW MISMATCH WITH COINCIDENT LOW STEAM GENERATOR (SG)
LEVEL. A HIGH STEAM FLOW SAFETY INJECTION (SI) ACTUATION AND OTHER
SYSTEM ABNORMALITIES OCCURRED DUE TO THE LOSS OF THE STATIC INVERTER.
THE FAILED SOLENOID VALVE WAS REPLACED AND ALL OTHER AFFECTED SYSTEMS
WERE VERIFIED TO BE FUNCTIONING NORMALLY BEFORE START-UP. TO PREVENT
RECURRENCE, THE DESIGN OF NO. 34 STATIC INVERTER WAS IMPROVED TO
ALLOW ISOLATION OF SINGLE BRANCH CIRCUITS IF A SHORT CIRCUIT DEVELOPS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
287 1986 002 0 8610240393 201534 09/17/86

DOCKET:287 OCONEE 3 TYPE:PWR
REGION: 2 NSSS:BW
ARCHITECTURAL:ENGINEER: DKBE
FACILITY OPERATOR: DUKE POWER CO.
SYMBOL: DPC

COMMENTS

STEP 9: TYPE 2837A16G03. STEP 20: MODEL 1152. OTHER REPORTABILITY-
50.72(B)(2)(II).

WATCH-LIST CODES FOR THIS LER ARE:


941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.
21 OTHER: Voluntary report, special report, Part 21 report,
etc.

ABSTRACT

POWER LEVEL - 100%. ON SEPTEMBER 17, 1986 AT 1336 HOURS, UNIT 3 WAS MANUALLY TRIPPED FROM 100% FULL POWER AFTER A PIPE RUPTURE IN THE TURBINE BUILDING. FOUR SECONDS FOLLOWING THE REACTOR TRIP, BOTH MAIN FEEDWATER PUMPS (MFDWP) TRIPPED AND EMERGENCY FEEDWATER (EFDW) WAS AUTOMATICALLY INITIATED. THE OPERATOR WAS REQUIRED TO MANUALLY CONTROL THE "A" TRAIN OF EFDW BECAUSE OF A FAILURE IN THE AUTOMATIC LEVEL CONTROL CIRCUITRY. APPROXIMATELY 13 MINUTES AFTER THE TRIP, A MOMENTARY LOSS OF 3KI ESSENTIAL AC POWER WAS EXPERIENCED. THIS RESULTED IN SEVERAL INSTRUMENT SPIKES INCLUDING A SIGNAL WHICH CAUSED THE POWER OPERATED RELIEF VALVE (PORV) TO LIFT FOR LESS THAN TWO SECONDS. THE IMMEDIATE CORRECTIVE ACTION WAS TO ESTABLISH THE UNIT AT HOT SHUTDOWN CONDITIONS. THE SUPPLEMENTAL CORRECTIVE ACTIONS INVESTIGATED THE TRIP AND MALFUNCTIONS WHICH OCCURRED DURING THE EVENT. NO TECHNICAL SPECIFICATION LIMITS WERE EXCEEDED, AND THERE WAS NO RELEASE OF RADIOACTIVITY. THEREFORE, THE HEALTH AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
295 1984 001 0 8402070172 188964 01/05/84

DOCKET: 295 ZION 1 TYPE: PWR
REGION: 3 NSSS: WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. A ZION UNIT 1 REACTOR TRIP OCCURRED ON JAN. 5, 1984 WHILE THE UNIT WAS IN COLD SHUTDOWN AS PART OF A REFUELING OUTAGE. THE INITIATING SIGNALS CAME FROM THE NUCLEAR INSTRUMENT SYSTEM (NIS) CHANNEL II INTERMEDIATE AND SOURCE RANGE BISTABLES. THE NIS TRIP SIGNALS OCCURRED DUE TO A MOMENTARY LOSS OF THE 120 VOLT POWER SUPPLY TO THE NIS CHANNEL II. THE VOLTAGE LOSS OCCURRED WHEN A CAPACITOR IN THE INSTRUMENT INVERTER 112, WHICH SUPPLIES VOLTAGE TO INSTRUMENT BUS 112, FAILED. NIS CHANNEL II IS FED FROM INSTRUMENT BUS 112. THE VOLTAGE LOSS CAUSED THE NIS CHANNEL II BISTABLES TO TRIP. THE NIS CHANNEL II INTERMEDIATE AND SOURCE TRIP SIGNALS ARE BLOCKED DURING NORMAL POWER OPERATION. LOSS OF ONE INSTRUMENT BUS'S VOLTAGE WILL NOT CAUSE A TRIP DURING NORMAL OPERATION. THE TRIP OCCURRED ONLY BECAUSE THE UNIT WAS IN SHUTDOWN WITH THE REACTOR TRIP BREAKERS UNTRIPPED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
295 1985 021 1 8606020004 199430 06/03/85

DOCKET:295 ZION 1, TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS


STEP 3: COMP RLX-LOGIC RELAY; STEP 4: COMP RLX-AUTO START RELAY.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. WHILE UNIT 1 WAS IN COLD SHUTDOWN AND THE REACTOR TRIP BREAKERS WERE CLOSED FOR SAFEGUARDS TESTING (PERIODIC TEST 10C), INSTRUMENT BUS 112 WAS SWITCHED FROM ITS ALTERNATE (DIRTY) POWER SUPPLY TO ITS NORMAL SUPPLY (INVERTER) AT 0947 HOURS AND THE MOMENTARY LOSS OF POWER CAUSED THE REACTOR TRIP BREAKERS TO OPEN. COMPONENT COOLING PUMP 0E ALSO AUTOSTARTED ON A LOW HEADER PRESSURE SIGNAL WHICH WAS FALSE. THE BREAKERS TRIPPED ON NIS INTERMEDIATE RANGE HI FLUX BECAUSE THE AC SUPPLY WAS MOMENTARILY INTERRUPTED AND THE TRIP COULD NOT BE BLOCKED IN COLD SHUTDOWN. THE ZION ELECTRICAL DISTRIBUTION PROCEDURE, ZED 2, HAS SUFFICIENT CAUTION STATEMENTS WARNING OF A REACTOR TRIP WITH A LOSS OF THE BUS IF THE SOURCE AND INTERMEDIATE RANGE NIS TRIPS WERE NOT BLOCKED, BUT WAS NOT REFERENCED PRIOR TO SWITCHING. THERE WERE NO ADVERSE EFFECTS ON THE PLANT. A WARNING SIGN HAS BEEN PLACED AT THE TRANSFER SWITCH TO CAUTION THE OPERATOR TO REFER TO THE PROCEDURE PRIOR TO SWITCHING AND A SIMILAR CAUTION STATEMENT WILL BE ADDED TO STANDARD OPERATING PROCEDURE SOI-63. THE TRAINING DEPARTMENT WILL REVIEW AND REVISE, AS NECESSARY, TRAINING PROGRAMS FOR OPERATORS AND SHIFT CONTROL ROOM ENGINEERS. NO FURTHER ACTION IS REQUIRED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
295 1989 017 0 8911080058 215788 10/04/89

DOCKET:295 ZION 1 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

WATCH-LIST CODES FOR THIS LER ARE:


60 SPURIOUS/ UNKNOWN CAUSE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. UNIT 1 WAS DEFUELED. SAFEGUARDS WAS DEENERGIZED. AT APPROXIMATELY 1330 ON 10/4/89, NUMEROUS ALARMS ASSOCIATED WITH STEAM GENERATOR (S/G) LEVEL AND FLOW INDICATION WERE RECEIVED. SIMULTANEOUSLY, THE UNIT 1 PROCESS COMPUTER WENT DOWN, AND AT APPROXIMATELY THE SAME TIME THE FOLLOWING INSTRUMENTS WERE OBSERVED AS BEING 'FAILED ON-SCALE' (FAILED ON-SCALE MEANS THEY SHOULD HAVE INDICATED ZERO, BUT WERE INSTEAD READING AN INTERMEDIATE POSITION): 1LI-537, 1LI-529, 1LI-549, 1LI-519, 1LI-502B, 1LI-548, 1FI-540, 1FI-520. ABOUT THREE MINUTES LATER, IT WAS NOTED THAT 1FCV-PR24A HAD CLOSED. 1FCV-PR24A IS ONE OF TWO SERIES CONTAINMENT ISOLATION VALVES THAT ARE ALSO SUCTION VALVES FOR THE CONTAINMENT SYSTEM PARTICULATE IODINE NOBLE GAS (SPING) MONITOR. THE SPING CLOSES THE CONTAINMENT PURGE ISOLATION VALVES UPON DETECTING A HIGH RADIATION CONDITION. NO SPECIFIC CAUSE FOR THE CLOSURE OF 1FCV-PR24A COULD BE FOUND. THE SAFETY SIGNIFICANCE IS MINIMAL BECAUSE THE UNIT WAS DEFUELED, AND CONTAINMENT PURGE WAS NOT IN PROGRESS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
302 1987 021 0 8800000000 209907 10/14/87

DOCKET:302 CRYSTAL RIVER 3 TYPE:PWR
REGION: 2 NSSS:BW
ARCHITECTURAL:ENGINEER: GLBT
FACILITY:OPERATOR: FLORIDA POWER CORPORATION
SYMBOL: FPC

COMMENTS

WATCH LIST 946 - SECURITY SAFEGUARDS EVENT DUE TO LOSS OF PLANT SECURITY SYSTEM. DETAILS OF SECURITY EVENT DISCUSSED IN SECURITY LER 01-S87-000.
WATCH 975 - SUSTAINED LOSS OF 2 VITAL INSTRUMENT BUSES PLUS LOSS OF EVENTS RECORDER SYSTEM, CONTROL BOARD ANNUNCIATOR, PLANT SECURITY SYSTEM, AND EMERGENCY NOTIFICATION SYSTEM. DETAILS OF LOSS OF POWER TO ANNUNCIATOR BOARD AND EVENT RECORDER NOT GIVEN. STEPS 19,23: MODEL 12HEA61C234X2. STEP 22: CAUSE LX - REPEATED RESET OF LOCKOUT FEATURE. STEP 8: CAUSE AX - TESTING.

WATCH-LIST CODES FOR THIS LER ARE:


946 PHYSICAL SECURITY/SAFEGUARDS
975 POSSIBLE SIGNIFICANT EVENT
942 UNUSUAL EVENT
35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. ON OCTOBER 14, 1987, CRYSTAL RIVER UNIT THREE EXPERIENCED A SUSTAINED LOSS OF ELECTRICAL POWER TO VITAL BUSES 'A' AND 'C'. THE PLANT WAS IN THE REFUELING MODE (MODE 6) AND THE ENGINEERED SAFEGUARDS (ES) ELECTRICAL BUSES WERE ALIGNED AS SHOWN IN FIGURES I AND II. THE EVENT WAS INITIATED WHEN THE 4160V ES BUS 3A WAS IMPROPERLY DE-ENERGIZED IN PREPARATION FOR MAINTENANCE AND MODIFICATION ACTIVITIES. BECAUSE OF A PROTECTIVE INTERLOCK BETWEEN THE 4160V BUS AND THE 480V CROSS-TIE BREAKER, POWER WAS ALSO LOST TO THE 480V ES BUS 3A AND THE ASSOCIATED VITAL BUSES. LOSS OF THE VITAL BUSES ACTUATED THE ENGINEERED SAFEGUARDS WHICH COMPLICATED THE RESTORATION OF POWER BY ACTUATING ADDITIONAL PROTECTIVE INTERLOCKS WITHIN THE ES ELECTRICAL DISTRIBUTION SYSTEM. RESTORATION WAS ALSO IMPACTED WHEN A PROTECTIVE RELAY COIL BURNED OUT. POWER WAS RESTORED BY RE-ESTABLISHING THE 480V ES BUS 3A CROSS-TIE WITH THE 480V ES BUS 3B. THE EVENT WAS CAUSED BY PERSONNEL NOT DE-ENERGIZING THE 4160V ES BUS 3A IN ACCORDANCE WITH THE PROCEDURE. THE PERSONNEL INVOLVED HAVE BEEN COUNSELED ON THE SIGNIFICANCE OF THE EVENT AND THE IMPORTANCE OF FOLLOWING WRITTEN PROCEDURES. THE BURNED OUT RELAY COIL WAS REPLACED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
302 1988 002 2 8911060206 215719 01/07/88

DOCKET:302 CRYSTAL RIVER 3 TYPE:PWR
REGION: 2 NSSS:BW
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: FLORIDA POWER CORPORATION
SYMBOL: FPC

COMMENTS

STEP 10: EFF AN - CLOSED TOO FAR (NOT OPENED ENOUGH). STEP 11: CAUSE NB -
CONDENSATION IN TURBINE OR STEAM LINE.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 302/85-012 2 302/86-021 3 302/88-001

ABSTRACT

POWER LEVEL - 000%. ON 1/7/88, CRYSTAL RIVER UNIT 3 WAS IN THE HOT
STANDBY MODE (MODE 3). AN EMERGENCY FEEDWATER ACTUATION OCCURRED ON A
LOSS OF BOTH MAIN FEEDWATER PUMPS. THE OPERATING FW PUMP TRIPPED WHEN
CONTROL POWER WAS LOST TO ITS GOVERNOR. THE MOTOR DRIVEN EF PUMP
STARTED AS DESIGNED, BUT THE STEAM DRIVEN EF PUMP STARTED AND THEN
TRIPPED ON AN OVERSPEED CONDITION. THE CAUSE OF THE LOSS OF POWER TO
THE FW PUMP GOVERNOR WAS AN ERROR BY AN I&C TECHNICIAN WORKING ON A
RADIATION MONITOR WHICH IS POWERED FROM THE SAME BREAKER AS THE FW
PUMP GOVERNOR. THE MFW PUMP SHOULD NOT HAVE TRIPPED WHEN CONTROL
POWER WAS LOST. THE CAUSE OF THE TRIP OF THE STEAM DRIVEN EF PUMP WAS
THE IMPROPER POSITIONING OF THE BYPASS VALVE AROUND THE STEAM SUPPLY
VALVES TO THE PUMP. THE IDLE FW PUMP WAS STARTED, AND ONCE IT WAS
VERIFIED THAT THE MAIN FEEDWATER SYSTEM WAS CONTROLLING LEVEL
PROPERLY, THE EF ACTUATION WAS RESET. THE TECHNICIAN INVOLVED HAS
BEEN COUNSELLED IN ACCORDANCE WITH APPROVED PLANT POLICIES. A
MECHANICAL LOCKING DEVICE HAS BEEN INSTALLED ON THE STEAM SUPPLY
BYPASS VALVE, AND A PROCEDURE CHANGE HAS BEEN MADE TO IMPROVE THE
MONITORING OF THIS VALVE'S POSITION.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
304 1981 008 2 8108210316 168316 05/07/81

DOCKET:304 ZION 2. TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

ABSTRACT

UNIT TWO TRIPPED AND SAFETY INJECTION ACTUATED DUE TO THE LOSS OF
INVERTER 213. LOSS OF 213 CAUSED ONE FEEDWATER PUMP TO TRIP DUE TO
LOSS OF SPEED CONTROL. AN INVERTER TASK FORCE INVESTIGATED THE
SHORTED SOLA TRANSFORMER AND DETERMINED HIGH INVERTER INVERTER
CIRCULATING CURRENT AS THE CAUSE FOR THE TRANSFORMER FAILURE. A
TECHNICAL STAFF SURVEILLANCE (TSS) WAS DEVELOPED TO MONITOR AND MAKE
THE NECESSARY TUNING ADJUSTMENTS TO LIMIT CIRCULATING CURRENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
304 1984 016 0 8408130456 191055 07/09/84

DOCKET:304 ZION:2 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS


STEP 1: EFFECT DX - DAMAGED. STEP 2: COMP XFMR - SLAVE TRANSFORMER. STEP 3:
COMP XFMR - INVERTER MASTER OUTPUT TRANSFORMER.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. A REACTOR TRIP FROM HOT STANDBY, MODE 2, OCCURRED
DUE TO AN INSTRUMENT INVERTER FAILURE AND CONSEQUENTIAL LOSS OF A
NUCLEAR INSTRUMENTATION SYSTEM INTERMEDIATE RANGE MONITOR CHANNEL.
THE INVERTER FAILURE WAS CAUSED BY A SHORT CIRCUIT IN AN OUTPUT
REGULATING TRANSFORMER. THE TRANSFORMER INSULATION FAILED DUE TO
PREVIOUS OVERHEATING CAUSED BY LONG-TERM CIRCULATING CURRENT PROBLEMS.
THESE PROBLEMS HAVE BEEN ADDRESSED AS A RESULT OF PREVIOUS
NON-REPORTABLE OCCURRENCES. ALL DAMAGED TRANSFORMERS IN THIS
APPLICATION ARE BEING REPLACED AS REPLACEMENT PARTS BECOME AVAILABLE.
PREVENTATIVE MAINTENANCE AND SURVEILLANCES TO PREVENT RECURRENCE OF
THE OVERHEATING PROBLEMS ARE BEING PERFORMED. THE UNIT TRIP WOULD NOT
HAVE OCCURRED IF THE UNIT HAD BEEN AT POWER WHEN THE TRIPS INVOLVED
ARE BLOCKED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
304 1987 005 0 8708250267 205832 07/23/87

DOCKET:304 ZION 2 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 1: CAUSE AX - CALIBRATION OF THE POWER RANGE NUCLEAR INSTRUMENT CHANNEL.

WATCH-LIST CODES FOR THIS LER ARE:

40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1.304/87-004

ABSTRACT

POWER LEVEL - 000%. ON JULY 23, 1987 AT 21:39 HOURS, UNIT 2 WAS IN COLD SHUTDOWN AND OPERATING WAS PERFORMING PROCEDURE PT-10 (SAFEGUARDS ACTUATION). THE REACTOR TRIP BREAKERS WERE CLOSED PER PROCEDURE. THE BISTABLE FOR POWER RANGE NUCLEAR INSTRUMENTATION (NIS) CHANNEL 43 WAS TRIPPED FOR MAINTENANCE. IN STEP 9H OF PT-10, THE OPERATOR MANUALLY TRIPPED THE 4KV BREAKER FEEDING SAFEGUARDS BUS 248, DE-ENERGIZING NIS CHANNEL 42. THIS 2/4 COMBINATION OF NIS CHANNELS TRIPPED THE REACTOR TRIP BREAKERS. THE ROOT CAUSE OF THIS EVENT WAS PROCEDURAL INADEQUACY, CONSISTING OF: 1) NO INITIAL CONDITIONS GIVEN FOR EACH INDEPENDENT TEST SECTION AND 2) A CAUTION STATEMENT FOR EACH BUS DROP SECTION REFERRING OPERATORS TO AN "APPENDIX A" WHICH DOESN'T PROVIDE ANY SPECIFIC BUS-RELATED INFORMATION. THE SAFETY SIGNIFICANCE OF THIS EVENT WAS MINIMAL BECAUSE UNIT 2 WAS IN COLD SHUTDOWN WITH ALL RODS INSERTED IN THE CORE. IF THIS EVENT HAD OCCURRED AT POWER OPERATIONS, THE RESULT WOULD HAVE BEEN AN INADVERTENT REACTOR TRIP AND/OR A SAFETY INJECTION. AS CORRECTIVE ACTION, PT-10 WILL BE REVISED TO INCLUDE SEPARATE INITIAL CONDITIONS FOR EACH SECTION OF THE TEST, IMPROVE EACH BUS DROP SECTION SO THAT THE OPERATOR IS REFERRED TO THE ZION ELECTRICAL DISTRIBUTION CONTROLLED DOCUMENT, DELTE APPENDIX A, AND CLOSE THE REACTOR TRIP BREAKERS ONLY WHEN REQUIRED.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
305 1985 023 0 8601160068 197722 12/12/85

DOCKET:305 KEWAUNEE TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: FLPR
FACILITY OPERATOR: WISCONSIN PUBLIC SERVICE CORP.
SYMBOL: WPS

REPORTABILITY CODES FOR THIS LER ARE:
13. 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AT 0135 CST ON 12-12-85 A LOSS OF POWER TO INSTRUMENT BUS I RESULTED IN A PARTIAL LOSS OF INSTRUMENTATION AND VARIOUS ALARMS. THE 1B MAIN FEEDWATER CONTROL VALVE ALSO CLOSED DUE TO LOSS OF POSITIONER POWER. A REACTOR/TURBINE TRIP THEN OCCURRED DUE TO A LO SG LEVEL SIGNAL COINCIDENT WITH A STEAM FLOW/FEEDWATER FLOW MISMATCH SIGNAL ON 1B SG. THE OPERATORS PERFORMED THE RECOVERY ACTIONS SPECIFIED IN EMERGENCY PROCEDURE E-0, 'REACTOR TRIP OR SAFETY INJECTION' AND A POSTTRIP REVIEW WAS COMPLETED. THE AFW SYSTEM STARTED AS A RESULT OF A LO-LO SG LEVEL SIGNAL, ASSURING AN ADEQUATE HEAT SINK FOR DECAY HEAT REMOVAL. INVESTIGATION OF THE INVERTER FOR INSTRUMENT BUS I REVEALED THE CONSTANT VOLTAGE TRANSFORMER HAD FAILED. THE INSTRUMENT BUS WAS SWITCHED TO AN ALTERNATE POWER SUPPLY AND THE INVERTER WAS DEENERGIZED. A PLANT STARTUP WAS COMMENCED AT 0524 ON 12-12-85. AT 0711 ON 12-12 THE CONSTANT VOLTAGE TRANSFORMER WAS REPLACED AND THE INSTRUMENT BUS WAS RETURNED TO ITS NORMAL POWER SUPPLY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
305 1986 005 0 8605210371 199401 04/17/86

DOCKET:305 KEWAUNEE TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: FLPR
FACILITY OPERATOR: WISCONSIN PUBLIC SERVICE CORP.
SYMBOL: WPS

COMMENTS

STEP 1: CAUSE AX - ALIGNMENT FOR ROD POSITION CALIBRATION; STEP 2: EFF IX -
VOLTAGE FLUCTUATIONS; STEP 3: EFF LX - CHATTERING

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 305/84-004. 2 305/84-012 3 305/84-016 4 305/84-021
5 305/85-012

ABSTRACT

POWER LEVEL - 000%. AT 0855 ON APRIL 17, 1986, WITH THE PLANT IN HOT SHUTDOWN PREPARING FOR STARTUP FOLLOWING THE ANNUAL REFUELING OUTAGE, A REACTOR TRIP OCCURRED DURING THE PERFORMANCE OF A WORK REQUEST ON INTERMEDIATE RANGE NUCLEAR INSTRUMENTATION CHANNEL N35. THE TRIP OCCURRED AS A RESULT OF A BREAKDOWN IN COMMUNICATION BETWEEN PLANT PERSONNEL. AN INSTRUMENT AND CONTROLS MAN MISINTERPRETED INSTRUCTIONS GIVEN BY THE SHIFT SUPERVISOR CONCERNING THE TROUBLESHOOTING HE WAS TO PERFORM ON N35 TO ELIMINATE CHATTERING OF THE P-6 BISTABLE. AS A RESULT, THE MAN REMOVED THE CONTROL POWER FUSES FOR THE CHANNEL PREMATURELY. THE LOSS OF CONTROL POWER COMPLETED THE ONE OUT OF TWO ACTUATION LOGIC FOR THE INTERMEDIATE RANGE HI FLUX REACTOR TRIP. THE OPERATORS PERFORMED THE IMMEDIATE ACTIONS PRESCRIBED IN THE REACTOR TRIP RESPONSE PROCEDURE. TO MITIGATE THE POSSIBILITY OF A SIMILAR OCCURRENCE, THE SHIFT SUPERVISOR NOTIFIED THE INSTRUMENT AND CONTROL SUPERVISOR OF THE SITUATION STRESSING THE IMPORTANCE OF MAINTAINING PROPER COMMUNICATION BETWEEN INSTRUMENT AND CONTROL GROUP AND CONTROL ROOM PERSONNEL WHILE SAFETY RELATED WORK IS BEING PERFORMED. THE REACTOR WAS IN THE SHUTDOWN CONDITION PRIOR TO THE EVENT AND THE REACTOR PROTECTION SYSTEM PERFORMED AS DESIGNED; HENCE, THERE WAS NO IMPACT ON PUBLIC HEALTH AND SAFETY.




DOCKET YEAR LER NUMBER REVISION OCS NUMBER NSIC EVENT DATE
309 1983 028 2 8312300094 188550 08/02/83

DOCKET: 309 MAINE YANKEE TYPE: PWR
REGION: 1 NSSS: CE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: MAINE YANKEE ATOMIC POWER CO.
SYMBOL: MYA

ABSTRACT

DURING A POST IMPLEMENTATION NRC REVIEW OF A BACKFIT TO THE MAIN FEEDWATER TRIP SYSTEM, MAINE YANKEE DETERMINED THAT IN SEVERAL SPECIFIC INSTANCES THE DESIGN DID NOT MEET SINGLE FAILURE CRITERIA. THE SPECIFIC INSTANCES ARE: A. A FAILURE OF BATTERY BUS NO. 1 WOULD PREVENT THE FEEDWATER TRIP SYSTEM FROM TRIPPING MAIN FEEDWATER FLOW TO STEAM GENERATOR NO. 2. B. A FAILURE OF BATTERY BUS NO. 3 WOULD PREVENT THE FEEDWATER TRIP SYSTEM FROM TRIPPING MAIN FEEDWATER FLOW TO STEAM GENERATOR NO. 3. C. A FAILURE OF BATTERY BUS NO. 1 OR 3 WOULD PREVENT THE FEEDWATER TRIP SYSTEM FROM TRIPPING THE ELECTRIC DRIVEN AUXILIARY FEED PUMPS IF THEY WERE RUNNING. THE BACKFIT TO THE FEEDWATER TRIP SYSTEM WAS ORIGINALLY INSTALLED TO INCREASE THE RELIABILITY OF THE SYSTEM. THE BACKFIT WAS TO ELIMINATE THE POTENTIAL FOR CONTINUED FEEDING OF A STEAM LINE BREAK DUE TO A SINGLE FAILURE OF THE FEEDWATER REGULATING VALVE. THE DEFICIENCY IN THE FEEDWATER TRIP SYSTEM LOGIC RESULTED FROM ERRORS MADE DURING THE SYSTEM DESIGN. THE DESIGN CHANGE DESCRIBED IN MAINE YANKEE LETTER DATED NOV. 2, 1983 WAS IMPLEMENTED TO REMOVE THE SINGLE FAILURE VULNERABILITIES IDENTIFIED IN THE MAIN FEEDWATER TRIP SYSTEM. A COMPLETE REVIEW OF THE MAIN FEEDWATER TRIP SYSTEM WAS CONDUCTED TO ENSURE THAT NO OTHER SIMILAR DEFICIENCIES EXIST.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
309 1984 007 0 8405220329 190365 04/13/84

DOCKET:309 MAINE YANKEE TYPE:PWR
REGION: 1, NSSS:CE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: MAINE YANKEE ATOMIC POWER CO.
SYMBOL: MYA

COMMENTS

STEP 8: CAUSE CODE AX-DRAINED TO FILL THE REFUELING CAVITY. STEP 16: CAUSE
CODE IX - VOLTAGE TRANSIENTS

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 309/84-006

ABSTRACT

POWER LEVEL - 000%. ON APR 13, WHILE IN A REFUELING SHUTDOWN
CONDITION, 3 INADVERTENT ACTUATIONS OF SAFEGUARDS SYSTEMS OCCURRED.
THE FIRST EVENT OCCURRED WHEN OPERATORS WERE REMOVING AN INVERTER FROM
SERVICE AFTER 2 OF THE AC VITAL BUSES HAD BEEN INCORRECTLY CROSS-TIED
TO THE INVERTER. WHEN THE INVERTER DE-ENERGIZED, SAFETY INJECTION
AUTOMATICALLY UNBLOCKED CAUSING THE ACTUATION OF SAFETY INJECTION,
RECIRCULATION AND THE FIRST PHASE OF CONTAINMENT ISOLATION. THE
SECOND EVENT OCCURRED AFTER THE INVERTERS WERE PROPERLY CROSS-TIED AND
THE FINAL EVENT OCCURRED WHILE RETURNING TO NORMAL ALIGNMENT. THE
LATTER 2 EVENTS WERE MOST LIKELY CAUSED BY VOLTAGE SPIKES ASSOCIATED
WITH TRANSFERRING BUSES, HOWEVER, THE ACTUAL CAUSES ARE NOT KNOWN.
THE PLANT WAS IN A REFUELING SHUTDOWN CONDITION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
309 1986 005 0 8609150212 200940 08/10/86

DOCKET:309 MAINE YANKEE TYPE:PWR
REGION: 1, NSSS:CE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: MAINE YANKEE ATOMIC POWER CO.
SYMBOL: MYA

COMMENTS

STEP 2: COMP RLX-AUTOMATIC POWER TRANSFER SWITCH DEVICE; MODEL KRP11AG.
STEP 3: MODEL V0658. STEP 10: MODEL 1NN-665. STEP 14: MODEL 5-020-0074-8.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1. 309/84-016 2. 309/86-003

ABSTRACT

POWER LEVEL - 099%. ON AUGUST 10, 1986, AT 0403, THE PLANT TRIPPED FROM 99% POWER DUE TO LOW STEAM GENERATOR LEVEL. AN AUTOMATIC POWER TRANSFER SWITCH DEVICE FOR THE NUMBER ONE FEEDWATER REGULATING SYSTEM (FRS) HAD FAILED AT SOME PREVIOUS TIME AND TRANSFERRED NUMBER ONE FRS POWER TO THE ALTERNATE POWER SUPPLY. WHEN THE ALTERNATE POWER SUPPLY WAS LOST DUE TO A FAILED STATIC INVERTER, THE NUMBER ONE MAIN FEEDWATER REGULATING VALVE CLOSED. THE PARTIAL LOSS OF FEEDWATER RESULTED IN A LOW STEAM GENERATOR LEVEL REACTOR PROTECTIVE SYSTEM TRIP OF THE REACTOR. THE INVERTER WAS REPAIRED, THE TRANSFER SWITCH WAS REPLACED, AND THE TRANSFER SWITCHES FOR NUMBERS TWO AND THREE FRS WERE VERIFIED OPERABLE BEFORE THE PLANT WAS RESTARTED. AFTER THE PLANT TRIP, AN UNRELATED CARDOX FIRE PROTECTION SYSTEM ALARM OCCURRED. INVESTIGATION REVEALED A GROUND IN THE MASTER SUPPLY VALVE SOLENOID HAD TRIPPED THE CARDOX SYSTEM POWER SUPPLY BREAKER, MAKING THE SYSTEM INOPERABLE.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
311 1982 141 1 8312300129 188529 11/21/82

DOCKET: 311 SALEM 2 TYPE: PWR
REGION: 1 NSSS: WE
ARCHITECTURAL ENGINEER: PSEG
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

REFERENCE LERS:
1 311/82-131, 2 272/83-039 3 272/83-043 4 272/83-045

ABSTRACT.
ON TWO SEPARATE OCCASIONS, ON NOV. 21 AND DEC. 4, 1982, DURING ROUTINE OPERATION, THE CONTROL ROOM OPERATOR DISCOVERED THAT THE P-250 COMPUTER WAS INOPERABLE DUE TO A PARITY ERROR. SINCE IT UTILIZES THE COMPUTER FOR INPUTS AND CALCULATIONS, THE REACTOR COOLANT SYSTEM (RCS) SUBCOOLING MONITOR WAS DECLARED INOPERABLE AND ACTION STATEMENT 3.3.3.7A WAS ENTERED. WIDE RANGE RCS TEMPERATURE AND PRESSURE INDICATIONS AND STEAM TABLES WERE AVAILABLE THROUGHOUT THE OCCURRENCE. THE EVENT CONSTITUTED OPERATION IN A DEGRADED MODE PER TECH SPEC 6.9.1.9B. THE MALFUNCTIONS OF THE COMPUTER WERE APPARENTLY RELATED WITH PERIODIC INCREASES IN AMBIENT TEMPERATURE DUE TO INSUFFICIENT VENTILATION. IN EACH CASE, THE COMPUTER WAS REPROGRAMMED AND THE ACTION STATEMENT TERMINATED. THE POWER SUPPLY BREAKER WAS REPLACED AND THE AIR CONDITIONING UNITS WERE REPAIRED. DCRS ARE BEING FORMULATED TO INSTALL SAFETY PARAMETER DISPLAY SYSTEMS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
311 1986 007 0 8610010321 201171 08/26/86

DOCKET: 311 SALEM 2 TYPE: PWR
REGION: 1 NSSS: WE
ARCHITECTURAL ENGINEER: PSEG
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

COMMENTS

OTHER REPORTABILITY - TECH SPECS 3.5.2 (ACTION B).

WATCH-LIST CODES FOR THIS LER ARE:

941 REPORT ASSOCIATED WITH 10 CFR 50.72
913 UPDATE NEEDED

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.
21. OTHER: Voluntary report, special report, Part 21 report,
etc.

REFERENCE LERS:

1 311/85-022 2 311/86-008

ABSTRACT.

POWER LEVEL - 100%. ON AUGUST 26, 1986, A REACTOR TRIP AND SAFETY INJECTION WERE INITIATED BY THE SPURIOUS ACTUATION OF BISTABLES AND CONTACTS RESULTING FROM A VOLTAGE SPIKE ON THE 2C VITAL INSTRUMENT BUS. FOLLOWING THE REACTOR TRIP AND SAFETY INJECTION, A "LOSS OF OFFSITE POWER" SIGNAL WAS RECEIVED. THE REACTOR TRIP/SAFETY INJECTION WAS CAUSED BY A TECHNICIAN INADVERTENTLY SHORTING THE "2C" VITAL INSTRUMENT BUS DURING TROUBLESHOOTING. THE "LOSS OF OFFSITE POWER" SIGNAL WAS APPARENTLY THE RESULT OF A SUSTAINED UNDERVOLTAGE CONDITION ON THE STATION POWER TRANSFORMERS (SPT'S). THE UNDERVOLTAGE CONDITION WAS APPARENTLY CAUSED BY THE TRANSFER OF THE GROUP BUSES FROM THE AUXILIARY POWER TRANSFORMER TO THE SPT'S AND AGGRAVATED BY MULTIPLE TRANSFERS BETWEEN THE STATION POWER TRANSFORMERS. INVESTIGATIONS ARE CONTINUING AS TO THE CAUSE OF THE MULTIPLE TRANSFERS BETWEEN THE SPT'S. BOTH UNITS (1 & 2) ARE BEING OPERATED AT REDUCED POWER SINCE THE LOAD ON THE ELECTRICAL DISTRIBUTION SYSTEM FOR SALEM GENERATING STATION MAY HAVE CONTRIBUTED TO THE SUSTAINED UNDERVOLTAGE CONDITION. A TRANSIENT ANALYSIS OF THE ELECTRICAL DISTRIBUTION SYSTEM FOR SALEM GENERATING STATION IS BEING CONDUCTED. THE REACTOR TRIP AND SAFETY INJECTION ARE REPORTABLE IN ACCORDANCE WITH 10CFR 50.73(A)(2)(IV) AND TECHNICAL SPECIFICATION 3.5.2 (ACTION B), RESPECTIVELY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
311 1988 014 0 8807290082 209958 06/22/88

DOCKET: 311 SALEM 2 TYPE: PWR
REGION: 1 NSSS: WE
ARCHITECTURAL ENGINEER: PSEG
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

COMMENTS

STEP 5: EFF KX - CYCLED OPEN/CLOSED. STEP 21: CAUSE AX - CLOSED DUE TO LEAKAGE. SDE/DE/1.

WATCH-LIST CODES FOR THIS LER ARE:

34 DESIGN ERROR OR INADEQUACY
941. REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 311/85-022 2 311/86-007

ABSTRACT

POWER LEVEL - 100%. ON 6/22/88, DURING ROUTINE POWER OPERATION, A REACTOR TRIP AND SAFETY INJECTION (SI) OCCURRED. THE REACTOR TRIP OCCURRED WHEN THE SOLID STATE PROTECTION SYSTEM (SSPS) (JC) SENSED NO. 23 REACTOR COOLANT PUMP (RCP) BREAKER OPEN. A REACTOR TRIP WILL OCCUR WHEN ONE OF THE FOUR RCP BREAKERS OPENS WITH POWER ABOVE P-8 (36%). THE SI WAS THE RESULT OF A COMBINATION OF THE INDICATION OF NOS. 22 AND 23 STEAMLINE LOW PRESSURE (LESS THAN 500 PSIG) AND NOS. 21 AND 22 HIGH STEAMLINE FLOW. THE UNIT WAS STABILIZED IN MODE 3 (HOT STANDBY). THE APPARENT ROOT CAUSE OF THIS EVENT HAS BEEN ATTRIBUTED TO THE FAILURE OF THE "C" VITAL INSTRUMENT BUS INVERTER. VALVE 2PR2 AND THE NOS. 23 AND 25 CFCUS (WHICH FAILED TO FUNCTION AS DESIGNED DURING THE EVENT) WERE TESTED TO ENSURE OPERABILITY. NO PROBLEMS WERE IDENTIFIED. THE "C" VITAL INSTRUMENT BUS INVERTER WAS REPAIRED. THE UNIT WAS RETURNED TO SERVICE ON JUNE 25, 1988. A DESIGN CHANGE HAS BEEN INITIATED (2EC-2245) TO DELETE THE REACTOR TRIP LOGIC WHICH OCCURS WHEN "ONE OUT OF FOUR RCP BREAKERS OPEN" IS MET. THIS DESIGN CHANGE WILL BE IMPLEMENTED DURING THE UPCOMING FOURTH REFUELING OUTAGE PENDING APPROVAL BY THE NRC OF A SUBMITTED LICENSE CHANGE REQUEST. A SIMILAR DESIGN CHANGE FOR SALEM UNIT 1 WILL BE IMPLEMENTED DURING ITS NEXT REFUELING OUTAGE. A DESIGN CHANGE IS BEING PREPARED TO REPLACE THE INVERTERS WITH STATE OF THE ART EQUIPMENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
311 1989 005 0 8904180088 213562 03/12/89

DOCKET:311 SALEM 2 TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: PSEG
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

COMMENTS

SPECIAL REPORT PURSUANT TO TECH SPECS 3.5.2 (ACTION B).

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON 3/12/89, BOTH STEAM GENERATOR FEED PUMPS (SGFPS) REDUCED THEIR TURBINE SPEED TO IDLE. THE REACTOR SUBSEQUENTLY TRIPPED ON NO. 23 STEAM GENERATOR (S/G) FEED FLOW/STEAM FLOW MISMATCH WITH LOW S/G LEVEL. AFTER THE REACTOR TRIPPED, A SAFETY INJECTION (SI) OCCURRED ON HIGH STEAMLINE FLOW COINCIDENT WITH LOW STEAMLINE PRESSURE. THE ROOT CAUSE OF THIS EVENT HAS BEEN ATTRIBUTED TO AN EQUIPMENT FAILURE: A CONTROL POWER FUSE, IN THE "D" VITAL INSTRUMENT INVERTER LOW VOLTAGE POWER SOURCE, CAME OUT OF ITS FUSE HOLDER RESULTING IN INVERTER FAILURE AND DEENERGIZATION OF "D" VITAL INSTRUMENT BUS. INVESTIGATIONS CONCLUDED THE FUSE MORE THAN LIKELY HAD COME OUT OF THE FUSE HOLDER DUE TO IMPROPER INSTALLATION AT SOME POINT IN THE PAST. THE FUSE ASSEMBLY DID NOT SHOW ANY SIGN OF DAMAGE OR IMPAIRMENT WHICH WOULD CAUSE THE FUSE TO DISLODGE. SUBSEQUENTLY, THE INVERTER FUSE WAS REINSTALLED AND SUCCESSFULLY CHECKED FOR CONTINUITY AND TIGHTNESS. THE STATIC INVERTER WAS STARTED, TESTED SATISFACTORILY AND RETURNED TO SERVICE. ENGINEERING IS INVESTIGATING THE FEASIBILITY OF SEPARATING THE PRESSURE CHANNELS TO OTHER VITAL INVERTERS THEREBY ELIMINATING THE POSSIBILITY OF THE OCCURRENCE OF A SIMILARLY CAUSED SI. NEW VITAL INVERTERS ARE SCHEDULED TO BE INSTALLED DURING THE NEXT UNIT 2 REFUELING OUTAGE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
312 1987 026 1 8708050042 205606 03/10/87

DOCKET:312 RANCHO SECO TYPE:PWR
REGION: 5 NSSS:BW
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: SACRAMENTO MUNICIPAL UTIL. DISTRICT
SYMBOL: SMU

COMMENTS

STEP 32: COMP XI- SATURATION INDICATOR.

WATCH-LIST CODES FOR THIS LER ARE:

- 33 CONSTRUCTION ERROR OR INADEQUACY
- 40 PROCEDURAL DEFICIENCY.

REPORTABILITY CODES FOR THIS LER ARE:


- 11 10 CFR 50.73(a)(2)(ii): Unanalyzed conditions.
- 14 10 CFR 50.73(a)(2)(v): Event that could have prevented fulfillment of a safety function.
- 15 10 CFR 50.73(a)(2)(vii): Single failure criteria.

REFERENCE LERS:

1 312/85-015 2 312/86-010 3 312/87-013

ABSTRACT.

POWER LEVEL - 000%. DURING THE PRESENT COLD SHUTDOWN CONDITIONS, IT WAS DETERMINED THAT SIX CLASS 1 INSTRUMENTATION CABLES (NOT ASSOCIATED WITH RPS/SFAS) ARE ROUTED IN POWER CONTROL RACEWAYS, TWENTY POWER CABLES ARE ROUTED IN CLASS 1 INSTRUMENTATION RACEWAYS, AND SIXTEEN CONTROL CABLES ARE ROUTED IN CLASS 1 INSTRUMENTATION RACEWAYS. THIS INTERMIXING IS CONTRARY TO THE REQUIREMENTS OF USAR SECTION 8.2.2.11.H.5 (10 CFR 50.73(A)(2)(II), 50.73(A)(2)(V) AND 50.73(A)(2)(VII)). IN ADDITION, CONTRARY TO THE REQUIREMENTS OF USAR SECTION 8.2.2.11.H.2, NINETEEN RPS/SFAS INSTRUMENTATION CABLES WERE ROUTED IN INSTRUMENTATION CABLE TRAYS INSTEAD OF CONDUIT. THE ASSESSMENT OF THE SAFETY CONSEQUENCES OF THE INTERMIXED CABLES IS CONTINUING. PRIOR TO ENTERING THE DECAY HEAT SYSTEM OUTAGE, THE INTERMIXED CABLES INVOLVED FOR THE DECAY HEAT SYSTEM OUTAGE HAD BEEN ANALYZED AND DETERMINED TO BE ACCEPTABLE EXCEPT FOR CABLE 122C336B, FOR WHICH CORRECTIVE ACTION WAS TAKEN. ALL INTERMIXED CABLES FOR THE DECAY HEAT SYSTEM OPERATING CONFIGURATION HAVE BEEN ANALYZED AND DETERMINED ACCEPTABLE. THE INSTRUMENTATION CABLES ROUTED IN INSTRUMENTATION CABLE TRAYS INSTEAD OF DEDICATED CONDUIT HAVE BEEN ANALYZED AND ARE ACCEPTABLE BASED ON THE BABCOCK AND WILCOX DESIGN INTERFACE CRITERIA DOCUMENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
312 1989 004 0 8905010104 213732 03/28/89

DOCKET: 312 RANCHO SECO TYPE: PWR
REGION: 5 NSSS: BW
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SACRAMENTO MUNICIPAL UTIL. DISTRICT
SYMBOL: SMU

COMMENTS

STEP 3: MODEL 500-GE-125-60-115; EFF IX - LARGE VOLTAGE SWING DURING
AUTORESTART. STEP 4: MODELS BFTA AND BFTB. STEPS 5, 6, 11: MODEL EHM-32AN.
STEP 21: COMP MEI - VALVE COVERS. STEP 22: EFF HK - LOW VACUUM.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR
34 DESIGN ERROR OR INADEQUACY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 312/78-001 2 312/79-001 3 312/84-007 4 312/85-023
5 312/85-025 6 312/88-018

ABSTRACT

POWER LEVEL - 093%. ON MARCH 28, 1989, AT 1516 HOURS, WHILE OPERATING
AT 93% POWER, THE PLANT'S MAIN FEEDWATER PUMPS (MFPS) EXPERIENCED
SPEED CONTROL PROBLEMS. THIS RESULTED IN A RAPID LOSS OF FEEDWATER
FLOW TO THE STEAM GENERATORS. THE CORRESPONDING INCREASE IN REACTOR
COOLANT SYSTEM (RCS) PRESSURE CAUSED THE PLANT TO AUTOMATICALLY SHUT
DOWN. BECAUSE OF THE MFP CONTROLLER PROBLEMS, THE INTEGRATED CONTROL
SYSTEM (ICS) RESPONSE TO THE PRE-TRIP UNDERFEED CAUSED THE POST-TRIP
FEEDWATER REFEED TO THE RCS TO BE GREATER THAN EXPECTED. THIS
RESULTED IN A PRESSURIZER LEVEL DROP TO THE ELEVATION OF THE LEVEL
INDICATOR TAP. THE PLANT DID NOT EXIT THE POST-TRIP WINDOW, AND NORMAL
POST-TRIP LEVELS WERE ESTABLISHED 14 MINUTES AFTER THE TRIP.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
317 1985 002 0 8503140392 194176 02/05/85

DOCKET:317: CALVERT CLIFFS 1 TYPE:PWR
REGION: 1 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: BALTIMORE GAS & ELECTRIC CO.
SYMBOL: BGE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AT 1658 ON 2-5-85, CALVERT CLIFFS UNIT 1 REACTOR TRIPPED FROM 100% POWER ON A LOW SG WATER LEVEL CONDITION CAUSED BY A TEMPORARY REDUCTION AND SUBSEQUENT LOSS OF MAIN FEEDWATER FLOW. THE UNIT 1 AUX BLDG OPERATOR INCORRECTLY DEENERGIZED A PORTION OF THE FEEDWATER REGULATING SYSTEM WHILE ATTEMPTING TO DEENERGIZE #11 INSTRUMENT AIR COMPRESSOR. THIS CAUSED THE STEAM GENERATOR FEED PUMPS TO SLOW DOWN EVEN THOUGH REACTOR POWER REMAINED AT 100%. REALIZING HE HAD OPENED THE WRONG BREAKER, THE AUX BLDG OPERATOR RESHUT THE BREAKER TO THE DEENERGIZED PORTION OF THE FEEDWATER REGULATING SYSTEM. THIS SENT THE ACTUAL 100% FEEDWATER DEMAND SIGNAL TO THE SG FEED PUMPS SPEED CONTROL SYSTEM AND CAUSED THE SG FEED PUMPS TO RAPIDLY ACCELERATE. THIS EXTREME TRANSIENT CAUSED THE SG FEED PUMPS TO TRIP ON LOW SUCTION PRESSURE. UNIT 1 THEN TRIPPED ON LOW SG WATER LEVEL.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
318 1988 002 2 8804200389 208918 01/22/88

DOCKET:318 CALVERT CLIFFS 2 TYPE:PWR
REGION: 1 NSSS:CE
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: BALTIMORE GAS & ELECTRIC CO.
SYMBOL: BGE

COMMENTS

STEP 15: EFF HX - PUMP FLOW ON HOLD (AS IS). STEP 20: EFF HL - CHANGE IN
NET POSITIVE SUCTION HEAD. \$MPA/PT

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 318/86-007

ABSTRACT

POWER LEVEL - 100%. DURING TROUBLESHOOTING OF THE THREE PHASE UNIT 2
COMPUTER INVERTER, POWER WAS LOST TO THE NON-VITAL 208/120V A.C.
INSTRUMENT BUS 22 (2Y10). THE DE-ENERGIZATION OF 2Y10 RESULTED IN
REDUCED FEEDWATER FLOW AND CAUSED THE REACTOR TO BE TRIPPED NEAR THE
LOW STEAM GENERATOR LEVEL SETPOINT. THE LOSS OF INSTRUMENT BUS 22
(2Y10) WAS CAUSED BY PERSONNEL ERROR WHEN A PLANT ELECTRICIAN'S
MISINTERPRETATION OF ELECTRICAL PRINTS AND UNCLEAR COMMUNICATIONS WITH
THE INVERTER VENDOR LED TO THE PLACEMENT OF TEMPORARY JUMPERS IN THE
INVERTER, CAUSING A DIRECT SHORT CIRCUIT THAT WAS REFLECTED BACK TO
THE MAIN POWER FEED CIRCUIT BREAKER CAUSING IT TO TRIP THUS
DE-ENERGIZING INSTRUMENT BUS 22 (2Y10). CORRECTIVE ACTIONS ARE: 1. A
STUDY OF THE PROPER SIZE FUSING AND FUSE TO CIRCUIT BREAKER
COORDINATION IS IN PROGRESS. 2. CLARIFY THE INVERTER MANUFACTURERS
ELECTRICAL PRINTS TO SHOW THE ACTUAL PLACEMENT, IN THE CIRCUIT, OF THE
POWER FACTOR CORRECTION CAPACITORS. 3. INVESTIGATE THE USE OF
"SPECIAL" PROCEDURES IN TROUBLESHOOTING COMPLEX EQUIPMENT. 4. ALL
MAINTENANCE ELECTRICIANS WILL BE TRAINED ON THE DETAILS OF THIS EVENT
AS PART OF OUR CONTINUING TRAINING PROGRAM.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
321 1985 010 1 8508230260 197783 01/16/85

DOCKET: 321 HATCH 1. TYPE: BWR
REGION: 2 NSSS: GE
ARCHITECTURAL ENGINEER: BESS
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

STEP 12: COMP MSC - SPRING, TAPPET AND BALL ASSEMBLY; STEP 18: EFFECT HX -
FLOW FLUCTUATIONS.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 321/85-003

ABSTRACT

POWER LEVEL - 061%. ON 1-16-85 AT 0955 CST, WITH THE REACTOR MODE SWITCH IN THE RUN POSITION AND REACTOR POWER AT 1496 MWT UNIT 1 RECEIVED A REACTOR SCRAM ON A REACTOR VESSEL LOW WATER LEVEL SIGNAL. THIS EVENT WAS THE RESULT OF A VITAL AC POWER SUPPLY TRIP, WHICH CAUSED BOTH 'A' AND 'B' REACTOR FEEDPUMPS TO RUN BACK. CONSEQUENTLY, A LOW WATER LEVEL CONDITION RESULTED. AT 1102 CST, WHILE PLANT PERSONNEL WERE LOWERING REACTOR PRESSURE, THE REACTOR VESSEL WATER LEVEL INCREASED TO THE HIGH LEVEL SETPOINT AND THE REACTOR FEEDPUMPS TRIPPED. BEFORE PLANT PERSONNEL COULD RESET THE FEEDPUMPS, WITH REACTOR POWER AT 0 MWT, THE REACTOR LEVEL DROPPED TO THE LOW LEVEL SETPOINT. THIS CAUSED AN ACTUATION OF THE RPS LOGIC (I.E., NOT A SCRAM BECAUSE ALL OF THE CONTROL RODS WERE STILL INSERTED AFTER THE 0955 CST SCRAM), AND A GROUP 2 ISOLATION. PLANT PERSONNEL RESTORED THE REACTOR LEVEL TO NORMAL VIA THE 'A' REACTOR FEEDPUMP AND THE BOOSTER PUMPS AS THE VESSEL CONTINUED TO DEPRESSURIZE. NO ACTUAL OR POTENTIAL SAFETY CONSEQUENCES OR IMPLICATIONS RESULTED FROM THESE EVENTS. THESE EVENTS HAD NO IMPACT ON ANY OTHER UNIT 1 SYSTEM OR UNIT 2. THESE ARE NON-REPETITIVE EVENTS; HOWEVER, THE LAST REACTOR SCRAM IS REFERENCED IN LER 50-321/85-03.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
321 1987 011 1 8906010264 213971 07/23/87

DOCKET: 321. HATCH. 1 TYPE: BWR
REGION: 2 NSSS: GE
ARCHITECTURAL ENGINEER: BESS
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

STEP 2: PSYS HS - VITAL AC ROOM. STEP 4: MODEL 120G2500-FE3. STEP 21: MODEL 8270-849.

WATCH-LIST CODES FOR THIS LER ARE:

34 DESIGN ERROR OR INADEQUACY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 321/85-010 2 366/87-006

ABSTRACT

POWER LEVEL - 100%. ON 7/23/87 AT APPROXIMATELY 2114 CDT, UNIT 1 WAS IN THE RUN MODE AT AN APPROXIMATE POWER LEVEL OF 2436 MWT (APPROXIMATELY 100 PERCENT OF RATED THERMAL POWER). AT THAT TIME, VITAL AC (EIIIS CODE EE) POWER WAS LOST. THIS RESULTED IN A DECREASE IN THE REACTOR FEEDWATER PUMPS FLOW AND A DECREASE IN REACTOR WATER LEVEL. THE REACTOR WATER LEVEL DECREASED TO THE REACTOR PROTECTION SYSTEM (RPS EIIIS CODE JC) ACTUATION SETPOINT AND A REACTOR SCRAM OCCURRED. THE ROOT CAUSE OF THIS EVENT IS ATTRIBUTED TO EQUIPMENT FAILURE DUE TO INADEQUATE VENTILATION DESIGN TO ENSURE THE VITAL AC EQUIPMENT IS PROPERLY COOLED. THE ELECTRONIC EQUIPMENT FAILURE IN THE INVERTERS IS ATTRIBUTED TO THE HIGH ROOM TEMPERATURES. CORRECTIVE ACTIONS FOR THIS EVENT INCLUDE: 1) REFURBISHING THE INVERTER, 2) ADDING TEMPORARY COOLING TO THE INVERTER ROOMS, 3) INSTALLING A NEW HVAC SYSTEM FOR COOLING INVERTER ROOMS, 4) DEVELOPING A PREVENTIVE MAINTENANCE PROCEDURE FOR THE UNIT 1 AND 2 INVERTERS, 5) PERFORMING AN ENGINEERING EVALUATION FOR INVERTER REPLACEMENT, 6) INSTALLING NEW VITAL AC INVERTERS FOR BOTH UNITS 1 AND 2, 7) REPLACING THE FAILED RCIC EGM MODULE, AND 8) PERFORMING A FOLLOW UP INSPECTION OF THE HPCI EGM MODULE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
322 1988 016 1 9005240099 218259 10/11/88

DOCKET: 322 SHOREHAM TYPE: BWR
REGION: 1, NSSS: GE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: LONG ISLAND LIGHTING CO.
SYMBOL: LIL

WATCH-LIST CODES FOR THIS LER ARE:

941. REPORT ASSOCIATED WITH 10 CFR 50.72
20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 322/85-040 2 322/85-046 3 322/86-030 4 322/86-031
5 322/88-001

ABSTRACT

POWER LEVEL - 000%. ON 10/11/88 AT 1134, LARGE FLUCTUATIONS IN SYSTEM VOLTAGE CAUSED THE UNPLANNED ACTUATION OF ONE ENGINEERED SAFETY FEATURE (ESF) AND VALVE MOVEMENT IN THREE OTHER ESF SYSTEMS. THE PLANT WAS IN OPERATIONAL CONDITION 4 (COLD SHUTDOWN) WITH THE MODE SWITCH IN SHUTDOWN AND ALL CONTROL RODS INSERTED. THE VOLTAGE FLUCTUATIONS WERE CAUSED BY MOMENTARY SHORTS TO GROUND WHERE THE 138 KV LINES AND THE 69 KV LINES RUN TOGETHER THROUGH A SUBSTATION LOCATED 5 MILES SOUTH OF THE SITE. A LOOSE SHIELD WIRE MOMENTARILY CAUSED THE 138 KV LINES TO SHORT TO GROUND, THEN SKIPPED OVER TO THE 69 KV LINES TO MOMENTARILY CAUSE ANOTHER SHORT TO GROUND. THIS EVENT ENDED WHEN A PASSING TRAIN CAUSED THE SHIELD WIRE TO DISENGAGE FROM THE TRANSMISSION LINES. THE VOLTAGE FLUCTUATIONS CAUSED THE REACTOR BUILDING STANDBY VENTILATION SYSTEM (RBSVS) TO ACTUATE ALONG WITH SOME VALVE MOVEMENT IN THE CONTROL ROOM AIR CONDITIONING (CRAC) SYSTEM, THE REACTOR BUILDING CLOSED LOOP COOLING WATER (RBCLCW) SYSTEM AND THE REACTOR BUILDING SERVICE WATER (RBSW) SYSTEM. OPERATORS TOOK THE NECESSARY ACTIONS TO RETURN THE ESF SYSTEMS TO THEIR NORMAL CONDITIONS. TO ENSURE PERSONNEL WERE AWARE OF THE RAMIFICATIONS OF SUCH AN EVENT, THIS LER WAS READY BY ALL OPERATORS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
322 1990 008 0 9010170325 219729 09/15/90

DOCKET:322 SHOREHAM TYPE:BWR
REGION: 1 NSSS:GE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: LONG ISLAND LIGHTING CO.
SYMBOL: LIL

COMMENTS

STEP 12: EFF IX - SWITCHED TO ALTERNATE POWER SUPPLY. STEP 15: COMP MEI -
REMOTE DATA ACQUISITION UNITS.

WATCH-LIST CODES FOR THIS LER ARE:

11 ACTS OF NATURE
941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 322/85-040 2 322/85-046 3 322/86-030 4 322/88-016

ABSTRACT

POWER LEVEL - 000%. ON 9/15/90, AT 0732, A LIGHTNING STRIKE DURING A SEVERE THUNDERSTORM CAUSED THE UNPLANNED ACTUATION OF ENGINEERED SAFETY FEATURE SYSTEMS REACTOR BUILDING STANDBY VENTILATION SYSTEM, AND CONTROL ROOM AIR CONDITIONING AND THE CLOSURE OF CONTAINMENT ISOLATION VALVES FOR THE REACTOR WATER CLEANUP SYSTEM, THE REACTOR BUILDING FLOOR DRAINS AND THE REACTOR BUILDING EQUIPMENT DRAINS. REACTOR PROTECTION SYSTEM BUS "B" WAS DEENERGIZED DUE TO TRIPPING OF AN ELECTRICAL PROTECTION ASSEMBLY BREAKER. OTHER EQUIPMENT EFFECTS CAUSED BY THE LIGHTING STRIKE INCLUDE TRIPPING OF THE STATION AIR COMPRESSORS, LOSS OF THE PLANT PROCESS COMPUTER, A CONTROL ROOM VENTILATION MONITOR GOING INTO A FAILURE MODE AND BLOWN CIRCUIT CARDS IN SEVERAL REMOTE DATA ACQUISITION UNITS IN THE PLANT SECURITY SYSTEM. OPERATORS AND TECHNICIANS RESTARTED THE AFFECTED EQUIPMENT AND RESTORED SYSTEMS TO THEIR NORMAL LINEUPS. PLANT MANAGEMENT PERSONNEL WERE NOTIFIED OF THE EVENT AND THE NRC WAS NOTIFIED AT 1006 PER 10CFR50.72(B)(2)(II). THIS LICENSEE EVENT REPORT IS BEING SUBMITTED PER 10CFR50.73(A)(2)(IV).




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC. EVENT DATE
325 1980 026 0 8003180395 155308 02/12/80

DOCKET: 325 BRUNSWICK 1 TYPE: BWR
REGION: 2 NSSS: GE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: CAROLINA POWER & LIGHT CO.
SYMBOL: CPL

ABSTRACT

POWER LEVEL - 099%. CAUSE - BLOWN FUSE IN 28 VDC POWER SUPPLY. DURING NORMAL FULL POWER OPERATION, THE CONTROL OPERATOR RECEIVED UPSCALE DOWNSCALE, INOPERABLE, AND ROD BLOCK ALARMS ON ROD BLOCK MONITOR "A". NO EVOLUTIONS OR TESTING WERE IN PROGRESS AT THE TIME. A BLOWN FUSE WAS FOUND IN THE 28 VDC POWER SUPPLY. THE FUSE WAS REPLACED AND THE 28 VDC POWER SUPPLY WAS CLOSELY MONITORED FOR THREE DAYS, WITH PROPER OPERATION OBSERVED. NO PROBLEM COULD BE DISCOVERED. BLOWN FUSES ON THIS EQUIPMENT HAS NOT BEEN A PROBLEM IN THE PAST.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
325 1980 091 0 8101200629 163557 12/11/80

DOCKET:325 BRUNSWICK 1 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: CAROLINA POWER & LIGHT CO.
SYMBOL: CPL

ABSTRACT

POWER LEVEL - 097%. CAUSE - DEFECTIVE POWER SUPPLY AND ZENER DIODE.
DURING TESTING, ROD BLOCK MONITOR B WAS OBSERVED INDICATING DOWNSCALE.
THE MONITOR WAS THEN DECLARED INOPERABLE AS REQUIRED BY TECH. SPECS.
THE MONITOR INDICATED DOWNSCALE DUE TO A FAILED POWER SUPPLY CAUSED BY
A DEFECTIVE POWER SUPPLY REGULATOR AND ZENER DIODE IN THE POWER
SUPPLY REGULATOR CIRCUIT. THE REGULATOR AND DIODE WERE REPLACED AND
THE MONITOR RETURNED TO NORMAL OPERATION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
325 1985 022 1 8507010620 197922 05/02/85

DOCKET:325 BRUNSWICK 1 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: UECX
FACILITY OPERATOR: CAROLINA POWER & LIGHT CO.
SYMBOL: CPL

COMMENTS


STEP 3: PART NO. 700DC-N200Z1.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. DURING A UNIT 1 REFUEL/MAINTENANCE OUTAGE, ON 5-02-85, AT 1407, A PRIMARY CONTAINMENT GROUP 6 ISOLATION OCCURRED, THE REACTOR BUILDING VENTILATION SYSTEM AUTOMATICALLY ISOLATED, AND TRAIN 1B OF THE REACTOR BUILDING STANDBY GAS TREATMENT (SBGT) SYSTEM AUTOMATICALLY STARTED. A REACTOR BUILDING FIRE WATCH HAD OBSERVED SMOKE EMANATING FROM SBGT TRAIN 1A AND REPORTED THE DISCOVERY TO THE CONTROL ROOM. OPERATIONS PERSONNEL ASSESSED THE PROBLEM AND DEENERGIZED THE POWER SUPPLY (CIRCUIT BREAKER NO. 25 IN POWER SUPPLY PANEL 1C) TO THE TROUBLE START CONTROL RELAY CIRCUITRY OF SBGT TRAIN 1A, THEREBY RESULTING IN THE EVENT. RELAY CR-4, WHICH IS IN THE CIRCUITRY TO THE UNIT SBGT TRAINS' HIGH TEMPERATURE CONTROL ROOM ANNUNCIATOR, HAD OVERHEATED AND CAUGHT FIRE. THE FIRE WAS REPORTED OUT AT 1418. SBGT TRAIN 1B WAS SECURED AND RETURNED TO STANDBY, AND THE ISOLATION SIGNALS WERE RESET. THE INVOLVED SMOKE DID NOT AFFECT OPERABILITY OF SBGT TRAIN 1B. ON 5-07-85, CR-4 (ALLEN-BRADLEY PART NO. 700DC-N200Z1) TO SBGT 1A WAS REPLACED. THE FAILURE OF CR-4 IS ATTRIBUTED TO RELAY COIL INSULATION BREAKDOWN RESULTING FROM INDETERMINATE CAUSES. THE CR-4 RELAYS IN SBGT 1B AND UNIT 2 SBGTS 2A AND 2B WERE VISUALLY INSPECTED FOR SIGNS OF OVERHEATING OR PHYSICAL DEGRADATION WITH NO PROBLEMS FOUND.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
327 1980 159 0 8011040606 160938 10/15/80

DOCKET: 327 SEQUOYAH 1 TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: TVAX
FACILITY: OPERATOR: TENNESSEE VALLEY AUTHORITY
SYMBOL: TVA

COMMENTS
STEP 2: ISYS SW - UNSPECIFIED AREAS.

ABSTRACT
POWER LEVEL - 000%. CAUSE - AFWS PUMP LOCK INDEPENDENT CONTROL POWER.
NOTIFICATION WAS RECEIVED FROM TVA ENGINEERING DESIGN THAT A MAJOR
FEEDWATER LINE RUPTURE ON EITHER STEAM GENERATOR 3 OR 4, CONCURRENT
WITH A LOSS OF CHANNEL Q-I VITAL INSTRUMENT POWER COULD PREVENT THE
AUXILIARY FEEDWATER SYSTEM FROM OPERATING AS ASSUMED IN THE SAR.
FAILURE OF ENGINEERING DESIGN TO PROVIDE SUFFICIENT INDEPENDENCE OF
CONTROL POWER SUPPLIES TO THE A AND B TRAIN MOTOR DRIVEN PUMPS
AUXILIARY FEEDWATER SYSTEMS AND THE TURBINE DRIVEN PUMP AUXILIARY
FEEDWATER SYSTEM. A MODIFICATION HAS BEEN MADE WHICH PROVIDES ADEQUATE
INDEPENDENCE OF THE CONTROL POWER SUPPLIES AND INSURES THAT THE
AUXILIARY FEEDWATER SYSTEM IS CAPABLE OF PERFORMING AS ASSUMED IN THE
SAR.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
328 1985 004 0 8503250308 194177 02/15/85

DOCKET:328 SEQUOYAH 2 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: TVAX
FACILITY OPERATOR: TENNESSEE VALLEY AUTHORITY
SYMBOL: TVA

COMMENTS


STEP 18: EFF HX - FLOW OSCILLATIONS; STEPS 15, 16: COMP MEI - FILTER COVER.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. TWO REACTOR TRIPS OCCURRED ON 2-15-85, AND 2-17-85, RESPECTIVELY, DUE TO LO-LO SG WATER LEVEL. ALL REACTOR PROTECTION AND ENGINEERED SAFEGUARD SYSTEMS PERFORMED AS DESIGNED, AND NO ANOMALIES WERE NOTED. INVESTIGATION INTO THE EVENT OF 2-15 REVEALED THAT POWER WAS LOST TO PROTECTION SET I INSTRUMENTATION, CAUSING A REDUCTION IN FEEDWATER FLOW TO ALL SG'S. FEED PUMP SPEED CONTROL HAS INPUT TO A SUMMING DEVICE FOR TOTAL STEAM FLOW. THIS SIGNAL CAN BE MANUALLY SELECTED AT THE MAIN CONTROL BOARD TO BE FED FROM EITHER PROTECTION SET I OR II INSTRUMENTATION. THE NORMAL OPERATING POSITION IS PROTECTION SET I, IN WHICH CASE, UPON LOSS OF POWER TO PROTECTION SET I, THE STEAM FLOW SIGNAL WENT TO A ZERO INPUT TO THE FEEDWATER PUMP SPEED CONTROLLER CAUSING THE FEEDWATER PUMP TO REDUCE SPEED. THIS REDUCED PUMP SPEED RESULTED IN A REDUCED FEED FLOW TO ALL SG'S WHEN ACTUAL STEAM FLOW WAS STILL AT FULL POWER RATING. ALSO, LOSS OF PROTECTION SET I CAUSED LOOPS 1 AND 3 FEEDWATER REGULATOR VALVES TO FAIL CLOSED. THE FINAL RESULT WAS A REACTOR TRIP ON LO-LO SG LEVEL IN LOOP 1. THE REASON FOR THE LOSS OF PROTECTION SET I POWER WAS A PERSONNEL ERROR MADE WHILE TRYING TO REMOVE VITAL INVERTER 2-I FROM SERVICE FOR MAINTENANCE. WHILE OPERATING AT 30% POWER, A SECOND REACTOR TRIP OCCURRED AT 0243 CST ON 2-17-85, DUE TO LO-LO SG LEVEL IN LOOP 2.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
328 1988 017 0 8805040152 209177 04/01/88

DOCKET: 328 SEQUOYAH 2 TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: TVAX
FACILITY OPERATOR: TENNESSEE VALLEY AUTHORITY
SYMBOL: TVA.

COMMENTS

STEP 2: MODEL NO. HGA-CFHLIQU. SAML/TE

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 327/84-006	2 327/84-007	3 327/84-013	4 327/84-026
5 327/84-031	6 327/84-033	7 327/84-036	8 327/84-054
9 327/84-064	10 327/85-029	11 327/87-005	12 328/84-008
13 328/84-014	14 328/84-015	15 328/84-016	16 328/84-017
17 328/84-018	18 328/84-020	19 328/84-021	20 328/85-001
21 328/85-002	22 328/85-004	23 328/85-009	24 328/88-006
25 328/88-013			

ABSTRACT

POWER LEVEL - 000%. ON APRIL 1, 1988, AN INADVERTENT REACTOR TRIP SIGNAL WAS GENERATED ON UNIT 2 WHEN THE ASSISTANT SHIFT SUPERVISOR (ASST. SS) WAS ATTEMPTING TO SECURE A CONTROL POWER FUSE ON THE SOURCE RANGE, NEUTRON FLUX CHANNEL N-31. THE FUSE LOCKS INTO POSITION BY A METAL CONNECTOR WHICH HAS TWO METAL TABS THAT LOCK INTO THE FUSE HOLDER AS THE CONNECTOR IS INSERTED AND ROTATED. ATTACHED TO THE OUTER PORTION OF THE FUSE CONNECTOR IS A PLASTIC COVER WHICH IS USED TO FACILITATE REMOVAL/INSTALLATION OF THE FUSE. THE PLASTIC COVER HAS TWO FLAT SURFACES WHICH ARE NORMALLY IN THE HORIZONTAL POSITION WHEN THE FUSE CONNECTOR IS LOCKED INTO POSITION CORRECTLY. BEFORE THIS EVENT, THE PLASTIC COVER WAS OBSERVED TO BE ROTATED SLIGHTLY SUCH THAT THE FLAT SURFACES WERE NOT HORIZONTAL. THUS, THE FUSE APPEARED TO BE IN A CONDITION SUCH THAT THE POTENTIAL EXISTED FOR THE FUSE TO DISCONNECT AT ANY TIME AND GENERATE A REACTOR TRIP SIGNAL. WHEN THE ASST. SS ATTEMPTED TO LOCK THE FUSE IN PLACE, CONTROL POWER WAS INTERRUPTED MOMENTARILY, AND SUBSEQUENTLY, THE REACTOR TRIP SIGNAL GENERATED. NO REACTOR TRIP OCCURRED BECAUSE THE REACTOR TRIP BREAKERS WERE OPEN AND THE RODS INSERTED.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
331 1984 028 1 8411270179 197271 07/14/84

DOCKET:331. ARNOLD TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL:ENGINEER: BECH
FACILITY OPERATOR: IOWA ELECTRIC LIGHT & POWER CO.
SYMBOL: IEL

COMMENTS

STEP 1: CAUSE XX - ACCIDENTAL MOTORING OF A 650.MWE GENERATOR AT A FOSSIL
UNIT; STEPS 9 AND 10: CAUSE IX - ELECTRICAL DISTURBANCE; STEP 10: MODEL 86.

REPORTABILITY CODES FOR THIS LER ARE:

- 13 10 CFR 50.73(a)(2)(iv): ESF actuations.
- 14 10 CFR 50.73(a)(2)(v): Event that could have prevented fulfillment of a safety function.

ABSTRACT

POWER LEVEL - 000%. ON 7-14-84 AT 1524 WITH THE REACTOR SUBCRITICAL IN THE STARTUP MODE, A DEGRADED VOLTAGE CONDITION ON THE OFFSITE POWER GRID RESULTED IN THE AUTOMATIC SWITCHING OF THE ESSENTIAL BUSES FROM OFFSITE TO ONSITE POWER. AS PER DESIGN, THE RPS LOGIC DE-ENERGIZED, INITIATING A SCRAM. ALL REQUIRED SYSTEMS OPERATED AS DESIGNED, INCLUDING THE 2 DG'S ASSUMING THE ESSENTIAL LOADS. HOWEVER, THE HPCI INBOARD STEAM SUPPLY VALVE ALSO CLOSED. THE REASON FOR THIS RESPONSE IS UNKNOWN AND UNDER INVESTIGATION. AFTER CONSULTATION WITH THE LOAD DISPATCHER CONFIRMING A RETURN TO GRID NORMALITY, THE DIESELS WERE SECURED. A POST-EVENT REVIEW CONFIRMED OPERABILITY OF ALL SYSTEMS, WHICH WERE THEN RETURNED TO SERVICE. REACTOR STARTUP COMMENCED 3 AND 1/2 HRS FOLLOWING THE SCRAM. ON 10-15-84, A SPECIAL TEST PROCEDURE DEMONSTRATED THAT THE CAUSE OF THE HPCI INBOARD STEAM SUPPLY CONTAINMENT ISOLATION VALVE CLOSURE WAS A SPURIOUS ISOLATION SIGNAL UPON RE-ENERGIZING FROM EITHER OR BOTH OF 2 TEMPERATURE SWITCHES IN THE HPCI STEAM LEAK DETECTION SYSTEM. A MINOR DESIGN CHANGE WITHIN THE PCI STEAM LEAK DETECTION SYSTEM HAS RESOLVED THIS PROBLEM.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
333 1990 001 0 9002260448 216910 01/19/90

DOCKET:333 FITZPATRICK TYPE:BWR
REGION: 1. NSSS:GE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: POWER AUTHORITY OF THE STATE OF NY
SYMBOL: PNY

COMMENTS

STEP 6: EFF AX - RAPID MANIPULATION OF EQUALIZING VALVE. STEP 23: EFF IX -
VOLTAGE TRANSIENT. STEP 24: EFF IX - TRANSFER TO DC SUPPLY. STEP 26: EFF IX
- RUNBACK TO NO. 2 LIMITER.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR
20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 333/85-012 2 333/87-020

ABSTRACT

POWER LEVEL - 100%. A REACTOR SCRAM FROM FULL POWER OCCURRED AT 10:45
A.M. ON JANUARY 19, 1990 DURING THE CALIBRATION OF REACTOR WATER LEVEL
INSTRUMENTATION. THE INSTRUMENT WHICH WAS BEING CALIBRATED SHARES
COMMON REFERENCE AND VARIABLE LEGS WITH INSTRUMENTS OF THE REACTOR
PROTECTION SYSTEM (RPS) (JE). WHILE ISOLATING THE INSTRUMENT UNDER
TEST, A VALVE PACKING LEAK DEVELOPED. DURING THE RESPONSE TO THIS
LEAK, VALVE ACTUATION CAUSED A FALSE LOW WATER LEVEL TO BE SENSED BY
THE RPS. THIS FALSE LOW LEVEL TRANSIENT WAS CAUSED BY RAPID VALVE
MOVEMENT BY THE FIELD TECHNICIAN PERFORMING THE VALVE MANIPULATIONS.
CORRECTIVE ACTIONS INCLUDE REVIEW OF THIS EVENT WITH ALL I&C
TECHNICIANS, GROOMING OF THE COMMUNICATION SYSTEM TO ELIMINATE NOISE,
AND REPAIR OF EQUIPMENT THAT MALFUNCTIONED DURING THE TRANSIENT.
RELATED LERS: 85-012 AND 87-020.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
334 1985 003 0 8503190194 193577 01/16/85

DOCKET:334 BEAVER VALLEY 1. TYPE:PWR
REGION: 1, NSSS:WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: DUQUESNE LIGHT CO.
SYMBOL: DUQ

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 096%. ON 1-16-85, AT 1528 HRS, METER AND CONTROL REPAIRMEN WERE PERFORMING MAINTENANCE SURVEILLANCE PROCEDURE 6.40, 'T-RC 432 DELTA-T T-AVG PROTECTION INSTRUMENT CHANNEL III CALIBRATION', WHEN THE FEEDER BREAKER FROM VITAL BUS III TO A PORTION OF PROTECTION CHANNEL III OPENED. THIS PRODUCED NUMEROUS ALARMS ASSOCIATED WITH THE SG WATER LEVEL CONTROL, PRESSURIZER PRESSURE AND LEVEL, AND THE RPS. WHILE RESPONDING TO THE ALARMS, THE OPERATORS NOTICED THE MAIN FEEDWATER REGULATING VALVES (FCV-FW-478, 488, 498) FULL OPEN, THE CONTROLLERS WERE PLACED IN MANUAL AND THE VALVES THROTTLED. AT 1530 HRS, A REACTOR TRIP AND SAFETY INJECTION OCCURRED. THE REACTOR TRIP WAS CAUSED BY A STEAM FLOW/FEED FLOW MISMATCH IN COINCIDENCE WITH A LOW WATER LEVEL IN THE 'B' SG. THE SAFETY INJECTION SIGNAL WAS CAUSED BY A LOW STEAMLINE PRESSURE SIGNAL IN 2 OUT OF 3 PRESSURE SENSORS ON THE 'C' LOOP. THE EMERGENCY OPERATING PROCEDURES WERE FOLLOWED TO RECOVER FROM THE INADVERTENT SAFETY INJECTION AND REACTOR TRIP. BREAKER 3-3 WAS THOUGHT TO HAVE OPENED DUE TO PERSONNEL ERROR DURING THE PERFORMANCE OF MSP 6.40. HOWEVER, A POST-TRIP SIMULATION PROVED INCONCLUSIVE. BREAKER 3-3 WAS REMOVED, REPLACED WITH A TESTED SPARE AND WAS BENCH TESTED SATISFACTORILY. SAFETY INJECTIONS TO DATE: 18 OPERATIONAL, 2 PRE-OPERATIONAL.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 002 0 8002210386 155548 01/04/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2. NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


STEP 1: MODEL SU-UNI-30A-BV; RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/76-037	2 335/78-021	3 335/79-006	4 335/80-023
5 335/80-033	6 335/80-034	7 335/80-035	8 335/80-036
9 335/80-043	10 335/80-045	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILURE. DURING NORMAL OPERATION, CEA 22 DROPPED TO FULL INSERTION. ACTION IN ACCORDANCE WITH TECH. SPECS WAS INITIATED AND REACTOR POWER WAS REDUCED. CEA 22 WAS RESTORED TO IT'S NORMAL POSITION WITHIN 1 HOUR. TQ WAS FOUND TO BE .044. TQ WAS DETERMINED TO BE WITHIN LIMITS IN LESS THAN 5 HOURS. NO OTHER CORE LIMITS WERE EXCEEDED. THE REACTOR WAS RETURNED TO 100% POWER. SIMILAR OCCURRENCES WERE REPORTED AS LERS 335-76-37, 78-21. AND 79-6. CEA #22 DROPPED DUE TO A FAILED 15V POWER SUPPLY (POWER RATE MODE SU-UNI-30A-BV) IN THE COIL POWER PROGRAMMER. NO CAUSE FOR THIS FAILURE COULD BE DETERMINED. IMMEDIATE CORRECTIVE ACTION WAS TO REPLACE THE POWER SUPPLY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 023 0 8006230495 157681 05/11/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


STEPS 1 AND 5: MODEL SU-UNI-30A-BV; RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/76-037	2 335/78-021	3 335/79-006	4 335/80-002
5 335/80-033	6 335/80-034	7 335/80-035	8 335/80-036
9 335/80-043	10 335/80-045	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 018%. CAUSE - POWER SUPPLY FAILURE. DURING POWER ASCENSION CEA 19 DROPPED TO FULL INSERTION. THE POWER SUPPLY UNIT FOR CEA 19 HAD FAILED. THE POWER SUPPLY WAS REPLACED AND CEA 19 WAS ALIGNED WITH ITS CEA GROUP HEIGHT. ON 5-11-80 CEA 58 DROPPED. APPROPRIATE ACTION WAS TAKEN AND CEA 58 WAS RESTORED TO ITS GROUP POSITION. SIMILAR OCCURRENCES WERE REPORTED AS LERS 335-76-37, 78-21, 79-6, 80-2. THE CAUSE OF BOTH DROPPED CEAS WAS DUE TO FAILED 15V POWER SUPPLY UNITS (SU-UNI-30A-BV). BOTH CEAS WERE RESTORED IN 30 MINUTES OR LESS AND NORMAL OPERATION WAS RESUMED. SINCE THESE POWER SUPPLIES ARE OF A NEW TYPE, IT IS POSSIBLE THAT THE RECENT FAILURES ARE ASSOCIATED WITH THE INITIAL BREAK-IN PERIOD.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 030 0 8007150636 158742 06/03/80


DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS

STEP 1: MODEL RB6-30.

ABSTRACT

POWER LEVEL - 100%. CAUSE - HIGH VOLTAGE POWER SUPPLY FAILURE. DURING NORMAL FULL POWER OPERATION, THE CRT ROD POSITION DISPLAY (METRASCOPE) WAS BRIEFLY DENERGIZED TO PERMIT REPLACEMENT OF A FAILING POWER SUPPLY. THIS ALSO DISABLED THE CEA BLOCK CIRCUIT. THE CIRCUIT WAS RETURNED TO SERVICE WITHIN 9 MINUTES, WHICH IS WELL WITHIN THE 6 HOUR LIMIT OF T.S. THE SOURCE OF CEA POSITION INDICATION WAS NOT LOST AND ANOTHER READOUT DEVICE WAS AVAILABLE. THIS IS THE FIRST TIME THE CEA BLOCK CIRCUIT WAS UNAVAILABLE FOR THIS PARTICULAR REASON. THE METRASCOPE CRT DISPLAY BEGAN TO FADE, AND INVESTIGATION SHOWED THAT THE HIGH VOLTAGE POWER SUPPLY (POWERMATE MODEL RB6-30) WAS FAILING. THE METRASCOPE WAS BRIEFLY DENERGIZED AND THE POWER SUPPLY WAS REPLACED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 032 0 8008250788 159370 07/14/80


DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL.

REFERENCE LERS:

1 335/80-023 2 335/80-010 3 335/80-007 4 335/80-002

ABSTRACT

POWER LEVEL - 100%. CAUSE - UNKNOWN. DURING FULL POWER OPERATION CEA 22 DROPPED TO FULL INSERTION. REACTOR POWER WAS REDUCED TO 70%, CEA 22 WAS REPAIRED, TESTED AND RETURNED TO NORMAL POSITION AND POWER WAS RAISED TO 100%. SEVERAL HOURS LATER CEA 22 AGAIN DROPPED TO FULL INSERTION. THE ABOVE SEQUENCE OF POWER REDUCTION REPAIR, REPOSITIONING, AND RETURN TO 100% POWER WAS REPEATED. SIMILAR OCCURRENCES WERE REPORTED ON LER'S 335-80-23, 80-10, 80-7, & 80-2. CEA 22 DROPPED BOTH TIMES DUE TO UNKNOWN CAUSES. IN THE FIRST INSTANCE THE TIMER MODULE WAS REPLACED. IN THE SECOND INSTANCE THE TIMER MODULE AND THE POWER SUPPLY WERE REPLACED. CAUSES OF THESE FAILURES COULD NOT BE DETERMINED.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 033 0 8009020372 159368 07/24/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS
RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:
1 335/80-023 2 335/80-032 3 335/80-034 4 335/80-035
5 335/80-036 6 335/80-043 7 335/80-045 8 335/80-046
9 335/80-048 10 335/80-049 11 335/80-050 12 335/80-051

ABSTRACT
POWER LEVEL - 100%. CAUSE - TECHNICIAN SHORTED POWER TO ROD DRIVE.
WHILE AT 100% POWER, CEA #63 DROPPED TO THE FULLY INSERTED POSITION.
POWER WAS REDUCED TO 65% AND CEA #63 WAS REALIGNED WITH THE OTHER
CEA'S IN ITS GROUP. THIS IS THE FIRST DROPPED CEA DUE TO MAINTENANCE
ACTIVITY. THE DROPPED CEA WAS CAUSED BY A TECHNICIAN ACCIDENTLY
SHORTING THE OUTPUT OF THE 15 VOLT POWER SUPPLY WHILE TAKING ROUTINE
VOLTAGE MEASUREMENTS. THESE MEASUREMENTS, INTENDED TO DETECT FAILING
SUPPLIES BEFORE FAILURE, HAVE BEEN DISCONTINUED DUE TO THE CLOSE
QUARTERS AND RISK OF SHORTING THESE SUPPLIES.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 034 0 8009120316 160120 08/01/80

DOCKET:335 ST. LUCIE 1. TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL.

COMMENTS


RECURRING PROBLEM WITH 15V. POWER SUPPLIES.

REFERENCE LERS:

1 335/80-002	2 335/80-007	3 335/80-010	4 335/80-023
5 335/80-032	6 335/80-033	7 335/80-035	8 335/80-036
9 335/80-043	10 335/80-045	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILURE. DURING FULL POWER OPERATION CEA 41 DROPPED TO FULL INSERTION. REACTOR POWER WAS REDUCED TO 70%, CEA 41 WAS REPAIRED, TESTED AND REALIGNED WITH ITS GROUP. POWER WAS INCREASED TO 100%. SIMILAR OCCURRENCES WERE REPORTED IN LER'S 335-80-23, 80-10, 80-7, 80-2, 80-32. CEA 41 DROPPED DUE TO A FAILURE IN ITS CORE POWER PROGRAMMER 15V POWER SUPPLY. THE POWER SUPPLY WAS REPLACED. A MODIFICATION IS UNDERWAY TO PROVIDE REDUNDANT 15V POWER SUPPLIES TO EACH CEA.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 035 0 8009120318 0 08/04/80

DOCKET:335 ST: LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/80-002	2 335/80-007	3 335/80-010	4 335/80-023
5 335/80-032	6 335/80-033	7 335/80-034	8 335/80-036
9 335/80-043	10 335/80-045	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILURE. ON 8/4/80, CEA 16 DROPPED TO FULL INSERTION. ACTION PER TS 3.1.3.1E WAS INITIATED. REACTOR POWER WAS REDUCED TO 70%, CEA 16 WAS REPAIRED, TESTED AND REALIGNED WITH ITS GROUP. SIMILAR OCCURRENCES WERE REPORTED IN LER'S 335/80-23, 80-10, 80-7, 80-2, AND 80-34. CEA 16 DROPPED DUE TO A FAILURE IN ITS CORE POWER PROGRAMMER 15V POWER SUPPLY. THE POWER SUPPLY WAS REPLACED. A MODIFICATION IS UNDERWAY TO PROVIDE REDUNDANT 15V POWER SUPPLIES TO EACH CEA.



DOCKET YEAR LER NUMBER. REVISION DCS NUMBER NSIC EVENT DATE
335 1980 036 0 8009150290 160119 08/05/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION:. 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V. POWER SUPPLIES.

REFERENCE LERS:

1 335/80-002	2 335/80-007	3 335/80-010	4 335/80-023
5 335/80-032	6 335/80-033	7 335/80-034	8 335/80-035
9 335/80-043	10 335/80-045	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILURE. DURING FULL POWER OPERATION CEA 23 DROPPED TO FULL INSERTION. RX POWER WAS REDUCED TO 70%, CEA 23 WAS REPAIRED, TESTED AND REALIGNED WITH ITS GROUP. POWER WAS INCREASED TO 100%. SIMILAR OCCURRENCES WERE REPORTED IN LER'S 335-80-23, 80-10, 80-7, 80-2, 80-32, 80-34, 80-35. CEA 23 DROPPED DUE TO A FAILURE IN ITS CORE POWER PROGRAMMER 15V POWER SUPPLY. THE POWER SUPPLY WAS REPLACED. A MODIFICATION IS UNDERWAY TO PROVIDE REDUNDANT 15V POWER SUPPLIES TO EACH CEA.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 043 0 8012100407 161804 08/21/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/80-002	2 335/80-007	3 335/80-010	4 335/80-023
5 335/80-033	6 335/80-034	7 335/80-035	8 335/80-036
9 335/80-045	10 335/80-046	11 335/80-048	12 335/80-049
13 335/80-050	14 335/80-051		

ABSTRACT

POWER LEVEL - 100%. CAUSE - FAILED POWER SUPPLY. CEDM 39 FAILED, THUS DROPPING ITS CEA TO FULL INSERTION. NO CEA MOTION WAS IN PROGRESS WHEN THE FAILURE OCCURRED. REACTOR POWER WAS REDUCED TO 70%, CEDM 39 WAS REPAIRED, TESTED AND RETURNED TO NORMAL OPERATION. FULL POWER OPERATION WAS RESUMED. NO CORE POWER DISTRIBUTION LIMITS WERE EXCEEDED. SIMILAR OCCURRENCES WERE REPORTED ON LERS 335-80-2, 80-7, 80-10 AND 80-23. THE CAUSE WAS A FAILED 15 VOLT POWER SUPPLY UNIT IN THE COIL POWER PROGRAMMER. NO CAUSE FOR THIS FAILURE COULD BE DETERMINED. THE POWER SUPPLY UNIT WAS REPLACED. REDUNDANT POWER SUPPLY UNITS ARE TO BE INSTALLED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 045 0 8010080673 160410 08/26/80

DOCKET:335 ST. LUCIE 1. TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL


COMMENTS
RECURRING PROBLEM WITH 15V. POWER SUPPLY.

REFERENCE LERS:

1 335/76-037	2 335/78-021	3 335/79-006	4 335/80-002
5 335/80-023	6 335/80-033	7 335/80-034	8 335/80-035
9 335/80-036	10 335/80-043	11 335/80-046	12 335/80-048
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILS. DURING FULL POWER OPERATION CEA 24 DROPPED TO FULL INSERTION. POWER WAS REDUCED TO 70%. THE POWER SUPPLY UNIT FOR CEA 24 HAD FAILED. THE POWER SUPPLY WAS REPLACED AND CEA 24 WAS ALIGNED WITH ITS CEA GROUP HEIGHT. SIMILAR OCCURRENCES WERE REPORTED AS LERS 335-76-37, 78-21, 79-6, 80-2, 80-23. INSTALLATION OF REDUNDANT POWER SUPPLIES IS IN PROGRESS.



DOCKET YEAR LER NUMBER: REVISION DCS NUMBER NSIC EVENT DATE
335 1980 046 1 8012020542 163510 08/27/80

DOCKET: 335 ST. LUCIE 1. TYPE: PWR
REGION: 2 NSSS: CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES. STEP 1: MODEL UNI-30 ABV.

REFERENCE LERS:

1 335/76-037	2 335/79-006	3 335/80-002	4 335/80-023
5 335/80-034	6 335/80-035	7 335/80-036	8 335/80-042
9 335/80-043	10 335/80-045	11 335/80-048	12 335/80-049
13 335/80-050	14 335/80-051		

ABSTRACT

POWER LEVEL - 100%. CAUSE - FAILED POWER SUPPLY. CEA #33 DROPPED TO ITS FULLY INSERTED POSITION. POWER WAS REDUCED TO 70%, THE CEDM DRIVE CONTROL FOR #33 WAS REPAIRED. #33 WAS RE-ALIGNED. THIS IS THE 11TH DROPPED CEA DUE TO A FAILED POWER SUPPLY (LER'S 335-76-37, 79-6, 80-2, 23, 34, 35, 36, 42, 43, 45). OF THESE 11, 8 WERE DUE TO THE FAILURE OF NEW POWER SUPPLIES (POWERMATE UNI-30 ABV) INSTALLED DURING THE SPRING '80 REFUELING OUTAGE. THE POWER SUPPLIES FOR ALL 61 FLCEA'S HAVE SINCE BEEN REPLACED WITH THE ORIGINAL TYPE SUPPLIES (POWERMATE UNI-88). THERE HAVE BEEN NO FAILURES IN THE 73 DAYS SINCE THIS REPLACEMENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 048 0 8010070477 160409 08/26/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL


COMMENTS
RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/76-037	2 335/78-021	3 335/79-006	4 335/80-002
5 335/80-023	6 335/80-033	7 335/80-034	8 335/80-035
9 335/80-036	10 335/80-043	11 335/80-045	12 335/80-046
13 335/80-049	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILURE. DURING FULL POWER OPERATION CEA 51 DROPPED TO FULL INSERTION. POWER WAS REDUCED TO 70%. THE POWER SUPPLY UNIT FOR CEA 51 HAD FAILED. THE POWER SUPPLY WAS REPLACED AND CEA 51 WAS ALIGNED WITH ITS CEA GROUP HEIGHT. SIMILAR OCCURRENCES WERE REPORTED AS LERS 335-76-37, 78-21, 79-6, 80-2, 80-23, 80-45. INSTALLATION OF REDUNDANT POWER SUPPLIES IS IN PROGRESS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 049 0 8010100322 160417 09/04/80

DOCKET:335 ST. LUCIE 1. TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/76-037	2 335/78-021	3 335/79-006	4 335/80-002
5 335/80-023	6 335/80-033	7 335/80-034	8 335/80-035
9 335/80-036	10 335/80-043	11 335/80-045	12 335/80-046
13 335/80-048	14 335/80-050	15 335/80-051	

ABSTRACT

POWER LEVEL - 100%. CAUSE - POWER SUPPLY FAILS. DURING FULL POWER OPERATION CEA 21 DROPPED TO FULL INSERTION. REACTOR POWER WAS REDUCED TO 70%. THE POWER SUPPLY UNIT FOR CEA 21 HAD FAILED. THE POWER SUPPLY WAS REPLACED AND CEA 21 WAS ALIGNED WITH ITS GROUP HEIGHT. SIMILAR OCCURRENCES WERE REPORTED AS LER'S 335-76-37, 78-21, 79-6, 80-2, 80-23, 80-45, 80-48. INSTALLATION OF REDUNDANT POWER SUPPLIES IS IN PROGRESS AND REPLACEMENT OF SUPPLIES WITH MORE RELIABLE OLDER SUPPLIES HAS BEEN COMPLETED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 050 0 8010100314 160832 09/04/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES.

REFERENCE LERS:

1 335/80-023	2 335/80-033	3 335/80-034	4 335/80-035
5 335/80-036	6 335/80-043	7 335/80-045	8 335/80-046
9 335/80-048	10 335/80-051		

ABSTRACT

POWER LEVEL - 070%. CAUSE - FAILURE OF PLANT PA SYSTEM. CONTROL ELEMENT DRIVE MECHANISMS POWER SUPPLIES WERE BEING SWITCHED TO MORE RELIABLE MODELS. THE POWER SUPPLIES FOR CEA 44 AND 42 WERE PARALLELED WHEN CEA 44 DROPPED, THEN SIX MINUTES LATER CEA 42 DROPPED. THE REACTOR WAS MANUALLY TRIPPED. THIS IS THE FIRST OCCURRENCE OF THIS TYPE. WHILE CHANGING THE 15V POWER SUPPLY FOR CEA 42, CEA 44 DROPPED, POSSIBLY DUE TO A VOLTAGE SPIKE. DUE TO A FAILURE OF THE PLANT PA SYSTEM, MAINTENANCE PERSONNEL WERE NOT NOTIFIED THAT CEA 44 DROPPED AND THEY CONTINUE REMOVING THE POWER SUPPLY FOR CEA 42. THIS LED TO THE OCCURRENCE OF THE DUAL ROD DROP.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1980 051 0 8010100345 160831 09/04/80

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL.

COMMENTS


RECURRING PROBLEM WITH 15V POWER SUPPLIES:

REFERENCE LERS:

1 335/80-023	2 335/80-033	3 335/80-034	4 335/80-035
5 335/80-036	6 335/80-043	7 335/80-045	8 335/80-046
9 335/80-048	10 335/80-049	11 335/80-050	

ABSTRACT

POWER LEVEL - 091%. CAUSE - BLOWN FUSE. DURING A RETURN TO FULL POWER OPERATION CONTROL ELEMENT ASSEMBLY 33 DROPPED TO FULL INSERTION. THE CAUSE WAS A FUSE BLOWING IN THE ALTERNATE PARALLEL SUPPLY LINE TO CEA 33 WHEN ITS SUPPLY BREAKER WAS OPENED. THE FUSE APPARENTLY BLEW DUE TO THE SLIGHT TRANSIENT INVOLVED. THE FUSE WAS REPLACED AND THE POWER SUPPLIES EXCHANGED. CEA 33 WAS ALIGNED WITH ITS CEA GROUP. REACTOR POWER WAS MAINTAINED AT 70% TO FINISH EXCHANGING POWER SUPPLIES.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1981 053 0 8201060355 171810 11/25/81.

DOCKET:335 ST. LUCIE 1. TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS

WATCH 975 - LOSS OF CONTROL ROOM ALARM FUNCTION.

WATCH-LIST CODES FOR THIS LER ARE:


975 POSSIBLE SIGNIFICANT EVENT

REFERENCE LERS:

1 335/79-028

ABSTRACT

B2 STATION SERVICE TRANSFORMER FAILED, DEENERGIZING THE B2 480V LOAD CENTER. ABOUT 3 MINUTES LATER THE 2 TIE BREAKERS FEEDING THE AB DC BUS FROM THE B BUS TRIPPED, DEENERGIZING THE AB DC BUS. LOSS OF THIS CAUSED A LOSS OF AB CONTROL POWER AND 120V VITAL AC WHICH FEEDS ALL CONTROL ROOM ALARMS BUT NOT INSTRUMENTS. THE DC BUS, 120V AC AND ALARMS WERE RESTORED WITHIN 15 MINUTES. SEE LER 335-79-28 FOR RELATED EVENTS. THE B TO AB TIE BREAKERS WERE THOROUGHLY TESTED AND INSPECTED. A LOOSE POWER TERMINATION WAS DISCOVERED ON THE B SIDE BREAKER AND THE INSTANTANEOUS OVER CURRENT TRIP WAS SET ON 'LO' ON BOTH BREAKERS. THE TRIP WAS RESET TO HI PER DESIGN AND ALL CONNECTIONS WERE TORQUED. ALL SIMILAR BREAKERS WERE CHECKED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1987 017 0 8801260221 207963 12/21/87

DOCKET:335 ST. LUCIE 1 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL


WATCH-LIST CODES FOR THIS LER ARE:
35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 335/82-071 2 335/87-010

ABSTRACT

POWER LEVEL - 100%. ON 12/21/87, WHILE OPERATING IN MODE 1 AT 100% POWER, ST. LUCIE UNIT #1 TRIPPED DUE TO THE LOSS OF THE 1MD 120 VOLT AC BUS. WITH THE REACTOR PROTECTIVE SYSTEM (RPS) HI START-UP RATE B CHANNEL BISTABLE IN TRIP, THE RPS LOGIC FOR HI START-UP RATE WAS 1 OF 3. THE LOSS OF THE 1D INSTRUMENT INVERTER CAUSED THE SUBSEQUENT LOSS OF THE 1MD 120 VOLT AC BUS, WHICH RESULTED IN THE ACTUATION OF THE DEENERGIZE TO ACTUATE FUNCTION OF THE RPS D CHANNEL TRIP BISTABLES THUS SATISFYING THE RPS TRIP LOGIC. THE ROOT CAUSE OF THE EVENT WAS A COGNITIVE PERSONNEL ERROR BY A UTILITY NON-LICENSED OPERATOR NOT ADEQUATELY FOLLOWING A PLANT APPROVED PROCEDURE FOR OPERATION OF THE 120 VOLT INSTRUMENT AC CLASS 1E SYSTEM. THE NON-LICENSED OPERATOR WAS COUNSELED BY HIS SUPERVISOR ON THE IMPORTANCE OF ADEQUATELY FOLLOWING APPROVED PROCEDURES AND THE NEED FOR GREATER ATTENTION TO DETAIL WHILE PERFORMING CRITICAL JOB RESPONSIBILITIES. A PROCEDURE FOR INFREQUENT OPERATIONS OR MANIPULATIONS IS BEING DRAFTED. THIS IS TO ASSURE A DETAILED REVIEW AND BRIEFING BY THE SHIFT SUPERVISOR WITH APPROPRIATE PERSONNEL FOR SAFE AND SATISFACTORY PERFORMANCE. THE PLANT TRAINING DEPARTMENT WILL EVALUATE THIS ITEM TO DETERMINE APPROPRIATE TRAINING METHODS AND REQUIREMENTS. A HUMAN PERFORMANCE EVALUATION IS BEING CONDUCTED TO IDENTIFY ANY AREAS THAT MAY BE OF CONCERN.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
335 1991 003 0 9106110130 22222 05/06/91

DOCKET: 335 ST. LUCIE 1 TYPE: PWR
REGION: 2 NSSS: CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS

STEP 1: MODEL NO. 601MPX. STEP 9: MODEL NO. 9852 376. STEP 7: REM - HEATER
DRAIN PUMP. STEP 16: COMP RLX - GROUND RELAY.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 335/90-007

ABSTRACT

POWER LEVEL - 096%. ON 5/6/91, ST. LUCIE UNIT 1 WAS IN MODE 1 AND HOLDING POWER AT 96% TO COMPLETE A NUCLEAR DELTA-T POWER CALIBRATION BEFORE RESUMING FULL POWER OPERATION FOLLOWING A SCHEDULED SHUTDOWN. THE 1A HEATER DRAIN PUMP TRIPPED AT 0508 AND, FOUR SECONDS LATER, THE 1A STEAM GENERATOR FEEDWATER PUMP TRIPPED CAUSING A TURBINE RUNBACK. THE UNIT WAS MANUALLY TRIPPED AT 0509 AT THE DIRECTION OF THE NUCLEAR PLANT SUPERVISOR IN ANTICIPATION OF AN AUTOMATIC REACTOR TRIP AND STANDARD PCST TRIP ACTIONS WERE PERFORMED. THE UNIT WAS THEN IN MODE 3, HOT STANDBY. THE MANUAL REACTOR TRIP WAS THE RESULT OF A TURBINE RUNBACK INITIATED WHEN BOTH THE 1A HEATER DRAIN PUMP AND THE 1A STEAM GENERATOR FEEDWATER PUMP TRIPPED. AN INVESTIGATION REVEALED A POSSIBLE GROUNDING OF THE 5A FEEDWATER HEATER HI-HI LEVEL SWITCH WHICH, IN TURN, OPENED CIRCUIT BREAKER 27 ON THE 120 VAC VITAL STATIC UNINTERRUPTIBLE POWER SUPPLY. THIS WOULD HAVE CAUSED THE NORMAL DRAIN VALVES TO CLOSE ON SEVERAL SECONDARY FEEDWATER HEATERS AND THE ALTERNATE DRAIN VALVES TO OPEN. IT WAS ALSO FOUND THAT THE PRESSURE SENSING ELEMENT SETPOINT FOR THE 1A SGFP HAD DRIFTED HIGH FROM THE NORMAL VALUE OF 275 PSIG TO 291 PSIG. THE END RESULT WAS A LOW SUCTION PRESSURE CONDITION ON THE FEEDWATER PUMP SUCTION LINE AND THE TRIP OF THE 1A STEAM GENERATOR FEEDWATER PUMP ON LOW SUCTION PRESSURE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
338 1984 019 1 8502050420 197272 11/14/84

DOCKET: 338 NORTH ANNA 1. TYPE: PWR
REGION: 2 NSSS: WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: VIRGINIA ELECTRIC POWER CO.
SYMBOL: VEP

COMMENTS


STEP 5: COMP RLX - RCP BREAKER POSITION RELAY.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT:

POWER LEVEL - 100%. ON 11-14-84 AT 0640 UNIT 1 TRIPPED DUE TO A VITAL BUS INVERTER FAILURE. THE INVERTER WAS SUPPLYING POWER TO THE 125V AC VITAL BUS 1-III. THE INVERTER FAILURE CAUSED THIS BUS AND ITS ASSOCIATED EQUIPMENT TO BECOME DEENERGIZED. LOSS OF POWER TO THE RELAY WHICH SENSES 'C' RCP BREAKER POSITION CAUSED THE REACTOR TRIP ON LOSS OF RCS FLOW COINCIDENT WITH REACTOR POWER GREATER THAN 30%. THE 'C' RCP NEVER STOPPED RUNNING DURING THIS EVENT. THE INVERTER HAD DAMAGED SCR'S AND A BLOWN FUSE WHICH PREVENTED IT FROM BEING REENERGIZED. THE MOST SIGNIFICANT EQUIPMENT RESPONSE INVOLVED 'B' SG. 'B' MAIN FEED VALVE (FCV-1488) AND 'B' FEED BYPASS VALVE (FCV-1489) BOTH FAILED CLOSED. 'B' WIDE RANGE SG LEVEL INDICATION (LI-1487) FAILED LOW. THE AUX FEEDWATER PUMP (1-FW-P-3B) WHICH SUPPLIES 'B' SG FAILED TO AUTO START AND WAS MANUALLY STARTED BY THE CONTROL ROOM OPERATOR. THESE ACTIONS CAUSED 'B' SG LEVEL TO DROP BELOW THE NARROW RANGE INDICATION WHILE NO WIDE RANGE LEVEL INDICATION WAS AVAILABLE. LOSS OF VITAL BUS 1-III ALSO DEENERGIZED ALL 4 WATER BOXES' VACUUM BREAKERS WHICH CAUSED ALL CIRCULATING WATER PUMPS TO TRIP. THIS VITAL BUS ALSO SUPPLIES POWER TO MANY CONTAINMENT ISOLATION TRIP VALVES INCLUDING COMPONENT COOLING TO THE RCP'S. OTHER SIGNIFICANT EQUIPMENT THAT WAS POWERED FROM THE 1-III VITAL BUS WAS ONE POWER RANGE DETECTOR (N43), 26 INCORE THERMOCOUPLES, SSPS CHANNEL III INPUTS, AND SSPS TRAIN 'B' OUTPUT RELAYS.



DOCKET, YEAR LER NUMBER, REVISION DCS NUMBER NSIC EVENT DATE
341 1988 004 0 8802160253 208236 01/10/88

DOCKET: 341. FERMI 2 TYPE: BWR
REGION: 3 NSSS: GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: DETROIT EDISON CO.
SYMBOL: DEC

COMMENTS
SMP/EC A/D

WATCH-LIST CODES FOR THIS LER ARE:


942 UNUSUAL EVENT
35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:

11 10 CFR 50.73(a)(2)(ii): Unanalyzed conditions.

ABSTRACT

POWER LEVEL - 049%. ON JANUARY 10, 1988, THE NORTH REACTOR FEED PUMP SPEED CONTROL POWER SUPPLY FAILED. THE PUMP RESPONDED TO THE LOSS OF CONTROL SIGNAL. A LOW REACTOR VESSEL WATER LEVEL RESULTED WHICH CAUSED A REACTOR SCRAM. HIGH PRESSURE COOLANT INJECTION AND REACTOR CORE ISOLATION COOLING SYSTEMS ACTUATED ALONG WITH THE APPROPRIATE ISOLATIONS. THE CAUSE FOR THE FEEDWATER TRANSIENT WAS THAT THE OVERVOLTAGE TRIP FOR THE POWER SUPPLY HAD DRIFTED INTO THE NORMAL OPERATING RANGE. THE POWER SUPPLY WAS REPLACED AND THE OVERVOLTAGE PROTECTION WAS SET TO THE MAXIMUM VALUE. DURING RESTORATION OF THE RWCU SYSTEM, A TECH SPEC REQUIREMENT WAS EXCEEDED. THE TECH SPEC ACTION STATEMENT FOR DEFEATING THE HIGH TEMPERATURE ISOLATION FUNCTION OF THE RWCU ISOLATION VALVES DOES NOT ALLOW SUFFICIENT TIME TO RESTART THE RWCU SYSTEM DURING HIGH OPERATOR ACTIVITY PERIODS. A TECH SPEC CHANGE WILL BE SUBMITTED TO DELETE THE REQUIREMENT FOR RWCU ISOLATIONS ON HIGH, NON-REGENERATIVE HEAT EXCHANGER OUTLET TEMPERATURE INDICATION.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
344 1985 010 0 8509240359 196745 08/26/85

DOCKET: 344 TROJAN TYPE: PWR
REGION: 5 NSSS: WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PORTLAND GENERAL ELECTRIC CO.
SYMBOL: PGC

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AT 11:55 AM PDT ON 8-26-85 A REACTOR TRIP OCCURRED DUE TO OVERPOWER/DELTA-T AND OVERTEMPERATURE/DELTA-T TRIP SIGNALS. THE COINCIDENT SIGNALS WERE GENERATED BY I&C MAINTENANCE TESTING IN CONJUNCTION WITH A SHORT IN A HEAT TRACING CIRCUIT WHICH RESULTED IN A VOLTAGE DROP ON THE Y-13 PREFERRED INSTRUMENT BUS. ALL EQUIPMENT OPERATED AS REQUIRED FOLLOWING THE TRIP AND THE PLANT WAS SAFELY SHUTDOWN. CORRECTIVE ACTION WAS TAKEN TO REPAIR THE DAMAGED HEAT TRACING CIRCUIT. IN THE COURSE OF PLANT RECOVERY, WITH THE REACTOR AT 3% POWER, SG WATER LEVEL CONTROL WAS IN MANUAL FOR THE PERFORMANCE OF MAIN TURBINE STOP VALVE TESTING. DURING THE TESTING, THE 'C' SG LEVEL EXCEEDED THE HIGH-HIGH LEVEL SETPOINT RESULTING IN A MAIN FEEDWATER PUMP AND TURBINE TRIP AND AN AUTOMATIC START OF THE AUX FEEDWATER PUMPS. THE WATER LEVEL IN THE SG WAS RETURNED TO NORMAL AND THE PLANT RECOVERY WAS CONTINUED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
346 1980 081 0 8012150118 161859 11/12/80

DOCKET: 346 DAVIS-BESSE 1 TYPE: PWR
REGION: 3 NSSS: BW
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: TOLEDO EDISON CO.
SYMBOL: TEC

COMMENTS


STEP 2: PSYS ZX - TESTING CONNECTION TO STEAM/FEEDWATER RUPTURE CONTROL
SYSTEM; COMP MEI - OSCILLOSCOPE FOR WAVEFORM TEST.

REFERENCE LERS:

1: 346/80-056

ABSTRACT

POWER LEVEL - 039%. CAUSE - MAINTENANCE ERROR. AT 1403 HOURS, THE
UNIT EXPERIENCED A LOSS OF ESSENTIAL BUS Y2. THIS BUS POWERS RPS
CHANNEL 2 WHICH WAS THE SOURCE OF RCS FLOW TO THE INTEGRATED CONTROL
SYSTEM. THE LOSS OF FLOW INDICATION STARTED A SERIES OF EVENTS WHICH
RESULTED IN A REACTOR TRIP ON HIGH RCS PRESSURE. THE CAUSE WAS THE USE
OF A GROUNDED OSCILLOSCOPE BY I&C PERSONNEL TO RECORD INPUT VOLTAGE
WAVEFORMS AT THE STEAM AND FEEDWATER RUPTURE CONTROL SYSTEM CH. 2
CABINET. THE GROUND FED BACK TO THE YV2 INVERTER INPUT FUSE WHICH TOOK
OUT THE Y2 BUS WHICH CAUSED THE LOSS OF RPS CH. 2. THE FUSE WAS
REPLACED AND ESSENTIAL 120 VAC POWER RESTORED TO Y2 AT 1530 HOURS.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
346 1982 020 2 8305130195 183451 04/09/82

DOCKET:346 DAVIS-BESSE 1 TYPE:PWR
REGION: 3 NSSS:BW
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: TOLEDO EDISON CO.
SYMBOL: TEC

ABSTRACT

(NP-33-82-24) ON APRIL 9, 1982 AT 1015 HOURS, THE STATION EXPERIENCED A LOSS OF 120 VAC DISTRIBUTION PANEL Y2 WHILE IN MODE 6. SINCE Y4 HAD ALREADY BEEN DE-ENERGIZED FOR ROUTINE MAINTENANCE, SFAS ACTUATION CHANNEL 2 ACTUATED WHEN POWER WAS LOST TO SFAS CHANNEL 2 AND RPS CHANNEL 2 DE-ENERGIZED CAUSING A LOSS OF ONE CHANNEL OF SOURCE RANGE NUCLEAR INSTRUMENTATION. THE STATION ENTERED THE ACTION STATEMENT OF TECH SPECS 3.8.2.2, 3.3.2.1, AND 3.9.2. THE AFFECTED SAFETY SYSTEMS WENT TO THEIR FAIL SAFE STATUS. THE LOSS OF Y2 WAS DUE TO A BLOWN Y2 INVERTER FUSE. THE FUSE BLEW WHEN A SHORT TO GROUND OCCURRED DURING MAINTENANCE ON THE CONTROL ROOM EMERGENCY VENTILATION SYSTEM. THE CONTROL POWER SUPPLIED FROM Y2 TO CONTROL POWER PANEL C6709 WAS OVERLOOKED WHEN THE SYSTEM WAS TAGGED OUT BY CONTRACTOR PERSONNEL. UNDER MWOS 82-1547 AND 82-1595, THE FUSES WERE REPLACED. THE RESPONSIBLE PERSON WAS COUNSELED BY THE MAINTENANCE ENGINEER.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
346 1983 072 0 8401300009 188346 12/17/83


DOCKET:346 DAVIS-BESSE 1 TYPE:PWR
REGION: 3 NSSS:BW
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: TOLEDO EDISON CO.
SYMBOL: TEC

WATCH-LIST CODES FOR THIS LER ARE:
900 POST EVENT DATA AVAILABILITY

REFERENCE LERS:
1 346/80-088 2 346/81-016 3 346/81-031 4 346/83-002

ABSTRACT

(NP-33-83-101) ON 12/17/83 AT 1515 HOURS, 120 VAC ESSENTIAL BUS Y1 WAS DE-ENERGIZED. AS A RESULT OF THE LOSS OF Y1, THE FOLLOWING CHANNELS WERE ALSO DE-ENERGIZED: REACTOR PROTECTION SYSTEM (RPS) CHANNEL 1, SAFETY FEATURES ACTUATION SYSTEM (SFAS) CHANNEL 1, AND STEAM AND FEEDWATER RUPTURE CONTROL SYSTEM (SFRCS) CHANNEL 1. WHEN POWER WAS LOST TO RPS CHANNEL 1, THE HIGH AUCTIONEERED POWER SIGNAL TO THE ICS WENT TO 0% POWER. THE ICS RESPONDED BY GIVING A COMMAND FOR CONTINUOUS CONTROL ROD MOTION OUTWARD. A REACTOR TRIP DUE TO HIGH FLUX RESULTED. THE CAUSE OF THE LOSS OF Y1 WAS PERSONNEL ERROR. WHILE REMOVING A SCREW ON THE TERMINALS IN CIRCUIT NUMBER Y120A, RT4597AB, CONTAINMENT POST-ACCIDENT HIGH RANGE RADIATION MONITOR, THE SCREW SLIPPED OFF THE SCREW STARTER AND THE LEAD PULLED THE SCREW BACK, WHICH THEN SHORTED IT TO GROUND. THE TECHNICIAN WAS COUNSELED BY THE LEAD I&C ENGINEER.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
354 1987 034 0 8709040487 206294 07/30/87

DOCKET: 354 HOPE CREEK 1 TYPE: BWR
REGION: 1 NSSS: GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

COMMENTS

STEP 1: EFF WX - UNKNOWN. STEP 2: COMP XI - "BLOWN MAIN FUSE" INDICATING LAMP.

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
36 INADEQUATE TRAINING
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. A REACTOR SCRAM OCCURRED WHEN A 120 VAC UNINTERRUPTABLE POWER SUPPLY (UPS) INVERTER WHICH POWERS THE FEEDWATER CONTROL CABINET BECAME DE-ENERGIZED DURING THE COURSE OF ROUTINE MAINTENANCE. THE RESULTANT LOSS OF FEEDWATER CONTROL CAUSED THE REACTOR TO SCRAM ON LOW LEVEL AT +12.5" DECREASING. SUBSEQUENT INVESTIGATION DETERMINED THAT THE INVERTER BECAME DE-ENERGIZED WHEN IT WAS BEING RETURNED TO A NORMAL CONFIGURATION. A SWITCHING ERROR CAUSED THE INVERTER MAIN POWER SUPPLY FUSE TO BLOW. SEVERAL FACTORS CONTRIBUTED TO A LACK OF AWARENESS ON THE PART OF THE OPERATOR INVOLVED THAT THE INVERTER MAIN FUSE HAD BLOWN. IN AN ATTEMPT TO CORRECT THE SWITCHING ERROR, THE BACKUP INFEED SOURCE TO THE INVERTER WAS ALSO DE-ENERGIZED. THESE ACTIONS COMBINED TO REMOVE THE ENTIRE INVERTER FROM SERVICE. CORRECTIVE ACTIONS INCLUDED VERIFYING FAULT INDICATING LAMPS ON ALL INVERTERS WERE INSTALLED, REVISING THE INVERTER OPERATING PROCEDURE, COUNSELLING THE OPERATOR INVOLVED, AND ENHANCING OPERATOR TRAINING ON INVERTER OPERATIONS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
354 1988 034 0 8901100190 212732 12/04/88

DOCKET: 354 HOPE CREEK 1 TYPE: BWR
REGION: 1 NSSS: GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PUBLIC SERVICE ELECTRIC & GAS CO.
SYMBOL: PEG

COMMENTS

STEPS 10,16: CAUSE IX - VOLTAGE TRANSIENTS.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 354/87-045

ABSTRACT

POWER LEVEL - 100%. ON 12/4/88 AT 1537, HOPE CREEK EXPERIENCED AN UNEXPECTED POWER REDUCTION AND ESF ACTUATION (REACTOR WATER CLEANUP SYSTEM ISOLATION). WHEN A LOGIC SYSTEM OPTICAL ISOLATOR CABINET INTERNAL POWER SUPPLY BECAME DE-ENERGIZED. AT THE ONSET OF THE EVENT, THE "B" REACTOR RECIRCULATION PUMP TRIPPED, AND THE RWCU INBOARD ISOLATION VALVE ISOLATED TRIPPING BOTH RWCU PUMPS; THESE RESPONSES WERE ACCOMPANIED BY VARIOUS INVALID ALARMS AND INDICATIONS. IMMEDIATE CONTROL ROOM RESPONSES INCLUDED STUFFING RODS IN ACCORDANCE WITH REACTOR ENGINEERING PROCEDURES TO COMPENSATE FOR REDUCED CORE FLOW/POWER LEVEL, ASSESSING PLANT STABILITY, VERIFYING ALARM/INDICATION STATUS, AND ESTABLISHING SINGLE RECIRCULATION LOOP OPERATIONS. AFTER OPERATIONS DEPARTMENT ASSURED THAT CONDITIONS WERE STABLE, I&C DEPARTMENT COMMENCED TROUBLESHOOTING TO DETERMINE THE CAUSE OF THE OPTICAL ISOLATOR CABINET POWER FAILURE. INITIAL TROUBLESHOOTING EFFORTS WERE FOCUSED ON A POTENTIALLY BAD POWER SUPPLY MONITOR CARD IN THE CABINET; SUBSEQUENT INVESTIGATION DETERMINED THAT THE CAUSE OF THE POWER FAILURE WAS LOOSE TERMINATIONS ON THE CABINET INTERNAL 24VDC POWER SUPPLY. IMMEDIATE CORRECTIVE ACTIONS CONSISTED OF REPLACING THE SUSPECT POWER SUPPLY MONITOR CARD IN THE CABINET, TIGHTENING LOOSE TERMINATIONS AT THE POWER SUPPLY, AND RE-ENERGIZING THE CABINET.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1982 138 0 8212070360 180064 11/09/82


DOCKET:361. SAN ONOFRE 2 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

WATCH-LIST CODES FOR THIS LER ARE:
975 POSSIBLE SIGNIFICANT EVENT

REFERENCE LERS:
1 361/82-136

ABSTRACT

MOMENTARY LOSS OF POWER TO THE FEEDWATER CONTROL SYSTEM (FCS) WAS EXPERIENCED. AS A PRECAUTION, THE REACTOR WAS MANUALLY TRIPPED. THE ECCS AUTOMATICALLY INITIATED DURING THE RESULTING COOLDOWN. THE CAUSE OF THIS EVENT WAS DUE TO THE INADVERTENT DISLODGING OF A POWER CORD RESULTING IN THE DEENERGIZATION OF THE FCS AND STEAM BYPASS CONTROL SYSTEM. IMMEDIATE CORRECTIVE ACTION INCLUDED MANUAL TRIPPING OF THE REACTOR. ALL CONTROL CABINETS WITH SIMILAR POWER SUPPLY CONNECTORS WERE SECURED BY "TIE-WRAPPS". A PERMANENT MODIFICATION WILL BE DEVELOPED. OPERATOR AND SHIFT TECHNICAL ADVISER TRAINING WILL BE UPDATED BASED ON THIS EVENT. LER 82-136 (DUE DECEMBER 9, 1982) WILL ADDRESS THE COOLDOWN TRANSIENT. LCO 3.4.8.1B AND A SPECIAL REPORT (DUE FEBRUARY 8, 1983) WILL ADDRESS THE ECCS INITIATION (LCO 3.5.2B).



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1984 043 0 8409170538 191386 08/08/84


DOCKET:361 SAN ONOFRE 2 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON AUGUST 8, 1984 AT 1710, WITH UNIT 2 IN MODE 1 AT 100% POWER, A PENALTY FACTOR FROM CONTROL ELEMENT ASSEMBLY CALCULATOR (CEAC 1) CAUSED THE CPC'S TO GENERATE LOW DEPARTURE FROM NUCLEATE BOILING RATIO TRIP SIGNALS TO THE REACTOR PROTECTION SYSTEM. THE REACTOR TRIPPED, AND THE EMERGENCY FEEDWATER SYSTEM ACTUATED ON LOW STEAM GENERATOR LEVEL DUE TO SHRINK. THE CEAC 1 PENALTY FACTOR RESULTED FROM SPURIOUS ROD POSITION INDICATIONS DUE TO AN ANALOG INPUT POWER SUPPLY FAILURE IN CPC B. EACH CONTROL ELEMENT ASSEMBLY (CEA) HAS TWO REED SWITCH POSITION TRANSMITTER STACKS. EACH STACK SUPPLIES CEA POSITION INDICATION TO ONE CEAC AND ONE CPC. THE FAILURE OF THE POWER SUPPLY IN CPC B CAUSED A FEEDBACK THROUGH THIS COMMON CIRCUIT TO CEAC 1 SUCH THAT THE CPC B TARGET CEA'S INDICATED PARTIALLY INSERTED AND CEAC 1 CALCULATED A PENALTY FACTOR BASED ON THESE ERRONEOUS INDICATIONS. THE DEFECTIVE POWER SUPPLY WAS REPLACED. ADDITIONALLY, COMPUTER TECHNICIANS HAVE BEEN DIRECTED TO SET THE CEAC INOP FLAG IN THE CPC'S WHEN PERFORMING CPC MAINTENANCE WHICH REQUIRES DEENERGIZING A CPC POWER SUPPLY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1985 041 0 8509060235 195433 08/01/85

DOCKET:361 SAN ONOFRE 2 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS


STEP 1: EFFECT IX - VOLTAGE TRANSIENT; STEP 2: COMP RLX - AUXILIARY RELAYS.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON 8-1-85, AT 1535 THE REACTOR TRIPPED IN RESPONSE TO LOSS OF LOAD TRIP SIGNALS. THE LOSS OF LOAD SIGNALS WERE GENERATED AS RESULT OF A SPURIOUS TURBINE TRIP. ALL SAFETY SYSTEMS WERE VERIFIED TO HAVE FUNCTIONED PROPERLY. THE SPURIOUS TURBINE TRIP WAS CAUSED BY A VOLTAGE TRANSIENT ON PHASE 'A' OF THE NON-1E UNINTERRUPTIBLE POWER SUPPLY (UPS) (EIIS SYSTEM CODE EE) INVERTER (EIIS COMPONENT CODE INVT) 2Y012. THIS INVERTER SUPPLIES POWER TO 2 AUX RELAYS (EIIS COMPONENT CODE RLY) ASSOCIATED WITH THE CONTROL ELEMENT DRIVE MECHANISM (CEDM) (EIIS COMPONENT CODE DRIV) UNDERVOLTAGE RELAYS WHICH MAKE UP PART OF THE TURBINE TRIP CIRCUITRY. THE TRANSIENT DE-ENERGIZED THE AUX RELAYS, CLOSED THEIR CONTACTS AND COMPLETED THE TURBINE TRIP LOGIC. THE TRANSIENT WAS VERIFIED TO HAVE OCCURRED BASED ON ALARMS ON SEVERAL INSTRUMENTS POWERED BY PHASE 'A' AND NO SUCH INDICATIONS ON INSTRUMENTS POWERED BY OTHER PHASES OF THE UPS. NO DEFECTS WERE FOUND IN INVERTER 2Y012. THE CAUSE OF THE VOLTAGE TRANSIENT IS UNKNOWN. AS CORRECTIVE ACTION, A DESIGN CHANGE HAS BEEN IMPLEMENTED WHICH RE-ARRANGED THE AUX RELAYS, SO THAT A SINGLE PHASE VOLTAGE TRANSIENT WILL NOT CAUSE A TURBINE TRIP.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1986 015 0 8607250177 200019 06/19/86

DOCKET: 361, SAN ONOFRE 2 TYPE: PWR
REGION: 5 NSSS: CE
ARCHITECTURAL ENGINEER: BECH.
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS


STEP 7: CAUSE AX - FOR TESTING.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 083%. ON JUNE 19, 1986, AT 1355 WITH UNIT 2 IN MODE 1. AT 83% POWER, THE REACTOR TRIPPED WHEN 120 VAC VITAL BUS 3 WAS DE-ENERGIZED DUE TO THE FAILURE OF INVERTER Y003. DE-ENERGIZATION OF VITAL BUS 3 ALSO DE-ENERGIZED CONTROL ELEMENT ASSEMBLY CALCULATOR (CEAC) NO. 2 WHILE CEAC NO. 1 WAS OUT OF SERVICE FOR TESTING. WITH BOTH CEACS INOPERABLE, COMPENSATORY PENALTY FACTORS RESULTED IN CORE PROTECTION CALCULATOR DEPARTURE FROM NUCLEATE BOILING RATIO AND LOCAL POWER DENSITY REACTOR TRIPS. THE FEEDWATER CONTROL SYSTEM (FWCS) FAILED TO SUFFICIENTLY REDUCE FEEDWATER FLOW AFTER THE TRIP RESULTING IN EXCESS FEEDWATER ADDITION TO THE STEAM GENERATORS (SG). OPERATORS APPROPRIATELY TRIPPED FEEDWATER PUMPS TO SUCCESSFULLY AVOID OVERCOOLING OF THE REACTOR COOLANT SYSTEM (RCS) AND ASSOCIATED RCS PRESSURE DECREASE. THE FWCS RESPONSE OCCURRED DUE TO AN EXCESSIVE MANUAL BIAS IN THE MAIN FEED PUMP TURBINE SPEED CONTROLLERS. PROCEDURES ARE BEING CHANGED AND OPERATORS HAVE BEEN INFORMED OF THE IMPACT OF EXCESSIVE BIAS SETTINGS ON POST REACTOR TRIP FWCS OPERATION. THE 2Y003 INVERTER FAILURE WAS CAUSED BY A SHORTED CAPACITOR WHICH WAS AN ISOLATED OCCURRENCE. THE CAPACITOR WAS REPLACED AND THE INVERTER WAS RETURNED TO SERVICE. THERE WERE NO SAFETY CONSEQUENCES ASSOCIATED WITH THIS EVENT SINCE ALL SAFETY-RELATED SYSTEMS OPERATED AS DESIGNED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1990 014 0 9101020188 220598 11/20/90

DOCKET:361 SAN ONOFRE 2 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS

STEP 4: EFF WX - ACTUATION SIGNAL.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR
16 MOISTURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 361/84-016

ABSTRACT

POWER LEVEL - 100%. AT 0946 ON 11/20/90, WITH UNIT 2 IN MODE 1 AT 100% POWER, THE SAFETY INJECTION SYSTEM (SIS), CONTAINMENT COOLING SYSTEM (CCS) AND CONTAINMENT SPRAY SYSTEM (CSS) WERE INADVERTENTLY ACTUATED WHILE PERFORMING A 31-DAY INTERVAL SURVEILLANCE OF THOSE SYSTEMS. ALL SYSTEMS AND COMPONENTS FUNCTIONED AS DESIGNED. AFTER VERIFYING THAT THE ACTUATIONS WERE SPURIOUS, CONTAINMENT SPRAY (CS) WAS SECURED AT APPROXIMATELY 0947. DURING THE ONE MINUTE PERIOD THAT CS WAS INITIATED, APPROXIMATELY 4800 GALLONS OF BORATED WATER FROM THE REFUELING WATER STORAGE TANKS WERE SPRAYED INTO CONTAINMENT. AT 1020, SIS AND CCS WERE RESET AND AT 1029, CSS WAS RESET AND ACTUATED COMPONENTS WERE STOPPED IN ACCORDANCE WITH APPROPRIATE PROCEDURES. ALTHOUGH NO SAFETY SYSTEMS WERE AFFECTED BY THE CONTAINMENT SPRAY, DEGRADED ELECTRICAL CONDITIONS WERE OBSERVED IN THE POWER SUPPLY TO THE CONTROL ELEMENT DRIVE MECHANISMS (CEDM). ON 11/23/90, UNIT 2 WAS SHUT DOWN TO CORRECT THESE DEGRADED CEDM ELECTRICAL CONDITIONS. THE ROOT CAUSE OF THIS EVENT IS PERSONNEL ERROR. DURING THE SURVEILLANCE, ONE TRIP PATH FOR SIS, CCS, AND CSS IS ACTUATED; CONTRARY TO THE PROCEDURE, THE FIRST TRIP PATH WAS NOT RESET PRIOR TO TESTING (AND ACTUATING) THE NEXT TRIP PATH. WITH THESE TWO TRIP PATHS ACTUATED, THE SELECTIVE 2 OF 4 ACTUATION LOGIC WAS SATISFIED, THUS INITIATING SIS, CCS, AND CSS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
361 1990 016 0 9101140111 220676 12/06/90

DOCKET:361; SAN:ONOFRE 2 TYPE:PHR
REGION: 5 NSSS:CE
ARCHITECTURAL:ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS

STEP 2: REM - MANUFACTURED BY CORNELL-DUBLIER ELECTRIC, PART NO. CDE
KBXK1056P OR SCI 020138. STEP 17: PART NO. SCI PC201. STEP 9: CAUSE IX -
MOMENTARY LOSS OF POWER. STEP 16: COMP MSC - TRANSISTOR. STEP 11: COMP MSC
- MECHANICAL LINKAGE. STEP 25: COMP XR - SEQUENCE OF EVENTS RECORDER.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE
34 DESIGN ERROR OR INADEQUACY
913 UPDATE NEEDED

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 362/89-001

ABSTRACT

POWER LEVEL - 100%. AT 2200 ON DECEMBER 6, 1990, UNIT 2 AUTOMATICALLY
TRIPPED FROM 100% POWER ON A REACTOR PROTECTION SYSTEM LOSS OF LOAD
(LOL) SIGNAL. THE LOL SIGNAL WAS CAUSED BY A TURBINE TRIP, WHICH
OCCURRED AS A RESULT OF A MOMENTARY LOSS OF POWER FROM THE NON-1E
UNINTERRUPTIBLE POWER SYSTEM (UPS), MOMENTARILY DE-ENERGIZING BUS
Q-069. EMERGENCY FEEDWATER ACTUATION SYSTEM (EFAS) 1 AND EFAS 2
ACTUATIONS PROPERLY OCCURRED. ONE 6.9 KV BUS DID NOT AUTOMATICALLY
TRANSFER TO OFFSITE POWER FOLLOWING THE TRIP, DE-ENERGIZING 2 REACTOR
COOLANT PUMPS (RCPS); TWO OTHER RCPS CONTINUED TO PROVIDE FORCED
CIRCULATION. APPROXIMATELY 1 TO 2 MINUTES FOLLOWING THE TRIP, A
COMPLETE LOSS OF POWER ON Q-069 OCCURRED. APPROPRIATE ACTIONS WERE
INITIATED IN ACCORDANCE WITH PROCEDURES TO COMPENSATE FOR THE
OPERATION OF CONTROL SYSTEMS WHICH WERE AFFECTED BY THE LOSS OF POWER
ON Q-069. ONE MAIN STEAM SAFETY VALVE FOR EACH STEAM GENERATOR MAY
HAVE LIFTED FOR A SHORT TIME AND PROPERLY RESEATED. BUS Q-069 POWER
WAS RESTORED AT 2220 VIA THE MANUAL BYPASS SWITCH. RECOVERY OF THE
PLANT OTHERWISE PROCEEDED NORMALLY. IT IS POSTULATED THAT FAILURE OF
1) A CAPACITOR IN THE NON-1E UPS INVERTER OUTPUT AND 2) A TRANSISTOR
IN THE STATIC SWITCH TRANSFER LOGIC CONTROL CIRCUIT COMBINED TO CAUSE
THE LOSS OF POWER ON BUS Q-069 (BOTH AT THE ONSET OF THE EVENT AND AT
1-2 MINUTES POST-TRIP). THE ROOT CAUSE EVALUATION IS CONTINUING.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
362 1991 001 0 9104220351 221467 03/15/91

DOCKET:362 SAN ONOFRE 3 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: SOUTHERN CALIFORNIA EDISON CO.
SYMBOL: SCE

COMMENTS

STEP 2: PART NO. CDE KBXK1056PI OR SCI 020138.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 361/86-029 2 361/90-016 3 362/89-001

ABSTRACT

POWER LEVEL - 100%. AT 0938 ON MARCH 15, 1991, UNIT 3 AUTOMATICALLY TRIPPED FROM 100% POWER ON A REACTOR PROTECTION SYSTEM LOSS OF LOAD (LOL) SIGNAL. THE LOL SIGNAL WAS CAUSED BY A TURBINE TRIP, WHICH OCCURRED AS THE RESULT OF A MOMENTARY INTERRUPTION IN POWER FROM THE NON-1E UNINTERRUPTIBLE POWER SYSTEM (UPS), DE-ENERGIZING BUS 3Q069. EMERGENCY FEEDWATER ACTUATION SYSTEM (EFAS) 1 AND EFAS 2 ACTUATIONS PROPERLY OCCURRED. ONE NON-1E 4.16 KV (3A03) BUS DID NOT AUTOMATICALLY TRANSFER FROM ITS NORMAL POWER SOURCE TO ITS ALTERNATE POWER SOURCE RESULTING IN THE LOSS OF THE ALTERNATE POWER SUPPLY (3B012) TO THE NON-1E BUS 3Q069. ONE MAIN STEAM SAFETY VALVE LIFTED FOR A SHORT TIME AND PROPERLY RESEATED. AT 1000, WHEN 3A03 WAS MANUALLY REENERGIZED, POWER WAS RESTORED TO 3Q069. APPROPRIATE ACTIONS WERE TAKEN IN ACCORDANCE WITH PROCEDURES TO COMPENSATE FOR THE OPERATION OF CONTROL SYSTEMS WHICH WERE AFFECTED BY THE LOSS OF POWER TO THE NON-1E UPS. POST-TRIP PLANT RECOVERY OTHERWISE PROCEEDED NORMALLY. AN OUTPUT CAPACITOR IN THE CONSTANT VOLTAGE TRANSFORMER (CVT) SECTION OF THE NON-1E UPS INVERTER FAILED CAUSING THE MOMENTARY INTERRUPTION IN POWER FROM THE NON-1E UPS. ALL CAPACITORS IN THE UNITS 2 AND 3 NON-1E UPS WERE REPLACED WITH AN UPGRADED MODEL. THE UNIT 3 INSTRUMENT BUSES POWERED BY THE NON-1E UPS WERE MODIFIED SUCH THAT POWER WILL BE MAINTAINED TO CRITICAL COMPONENT SYSTEMS.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
366 1982 105 0 8210290209 179109 09/18/82

DOCKET:366 HATCH 2 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

ABSTRACT

PERSONNEL WERE SELECTING RODS TO INCREASE POWER FROM 875 MWT. DURING THIS, THE ROD OUT PERMISSIVE LIGHT WENT OUT; HOWEVER, ROD BLOCK ALARMS WERE NOT RECEIVED. ROD BLOCK MONITOR B WAS SUBSEQUENTLY DETERMINED TO BE INOPERABLE; ROD BLOCK MONITOR A REMAINED OPERABLE. THE UNIT WAS PLACED IN A 24 HOUR LCO IN ACCORDANCE WITH TECH SPECS 3.1.4.3 ACTION A. THE PROBLEM WITH B RBM WAS FOUND TO BE A BLOWN POWER FUSE. THE FUSE WAS REPLACED. VOLTAGES TO THE RBM WERE CHECKED AND NO PROBLEMS WERE FOUND. PROPER OPERATION WAS VERIFIED BY SELECTING RODS AND OBSERVING CORRECT CONTROL BOARD LIGHT INDICATIONS. THE LCO WAS CLEARED WITHIN THE REQUIRED TIME LIMIT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
366 1987 006 1 8906010268 213972 07/26/87

DOCKET:366 HATCH 2 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

OTHER REPORTABILITY: TECH SPEC 3.5.1. STEP 2: PSYS HS - VITAL AC ROOM. STEP
3: MODEL SV12250. STEP 7: COMP MSC - LATCHING ARM.

WATCH-LIST CODES FOR THIS LER ARE:

34 DESIGN ERROR OR INADEQUACY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 321/85-010 2 321/87-011

ABSTRACT

POWER LEVEL - 089%. ON 7/26/87, AT APPROXIMATELY 1405 CDT, UNIT 2 WAS IN THE RUN MODE AT AN APPROXIMATE POWER LEVEL OF 2170 MWT (APPROXIMATELY 89 PERCENT OF RATED THERMAL POWER). AT THAT TIME, VITAL AC (EIIIS CODE EE) POWER WAS LOST. THIS RESULTED IN A DECREASE IN THE REACTOR FEEDWATER PUMPS FLOW AND A DECREASE IN REACTOR WATER LEVEL. THE REACTOR WATER LEVEL DECREASED TO THE REACTOR PROTECTION SYSTEM (RPS EIIIS CODE JC) ACTUATION SETPOINT AND A REACTOR SCRAM OCCURRED. THE ROOT CAUSE OF THIS EVENT IS ATTRIBUTED TO EQUIPMENT FAILURE DUE TO INADEQUATE HEATING VENTILATION AND AIR CONDITIONING (HVAC) DESIGN TO ENSURE THE VITAL AC EQUIPMENT (I.E., ELECTRICAL INVERTER) IS PROPERLY COOLED. THE ELECTRONIC EQUIPMENT FAILURE IN THE INVERTER IS ATTRIBUTED TO THE HIGH ROOM TEMPERATURES. CORRECTIVE ACTIONS FOR THIS EVENT INCLUDE: 1) REFURBISHING THE INVERTER, 2) ADDING TEMPORARY COOLING TO THE INVERTER ROOMS, 3) INSTALLING A NEW HVAC SYSTEM FOR COOLING INVERTER ROOMS, 4) DEVELOPING A UNIT COMMON PREVENTIVE MAINTENANCE PROCEDURE FOR BOTH INVERTERS AND, 5) INSTALLING NEW VITAL AC INVERTERS FOR BOTH UNITS 1 AND 2.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
366 1987 009 1 8801250292 207902 08/03/87

DOCKET:366 HATCH 2 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

OTHER REPORTABILITY: TECH SPEC 3.5.1. STEPS 15,16: MODEL CAT CJ2-G3-U.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.
21 OTHER: Voluntary report, special report, Part 21 report,
etc.

REFERENCE LERS:

1 321/85-010 2 321/87-011 3 366/87-006

ABSTRACT

POWER LEVEL - 090%. ON 8/3/87 AT APPROXIMATELY 1152 CDT, UNIT 2 WAS IN THE RUN MODE AT AN APPROXIMATE POWER LEVEL OF 2193 MWT (APPROXIMATELY 90 PERCENT OF RATED THERMAL POWER). AT THAT TIME, VITAL AC (EIIS CODE EE) POWER WAS LOST. THIS RESULTED IN A DECREASE IN THE REACTOR FEEDWATER PUMPS FLOW AND A DECREASE IN REACTOR WATER LEVEL. THE REACTOR WATER LEVEL DECREASED TO THE REACTOR PROTECTION SYSTEM (RPS EIIS CODE JC) ACTUATION SETPOINT AND A REACTOR SCRAM OCCURRED. THE ROOT CAUSE OF THIS EVENT IS ELECTRICAL EQUIPMENT FAILURE. SPECIFICALLY, CIRCUIT BREAKER CB-4 WOULD OPEN UNDER UNDULY LOW FORCE CONDITIONS. IT WAS CONCLUDED AFTER FIELD TESTING AND CONSULTATION WITH THE MANUFACTURER THAT THE TRIPPING MECHANISM WAS WEAK. CORRECTIVE ACTIONS FOR THIS EVENT INCLUDED: 1) INSTALLING JUMPERS AND REMOVING EQUIPMENT FROM SERVICE, 2) DESIGNING AND INSTALLING BARRIER BOXES, 3) VERIFYING TRIP INSTRUMENTATION AND LEVEL TRANSMITTERS IN CALIBRATION, 4) VENTING INSTRUMENT LINES AND TRANSMITTERS, 5) PERFORMING EVALUATIONS OF AIR ENTRAINMENT AND SPIKING IN INSTRUMENT LINES, 6) INITIATING PROCEDURE REVISIONS, AND 7) VERIFYING CERTAIN OTHER SYSTEMS DO NOT HAVE LOW SUCTION TRIPS.



DOCKET YEAR. LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
366 1988 020 0 8809140065 210345 08/05/88

DOCKET:366 HATCH 2 TYPE:BWR
REGION: 2 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

STEP 4: MODEL NO. FRN-R3. STEP 16: MODEL NO. 1154DP5.

WATCH-LIST CODES FOR THIS LER ARE:


34 DESIGN ERROR OR INADEQUACY
941. REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON 08/05/88, AT APPROXIMATELY 1546CDT, UNIT 2 WAS IN THE RUN MODE AT AN APPROXIMATE POWER LEVEL OF 2424 MWT (APPROXIMATELY 100 PERCENT OF RATED THERMAL POWER). WHEN REINSTALLING A REPAIRED FEEDWATER MINIMUM FLOW CONTROLLER, A FUSE BLEW, CAUSING MINIMUM FLOW VALVES ON THE CONDENSATE, CONDENSATE BOOSTER AND REACTOR FEED PUMPS TO FAIL OPEN. THIS RESULTED IN A LOSS OF SUCTION AND SUBSEQUENT TRIPPING OF THE CONDENSATE BOOSTER PUMPS AND REACTOR FEED PUMPS. THE RAPID DECREASE IN REACTOR WATER LEVEL RESULTED IN A REACTOR SCRAM, A PRIMARY CONTAINMENT ISOLATION SYSTEM VALVE GROUP 2 AND PARTIAL GROUP 5 ISOLATION. REACTOR WATER LEVEL WAS RESTORED USING THE 'A' REACTOR FEED PUMP, THE HIGH PRESSURE COOLANT INJECTION SYSTEM AND THE REACTOR CORE ISOLATION COOLING SYSTEM. THE EVENT WAS CAUSED BY A DESIGN DEFICIENCY. AN ELECTRICAL CIRCUIT CONTAINING TWELVE INSTRUMENTS, INCLUDING FOUR CONDENSATE AND FEEDWATER SYSTEM CONTROLLERS, HAD ONLY ONE IN-LINE FUSE. AS A RESULT, AN IN-LINE FUSE (2N21-F7) FAILED WHICH RESULTED IN A LOSS OF SUCTION FOR AND THE TRIPPING OF THE CONDENSATE BOOSTER PUMPS AND THE REACTOR FEED PUMPS. THE FUSE WAS REPLACED AND A DESIGN REVIEW OF THE FEEDWATER CONTROL SYSTEM WAS INITIATED TO IDENTIFY AND CHANGE ANY SIMILAR DEFICIENT CONDITIONS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
369 1981 145 0 8110010131 169077 08/22/81


DOCKET:369 MCGUIRE 1. TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: DUKE
FACILITY OPERATOR: DUKE POWER CO.
SYMBOL: DPC

COMMENTS

STEP 6: COMPONENT XI - CONTROL BOARD INDICATOR.

ABSTRACT

A LOSS OF CONTROL POWER TO NUCLEAR INSTRUMENTATION POWER RANGE CHANNEL N-44 CAUSED THE TRIP OF THE ASSOCIATED CHANNEL REACTOR TRIP BISTABLES AND THE ACTUATION OF ATTENDANT CONTROL BOARD INDICATORS AND ALARMS. WHILE PERFORMING CORRECTIVE MAINTENANCE IN THE COMPARATOR AND RATE PORTION OF THE NUCLEAR INSTRUMENTATION SYSTEM, A TECHNICIAN ACCIDENTALLY GROUNDED PART OF THE CHANNEL N-44 CIRCUITRY CAUSING THE POWER SUPPLY BREAKER TO OPEN, REMOVING ALL POWER FROM THE CHANNEL. THE PROCEDURE MALFUNCTION OF NUCLEAR INSTRUMENTATION WAS IMPLEMENTED, AND THE POWER SUPPLY BREAKER WAS CLOSED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
370 1987 016 1 8712220087 207557 09/06/87

DOCKET:370 MCGUIRE 2 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: DUKE
FACILITY OPERATOR: DUKE POWER CO.
SYMBOL: DPC

COMMENTS

STEP 10: MODEL #1MA459833-G1-LY. STEP 49: COMP XC - AUTO START CONTROLLER.

WATCH-LIST CODES FOR THIS LER ARE:

19 VIBRATION
10 ENVIRONMENTAL CONDITIONS

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 369/84-024 2 370/85-026 3 370/86-016 4 370/86-021.

ABSTRACT

POWER LEVEL - 100%. AT 100% POWER ON SEPTEMBER 6, 1987 AT 1035, A UNIT 2 REACTOR/TURBINE TRIP OCCURRED DUE TO HIGH PRESSURIZER PRESSURE WHEN MAIN TURBINE GOVERNOR AND INTERCEPT VALVES CLOSED AS DIRECTED BY THE DIGITAL ELECTRO-HYDRAULIC (DEH) TURBINE CONTROL SYSTEM. THE GOVERNOR AND INTERCEPT VALVE CLOSE SIGNAL WAS GENERATED BY LOSS OF POWER TO A DEH TURBINE CONTROL SYSTEM RELAY WHEN POWER WAS LOST TO KXB. POWER WAS LOST ON AUXILIARY POWER PANELBOARD KXB DUE TO AN OVERCURRENT FAULT BREAKER TRIP CAUSED BY A GROUNDED MOTOR LEAD CONNECTOR (INSULATING TAPE HAD WORN ALLOWING CONNECTING LUG TO GROUND TO MOTOR FRAME) ON INSTRUMENT AIR (VI) COMPRESSOR A. OPERATIONS IMPLEMENTED THE REACTOR TRIP PROCEDURE. POWER WAS RESTORED TO AUXILIARY POWER PANELBOARD KXB FROM STATIC INVERTER KXB. UNIT 2 RETURNED TO MODE 1, POWER OPERATION, ON SEPTEMBER 7, AT 2110. THE CONNECTING LUG WAS REINSULATED IN THE CONNECTION BOX AND THE COMPRESSOR WAS RETURNED TO SERVICE. VI COMPRESSOR MOTORS B&C WILL BE INSPECTED FOR SIMILAR CONDITION. SIMILAR MOTORS IN OTHER APPLICATIONS WILL BE INSPECTED AND RETAPED AS NECESSARY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
373 1988 004 0 8806010027 209475 04/22/88

DOCKET:373 LA SALLE 1 TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 3:"NON" TYPE, 6 AMP. STEP 5: COMP.MSC - TRANSISTOR. SMP/T/1.MP/T/1/374

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 373/87-084

ABSTRACT

POWER LEVEL - 000%. ON APRIL 22, 1988 AT 1319 HOURS, WITH UNIT 1 DEFUELED AND UNIT 2 IN OPERATIONAL CONDITION 1 (RUN) AT 96% POWER, DURING THE PERFORMANCE OF WORK REQUEST L79559 BY THE INSTRUMENT MAINTENANCE (IM) DEPARTMENT, REACTOR PROTECTION SYSTEM (RPS) BUS "A" TRIPPED. IN ACCORDANCE WITH THE WORK REQUEST, THE TECHNICIAN WAS REPLACING RELAY 1C51B-K1 IN AVERAGE POWER RANGE MONITOR (APRM) "A" PANEL 1H13-0608, WHEN A SMALL SPARK OCCURRED NEAR THE RELAY SOCKET. WITH THE TRIP OF RPS BUS "A" ON UNIT 1, A NUMBER OF AUTOMATIC ACTIONS OCCURRED AS A RESULT OF THE SUBSEQUENT GROUP II THROUGH VII ISOLATIONS AND HALF SCRAM. IMMEDIATE INVESTIGATION REVEALED THAT THE 1C71-S003A & C POWER MONITORING ASSEMBLIES (PMA'S), THE 175 AMP "A" RPS GENERATOR OUTPUT BREAKER WERE TRIPPED, AND A 6 AMP FUSE (1C71-F12A) WAS BLOWN, ALL OF WHICH FEED THE APRM CIRCUITRY. THE INITIATION OF THE EVENT WAS DETERMINED TO BE A SHORT TO GROUND WHICH OCCURRED WHEN THE REPLACEMENT 1C51B-K1 RELAY WAS MISPOSITIONED WHILE BEING INSERTED INTO THE RELAY SOCKET BY THE IM TECHNICIAN. THE SAFETY CONSEQUENCES OF THE EVENT WERE MINIMAL SINCE UNIT 1 WAS DEFUELED. ALL ISOLATIONS AND ACTUATIONS (HALF SCRAM ON UNIT 1 S8GT INITIATION) OCCURRED AS DESIGNED. THE 1C51B-K1 RELAY WHICH WAS BEING INSTALLED IN THE APRM CIRCUITRY WHEN THE "A" RPS BUS TRIPPED WAS BENCH TESTED BY THE IM DEPARTMENT AND FOUND TO BE UNDAMAGED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
374 1986 008 0 8606120533 199783 05/09/86


DOCKET:374 LA SALLE 2 TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 086%. ON MAY 9, 1986 AT 0910 HOURS, WITH LASALLE UNIT 2 AT 86% POWER, A REACTOR SCRAM OCCURRED WHEN A STATIONMAN ACCIDENTALLY BUMPED OPEN A BREAKER WHILE SWEEPING THE FLOOR. THE BREAKER WAS A PRIMARY TRANSFORMER DISCONNECT FEEDING THE 120/208V DISTRIBUTION PANEL AT MOTOR CONTROL CENTER (MCC) 235X-3. THE DISTRIBUTION PANEL FEEDS THE FEEDWATER LEVEL CONTROL PANEL 2H13-P612. WITH A LOSS OF AC POWER TO THIS PANEL, THE 2B TURBINE DRIVEN REACTOR FEED PUMP LOCKED OUT AT 41% DEMAND AND THE 2A TURBINE DRIVEN REACTOR FEED PUMP COASTED DOWN TO ZERO OUTPUT. WITH 41% FLOW FROM ONLY ONE FEED PUMP, THE REACTOR WATER LEVEL DROPPED RAPIDLY AND A FULL AUTO SCRAM OCCURRED. THE MOTOR DRIVEN REACTOR FEED PUMP WAS MANUALLY STARTED DURING THE EVENT, BUT DUE TO THE LOSS OF CONTROL POWER THE FEEDWATER REGULATING VALVE WAS LOCKED OUT. THE CAUSE OF THE SCRAM WAS A LOSS OF FEEDWATER DUE TO LOSS OF POWER TO THE FEEDWATER LEVEL CONTROL PANEL. AN INVESTIGATION MEETING AND TRAINING TAILGATE MEETING WERE HELD ON MAY 9, 1986 WITH THE STATIONMAN INVOLVED AND WITH ALL OTHER STATIONMEN. THE SESSIONS STRESSED THE IMPORTANCE OF CAUTION WHEN WORKING AROUND ANY PLANT EQUIPMENT, ESPECIALLY DISTRIBUTION CENTERS AND INSTRUMENT RACKS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
374 1986 011 1 8612020003 201908 06/01/86

DOCKET:374 LA SALLE 2 TYPE:BWR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

WATCH LIST 975- REACTOR FAILED TO SCRAM ON LOW LEVEL. STEP 3: T/D FEEDWATER PUMP STOP VALVE WAS BEING TESTED. STEP 5: EFF IX - VOLTAGE SPIKES. STEP 12: OPERATOR RESET CONTROL LOCKOUT WITHOUT ZEROING THE SIGNAL DEVIATION OR SWITCHING TO MANUAL MODE. STEP 22: CAUSE SD- LEVEL RECORDER, PEN FAILED TO MARK THE LOWEST REACTOR LEVEL WITH INK (BUT IT DID CREASE THE PAPER), SO OPERATORS FAILED TO IMMEDIATELY RECOGNIZE THE FAILURE TO SCRAM ON LOW LEVEL.

WATCH-LIST CODES FOR THIS LER ARE:


975 POSSIBLE SIGNIFICANT EVENT
943 ALERT
233 TRANSIENT PROCEEDS IN A SIGNIFICANT, UNEXPECTED

REPORTABILITY CODES FOR THIS LER ARE:

11 10 CFR 50.73(a)(2)(ii): Unanalyzed conditions.
14 10 CFR 50.73(a)(2)(v): Event that could have prevented fulfillment of a safety function.

ABSTRACT

POWER LEVEL - 095%. AT 4:20 AM, 6-1-86, LASALLE STATION 2 WAS OPERATING AT 95% OF FULL POWER, WHEN A FEEDWATER TRANSIENT OCCURRED WHICH CAUSED REACTOR VESSEL LEVEL TO DROP TO THE LEVEL 3 TRIP SETPOINT. THE LEVEL TRANSIENT ENDED WITH THE OPERATORS ABLE TO RESTORE LEVEL TO THE NORMAL OPERATING RANGE. SUBSEQUENT INVESTIGATION DETERMINED THAT THE INDICATED LEVEL HAD DROPPED BELOW THE TRIP SETPOINT AND A REACTOR SCRAM HAD NOT OCCURRED. A TRIP WAS RECEIVED ON THE "B" RPS CHANNEL. THE CAUSE OF THIS EVENT WAS DUE TO A FAILURE OF THE REACTOR VESSEL LEVEL 3 SWITCHES (MANUFACTURED BY SOR, INC.) TO TRIP AT THE SET LEVEL. THE EXACT CAUSE OF THE SWITCH FAILURE HAS NOT BEEN DETERMINED. THE ACTIONS TAKEN WERE TO COMMENCE AN ORDERLY REACTOR SHUTDOWN, MANUALLY TRIP THE "A" RPS CHANNEL AND TO INSTRUCT THE OPERATORS TO MANUALLY TRIP THE REACTOR IF THE REACTOR VESSEL LEVEL DROPPED TO THE LEVEL 3 TRIP SETPOINT, AND TO DECLARE A GSEP ALERT. TO DATE, THE COMMONWEALTH EDISON COMPANY SOR TESTING PROGRAM HAS BEEN ABLE TO CHARACTERIZE THE VARIABILITY IN THE SOR DIFFERENTIAL PRESSURE SWITCH SETPOINTS. AN EXACT CAUSE FOR THE VARIABILITY OF THE SETPOINTS HAS NOT BEEN DETERMINED. AN ACTION PLAN HAS BEEN DEVELOPED FOR INTERIM AND LONG TERM CORRECTIVE ACTION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
382 1988 033 0 8901110062 212794 12/08/88

DOCKET:382 WATERFORD 3 TYPE:PWR
REGION: 4 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: LOUISIANA POWER & LIGHT CO.
SYMBOL: LPL

COMMENTS

WATCH 932 - INFORMATION NOTICE 85-77. STEP 28: EFF WX - TRIP ON CALCULATED
DNBR.

WATCH-LIST CODES FOR THIS LER ARE:


31 ACCIDENTAL ACTION
35 HUMAN ERROR
932 RESULT OF IE BULLETINS, ORDERS, ETC.(IEB 81-7)

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AT 1311 HOURS ON DECEMBER 8, 1988, WATERFORD STEAM
ELECTRIC STATION UNIT 3 WAS OPERATING AT 100% POWER WHEN A TRANSIENT
INDUCED BY THE CYCLING OF POWER DISTRIBUTION PANEL (PDP) 3014AB
BREAKERS CAUSED THE REACTOR TO TRIP ON LOW DEPARTURE FROM NUCLEATE
BOILING RATIO (DNBR). THE PDP COVER SLIPPED WHILE BEING REMOVED FOR
MAINTENANCE, CAUSING ONE-HALF OF THE PDP BREAKERS TO OPEN. THE
MAINTENANCE PERSONNEL CLOSED THE BREAKERS CAUSING PRESSURIZER PRESSURE
INSTRUMENT CONTROL LOOPS TO REENERGIZE; THIS APPEARED TO THE STEAM
BYPASS CONTROL SYSTEM AND REACTOR POWER CUTBACK SYSTEM (RPCS) AS A
LARGE LOAD REJECTION. STEAM BYPASS CONTROL VALVES QUICK-OPENED AND
THE RPCS ACTUATED. DUE TO THE LOSS OF POWER TO MAIN TURBINE (MT)
CONTROL CIRCUITS, THE MT WAS NOT SETBACK BY THE RPCS. WITH THE
RESULTING STEAM DEMAND GREATER THAN REACTOR POWER, REACTOR COOLANT
SYSTEM (RCS) PRESSURE DECREASED AND THE CORE PROTECTION CALCULATORS
TRIPPED THE REACTOR ON ANTICIPATED LOW DNBR. THE ROOT CAUSE OF THIS
EVENT IS INADEQUATE ADMINISTRATIVE CONTROL OF WORK PERFORMED ON OR
AROUND EQUIPMENT THAT COULD CAUSE A PLANT TRIP OR SAFETY SYSTEM
ACTUATION. A DIRECTIVE IS BEING DEVELOPED TO AID IN THE PLANNING AND
APPROVAL OF HIGH RISK TASKS. SINCE SAFETY SYSTEMS FUNCTIONED TO
PROTECT THE PLANT, THERE WAS NO DANGER TO THE HEALTH OR SAFETY OF THE
PUBLIC OR PLANT PERSONNEL.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
382 1990 002 0 9004270164 218033 03/22/90

DOCKET: 382 WATERFORD 3 TYPE: PWR
REGION: 4 NSSS: CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: LOUISIANA POWER & LIGHT CO.
SYMBOL: LPL

COMMENTS

STEP 2: COMP MSC - DRAWER SLIDES.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 382/86-001 2 382/86-002 3 382/86-009 4 382/86-013
5 382/86-023 6 382/89-017

ABSTRACT

POWER LEVEL - 100%. AT 2133 HOURS ON MARCH 22, 1990, AN AUTOMATIC REACTOR TRIP OCCURRED AT WATERFORD STEAM ELECTRIC STATION UNIT 3 WHILE THE PLANT WAS OPERATING AT 100% POWER. THE REACTOR TRIP WAS INITIATED BY THE PLANT PROTECTION SYSTEM WHEN TWO CONTROL ELEMENT ASSEMBLIES (CEAS) DROPPED TO THE FULLY INSERTED POSITION WHILE THEIR DRIVE MECHANISMS WERE BEING TRANSFERRED FROM THEIR NORMAL POWER SUPPLY TO THE CONTROL ELEMENT DRIVE MECHANISM SYSTEM (CEDMCS) HOLD BUS. THIS EVENT IS REPORTABLE BY REASON OF THE OCCURRENCE OF AN AUTOMATIC REACTOR PROTECTION SYSTEM ACTUATION. THE ROOT CAUSE OF THIS EVENT WAS AN EQUIPMENT MALFUNCTION. INSPECTIONS SUBSEQUENT TO THE TRIP REVEALED THAT SEVERAL ELECTRICAL CONNECTORS USED TO TRANSMIT POWER FROM THE CEDMCS PANELS TO A CEA DRIVE MECHANISM WERE DAMAGED FROM MISALIGNMENT DURING PREVIOUSLY PERFORMED MAINTENANCE. THIS CONDITION DISRUPTED THE POWER SUPPLY CIRCUITRY OF THE CEA DRIVE MOTORS AFFECTED, CAUSING DISENGAGEMENT OF THE DRIVE MECHANISMS FOR THESE CEAS. THE DAMAGED COMPONENTS IN THE POWER SUPPLY CIRCUITRY WERE REPLACED AND OPERATIONALLY CHECKED TO BE SATISFACTORY. ALL PLANT PROTECTIVE FEATURES FUNCTIONED AS DESIGNED AND NO THREAT WAS POSED TO THE HEALTH OR SAFETY OF THE GENERAL PUBLIC OR PLANT PERSONNEL DURING THIS EVENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
387 1984 029 0 8408090421 191267 07/03/84

DOCKET:387 SUSQUEHANNA 1 TYPE:BWR
REGION: 1. NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PENNSYLVANIA POWER & LIGHT CO.
SYMBOL: PPL

COMMENTS


STEP 7: IX = VOLTAGE TRANSIENT; STEP 9: ISYS HS = COMMON REFUELING FLOOR.
STEP 12: EFFECT HX = CONSTANT SPEED AND FLOW.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AS A RESULT OF A LIGHTNING STRIKE ON A 230KV TRANSMISSION LINE, THE UNIT 1 START-UP TRANSFORMER T-10 ISOLATED 1 OF 2 SOURCES OF OFFSITE POWER. THE LOSS OF THE T-10 TRANSFORMER CAUSED A TRIP TO THE UNIT 1 AND 2 'A' RPS. REACTOR BLDG ZONE I, II, AND III HVAC SYSTEMS TRIPPED AND STANDBY GAS TREATMENT SYSTEM INITIATED DUE TO THE LOSS OF RPS. THE EFFECT ON FEEDWATER AND REACTOR RECIRCULATION CONTROLS CAUSED A REACTOR VESSEL LEVEL INCREASE. MANUAL FEEDWATER CONTROL WAS TAKEN TO DECREASE REACTOR VESSEL LEVEL. THE 'A' REACTOR FEEDWATER TURBINE TRIPPED 3 SECS AFTER BEING RESET. THE 'C' REACTOR FEEDWATER TURBINE FLOW DECREASED DUE TO THE STEAM SUPPLY ISOLATING. THE 'B' REACTOR FEEDWATER PUMP DID NOT PROVIDE SUFFICIENT FLOW TO MAINTAIN REACTOR VESSEL LEVEL. THE REACTOR SCRAMMED ON LOW LEVEL. REACTOR VESSEL LEVEL DECREASED AND INITIATED THE HPCI AND RCIC SYSTEMS, AND CLOSED THE MSIV'S. REACTOR VESSEL LEVEL INCREASED TO THE TRIP POINT FOR HPCI, RCIC, AND REACTOR FEEDWATER TURBINES. ALL SAFETY SYSTEMS WHICH WERE REQUIRED OPERATED SATISFACTORY. THIS EVENT IS REPORTABLE PER 10CFR50.73(A)(2)(IV) SINCE AN UNPLANNED ENGINEERED SAFETY FEATURE (ESF) ACTUATION OCCURRED AND THE RPS TRIPPED.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
387 1986 028 0 8609050092 200912 08/01/86

DOCKET:387 SUSQUEHANNA 1. TYPE:BWR
REGION: 1. NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PENNSYLVANIA POWER & LIGHT CO.
SYMBOL: PPL

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT
POWER LEVEL - 100%. ON AUGUST 1, 1986 AND AUGUST 6, 1986 LIGHTNING STRIKES TO THE MONTOUR MOUNTAIN 230 KV TRANSMISSION LINE CAUSED THE UNIT 1 STARTUP BUS TRANSFER (T-10) BREAKER FEEDING STARTUP BUS 10 TO OPEN. ON BOTH OCCASIONS BUS 10 LOADS TRANSFERRED TO BUS 20 AS DESIGNED. VARIOUS TRIPS AND ISOLATIONS WERE INCURRED. THE TWO UNITS WERE STABILIZED AFTER EACH EVENT AND THE AFFECTED SYSTEMS WERE RESTORED AS APPLICABLE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
387 1987 015 0 8705280421 204591 04/21/87

DOCKET:387 SUSQUEHANNA 1 TYPE:BWR
REGION: 1 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PENNSYLVANIA POWER & LIGHT CO.
SYMBOL: PPL

COMMENTS

STEPS 51,52: DI X-10. STEPS 53,54: DI X-11.

WATCH-LIST CODES FOR THIS LER ARE:

20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 387/84-014 2 387/85-020 3 387/86-022 4 387/87-007

ABSTRACT

POWER LEVEL - 100%. ON 4/21/87 AT 1634 WITH UNIT 1 OPERATING AT 100% POWER, AND UNIT 2 IN CONDITION 4 AT 0% POWER, MULTIPLE PLANT DISTURBANCES OCCURRED WHEN A LIGHTNING ARRESTOR FAILED AT A CONSTRUCTION SUBSTATION. THE FAILURE RESULTED IN A PHASE TO GROUND FAULT ON THE 230 KV SUPPLY LINE TO UNIT 2 STARTUP TRANSFORMER T-20. POWER INTERRUPTIONS CAUSED BY REALIGNMENT OF THE ELECTRICAL DISTRIBUTION SYSTEM WHEN T-20 WAS LOST RESULTED IN NUMEROUS TRIPS OR AUTO STARTS OF EQUIPMENT/SYSTEMS IN BOTH UNITS INCLUDING ENGINEERED SAFETY FEATURE ACTUATIONS OF REACTOR WATER CLEANUP, STANDBY GAS TREATMENT, CONTROL ROOM EMERGENCY OUTSIDE AIR SUPPLY, ZONE III HEATING VENTILATION AND AIR CONDITIONING ISOLATION AND ISOLATION OF UNIT 2 CONTAINMENT ISOLATION SAMPLE VALVES. THE ELECTRICAL DISTRIBUTION SYSTEM WAS RETURNED TO A NORMAL OPERATING LINEUP, PLANT SYSTEMS WERE RESTORED AND NO SAFETY CONSEQUENCES OR COMPROMISE TO PUBLIC SAFETY OCCURRED. THE FAILED LIGHTNING ARRESTOR WAS REPLACED. SINCE A PREVIOUSLY FAILED LIGHTNING ARRESTOR HAD TO BE REPLACED A MONTH EARLIER AS CORRECTIVE ACTION FOR A SIMILAR EVENT, IT WAS DECIDED TO ALSO REPLACE THE THIRD AND FINAL LIGHTNING ARRESTOR AT THE CONSTRUCTION SUBSTATION AS A PRECAUTIONARY MEASURE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
388 1985 015 0 8506050225 194924 04/21/85

DOCKET:388 SUSQUEHANNA 2 TYPE:BWR
REGION: 1 NSSS:GE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: PENNSYLVANIA POWER & LIGHT CO.
SYMBOL: PPL

REPORTABILITY CODES FOR THIS LER ARE:


10 10 CFR 50.73(a)(2)(i): Shutdowns or technical
specification violations.

REFERENCE LERS:

1 387/85-016

ABSTRACT

POWER LEVEL - 100%. ON 4-21-85, TWO OPEN SLIDING STATES LINK TERMINAL
BLOCKS WERE FOUND OPEN IN THE AUX CONTROL CIRCUIT FOR THE SPRAY POND
BYPASS VALVE IN THE 'A' LOOP OF EMERGENCY SERVICE WATER (ESW). THIS
CIRCUIT PROVIDES FOR THE AUTOMATIC FUNCTIONING OF THE VALVE ON PUMP
STARTS AND SHUTDOWNS. INVESTIGATION DETERMINED THAT THE 'A' LOOP OF
ESW WAS INOPERABLE FROM 4-4-85 UNTIL 4-21-85, WHICH EXCEEDS THE LCO
ALLOWED BY TECH SPECS. A WALKDOWN WAS PERFORMED OF SAFETY RELATED
PANELS IN UNIT 1, 2, AND COMMON TO IDENTIFY AND CORRECT OPEN STATES
LINKS. A STATION POLICY IS BEING IMPLEMENTED TO BETTER CONTROL THE
STATUS OF STATES LINKS POSITION INCLUDING AN ADMINISTRATIVE PROCEDURE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
389 1990 001 0 9002230298 216923 01/14/90

DOCKET:389 ST. LUCIE 2 TYPE:PWR
REGION: 2 NSSS:CE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: FLORIDA POWER & LIGHT COMPANY
SYMBOL: FPL

COMMENTS

STEP 7: CONDENSATE PUMP. STEP 12: MODEL PG-PL.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 335/88-008 2 335/89-003 3 389/86-010

ABSTRACT

POWER LEVEL - 050%. ON 1/14/90, ST. LUCIE UNIT 2 WAS IN MODE 1 AND PERFORMING POWER ASCENSION TOWARDS 100% POWER FOLLOWING A REACTOR STARTUP FROM A MAINTENANCE OUTAGE. TURBINE STARTUP PROCEDURE WAS BEING UTILIZED. THE 2B STEAM GENERATOR FEED PUMP AND 2B CONDENSATE PUMP WERE IN SERVICE. REACTOR POWER WAS APPROACHING 50% WITH THE TURBINE POWER INCREASING AT 4.0 MEGAWATTS PER MINUTE WHEN THE 2B STEAM GENERATOR FEED PUMP LOW SUCTION PRESSURE ALARM WAS RECEIVED. UTILITY LICENSED OPERATORS ATTEMPTED TO START THE 2A CONDENSATE PUMP BUT IT WOULD NOT START. THE 2B STEAM GENERATOR FEED PUMP TRIPPED ON LOW SUCTION PRESSURE. PUMP WAS UNABLE TO BE RESTARTED. THE STEAM GENERATOR WATER LEVELS DECREASED TO THE AUTOMATIC TRIP SETPOINT AND THE UNIT AUTOMATICALLY TRIPPED AT 2325. THE 2C AFW PUMP TRIPPED ON OVERSPEED UPON RECEIVING AN AFW ACTUATION SIGNAL. STANDARD POST TRIP ACTIONS WERE PERFORMED AND THE UNIT WAS STABILIZED IN MODE 3. THE SECOND CONDENSATE PUMP COULD NOT BE STARTED PRIOR TO THE TRIP BECAUSE ITS CONTROL FUSES HAD NOT BEEN RE-INSTALLED FOLLOWING OUTAGE WORK. PROCEDURES HAVE BEEN CHANGED TO ENSURE THE AVAILABILITY OF THE SECOND CONDENSATE AND FEEDWATER PUMP FURTHER IN ADVANCE OF BEING NEEDED AND TO CLARIFY THE POWER ASCENSION PROCEDURE. A COGNITIVE PERSONNEL ERROR BY UTILITY LICENSED OPERATORS LED TO THE AUTOMATIC REACTOR TRIP.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
395 1984 051 0 8501280200 192753 12/19/84

DOCKET:395 SUMMER 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: SOUTH CAROLINA ELECTRIC & GAS CO.
SYMBOL: SCC

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. ON 12-19-84, AT 1736 HRS, AN ACTUATION OF THE RPS OCCURRED ON HIGH NEUTRON FLUX. THE PLANT WAS IN MODE 3 WITH CONTROL RODS INSERTED AND THE SHUTDOWN BANKS WITHDRAWN WHEN THE FALSE TRIP SIGNAL WAS RECEIVED. PLANT RESPONSE TO THE TRANSIENT WAS AS EXPECTED. THE CAUSE OF THE FALSE HIGH NEUTRON FLUX SIGNAL WAS THE DEENERGIZATION OF NUCLEAR INSTRUMENTATION SOURCE AND INTERMEDIATE RANGE CHANNELS. A TRANSFORMER FAILURE IN 120V AC VITAL INVERTER XIT-5902 RESULTED IN THE LOSS OF ITS ASSOCIATED 120V AC INSTRUMENT BUS WHICH POWERED THE NI CHANNELS. THE 120V AC INSTRUMENT BUS WAS RESTORED AT 1750 HRS FROM BACKUP INVERTER XIT-5907. THE LICENSEE IS PRESENTLY REPAIRING XIT-5902 AND INVESTIGATING THE CAUSE OF THE TRANSFORMER FAILURE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
395 1987 027 0 8712040171 207342 10/29/87

DOCKET:395 SUMMER 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: SOUTH CAROLINA ELECTRIC & GAS CO.
SYMBOL: SCC

WATCH-LIST CODES FOR THIS LER ARE:


- 20 EQUIPMENT FAILURE
- 34 DESIGN ERROR OR INADEQUACY
- 941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

- 13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON OCTOBER 29, 1987, AT 0313 HOURS WITH THE PLANT AT 100% POWER, BOTH THE PRIMARY AND BACKUP POWER SUPPLIES TO ONE OF THE WESTINGHOUSE 7300 SYSTEM PROCESS RACK PANELS FAILED. THIS RESULTED IN A LOSS OF VARIOUS INSTRUMENTATION AND CONTROL FUNCTIONS INCLUDING FEEDWATER CONTROLS, PRESSURIZER PRESSURE AND LEVEL CONTROLS, AND STEAM DUMP CONTROLS. MANUAL CONTROL OF THE FEEDWATER SYSTEM WAS ATTEMPTED, BUT DUE TO THE NATURE OF THE CONTROL FAILURES, RECOVERY WAS NOT POSSIBLE. THE PLANT TRIPPED ON LOW STEAM GENERATOR "C" LEVEL COINCIDENT WITH STEAM FLOW/FEED FLOW MISMATCH. A PRESSURIZER POWER OPERATED RELIEF VALVE LIFTED, THE STEAMLINE POWER OPERATED RELIEF VALVES LIFTED, AND THE MOTOR DRIVEN AND TURBINE DRIVEN EMERGENCY FEEDWATER PUMPS STARTED. WITHIN APPROXIMATELY 13 MINUTES I&C PERSONNEL HAD RESTORED POWER TO THE PANEL AND CONTROL SYSTEMS RETURNED TO NORMAL. THE PLANT, UTILIZING THE REESTABLISHED CONTROL FUNCTIONS, RECOVERED NORMALLY FROM THE TRIP. THE CAUSE OF THE EVENT WAS ATTRIBUTED TO A FAILED CAPACITOR ON A STEAM DUMP CONTROL SIGNAL CONVERTER CARD IN ONE OF THE PROCESS RACK PANELS. THIS CAPACITOR SHORTED TO GROUND CAUSING THE BREAKERS TO BOTH THE PRIMARY AND BACKUP POWER SUPPLIES FOR THE PROCESS RACK PANEL TO TRIP. FICIENCIES RESULTING FROM DESIGN CHANGES.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
395 1988 001 0 8803070227 208519 02/04/88

DOCKET:395 SUMMER 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: SOUTH CAROLINA ELECTRIC & GAS CO.
SYMBOL: SCC

COMMENTS

STEP 5: COMP MEI - PERIMETER CAMERAS. STEP 10: COMP MEI - PORTAL ACCESS
CONTROLLER UNITS. STEP 11: COMP MSC - ELECTRIC DOOR STRIKES. STEP 12: PSYS
SW - UNKNOWN VITAL AREAS. STEP 9: PART NUMBERS 200140 AND 200569 SPM/E E/D

WATCH-LIST CODES FOR THIS LER ARE:


34 DESIGN ERROR OR INADEQUACY
946 PHYSICAL SECURITY/SAFEGUARDS

REPORTABILITY CODES FOR THIS LER ARE:

20 10 CFR 73.71(c): Physical security system threatened.

ABSTRACT

POWER LEVEL - 100%. AT APPROXIMATELY 0830 HOURS, FEBRUARY 4, 1988, TWO
PLANT ELECTRICIANS CRIMPED AN ELECTRICAL LEAD WHILE REPLACING AN
ELECTRICAL DISTRIBUTION PANEL COVER. THE CIRCUIT SHORTED TO GROUND
AND TRIPPED A CIRCUIT BREAKER WHICH RESULTED IN A LOSS OF THREE
PERIMETER CAMERAS. SIMULTANEOUSLY, THE CURRENT TO GROUND SITUATION
CAUSED THE ASSOCIATED INVERTER TO TEMPORARILY OVERLOAD CREATING A
MOMENTARY, BUT SIGNIFICANT REDUCTION IN VOLTAGE THAT RESULTED IN SIX
ELECTRIC DOOR STRIKES FAILING IN THE UNLOCKED (ENERGIZED) POSITION.
AT APPROXIMATELY 0840 HOURS, SECURITY PROCEDURES WERE IMPLEMENTED TO
COMPENSATE FOR THE LOSS OF THE CAMERAS AND TOTAL LOSS OF THE SECURITY
COMPUTER SYSTEM. AT APPROXIMATELY 0907 HOURS, ELEVEN ADDITIONAL
SECURITY FORCE PERSONNEL REPORTED FOR DUTY FROM THE TRAINING
AUGMENTATION TO COMPENSATE FOR THE LOSS OF ALARM CAPABILITY AND
LOCKING MECHANISMS AT THE VITAL AREAS AFFECTED BY THE OUTAGE.
OPERATIONAL TESTS WERE CONDUCTED ON ALL VITAL DOORS AND PERIMETER
INTRUSION DETECTION SEGMENTS AFFECTED. ALL TESTS WERE SATISFACTORILY
COMPLETED AT 1243 HOURS, FEBRUARY 4, 1988. COMPENSATORY POSTS AT EACH
VITAL AREA REMAINED IN EFFECT UNTIL EACH DOOR WAS OPERATIONALLY
TESTED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
397 1984 079 1 8412270018 196934 08/09/84

DOCKET:397 WPPSS 2 TYPE:BWR
REGION: 5 NSSS:GE
ARCHITECTURAL ENGINEER: BNRO
FACILITY OPERATOR: WASHINGTON PUBLIC POWER SUPPLY SYSTEM
SYMBOL: WPP

COMMENTS

OTHER REPORTABILITY: 50.72 (B)(2)(II).

WATCH-LIST CODES FOR THIS LER ARE:


941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

- 13 10 CFR 50.73(a)(2)(iv): ESF actuations.
- 21 OTHER: Voluntary report, special report, Part 21 report, etc.

ABSTRACT

POWER LEVEL - 015%. A REACTOR SCRAM OCCURRED AUTOMATICALLY ON LOW REACTOR WATER LEVEL AFTER THE REACTOR FEED WATER (RFW) PUMP TRIPPED DUE TO LOSS OF CONTROL POWER. WHILE PREPARING TO ROLL THE TURBINE IN A NORMAL RAMP UP MODE THE CONTROL ROOM OPERATOR STARTED THE THIRD LARGE CIRCULATING WATER PUMP. AT THIS TIME, THE PLANT WAS BEING SUPPLIED BY THE STARTUP TRANSFORMER (TR-S) WHICH WAS HEAVILY LOADED. THE LARGE STARTING CURRENT FOR THIS MOTOR (APPROX 3300 AMPS) COINCIDENT WITH THE HEAVILY LOADED CONDITION OF THE STARTUP TRANSFORMER, RESULTED IN A VOLTAGE DROP ON THE SECONDARY OF THE TRANSFORMER. THIS VOLTAGE DROPPED BELOW THE SETPOINT FOR THE SECOND LEVEL (DEGRADED) UNDERVOLTAGE PROTECTION. THE VOLTAGE HAD NOT EXCEEDED THE RESET SETPOINT WITHIN THE EIGHT SECOND PROTECTION. THE VOLTAGE HAD NOT EXCEEDED THE RESET SETPOINT WITHIN THE EIGHT SECOND TIME DELAY AND THE SECOND LEVEL UNDERVOLTAGE CIRCUITRY INITIATED LOAD SHEDDING AS DESIGNED ON DIV. I AND DIV. III. THE TEMPORARY LOSS OF POWER TO THE CONTROL CIRCUITRY RESULTED IN TRIPPING OF THE RFW PUMP. THE LOSS OF FEEDWATER TO THE REACTOR RESULTED IN A DROP OF REACTOR WATER LEVEL TO LEVEL THREE (+12") AND THE REACTOR SCRAMMED AS DESIGNED. REACTOR WATER LEVEL WAS RESTORED USING THE RCIC SYSTEM. THE PLANT ELECTRICAL LINEUP WAS RESTORED TO A NORMAL CONFIGURATION.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
397 1989 002 0 8903130165 213225 01/30/89

DOCKET:397 WPPSS 2 TYPE:BWR
REGION: 5 NSSS:GE
ARCHITECTURAL ENGINEER: BNRO
FACILITY OPERATOR: WASHINGTON PUBLIC POWER SUPPLY SYSTEM
SYMBOL: WPP

COMMENTS

STEPS 24-27: COMP LX - CONTAINMENT ISOLATION AND ADS ACTIVATION.

WATCH-LIST CODES FOR THIS LER ARE:

34 DESIGN ERROR OR INADEQUACY
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1. 397/85-002 2 397/85-003 3 397/87-018

ABSTRACT

POWER LEVEL - 100%. ON 1/30/89, AT 0514 HRS, A REACTOR SCRAM OCCURRED DUE TO TURBINE CONTROL VALVE FAST CLOSURE ACTUATION OF THE REACTOR PROTECTIVE SYSTEM LOGIC. THIS LOGIC WAS ACTUATED WHEN THE MAIN GENERATOR 500KV OUTPUT BREAKERS TRIPPED AS A RESULT OF HIGH CURRENTS CREATED WHEN A PORCELAIN INSULATOR ON THE OUTPUT SIDE OF 25/500KV MAIN TRANSFORMER TR-M1 SHORTED TO GROUND. PLANT OPERATORS RESPONDED TO MANEUVER THE PLANT TO A SAFE SHUTDOWN CONDITION. THE DAMAGED 500KV INSULATOR STACK WAS REPLACED. ALL OTHER 500KV AND 115KV INSULATORS IN THE TRANSFORMER YARD WERE CLEANED AND INSPECTED. TRANSFORMER TR-M1 WAS TESTED TO DETERMINE ITS ACCEPTABILITY FOR CONTINUED USE. THE IMMEDIATE CAUSE OF THE INSULATOR FAILURE WAS THE BUILD UP OF A CHEMICAL RESIDUE DEPOSITED BY THE VAPOR PLUME FROM THE CIRCULATING WATER SYSTEM COOLING TOWERS. THIS RESIDUE WAS FOUND TO BE CONDUCTIVE WHEN WET. THE RESIDUE CONSISTED OF RIVER WATER MINERALS AND SULFATE COMPOUNDS GENERATED BY SULFURIC ACID ADDITION USED TO CONTROL THE PH OF CIRCULATING WATER. TWO ROOT CAUSES WERE IDENTIFIED: 1) EQUIPMENT DESIGN DEFICIENCY (PROBLEM NOT ANTICIPATED). THE INSULATORS USED AT WNP-2 ARE NOT OF THE TYPE OR NUMBER RECOMMENDED FOR CONTAINMENTED ENVIRONMENTS. 2) EQUIPMENT MAINTENANCE DEFICIENCY. NO FORMAL MAINTENANCE/INSPECTION PROGRAM EXISTED WHICH IDENTIFIED THIS EQUIPMENT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
397 1989 023 0 8907100048 214570 05/31/89

DOCKET:397 WPPSS 2 TYPE:BWR
REGION: 5 NSSS:GE
ARCHITECTURAL ENGINEER: BNRO
FACILITY OPERATOR: WASHINGTON PUBLIC POWER SUPPLY SYSTEM
SYMBOL: WPP

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. ON 5/31/89 AT 1406 HRS AN ELECTRICAL PROTECTION ASSEMBLY (EPA) BREAKER TRIPPED CAUSING A LOSS OF POWER TO REACTOR PROTECTION SYSTEM (RPS) BUS B. LOSS OF POWER TO RPS BUS B CAUSED A HALF-SCRAM IN RPS DIVISION B AND MULTIPLE PRIMARY AND SECONDARY CONTAINMENT ISOLATIONS AND ESF ACTUATIONS OF VENTILATION SYSTEMS. PLANT WAS SHUTDOWN FOR ANNUAL MAINTENANCE AND REFUELING OUTAGE. LOSS OF RPS B POWER CAUSES NUCLEAR STEAM SUPPLY SHUTOFF SYSTEM CONTAINMENT INBOARD AND OUTBOARD ISOLATIONS FOR GROUPS 1,2,5,6 AND 7; AND A REACTOR BLDG EXHAUST PLENUM RADIATION MONITOR "Z" SIGNAL WHICH INITIATES SEVERAL ESF ACTUATIONS INCLUDING STANDBY GAS TREATMENT (SGT) SYSTEM, THE CONTROL ROOM EMERGENCY FILTRATION SYSTEM, AND A REACTOR BLDG VENTILATION SYSTEM ISOLATION. PLANT OPERATORS RESPONDED BY RESTORING ALL SYSTEMS, INCLUDING RESIDUAL HEAT REMOVAL (RHR) SHUTDOWN COOLING, TO PRE-EVENT LINEUP STATUS BY 1430 HRS. THE CAUSES OF THIS EVENT ARE PERSONNEL ERROR IN THAT A PLANT TEST ENGINEER AND PLANT OPERATORS DID NOT ADEQUATELY REVIEW THE CONSEQUENCES OF STARTING A REACTOR RECIRCULATION PUMP WHILE THE PLANT WAS ALIGNED FOR THE PERFORMANCE OF LOGIC SYSTEM FUNCTIONAL TESTING (LSFT) OF THE ATWS RECIRCULATION PUMP "A" TRIP SYSTEM, AND 2) INADEQUATE PROCEDURE IN THAT THE LSFT PROCEDURE DID NOT SPECIFICALLY CAUTION AGAINST STARTING AN RRC PUMP DURING TEST PERFORMANCE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
400 1987 054 0 8710200569 206693 09/15/87

DOCKET:400 SHEARON HARRIS 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: EBAS
FACILITY OPERATOR: CAROLINA POWER & LIGHT CO.
SYMBOL: CPL

COMMENTS

WATCH 931 - 10CFR21 REPORT SUBMITTED FOR THIS EVENT. STEP 1: COMP PX -
DESIGN RESPONSIBILITIES WERE COMBINED AMONG UTILITY, AE, AND REACTOR
VENDOR. STEP 5: COMP EC - FIELD FLASHING CIRCUIT. STEP 10: COMP 52 - BUS
TIE BREAKERS IN THE EMERGENCY AC SYSTEM.

WATCH-LIST CODES FOR THIS LER ARE:


931 REPORTS ASSOCIATED WITH PART 21
34 DESIGN ERROR OR INADEQUACY
241 FAILURES THAT COULD EASILY ESCAPE DETECTION

REPORTABILITY CODES FOR THIS LER ARE:

11 10 CFR 50.73(a)(2)(ii): Unanalyzed conditions.

ABSTRACT

POWER LEVEL - 100%. ON SEPTEMBER 15, 1987, AT 2000, WITH THE PLANT IN
MODE 1 AT 100% POWER, IT WAS DETERMINE THAT A MORE LIMITING SINGLE
FAILURE THAN HAD BEEN PREVIOUSLY ANALYZED MIGHT EXIST, AND THAT IF
VALID, CONTINUED OPERATION OF THE PLANT WAS NOT JUSTIFIED. A PLANT
SHUTDOWN COMMENCED AT 2015, AND THE UNIT WAS OFF-LINE AT 0040 ON
SEPTEMBER 16, 1987. THE UNANALYZED FAILURE INVOLVED A LOSS OF "B"
VITAL DC BUS CAUSING A FAILURE OF THE TURBINE-DRIVEN AUXILIARY
FEEDWATER (AFW) PUMP AND THE "B" MOTOR-DRIVEN AFW PUMP. THE FINAL
SAFETY ANALYSIS REPORT (FSAR) ACCIDENT ANALYSIS FOR MAIN FEEDWATER
LINE BREAK ASSUMES THE AVAILABILITY OF BOTH MOTOR-DRIVEN PUMPS "A" AND
"B". THE PLANT WAS COOLED DOWN TO MODE 4 AT 0440 ON SEPTEMBER 16,
1987, WHERE AUXILIARY FEEDWATER IS NOT REQUIRED TO BE OPERABLE BY
TECHNICAL SPECIFICATIONS. ON SEPTEMBER 16, 1987, TWO ADDITIONAL
POTENTIAL FAILURE MODES WERE IDENTIFIED; ONE INVOLVED THE SPURIOUS
FAILURE OF A RELAY IN THE SOLID STATE PROTECTION SYSTEM (SSPS) CAUSING
INADVERTENT ISOLATION OF AFW TO ONE STEAM GENERATOR. THE SECOND WAS
THAT FAILURE OF "B" VITAL DC BUS COINCIDENT WITH A LOSS OF OFF-SITE
POWER WOULD ISOLATE AFW TO ALL THREE STEAM GENERATORS. REANALYSIS OF
ACCIDENTS WITH A REDUCED AFW CAPABILITY WAS DONE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
409 1985 016 0 8510150329 196363 09/14/85

DOCKET:409 LACROSSE TYPE:BWR
REGION: 3 NSSS:AC
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: DAIRYLAND POWER COOPERATIVE
SYMBOL: DLP

COMMENTS


PREVIOUS SIMILAR EVENT IN 1979; STEP 2: COMPONENT MSC - SWITCH COVER.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 096%. DURING MAINTENANCE ON A RECORDER, THE TECHNICIAN CAUSED A SHORT WHICH BLEW FUSE 32-1, WHICH SUPPLIED SOME CONTROL ROOM INSTRUMENTATION FROM THE 1B NONINTERRUPTIBLE BUS. ONE OF THE SIGNALS DE-ENERGIZED WAS FEEDWATER FLOW. THIS CAUSED THE REACTOR WATER LEVEL CONTROL SYSTEM TO INCREASE THE REACTOR FEED PUMP SPEED TO INCREASE FEEDWATER FLOW. THE REACTOR SCRAMMED ON HIGH WATER LEVEL. WATER LEVEL STABILIZED AT 20 INCHES ABOVE NORMAL. THE REACTOR FEED PUMP WAS SECURED, FUSE 32-1 WAS REPLACED. AS A LONG TERM PROJECT, SEPARATION OF SOME OF THE INSTRUMENTATION CURRENTLY SUPPLIED THROUGH FUSE 32-1 WILL BE CONSIDERED.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
409 1986 002 0 8602140240 197906 01/10/86

DOCKET:409 LACROSSE TYPE:BWR
REGION: 3 NSSS:AC
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: DAIRYLAND POWER COOPERATIVE
SYMBOL: DLP

COMMENTS


STEP 2: OPERATOR FAILED TO RECLOSE THE MAIN FEED TIE BREAKER BEFORE OPENING
THE RESERVE FEED BREAKER; STEP 6: CAUSE AX - TROUBLESHOOTING OF THE
CONTROL ROOM ANNUNCIATOR SYSTEM WAS CAUSING A CONTINUOUS AUDIBLE ALARM.

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. THE 120V NONINTERRUPTIBLE BUS 1B WAS MOMENTARILY
DE-ENERGIZED WHEN IT WAS BEING RETURNED TO ITS NORMAL POWER SUPPLY DUE
TO AN INCORRECT BREAKER ALIGNMENT. THE PLANT WAS IN COLD SHUTDOWN AT
THE TIME. DUE TO THE MOMENTARY LOSS OF POWER TO THE BUS, BOTH
EMERGENCY DG'S, BOTH HIGH PRESSURE CORE SPRAY PUMPS AND THE 1A HIGH
PRESSURE SERVICE WATER/ALTERNATE CORE SPRAY PUMP STARTED AND
CONTAINMENT BLDG ISOLATED. THE 1B HPSW/ACS PUMP WAS ALREADY RUNNING
DUE TO OTHER WORK IN PROGRESS. THE EQUIPMENT THAT STARTED WAS SECURED.
THE IMPORTANCE OF PROPER PERFORMANCE OF DUTIES WILL BE EMPHASIZED IN
UPCOMING OPERATIONS DEPARTMENT TRAINING AND A PROCEDURE WILL BE
REVISED.



DOCKET , YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
423 1987 027 0 8707090095 205195 06/05/87

DOCKET:423 MILLSTONE 3 TYPE:PWR
REGION: 1 NSSS:WE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: NORTHEAST NUCLEAR ENERGY CO.
SYMBOL: NNE

WATCH-LIST CODES FOR THIS LER ARE:


- 31 ACCIDENTAL ACTION
- 941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

- 13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. AT 1323 ON JUNE 5, 1987, WITH THE PLANT AT 100% POWER, THE NORMAL SUPPLY BREAKER TO TRAIN "A" VITAL BUS 34C WAS TRIPPED OPEN. THE MAIN STEAM ISOLATION VALVES IMMEDIATELY CLOSED ON LOSS OF 120VAC TO THEIR SOLENOID TEST CONTROL CIRCUITRY. A REACTOR TRIP FOLLOWED ON LOW-LOW STEAM GENERATOR LEVELS, WHICH SIGNED A TURBINE TRIP. A TRAIN "A" LOSS OF POWER SIGNAL WAS GENERATED, THE EMERGENCY DIESEL GENERATOR STARTED AND SUCCESSFULLY ENERGIZED VITAL LOADS. THE MAIN STEAM ATMOSPHERIC RELIEF VALVES AND STEAM GENERATOR CODE SAFETIES OPENED AS DESIGNED. A TRAIN "A" CONTROL BUILDING ISOLATION, AND TRAIN "A" AND "B" FEEDWATER ISOLATION RESULTED FROM THE EVENT. THE PLANT WAS IN HOT STANDBY (MODE 3) BY 1600 HOURS, JUNE 5, 1987. THE CAUSE OF BUS 34C TRIP WAS A RESULT OF PERSONNEL ERROR, DUE TO AN OPERATOR DROPPING A RACKING MOTOR ONTO THE 4.16KV SWITCHGEAR.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
424 1990 023 0 9101220420 220828 12/18/90

DOCKET:424 VOGTLE 1 TYPE:PWR
REGION: 2 NSSS:WE
ARCHITECTURAL ENGINEER: BESS
FACILITY OPERATOR: GEORGIA POWER CO.
SYMBOL: GPC

COMMENTS

STEP 2: CLASS AA/FA, 3 PHASE, DRY TYPE TRANSFORMER. STEP 18: MODEL NO.
5HK350-3000.


WATCH-LIST CODES FOR THIS LER ARE:
20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 424/90-016

ABSTRACT

POWER LEVEL - 100%. ON 12-18-90 AT 1936 CST, UNIT WAS OPERATING AT 100% POWER WHEN A 4160/480 VOLT NON-1E TRANSFORMER (1NB10X) EXPERIENCED AN INTERNAL FAULT. THIS FAILURE RESULTED IN A LOSS OF POWER FOR THE SPEED CONTROL CIRCUITRY FOR THE 1B MAIN FEEDWATER PUMP (MFP) TURBINE AND CERTAIN SUPPORT SYSTEMS FOR EMERGENCY DIESEL GENERATOR 1B. FEEDWATER PUMP SPEED, FEEDWATER FLOW, AND STEAM GENERATOR (SG) LEVELS DECREASED. THE REACTOR OPERATOR INITIATED A MANUAL REACTOR TRIP AT 1937 CST AFTER EFFORTS TO MAINTAIN SG LEVELS WERE UNSUCCESSFUL. ALL SAFETY RELATED FUNCTIONS OCCURRED PER DESIGN FOLLOWING THE REACTOR TRIP; HOWEVER, A NON-1E 4160 VOLT BUS FAILED TO AUTOMATICALLY TRANSFER TO THE RESERVE AUXILIARY TRANSFORMERS CAUSING A TEMPORARY LOSS OF VARIOUS NON-1E HOUSE LOADS. TRANSFER OF THE 4160 VOLT BUS WAS COMPLETED MANUALLY AND NORMAL PLANT CONDITIONS WERE ESTABLISHED FOR HOT STANDBY BY 1956 CST. THE ROOT CAUSE FOR THE TRANSFORMER FAILURE IS INDETERMINATE; HOWEVER, SEVERAL SIMILAR TRANSFORMER FAILURES HAVE OCCURRED AT VEGP (REFERENCE LER 50-424/1990-016). THE INVOLVED TRANSFORMERS ARE GE CLASS AA/FA, THREE PHASE, DRY TYPE TRANSFORMERS. THE FAILED TRANSFORMER HAS BEEN REPLACED AND FURTHER STUDY OF POSSIBLE FACTORS WHICH MAY HAVE LED TO THE FAILURE IS IN PROGRESS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
440 1988 023 0 8807120238 209845 06/08/88

DOCKET:440 PERRY 1 TYPE:8WR
REGION: 3 NSSS:GE
ARCHITECTURAL ENGINEER: GLBT
FACILITY OPERATOR: CLEVELAND ELECTRIC ILLUMINATING CO.
SYMBOL: CEI

COMMENTS

STEPS 16 - 18: COMP LX - ISOLATION/ RECIRC SYSTEM TRIP. SL/CT/9.

WATCH-LIST CODES FOR THIS LER ARE:

35 HUMAN ERROR

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 440/87-072

ABSTRACT

POWER LEVEL - 023%. ON JUNE 8, 1988 AT 0923, A REACTOR SCRAM AND NUCLEAR STEAM SUPPLY SHUTOFF SYSTEM BALANCE OF PLANT (BOP) CONTAINMENT ISOLATION OCCURRED DUE TO LOSS OF POWER TO BOTH REACTOR PROTECTION SYSTEM (RPS) POWER DISTRIBUTION BUSES. AT 0922 THE MAIN TURBINE TRIPPED DUE TO HIGH LEVEL IN A MOISTURE SEPARATOR REHEATER DRAIN TANK. DURING RECOVERY FROM THE MAIN TURBINE TRIP, AN OPERATOR INADVERTENTLY TRIPPED THE TWO MAINLINE BREAKERS FEEDING THE BOP ELECTRICAL DISTRIBUTION BUSES. CONSEQUENTLY, BOTH RPS BUSES WERE DEENERGIZED, RESULTING IN A REACTOR SCRAM, A FULL CONTAINMENT ISOLATION, BOTH REACTOR RECIRCULATION PUMPS TRIPPING AND LOSS OF FEEDWATER. THE CONTROL ROOM OPERATORS VERIFIED ALL AUTOMATIC ACTUATIONS OCCURRED. THE REACTOR CORE ISOLATION COOLING SYSTEM WAS STARTED AT 0926 AND UTILIZED TO CONTROL REACTOR VESSEL LEVEL AND PRESSURE. THE CAUSE OF THE EVENT WAS PERSONNEL ERROR. THE SUPERVISING OPERATOR TURNED THE CONTROL SWITCHES IN THE WRONG DIRECTION WHEN ATTEMPTING TO RESET THE BREAKER POSITION INDICATION FLAGS RESULTING IN THE BOP SUPPLY BREAKERS OPENING. THE OPERATOR HAS BEEN COUNSELED BY PLANT MANAGEMENT AND DISCIPLINARY ACTION HAS BEEN TAKEN. IN ACCORDANCE WITH THE LICENSED OPERATOR REQUALIFICATION TRAINING PROGRAM, OPERATORS WILL RECEIVE TRAINING ON THE SEQUENCE OF EVENTS WHICH LED TO THIS REPORT.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
445 1990 023 0 9009100049 220895 08/08/90

DOCKET:445 COMANCHE 1 TYPE:PWR
REGION: 4 NSSS:WE
ARCHITECTURAL ENGINEER: GIBB
FACILITY OPERATOR: TEXAS UTILITIES GENERATING CO.
SYMBOL: TUG

COMMENTS

STEP 2: SUCHANAN CONSTRUCTION MODEL NO. 361.

WATCH-LIST CODES FOR THIS LER ARE:


20 EQUIPMENT FAILURE
941. REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 017%. ON 8/8/90, COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1 WAS IN MODE 1, POWER OPERATIONS, WITH REACTOR POWER AT 17%. A LOOSE FUSE IN THE MAIN FEEDWATER CONTROL POWER CIRCUIT CAUSED CLOSURE OF A VALVE IN THE FEEDWATER FLOW PATH TO STEAM GENERATOR NUMBER 4. WATER LEVEL IN STEAM GENERATOR NUMBER 4 DECREASED TO THE LO-LO LEVEL SETPOINT, INITIATING A REACTOR TRIP SIGNAL. CORRECTIVE ACTIONS INCLUDED INSPECTION OF SIMILAR COMPONENTS IN OTHER APPLICATIONS, MAINTENANCE ON THE MALFUNCTIONING COMPONENT, AND PERSONNEL TRAINING.



DOCKET YEAR LER NUMBER. REVISION DCS NUMBER NSIC EVENT DATE
445 1990 028 0 9010220016 219779 09/08/90

DOCKET:445 COMANCHE 1 TYPE:PWR
REGION: 4 NSSS:WE
ARCHITECTURAL ENGINEER: GIBB
FACILITY OPERATOR: TEXAS UTILITIES GENERATING CO.
SYMBOL: TUG

WATCH-LIST CODES FOR THIS LER ARE:


11 ACTS OF NATURE
941 REPORT ASSOCIATED WITH 10 CFR 50.72

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 038%. AT 1428 ON SEPTEMBER 8, 1990, COMANCHE PEAK STEAM ELECTRIC STATION UNIT 1 WAS AUTOMATICALLY TRIPPED FROM 38 PERCENT POWER. A LIGHTNING STRIKE IS BELIEVED TO HAVE CAUSED A SURGE IN THE INPUT POWER RESULTING IN THE DE-ENERGIZATION OF POWER SUPPLIES IN THE ROD DRIVE SYSTEM, CAUSING THE RODS CONTROLLED BY ONE ROD CONTROL CABINET TO DROP INTO THE CORE. THIS RESULTED IN THE REACTOR TRIP FORM HIGH NEGATIVE FLUX RATE. NO SPECIFIC COMPONENT OR SYSTEM FAILURES WERE IDENTIFIED AS THE CAUSE OF THIS EVENT. THE INSTALLATION OF SURGE SUPPRESSORS IN THE INPUT SUPPLY TO ROD DRIVE POWER SUPPLIES WILL PROVIDE ADDITIONAL ASSURANCE THAT POWER SUPPLIES REMAIN AVAILABLE DURING LIGHTNING STRIKES.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
454 1984 030 0 8501210416 192758 12/18/84

DOCKET:454 BYRON 1 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. WITH THE PLANT OPERATING IN MODE 5, AC INSTRUMENT BUS 111 DE-ENERGIZED AND THE BORON DILUTION PROTECTION SYSTEM (BDPS) WAS ACTUATED DUE TO THE RESULTING DE-ENERGIZATION OF NUCLEAR INSTRUMENTATION CHANNEL I. THIS SWITCHED THE SUCTION FOR THE CENTRIFUGAL CHARGING PUMP FROM ITS NORMAL LETDOWN SOURCE (VOLUME CONTROL TANK) TO ITS BORATED WATER SOURCE (REFUELING WATER STORAGE TANK). THE TRAIN A ESF SEQUENCING CABINET, SOLID STATE PROTECTION SYSTEM (SSPS) TRAIN A OUTPUT, AND SSPS TRAIN A AND B INPUT CABINETS WERE ALSO DE-ENERGIZED BY THE LOSS OF THE AC INSTRUMENT BUS 111 AND THIS PREVENTED TRAIN A OF THE BDPS FROM ACTUATING. THE OPERATOR RESET THE BDPS AND RE-ENERGIZED BUS 111 FROM A STANDBY POWER SOURCE. THE AC BUS FAILURE WAS TRACED BACK TO A DEGRADED CAPACITOR IN THE BUS INVERTER, WHICH CAUSED THE INVERTER OUTPUT FUSE TO BLOW. THE CAPACITOR FAILURE IS ATTRIBUTED TO AGE DEGRADATION. TO PREVENT RECURRENCE OF THIS EVENT, NEW CAPACITORS ARE BEING INSTALLED AND MAINTENANCE PROCEDURES HAVE BEEN IMPLEMENTED TO MAINTAIN CAPACITORS.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
454 1985 046 0 8505200128 194852 04/21/85

DOCKET:454 BYRON 1 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 1: COMP RLX - AUXILIARY RELAY; MODEL AR 880AR. STEP 7: EFFECT IX -
VOLTAGE FLUCTUATIONS.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 454/85-036

ABSTRACT

POWER LEVEL - 049%. WITH THE PLANT OPERATING IN MODE 1, A REACTOR TRIP OCCURRED DUE TO STEAM GENERATOR LO-2 LEVEL. THE STEAM GENERATOR LEVEL DROP WAS CAUSED BY AN AUXILIARY RELAY STICKING IN THE ENERGIZED POSITION DURING A FEEDWATER ISOLATION VALVE SLAVE RELAY SURVEILLANCE AND PRODUCING AN ACTUAL ISOLATION OF THE FEEDWATER CONTROL VALVES. THE REACTOR TRIP PRODUCED A VOLTAGE FLUCTUATION ON THE ESF BUS SUPPLYING A CONTROL ROOM VENTILATION INTAKE RADIATION MONITOR. THIS CAUSED THE RADIATION MONITOR TO ENTER AN INTERLOCK CONDITION WHICH IN TURN PLACED THE CONTROL ROOM VENTILATION SYSTEM IN THE MAKE-UP MODE. THE POWER FAILURE SETPOINTS ON THE RADIATION MONITORS ARE BEING LOWERED TO MAKE THE MONITORS LESS SENSITIVE TO VOLTAGE SWINGS (SEE ALSO LER 85-036-00). THE FAULTY RELAY WAS SUBSEQUENTLY REPLACED AND THE SYSTEM RETESTED SUCCESSFULLY.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
455 1987 019 1 8806230261 209583 10/02/87

DOCKET:455 BYRON 2 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 6: EQUIPMENT OPERATOR OPENED STATION AUX TRANSFORMER DISCONNECT
INSTEAD OF THE MAIN TRANSFORMER DISCONNECT.

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
942 UNUSUAL EVENT
20 EQUIPMENT FAILURE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 013%. ON OCTOBER 2, 1987, AT 0446, UNIT 2 WAS RETURNING TO SERVICE. WHEN UNIT 2 WAS SYNCHRONIZED TO THE GRID, THE STEAM GENERATOR (SG) LEVELS INCREASED AND CAUSED A HI-2 S/G LEVEL TRIP. THE HI-2 SG LEVEL WAS REACHED ON SG 2C DUE TO EXCESSIVE "LEAK BY" OF THE 2FW530 VALVE. THE HIGH S/G LEVEL CAUSED A TURBINE TRIP AND A SUBSEQUENT REACTOR TRIP BECAUSE REACTOR POWER WAS ABOVE 10%. AN EQUIPMENT OPERATOR (EO) WAS INSTRUCTED TO REALIGN THE SWITCHYARD RING BUS AFTER THE TRIP. THE EO OPENED THE SYSTEM AUX TRANSFORMER DISCONNECTS INSTEAD OF THE MAIN POWER TRANSFORMER DISCONNECTS. THE SAFETY RELATED 4KV BUSES WERE DEENERGIZED CAUSING THE EMERGENCY DIESEL GENERATORS TO START, REENERGIZE THE BUSES, AND SEQUENCE THE SAFE SHUTDOWN LOADS. THE ROOT CAUSE OF THE LOSS OF OFFSITE POWER WAS DUE TO PERSONNEL ERROR. THE EO OPENED THE WRONG DISCONNECT. THE CORRECTIVE ACTIONS ARE AS FOLLOWS: DISCIPLINARY ACTION WAS TAKEN WITH THE EO; ADMINISTRATIVE PROCEDURES WERE REVISED TO ENSURE THAT NO SWITCHYARD OPERATIONS ARE PERFORMED WITHOUT A SECOND INDIVIDUAL PRESENT; PERMANENT, DESCRIPTIVE LABELS HAVE BEEN PLACED ON MPT & SAT SWITCHYARD DISCONNECTS; A WALK THROUGH OF THE SWITCHYARD WITH DIVISION SUPERINTENDENT OF POWER SUPPLY TO DEMONSTRATE PROPER OPERATIONS AND COMMUNICATIONS WAS CONDUCTED; THE SAT DISCONNECTS ARE LOCKED WITH UNIQUE LOCKS FOR EACH UNIT, ETC.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
456 1988 023 0 8811210116 211414 10/17/88

DOCKET:456 BRAIDWOOD 1 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: SLXX
FACILITY OPERATOR: COMMONWEALTH EDISON CO.
SYMBOL: CWE

COMMENTS

STEP 5: MODEL 764. STEP 6: MODEL 752. STEP 7: MODEL 763. STEP 22: COMP MEI
- GROUNDING EQUIPMENT.

WATCH-LIST CODES FOR THIS LER ARE:


20 EQUIPMENT FAILURE
34 DESIGN ERROR OR INADEQUACY
11 ACTS OF NATURE

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.
15 10 CFR 50.73(a)(2)(vii): Single failure criteria.

ABSTRACT

POWER LEVEL - 000%. A SEVERE LIGHTNING STORM OCCURED AT THE PLANT SITE. UNIT 1 WAS SHUTDOWN. AT 1542 ON OCTOBER 17, 1988 VARIOUS UNIT 1 INDICATIONS REVEALED ERRATIC BEHAVIOR AND THE OVER PRESSURE DELTA TEMPERATURE (OP DELTA T) AND OVER TEMPERTURE DELTA TEMPERATURE (OT DELTA T) COINCIDENCE WAS MET FOR A REACTOR TRIP. ON UNIT 2 A REACTOR TRIP AND A LOCK UP OF THE COMPUTER MEMORY FOR THE REACTOR VESSEL LEVEL INDICATING SYSTEM (RVLIS) OCCURRED. THE ROOT CAUSE IS A VOLTAGE TRANSIENT INTO THE STATION GROUND SYSTEM FROM LIGHTNING STRIKES WHICH ACTUATED THE OVERVOLTAGE PROTECTION FOR THE RD POWER SUPPLIES, FOR BOTH UNITS, SUBSEQUENTLY RESULTING IN THE UNIT 2 REACTOR TRIP. RVLIS FAILED FROM AN OVERVOLTAGE CONDITION. ON UNIT 1, THE INSTRUMENT LOOP TRANSMITTERS WERE REPLACED AND ALL POWER SUPPLIES WERE RESET. THERE WERE NO EQUIPMENT FAILURES WITH THE OP DELTA T AND OT DELTA T INSTRUMENT CHANNELS. INVESTIGATION REVEALED THE STATION GROUNDING SCHEME IS ADEQUATE; HOWEVER, THE VENT STACK GROUNDING IS INCOMPLETE. THIS DID NOT CONTRIBUTE TO THE UNIT 2 TRIP. ADDITIONAL GROUNDING AND ADDITIONAL PROTECTIVE MEASURES FOR THE RD SYSTEM ARE BEING INVESTIGATED. THERE WERE NO PREVIOUS OCCURRENCES.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
458 1987 012 1 8802190192 208258 06/18/87

DOCKET:458 RIVERBEND 1 TYPE:BWR
REGION: 4 NSSS:GE
ARCHITECTURAL ENGINEER: SWXX
FACILITY OPERATOR: GULF STATES UTILITIES
SYMBOL: GSU

COMMENTS

STEP 1: PART #633-270-40, ASSEMBLY J901.

WATCH-LIST CODES FOR THIS LER ARE:


35 HUMAN ERROR
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 070%. ON 6/18/87 AT 0322, WITH THE UNIT AT APPROXIMATELY 70 PERCENT POWER, A REACTOR TRIP OCCURRED. INITIATION OF THE REACTOR PROTECTION SIGNAL WAS CAUSED BY A REACTOR VESSEL WATER LEVEL - HIGH LEVEL 8 (51 INCHES) CONDITION. A LOSS OF CONTROL POWER TO PANEL 1VBN-PNLD01B1 OCCURRED INADVERTENTLY DURING THE TROUBLE SHOOTING OF BATTERY INVERTER 1BYS-INVO1BB *INVT*. LOSS OF CONTROL POWER TO THE FEEDWATER REGULATING VALVES CAUSED THEM TO LOCKUP IN A POSITION CONSISTENT WITH 70 PERCENT REACTOR POWER. ALSO, AS A RESULT OF THE LOSS OF THE INVERTER, THE RECIRCULATION SYSTEM FLOW CONTROL VALVES RAN BACK. SIMULTANEOUSLY, THE RECIRCULATION PUMPS RECEIVED A SIGNAL TO TRANSFER TO THE LOW FREQUENCY MOTOR GENERATORS. THIS CAUSED SUFFICIENT FEEDWATER FLOW/STEAM FLOW MISMATCH TO INCREASE THE VESSEL LEVEL TO HIGH LEVEL 8. OPERATIONS PERSONNEL RESPONDED BY SATISFACTORILY IMPLEMENTING THE IMMEDIATE AND SUBSEQUENT ACTIONS REQUIRED BY "REACTOR SCRAM" PROCEDURES. PROCEDURAL REVISIONS HAVE BEEN COMPLETED THAT WILL PRECLUDE RECURRENCE BY REQUIRING THE PLACEMENT OF THE BATTERY INVERTER IN MANUAL BYPASS MODE PRIOR TO TROUBLE SHOOTING. THERE WAS NO ADVERSE IMPACT ON THE SAFE OPERATION OF THE PLANT OR TO THE HEALTH AND SAFETY OF THE PUBLIC AS A RESULT OF THIS EVENT. THE PLANT'S RESPONSE WAS IN A CONSERVATIVE DIRECTION WITH NO IMPACT ON SAFETY SYSTEMS. PLANT STAFF'S RESPONSE WAS IN ACCORDANCE WITH APPROVED PROCEDURES.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
482 1985 054 0 8509030089 195477 07/23/85

DOCKET:482 WOLF CREEK 1 TYPE:PWR
REGION: 4 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: WOLF CREEK NUCLEAR OPER. CORP.
SYMBOL: WCN

COMMENTS

STEP 2: EFFECT AX - IMPROPER CRIMP ON TERMINAL LUG; STEP 4: MODEL
RT-481260N; STEP 18: MODEL 90-207X1; STEP 17: MODEL SMB00-5.

REPORTABILITY CODES FOR THIS LER ARE:


13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:

1 482/85-058

ABSTRACT

POWER LEVEL - 075%. ON 7-23-85, AT 0808 CDT, A REACTOR TRIP, MAIN
TURBINE TRIP, AUX FEEDWATER ACTUATION, FEEDWATER ISOLATION AND SG
BLOWDOWN AND SAMPLE ISOLATION OCCURRED AS A RESULT OF A LOW-LOW WATER
LEVEL CONDITION IN ALL 4 SG'S. PLANT RESPONSE THROUGHOUT THE EVENT
WAS NORMAL AND ALL REQUIRED RPS AND ESF'S EQUIPMENT RESPONDED
PROPERLY. THE CAUSE OF THIS EVENT WAS FAILURE OF A WIRE SUPPLYING
POWER TO A 120V INSTRUMENT AC DISTRIBUTION PANEL. THIS RESULTED IN A
LOSS OF GOVERNOR CONTROL POWER TO MAIN FEEDWATER PUMP 'B', ALLOWING
THE PUMP TO SLOW DOWN AND DECREASE FEEDWATER FLOW TO THE SG'S. THE
WIRE FAILURE HAS BEEN ATTRIBUTED TO A FAULTY CRIMPED CONNECTION. THIS
CONNECTION HAS BEEN REPAIRED AND AN INSPECTION FOR OTHER FAULTY
CONNECTIONS DID NOT REVEAL ANY ADDITIONAL PROBLEMS.




DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
483 1984 047 0 8411140211 192075 10/06/84

DOCKET:483 CALLAWAY 1 TYPE:PWR
REGION: 3 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: UNION ELECTRIC CO.
SYMBOL: UEC

REPORTABILITY CODES FOR THIS LER ARE:
13 10.CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 000%. ON 10/6/84 A TECHNICIAN WAS PERFORMING MAINTENANCE ON THE SOURCE RANGE NUCLEAR INSTRUMENTATION POWER SUPPLY CABLES. FOR SAFETY REASONS, THE TECHNICIAN REMOVED BOTH THE INSTRUMENT POWER AND CONTROL POWER FUSES TO THE SOURCE RANGE HIGH VOLTAGE POWER SUPPLY, UNAWARE THAT THE REACTOR TRIP BREAKERS WERE CLOSED. AS DESIGNED, REMOVAL OF THE CONTROL POWER FUSES INITIATED A SOURCE RANGE HI FLUX SIGNAL WHICH IN TURN CAUSED A REACTOR TRIP AND FEEDWATER ISOLATION. ALL EQUIPMENT AND PERSONNEL PERFORMED AS EXPECTED. THE PLANT WAS RESTORED FROM THE TRIP USING PLANT OPERATING PROCEDURES. THE CAUSE OF THIS EVENT WAS DETERMINED TO BE MISCOMMUNICATION ON CURRENT PLANT STATUS BETWEEN THE TECHNICIAN AND OPERATIONS PERSONNEL. TO PREVENT RECURRENCE, THE ADMINISTRATIVE PROCEDURE WHICH CONTROLS THE INITIATION AND PROCESSING OF WORK REQUESTS IS BEING REVIEWED FOR REVISION TO BETTER INFORM THE WORK GROUPS AND OPERATIONS PERSONNEL AS TO THE CONSEQUENCE OF A WORK ACTIVITY. THIS REVIEW IS EXPECTED TO BE COMPLETE BY 11/16/84.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
499 1989 020 0 8910040297 215393 08/29/89

DOCKET:499 SOUTH TEXAS 2 TYPE:PWR
REGION: 4 NSSS:WE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: HOUSTON LIGHTING & POWER CO.
SYMBOL: HLP

COMMENTS

STEP 2: COMP XS - STATIC TRANSFER SWITCH.

WATCH-LIST CODES FOR THIS LER ARE:


20 EQUIPMENT FAILURE
34 DESIGN ERROR OR INADEQUACY

REPORTABILITY CODES FOR THIS LER ARE:

13 10 CFR 50.73(a)(2)(iv): ESF actuations.

ABSTRACT

POWER LEVEL - 100%. ON 8/29/89, UNIT 2 WAS IN MODE 1 AT 100% POWER. AT 1400 HOURS ALL THREE OPERATING TURBINE DRIVEN FEEDWATER PUMPS TRIPPED. THE LICENSED CONTROL ROOM OPERATOR IMMEDIATELY TRIPPED THE REACTOR IN ANTICIPATION OF LOW STEAM GENERATOR LEVEL. AN AUXILIARY FEEDWATER ACTUATION SUBSEQUENTLY OCCURRED ON LOW STEAM GENERATOR LEVEL. THE UNIT WAS STABILIZED IN MODE 3 WITH NO UNEXPECTED POST-TRIP TRANSIENTS. THE CAUSE OF THIS EVENT WAS A MOMENTARY INTERRUPTION OF CONTROL POWER TO THE FEEDWATER PUMP OVERSPEED PROTECTION CIRCUITS DUE TO THE FAILURE OF AN INVERTER. A CONTRIBUTING CAUSE WAS THE DESIGN OF THE FEEDWATER PUMP OVERSPEED PROTECTION CIRCUITS WHICH COULD NOT TOLERATE THE MOMENTARY LOSS OF CONTROL POWER WITHOUT TRIPPING THE PUMPS. THE INVERTER HAS BEEN REPAIRED AND RETURNED TO SERVICE. THE DESIGN OF THE FEEDWATER PUMP OVERSPEED PROTECTION HAS BEEN MODIFIED TO AN "ENERGIZE TO TRIP" SCHEME ON UNIT 2 AND WILL BE MODIFIED ON UNIT 1 PRIOR TO STARTUP FROM THE FIRST REFUELING OUTAGE.



DOCKET YEAR LER NUMBER REVISION DCS NUMBER NSIC EVENT DATE
529 1987 004 1 9010150198 219678 04/16/87

DOCKET:529 PALO VERDE 2 TYPE:PWR
REGION: 5 NSSS:CE
ARCHITECTURAL ENGINEER: BECH
FACILITY OPERATOR: ARIZONA PUBLIC SERVICE CO.
SYMBOL: APS

WATCH-LIST CODES FOR THIS LER ARE:
40 PROCEDURAL DEFICIENCY

REPORTABILITY CODES FOR THIS LER ARE:
13 10 CFR 50.73(a)(2)(iv): ESF actuations.

REFERENCE LERS:
1 529/85-049

ABSTRACT

POWER LEVEL - 100%. AT 1346 MST ON APRIL 16, 1987, PALO VERDE UNIT 2 WAS OPERATING AT 100 PERCENT POWER WHEN A REACTOR TRIP AND TURBINE TRIP OCCURRED. THE TRIP WAS CAUSED BY HIGH LOCAL POWER DENSITY (LPD) TRIP SIGNALS GENERATED BY THE CORE PROTECTION CALCULATORS (CPC). PRIOR TO THE TRIP, CONTROL ROOM OPERATORS AND ELECTRICAL MAINTENANCE PERSONNEL WERE IN THE PROCESS OF LOCATING A GROUND ON THE "B" TRAIN 120 VAC - CLASS 1E BUS DISTRIBUTION PANEL 2E-PNB-D26. WHEN DISTRIBUTION BREAKER D2603 WAS OPENED AND RESHUT AN ERRONEOUS HIGH LPD TRIP SIGNAL WAS GENERATED ON ALL FOUR (4) PLANT PROTECTION SYSTEM CHANNELS RESULTING IN A REACTOR TRIP. THE ROOT CAUSE OF THIS EVENT WAS THE PARTIAL INTERRUPTION AND RESTORATION OF POWER TO THE CONTROL ELEMENT ASSEMBLY CALCULATOR (CEAC) RESULTING IN AN ERRONEOUS HIGH PENALTY FACTOR TRANSMISSION TO ALL CPC'S. THIS ANOMALY WAS KNOWN HOWEVER, THE ANOMALY WAS CONSIDERED TO BE A MINOR OPERATIONAL CONCERN. THE PROCESS USED FOR DETERMINING THE LOCATION OF GROUNDS WAS SYSTEMATIC AND IN ACCORDANCE WITH APPROVED PLANT PROCEDURES HOWEVER, OPERATIONS PERSONNEL WERE NOT AWARE OF THE INFORMATION CONCERNING THE ANOMALY. AS CORRECTIVE ACTION, THE EFFECTS OF CYCLING EACH BREAKER ON THE CLASS 1E INSTRUMENT AC DISTRIBUTION PANELS WILL BE INCORPORATED, AS APPROPRIATE, INTO OPERATIONS GUIDELINES.

*

THIS SESSION HAS USED 7.23 SECONDS OF CPU TIME AND
HAS BEEN ACTIVE FOR 87.23 SECONDS

THE ESTIMATED COST OF THE RUN IS \$ 2.19

