

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: B608080130 DOC. DATE: 86/08/01 NOTARIZED: NO DOCKET #
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME AUTHOR AFFILIATION
 MANAGAN, C. V. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 ZWOLINSKI, J. A. BWR Project Directorate 1

SUBJECT: Discusses Spring 1984 & 1986 CRD penetration leakage roll repairs & current operation w/previously rolled CRD penetration leakage. Leak meets leakage criteria. Further actions listed. Meeting planned w/NRC, per B60731 agreement.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	BWR EB	1	1	BWR EICSB	2	2
	BWR FOB	1	1	BWR PD1 LA	1	0
	BWR PD1 PD 01	5	5	KELLY, J	1	1
	BWR PSB	1	1	BWR RSB	1	1
INTERNAL:	ADM/LFMB	1	0	ELD/HDS3	1	0
	NRR/ORAS ,	1	0	<u>REG FILE</u> 04	1	1
	RGN1	1	1			
EXTERNAL:	EG&G BRUSKE, S	1	1	LPDR 03	1	1
	NRC PDR 02	1	1	NSIC 05	1	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 18

CONFIDENTIAL

... ..
... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..
... ..

...
...
...
...
...
...
...
...
...
...

August 1, 1986
NMP1L 0083

Director of Nuclear Reactor Regulation
Attention: Mr. John A. Zwolinski, Project Director
BWR Project Directorate Number 1
Division of BWR Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Re: Nine Mile Point Unit 1
Docket No. 50-220
DPR-63

Dear Mr. Zwolinski:

During the Nine Mile Point Unit 1, Spring 1984 Refueling and Maintenance Outage, leakage from several control rod drive (CRD) penetrations was observed. These penetrations were repaired by roll expanding the CRD housings into the reactor vessel wall. These roll repairs were implemented for the purpose of limiting leakage. The examinations and repairs performed on the stub tubes were reviewed by your staff and documented in a Safety Evaluation, dated June 29, 1984. As discussed in the Safety Evaluation, leakage from the penetrations does not represent a significant safety consideration.

During the Spring 1986 Refueling and Maintenance Outage, one additional CRD penetration was repaired by roll expanding and two previously repaired penetrations were rolled above and below the previously rolled area. The additional rolling was performed on the two penetrations to further limit leakage resulting from joint relaxation during the previous cycle.

As you have been advised, we are presently operating with a CRD penetration which leaked at approximately 4 drops per minute during a 900 psig pressure test. This penetration (46-27) was previously rolled in 1984. While this leak rate meets our leakage criteria, we plan to evaluate and if possible, take further actions to minimize leakage. The specific actions to be considered include the following:

- a) Secure cooling water flow to the control rod drive 46-27. Analysis and actual experience shows this will increase contact pressure significantly and thereby minimize leakage.

8608080130 860801
PDR ADDCK 05000220
P PDR

Acc
1/0

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

In the second section, the author details the various methods used to collect and analyze the data. This includes both manual and automated techniques. The goal is to ensure that the information gathered is both reliable and comprehensive.

The third part of the report focuses on the results of the analysis. It shows a clear upward trend in the data over the period studied. This suggests that the implemented measures are having a positive impact on the overall performance.

Finally, the document concludes with a series of recommendations for future work. It suggests that further research should be conducted to explore additional factors that could influence the results. This will help in refining the current model and improving its accuracy.

Mr. John A. Zwolinski, Project Director
July 31, 1986
Page 2

- b) Roll above and below the previously rolled area using procedures qualified prior to the 1986 outage. This will be performed during a scheduled outage of sufficient duration (i.e. at least one week) to allow the necessary work activities associated with re-rolling to proceed in an orderly fashion, but not later than the spring 1988 outage.

As we agreed on July 31, 1986, we plan to meet with you in the near future to provide details on the work completed to date and our future plans.

Very truly yours,

C. V. Mangan

C. V. Mangan
Senior Vice President

LK/ar
Attachment
1740J



Handwritten marks in the top right corner, possibly initials or a signature.



Faint, illegible text or markings at the top of the page.

A line of faint, illegible text in the upper middle section.

A line of faint, illegible text in the middle section.

A small, faint mark or text fragment in the lower middle section.

A small, faint mark or text fragment in the lower middle section.

A small, faint mark or text fragment in the lower right section.