

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8805130028 DOC.DATE: 88/05/04 NOTARIZED: NO DOCKET #  
 FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410  
 AUTH.NAME AUTHOR AFFILIATION  
 JENKINS,R.E. Niagara Mohawk Power Corp.  
 WILLIS,J.L. Niagara Mohawk Power Corp.  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-020-00:on 880407,ESF actuation caused by high  
 radiation signals due to electrical noise.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 6  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 LA	1 1	PD1-1 PD	1 1
	HAUGHEY,M	1 1	BENEDICT,R	1 1
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1 1
	NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
	NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
	NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
	NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1 1
	NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	<del>REG-FILE</del> 02	1 1
	RES TELFORD,J	1 1	RES/DE/EIB	1 1
	RES/DRPS DEPY	1 1	RGN1 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC HARRIS,J	1 1
	NSIC MAYS,G	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 47 ENCL 46



3  
/

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Nine Mile Point Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 410				PAGE (3) 1 OF 05		
TITLE (4) Engineered Safety Feature Actuation Caused by High Radiation Signals Due to Electrical Noise																
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)				
									N/A			0 5 0 0 0				
04	07	88	88	020	00	05	04	88	N/A			0 5 0 0 0				
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)														
1		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)		73.71(b)				
POWER LEVEL (10)		20.405(a)(1)(i)				50.38(c)(1)				<input type="checkbox"/> 50.73(a)(2)(v)		73.71(c)				
100		20.405(a)(1)(ii)				50.38(c)(2)				<input type="checkbox"/> 50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
		20.405(a)(1)(iii)				50.73(a)(2)(i)				<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
		20.405(a)(1)(v)				50.73(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(x)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME Robert E. Jenkins, Assistant Supervisor Technical Support										TELEPHONE NUMBER AREA CODE 315 349-4220						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS						
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 7, 1988 at 0952 hours and at 1026 hours with the reactor at approximately 100% power and the mode switch in "RUN", Nine Mile Point Unit 2 (NMP2) experienced Engineered Safety Feature (ESF) actuations. Both events consisted of a secondary containment isolation and the automatic initiation of the Standby Gas Treatment System (SBGTS), an emergency recirculation unit cooler, and reactor building unit coolers. Both events occurred while attempting to perform surveillance procedure N2-OSP-HCS-SA001, "DBA Hydrogen Recombiner Functional and Electrical Continuity Test".

The ESF actuations occurred, as designed, on a spurious high radiation signal. The immediate cause of the spurious radiation signal has been determined to be electrical noise. The noise was a result of "chattering" at the contactor associated with recombinder inlet valve 2HCS\*MOV25B. 2HCS\*MOV25B is throttled per steps in N2-OSP-HCS-SA001. The cause of the contactor "chattering" has been determined to be an increased valve torque requirement since the previous torque switch setting.

Corrective actions consist of the following:

1. Adjustment of 2HCS\*MOV25B's torque switch to a higher setting.
2. Electrical preventive maintenance procedure N2-EPM-GEN-V522, "Limitorque Motor Operated Valve Testing Utilizing MOVATS-2000" has been scheduled to verify the settings of 2HCS\*MOV25A and 2HCS\*MOV25B.
3. A problem report will be submitted to Engineering to reverify the torque switch settings and calculate the recommended and maximum valve thrust.



FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Nine Mile Point Unit 2	0   5   0   0   0   410	88	020	00	02	OF	05	

TEXT (If more space is required, use additional NRC Form 368A's) (17)

## I. DESCRIPTION OF EVENTS

On April 7, 1988 at 0952 hours with the reactor at approximately 100% power and the mode switch in "RUN", Nine Mile Point Unit 2 (NMP2) experienced an Engineered Safety Feature (ESF) actuation. At 1026 the same day, with the reactor at approximately 100% power and the mode switch in "RUN", NMP2 experienced a second ESF actuation. Both events consisted of a secondary containment isolation and the automatic initiation of the Standby Gas Treatment System (SBGTS), an emergency recirculation unit cooler, and reactor building unit coolers.

On April 7, 1988 at 0952 hours a "spike" occurred on reactor building ventilation exhaust radiation monitors 2HVR\*RE14B and 2HVR\*RE32B. As designed, the following occurred on a high radiation signal: 1) Secondary Containment Isolation, 2) SBGTS Train "A" and Train "B" auto start, 3) Emergency Recirculation Unit Cooler 2HVR\*UC413B auto start, 4) Reactor Building Unit Coolers auto start. Containment monitoring system radiation monitor 2CMS\*RE10B also "spiked".

After verifying a high radiation condition did not exist, Operations personnel secured the ESF equipment which had started and restored reactor building ventilation to normal. The duration of this event was approximately 32 minutes.

On April 7, 1988 at 1026 hours a second "spike" occurred on radiation monitors 2HVR\*RE14B, 2HVR\*RE32B and 2CMS\*RE10B. As designed, the following occurred on a high radiation signal: 1) Secondary Containment Isolation, 2) SBGTS Train "A" and Train "B" auto start, 3) Unit Cooler 2HVR\*UC413B auto start, 4) Reactor Building Unit Coolers auto start.

At this time it became apparent the high radiation spikes and subsequent ESF actuations were occurring simultaneously with the performance of surveillance test N2-OSP-HCS-SA001, "DBA Hydrogen Recombiner Functional and Electrical Continuity Test". Specifically, the high radiation spikes appeared to coincide with the throttling of Recombiner "B" inlet flow valve 2HCS\*MOV25B. Troubleshooting activities were then performed by Operations and other station personnel. The duration of the second event was approximately 47 minutes.

Operations issued work request WR 135995 to troubleshoot 2HCS\*MOV25B, aborted further performance of N2-OSP-HCS-SA001 to prevent further isolations and declared Recombiner "B" inoperable. ESF equipment which started earlier was secured and normal reactor building ventilation restored.

There were no components or systems which were inoperable and/or out of service which contributed to the event. No plant system or component failures resulted from the event.



## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Nine Mile Point Unit 2	0 5 0 0 0 410	88	020	00	03	OF	05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

## II. CAUSE OF EVENT

The ESF actuations occurred, as designed, on a high radiation signal. 2HVR\*RE14A(B) and 2HVR\*RE32A(B) provide for Division I(II) above and below refueling floor radiation monitoring, respectively.

The immediate cause of the high radiation spikes in 2HVR\*RE14B and 2HVR\*RE32B have been attributed to electrical noise produced when throttling recombiner inlet valve 2HCS\*MOV25B. (See attached electrical schematic.) The electrical noise was reflected back to emergency load center 2EJS\*US3, reflected through uninterruptible power supply 2VBA\*UPS2B and fed to the input power of the radiation monitors. The noise was a result of "chattering" at the contactor associated with inlet valve 2HCS\*MOV25B. The cause of the contactor "chattering" has been determined to be an increased valve torque requirement since the previous torque switch setting. Per N2-OSP-HCS-SA001, Operations personnel throttled the recombiner inlet valve to bring about a desired flow rate. With the valve torque switch set low, the torque generated during normal valve movement was near valve dropout torque. Further investigation of the valve showed the torque switch was arcing and causing the contactor to rapidly drop out and then pick up again.

## III. ANALYSIS OF EVENTS

In reference to both events, the secondary containment isolations and initiations of the standby gas treatment system and recirculation unit coolers are conservative actions and pose no adverse safety consequences at any reactor power level. The events did not in any way adversely affect any other safety systems nor the operators ability to achieve safe shutdown.

This event analysis is considered reportable via 10CFR50.73(a)(2)(iv), any event or condition that resulted in automatic actuation of any Engineered Safety Feature (ESF).

## IV. CORRECTIVE ACTIONS

Corrective actions consist of the following:

1. Adjustment of recombiner inlet valve 2HCS\*MOV25B open torque switch from a setting of 1 1/2 to a setting of 3 1/2. EP-410H, "Motor Operated Valve Setpoints and Operation Data" list the recommended torque switch setting for 2HCS\*MOV25B as 1.5 and the maximum setting at 3.5.
2. Electrical preventive maintenance procedure N2-EPM-GEN-V522, "Limitorque Motor Operated Valve Testing Utilizing MOVATS-2000" has been scheduled to verify the settings of 2HCS\*MOV25A and 2HCS\*MOV25B. This work will be performed during the NMP2 May, 1988 outage.
3. A problem report will be submitted to Engineering to reverify the torque switch settings and calculate the recommended and maximum valve thrust.

NOTE: N2-OSP-HCS-SA001 Train "B" was performed successfully on April 21, 1988.





## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Nine Mile Point Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   410	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		88	020	00	04	OF	05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

## V. ADDITIONAL INFORMATION

## Identification of Components Referred to in this LER

Component	IEEE 803 EIIS Funct	IEEE 805 System ID
Radiation Monitor	MON	VA
Reactor Building Ventilation (HVR)	N/A	VA
Standby Gas Treatment System	N/A	VA
Reactor Building	N/A	NG
Emergency Recirculation Unit	FAN	V

Component Failures - None

There have been no previous similar events. There has been an SBGTS initiation event resulting from a spurious high radiation signal. However, the cause of this event was not similar. Details can be found in LER 86-11.







NINE MILE POINT NUCLEAR STATION / P.O. BOX 32 LYCOMING, NEW YORK 13093 / TELEPHONE (315) 343-2110

May 4, 1988

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 88-20

Gentlemen:


In accordance with 10 CFR 50.73, we hereby submit the following  
Licensee Event Report:

LER 88-20 Is being submitted in accordance with 10 CFR 50.73  
(a) (2) (iv), "Any event or condition that resulted  
in manual or automatic actuation of any Engineered  
Safety Feature (ESF), including the Reactor  
Protection System (RPS)."

A 10CFR50.72 report was made at 1236 hours on April 7, 1988.

This report was completed in the format designated in NUREG-1022,  
Supplement 2, dated September 1985.

Very truly yours,

  
J. L. Willis  
General Superintendent  
Nuclear Generation

JLW/JMT/mjd

Attachments

cc: Regional Administrator, Region 1  
Sr. Resident Inspector, W. A. Cook

JE22  
11

2  
1