

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9201100004 DOC.DATE: 92/01/02 NOTARIZED: NO DOCKET #  
 FACIL:50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220  
 AUTH.NAME AUTHOR AFFILIATION  
 FIRLIT,J.F. Niagara Mohawk Power Corp.  
 RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Special rept:on 911218,containment hydrogen monitoring sys  
 12 declared inoperable.Caused by inadvertently grounding  
 jumper resulting in blown fuse.Root cause evaluation &  
 lessons learned transmittal will be completed by Feb 1992.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-1 LA	1	PD1-1 PD	1
	BRINKMAN,D.	1		
INTERNAL:	ACNW	2	ACRS	2
	AEOD/DOA	1	AEOD/DSP/TPAB	1
	AEOD/ROAB/DSP	2	NRR/DET/ECMB 9H	1
	NRR/DET/EMEB 7E	1	NRR/DLPQ/LHFB10	1
	NRR/DLPQ/LPEB10	1	NRR/DOEA/OEAB	1
	NRR/DREP/PRPB11	2	NRR/DST/SELB 8D	1
	NRR/DST/SICB8H3	1	NRR/DST/SPLB8D1	1
	NRR/DST/SRXB 8E	1	REG FILE 02	1
	RES/DSIR/EIB	1	RGNI FILE 01	1
EXTERNAL:	EG&G BRYCE,J.H	3	L ST LOBBY WARD	1
	NRC PDR	1	NSIC MURPHY,G.A	1
	NSIC POORE,W.	1	NUDOCS FULL TXT	1

*Cent no  
p850966986*

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 33 ENCL 33-0

*IA2*



Joseph F. Firlit  
Vice President  
Nuclear Generation

January 2 , 1992

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-220  
SPECIAL REPORT

Gentlemen:

In accordance with Nine Mile Point Unit 1 Technical Specification Table 3.6.11-1(6), Action Statement Table 3.6.11-2(4), we are submitting the following Special Report concerning the inoperability of the #12 Containment Hydrogen Monitoring System.

**EVENT DESCRIPTION**

On December 18, 1991 at 1045 hours, the #12 Containment Hydrogen Monitoring System was declared inoperable when a fuse was blown during the performance of N1-ISP-201-012, "Containment H<sub>2</sub> Check and Calibration."

**CAUSE OF EVENT**

The cause of the event was a blown fuse. While performing the procedure N1-ISP-201-012, a jumper inadvertently went to ground, resulting in a blown fuse.


**ACTIONS TAKEN**

The #12 Containment Hydrogen Monitoring System was declared inoperable by the Station Shift Supervisor (SSS). The fuse was replaced per WR# 197565.

The #12 Containment Hydrogen Monitoring System was declared operable on December 18, 1991, by the SSS upon completion and close out of WR# 197565.

A Root Cause Evaluation and a Lessons Learned Transmittal will be completed by February 1992.

Very truly yours,



Joseph F. Firlit  
Vice President - Nuclear Generation

JFF/AC/lmc

xc: Thomas T. Martin, Regional Administrator Region I  
Wayne L. Schmidt, Sr. Resident Inspector

9201100004 920102  
PDR ADOCK 05000220  
S FDR

*Out No  
9850966 986  
IF22  
110*

