

APPENDIX A
NOTICE OF VIOLATION

Niagara Mohawk Power Corporation
Nine Mile Point Unit 2

Docket No. 50-410
License No. NPF-54

As a result of the NRC inspection conducted on February 3-7, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions", 10 CFR 2, Appendix C (1991), the violation is listed below.

10 CFR 50.36 (a) states in part that each license authorizing operation of a production or utilization facility will include technical specifications. Plant Technical Specification 6.12 states in part that for High Radiation Areas, the area be conspicuously posted and entrance be controlled by requiring issuance of a Radiation Work Permit. Any individual or group of individuals permitted to enter the area shall be provided with or accompanied by: a radiation monitoring device which continuously indicates radiation dose rates, or; a radiation monitoring device which continuously integrates the radiation dose rate in the area and alarms when a preset integrated dose is received, or; an individual qualified in radiation protection, with a radiation dose rate monitoring device.

Contrary to the above, on October 23, 1991, five members of the licensee's Operations Department entered the Northeast and Northwest Condenser Area on the 277' elevation of the Turbine Building, a posted High Radiation Area, without being on a Radiation Work Permit, and without a dose rate meter, an alarming dosimeter, or accompanied by a radiation protection technician with a meter.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Niagara Mohawk Power Corporation is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to



extending the response time.

Dated at King of Prussia, Pennsylvania
this 11th day of February, 1992



APPENDIX B
NOTICE OF VIOLATION

Niagara Mohawk Power Corporation
Nine Mile Point Unit 1

Docket No. 50-220
License No. DPR-63

As a result of the NRC inspection conducted on February 3-7, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions", 10 CFR 2, Appendix C (1991), the violation is listed below.

10 CFR 50.36 (a) states in part that each license authorizing operation of a production or utilization facility will include technical specifications. Plant Technical Specification 6.12 states in part that for High Radiation Areas, the area be conspicuously posted and entrance be controlled by requiring issuance of a Radiation Work Permit. Any individual or group of individuals permitted to enter the area shall be provided with or accompanied by: a radiation monitoring device which continuously indicates radiation dose rates, or; a radiation monitoring device which continuously integrates the radiation dose rate in the area and alarms when a preset integrated dose is received, or; an individual qualified in radiation protection, with a radiation dose rate monitoring device.

Contrary to the above, on December 16, 1991, three members of the licensee's Operations Department entered the South Condenser Moisture Separator Room on the 277' elevation of the Turbine Building, a posted High Radiation Area, without being on a Radiation Work Permit, and without a dose rate meter, an alarming dosimeter, or accompanied by a radiation protection technician with a meter.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Niagara Mohawk Power Corporation is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to



extending the response time.

Dated at King of Prussia, Pennsylvania
this 11th day of February, 1992

