

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9106130015      DOC. DATE: 91/06/03      NOTARIZED: NO      DOCKET #  
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha      05000410  
 AUTH. NAME      AUTHOR AFFILIATION  
 CONWAY, J.T.      Niagara Mohawk Power Corp.  
 FIRLIT, J.F.      Niagara Mohawk Power Corp.  
 RECIP. NAME      RECIPIENT AFFILIATION

SUBJECT: LER 91-009-00: on 910503, ESF actuation & secondary  
 containment isolation occurred, causing reactor bldg  
 recirculation unit cooler to start. Caused by spurious high  
 radiation signal. Work request initiated. W/910603 ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 LA BRINKMAN, D	1 1 1 1	PD1-1 PD OUDINOT, D	1 1 1 1
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB 7E	1 1	NRR/DLPQ/LHFB10	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB8H3	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	3 3	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

Cont No  
 P733438986

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 34 ENCL 34

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S



Joseph F. Firlit  
Vice President  
Nuclear Generation

NMP80513

June 3, 1991

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 91-09

Gentlemen:


In accordance with 10CFR50.73, we hereby submit the following Licensee Event Report:

LER 91-09 Is being submitted in accordance with 10CFR50.73 (a)(2)(iv), "Any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS)".

A 10CFR50.72 (b)(2)(ii) report was made at 1017 hours on May 3, 1991.

This report was completed in the format designated in NUREG-1022, Supplement 2, dated September 1985.

Very truly yours,



Joseph F. Firlit  
Vice President - Nuclear Generation

JFF/RM/lmc  
ATTACHMENT

xc: Thomas T. Martin, Regional Administrator Region I  
William A. Cook, Sr. Resident Inspector

9106130015 910603  
PDR ADOCK 05000410  
S PDR

*Cent No*  
*8733438 986*  
*IF22*  
*11*



LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>Nine Mile Point Unit 2</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 4 1 0</b>	PAGE (3) <b>1 OF 0 5</b>
--	---	-----------------------------

TITLE (4)  
**Engineered Safety Feature Actuation due to a Spurious High Radiation Level Signal**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)		
0	5	03	91	009	00	0	6	03	N/A			0 5 0 0 0		
0	5	03	91	009	00	0	6	03	N/A			0 5 0 0 0		

OPERATING MODE (9) <b>1</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)									
POWER LEVEL (10) <b>1 0 0</b>	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.38(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.38(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)						
	<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)	
NAME <b>John T. Conway, Manager Technical Support NMP2</b>	TELEPHONE NUMBER AREA CODE: <b>3 1 5</b> NUMBER: <b>3 4 9 1 2 6 9 8</b>

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	
X	I L	S O L	K O 2 0							

SUPPLEMENTAL REPORT EXPECTED (14)			EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO			0	8	01

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On May 3, 1991, at 0831 hours, Nine Mile Point Unit 2 experienced an actuation of an Engineered Safety Feature (ESF). Specifically, the Secondary Containment (Reactor Building) isolated and the Reactor Building Emergency Recirculation Unit Cooler and Standby Gas Treatment System (GTS) started automatically. The ESF actuation was initiated by a high radiation level signal in the Reactor Building Ventilation System (HVR). At the time of the event, the reactor mode switch was in the "RUN" position (Mode 1) with the reactor operating at 100% rated thermal power.

The root cause of the event is still under investigation.

The Control Room operators implemented the Emergency Operating Procedure (EOP) for Secondary Containment control until Reactor Building radiation was verified at normal operating levels and the cause for the ESF actuation was determined to be a spurious high radiation level trip. Other corrective actions included returning the HVR system to a normal line up after welding was complete, replacing a failed component in the radiation monitoring cabinet, and as an interim measure, issuing guidance to welders to ensure their welding cables are not in contact with any instrumentation cables.



A

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Nine Mile Point Unit 2	DOCKET NUMBER (2)  0 5   0   0   0   4   1   0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9   1	—   0   0   9	—   0   0	0   2	OF 0   5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

**I. DESCRIPTION OF EVENT**

On May 3, 1991, at 0831 hours, Nine Mile Point Unit 2 experienced an actuation of an Engineered Safety Feature (ESF). Specifically, the Secondary Containment (Reactor Building) isolated and the Reactor Building Emergency Recirculation Unit Cooler and Standby Gas Treatment System (GTS) started automatically. The ESF actuation was initiated by a high radiation level signal in the Reactor Building Ventilation System (HVR). At the time of the event, the reactor mode switch was in the "RUN" position (Mode 1) with the reactor operating at 100% rated thermal power.

The high radiation level trip signal was generated by the Division II "above refuel floor" radiation monitor which responded as though a high radiation level condition existed. The circuitry functioned per its design initiating a Secondary Containment isolation, and automatic starts of the Division II Emergency Recirculation Unit Cooler (2HVR\*UC413B) and Division I and II trains of GTS.

Immediately, the Control Room operators implemented the Emergency Operating Procedure (EOP) for Secondary Containment Control (N2-EOP-Secondary Containment Control), verified the Secondary Containment did isolate, verified the automatic start of the Emergency Recirculation Unit Cooler and Division I and II trains of GTS, and noted the indication for process radiation monitor 2HVR\*CAB14B to be above the alarm setpoint (indicated level 1.46 E-2 micro ci/cc; alarm level 1.00 E-4 micro ci/cc).

At 0833 hours, the Control Room operators noted the indication for other radiation monitors in the Reactor Building were normal including 2HVR\*CAB14A which indicated 3.60 E-7 micro ci/cc. A radiation survey of the Reactor Building was commenced and at 0844 hours, radiation levels were verified normal allowing the operators to exit the EOP for Secondary Containment Control.

An investigation into the cause of the spurious actuation revealed Direct Current (DC) Shielded Metal Arc Welding was in progress four feet above the radiation monitoring microprocessor 2HVR\*RUW14B. Several attempts to duplicate the initial radiation trip signal were unsuccessful, but it was determined from Digital Radiation Monitoring System (DRMS) memory and discussions with the welder that electrical noise was being detected by the radiation monitoring microprocessor during the same time frame as welding was in progress.





LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Nine Mile Point Unit 2	DOCKET NUMBER (2)  0 5   0 0   0 4   1 0	LER NUMBER (6)			PAGE (3)		
		YEAR 9 1	SEQUENTIAL NUMBER 0 0 9	REVISION NUMBER 0 0	0 3	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. DESCRIPTION OF EVENT (cont.)

During the investigation into the spurious trip, it was noted that a low flow alarm existed for the process radiation monitor 2HVR\*CAB14B. Investigation of the alarm found a blown fuse in the junction box supplying power to the motor operated flow control valve for sample flow to the process radiation monitor. It was determined that the already shut valve received a false shut signal which caused an overload of the valve operating motor and the blown fuse.

The fuse was replaced and welding was completed by 1600 hours on the same day and a functional test (N2-RSP-RMS-M108) of the process radiation monitor was commenced. During this test, a failed check source positioning solenoid was discovered, and the functional test of the process radiation monitor was aborted. The source check positioning solenoid was replaced, and the functional test of the process radiation monitor was then completed satisfactorily.

On May 4, 1991, at 2112 hours, the Control Room operators returned the GTS system and Emergency Recirculation Unit Coolers to standby and restored the Reactor Building Ventilation System to its normal line up per operating procedure N2-OP-52 "Reactor Building Ventilation System".

II. CAUSE OF EVENT

The immediate cause of the event was a Division II "above refuel floor" high radiation level signal. The root cause evaluation for this event is continuing per Nuclear Division Procedure NDP-16.01, "Root Cause Evaluations."

The root cause of this event is unknown at this time. When established, the root cause will be reported in a supplement to this Licensee Event Report.

III. ANALYSIS OF EVENT

This event is reportable per 10CFR50.73 part (a)(2)(iv), "Any event or condition that results in manual or automatic actuation of any Engineered Safety Feature (ESF)".

Secondary Containment isolation, Reactor Building Emergency Recirculation Unit Cooler automatic start, and GTS automatic starts are conservative actions having no adverse



**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Nine Mile Point Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 4 1 0	LER NUMBER (6)			PAGE (3)		
		YEAR 9 1	SEQUENTIAL NUMBER 0 0 9	REVISION NUMBER 0 0	0 4	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

III. ANALYSIS OF EVENT (cont.)

safety consequences, for the general public or the plant, at any reactor power level. The event in no way adversely affected any other safety system nor the operators ability to achieve safe reactor plant conditions.

The duration of the event was 1 day, 12 hours, 41 minutes.

IV. CORRECTIVE ACTIONS

The immediate corrective actions were to determine the validity and cause of the high radiation level trip signal.

Follow-up corrective actions for this event included:

1. Radiation monitor 2SWP\*CAB14B was declared inoperable, GTS and the Reactor Building Emergency Recirculation Unit Coolers remained in operation, and the DRMS computer was monitored for the duration of welding operations.
2. A blown fuse for the process radiation monitor flow control valve was replaced.
3. A Work Request (WR #154660) was initiated and the failed check source positioning solenoid was replaced.
4. A functional check of the process radiation monitor (2HVR\*CAB14B) was performed.
5. The current welding instructions provide specific guidance and Engineering evaluation for high frequency AC TIG welding to ensure instrumentation is not impacted. No such controls exist for DC welding. Therefore, until the root cause is determined, a memo has been written to the Maintenance Managers from Nine Mile Point Units 1 and 2 emphasizing caution when performing any welding near instrumentation. This memo directs that welding cables are routed away from instrumentation cables.



**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Nine Mile Point Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   4   1   0	LER NUMBER (6)			PAGE (3)		
		YEAR 9   1	SEQUENTIAL NUMBER —   0   0   9	REVISION NUMBER —   0   0			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

V. ADDITIONAL INFORMATION

A. Failed component identification:

- Component description - check source positioning solenoid
- Mark number - CS01
- Manufacturer - Kaman Instrumentation Corp.
- Part Number - 823779-026A
- Symbol Number - 9311296
- Niagara Mohawk Drawing - 1.73L-801-055
- Niagara Mohawk Spec - P281F

B. Previous similar events:

There have been several previous Reactor Building isolations with emergency ventilation starts caused by spurious high radiation level signals. Because the root cause varies between events and the root cause of this event is unknown, an accurate comparison can not be made. Previous similar events will therefore be listed and compared when the root cause has been determined.

V. ADDITIONAL INFORMATION

C. Identification of components referred to in this LER:

COMPONENT	IEEE 803 EIS FUNCTION	IEEE 805 SYSTEM ID
Secondary Containment (Reactor Building)	N/A	NG
Reactor Building Unit Coolers	CLR	VA
Standby Gas Treatment System	N/A	BH
Reactor Building Ventilation System	N/A	VA
Above Refuel Floor Process Radiation Monitor and Microprocessor	MON	IL
Digital Radiation Monitoring System	MON	IL
Flow Control Valve	FCV	IL
Check Source Positioning Solenoid	SOL	IL

