



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555

June 27, 1990

Docket No. 50-410

LICENSEE: Niagara Mohawk Power Corporation  
FACILITY: Nine Mile Point Nuclear Station, Unit 2  
SUBJECT: MEETING MINUTES REGARDING THE JUNE 19, 1991, MEETING TO DISCUSS THE UPCOMING MID-CYCLE INSPECTION AND POSSIBLE REPAIR OF THE HPCS NOZZLE AT NINE MILE POINT 2.

A meeting was held in the NRC One White Flint North Office in Rockville, Maryland, with Niagara Mohawk Power Corporation (NMPC) and NRC staff representatives to discuss the planned inspections, fracture mechanics analysis, and possible repairs of the HPCS nozzle at Nine Mile Point 2 during the upcoming mid-cycle inspection. Enclosure 1 is a list of the meeting attendees. The handout material used by the licensee during the meeting is attached as Enclosure 2.


By letter dated December 28, 1990, NMPC submitted for NRC staff review and approval a fracture mechanics evaluation of a flaw that had been detected in the weld (KC-32) joining the HPCS nozzle safe end to the safe end extension. The flaw had been detected by a scheduled ultrasonic inservice inspection during the plant's first refueling outage. After subjecting the weld to a Mechanical Stress Improvement Process, the licensee determined the flaw to be 41% of wall thickness and to extend 11.3% of the wall circumference. The NRC staff reviewed the licensee's submittal and requested the licensee commit to performing a mid-cycle inspection of the subject weld. By letter dated January 7, 1991, the licensee committed to perform the requested mid-cycle inspection between the beginning of the fifth and end of the tenth month of the second refueling cycle. The NRC staff's safety evaluation of the licensee's analysis concluded that the Nine Mile Point 2 reactor pressure vessel was acceptable for service without excavation and weld repair of the flaw in weld KC-32 provided the flaw would be ultrasonically reexamined during the committed mid-cycle inspection. The NRC staff's safety evaluation also recommended that the licensee submit for staff review and approval, a revised fracture mechanics analysis performed in accordance with recommendations contained in the safety evaluation. A further recommendation was to consider using radiographic examination techniques for examination of weld KC-32 during the mid-cycle inspection.

The licensee requested this meeting to update the NRC staff on the status of the revised analysis and to inform the staff that attempts to perform radiographic examination of weld KC-32 did not produce radiographs of acceptable quality and therefore this technique will not be used during the

NRC FILE CENTER COPY

*Handwritten notes:*  
Memo  
JFOL  
11

9107050046 910627  
PDR ADOCK 05000410  
PDR



mid-cycle inspection. During the meeting, the licensee committed to submit a revised fracture mechanics analysis by June 28, 1991. The NRC staff agreed to promptly review this revised analysis as well as the proposed repair plan submitted on June 10, 1991. It was agreed that if any significant growth (to be defined by NMPC and agreed to by the NRC staff) of this flaw is detected during the mid-cycle inspection, further evaluation will be required as well as a probable repair. However, if the NRC staff determines the revised analysis to be submitted on June 28, 1991, is acceptable and there is no significant growth of the flaw, the plant may resume and continue operation without repairing the weld (KC-32) until the next refueling outage when the weld will be reinspected.

*Donald S. Brinkman*

Donald S. Brinkman, Senior Project Manager  
Project Directorate I-1  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation

Enclosures:

1. List of Attendees
2. Licensee Handout Material

cc w/enclosures:

See next page

118  
25.  
4  
32  
1



v

- 5 -

- 10 -

.

.

.

.

.

.

.

Mr. B. Ralph Sylvia  
Niagara Mohawk Power Corporation

Nine Mile Point Nuclear Station  
Unit 2

cc:

Mr. Mark J. Wetterhahn, Esquire  
Winston & Strawn  
1400 L Street, NW.  
Washington, D.C. 20005-3502

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, Pennsylvania 19406

Mr. Richard Goldsmith  
Syracuse University  
College of Law  
E. I. White Hall Campus  
Syracuse, New York 12223

Charlie Donaldson, Esquire  
Assistant Attorney General  
New York Department of Law  
120 Broadway  
New York, New York 10271

Resident Inspector  
Nine Mile Point Nuclear Power Station  
P. O. Box 126  
Lycoming, New York 13093

Mr. Richard M. Kessel  
Chair and Executive Director  
State Consumer Protection Board  
99 Washington Avenue  
Albany, New York 12210

Mr. Gary D. Wilson, Esquire  
Niagara Mohawk Power Corporation  
300 Erie Boulevard West  
Syracuse, New York 13202


Mr. Martin J. McCormick Jr.  
Plant Manager, Unit 2  
Nine Mile Point Nuclear Station  
Niagara Mohawk Power Corporation  
P. O. Box 32  
Lycoming, NY 13093

Mr. David K. Greene  
Manager Licensing  
Niagara Mohawk Power Corporation  
301 Plainfield Road  
Syracuse, New York 13212

Mr. Joseph F. Firlit  
Vice President - Nuclear Generation  
Nine Mile Point Nuclear Station  
Niagara Mohawk Corporation  
P. O. Box 32  
Lycoming, New York 13093

Ms. Donna Ross  
New York State Energy Office  
2 Empire State Plaza  
16th Floor  
Albany, New York 12223

Supervisor  
Town of Scriba  
R. D. #4  
Oswego, New York 13126



ATTENDANCE LIST

June 19, 1991 Meeting With Niagara Mohawk Power Corporation  
to Discuss Upcoming Mid-cycle Inspection and Possible  
Repair of HPCS Nozzle at Nine Mile Point 2

<u>Name</u>	<u>Position</u>	<u>Organization</u>
Donald S. Brinkman	Senior Project Manager	NRC/NRR/PDI-1
Robert A. Capra	Project Director	NRC/NRR/PDI-1
C. Y. Cheng	Chief, Mat and Chem Eng. Br.	NRR/DET/EMCB
W. David Baker	Licensing-Program Director	Niagara Mohawk
John Tsao	Materials Engineer	NRR/DET/EMCB
Richard B. Abbott	NMPC Mgr. Unit 2 Eng.	NMPC
W. A. Koo	Materials Engineer	NRR/DET/EMCB
Tom Fay	NMPC - Licensing	NMPC
M. Banic	Materials Engineer	NRR/DET/EMCB
John Swenszkowski	NMPC - QA/NDE Group Lead	NMPC
Christopher A. Boen	Materials Co-op	NRC/Rgn I
H. Kaplan	Reactor Inspector	NRC/Rgn I
Robert Hermann	Chief, Met Sect	NRC/NRR/DET
W. S. Fingrutd	GE - Sr. Welding Spec.	GE
Sam Ranganath	Manager, Mat, Mon & Stru Anal	GE-NE
Carl Terry	VP - Nuclear Engineering	NMPC
Martin J. McCormick, Jr.	Plant Manager NMP2	NMPC
Shashi Dhar	Mech Engineer NMP2	NMPC
Robert Deuval1	Supervisor Mech Eng NMP2	NMPC
Daniele Oudinot	Project Engineer	NRC/NRR/PDI-1



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200




**NIAGARA MOHAWK POWER CORPORATION**

**HPCS CORE SPRAY NOZZLE MEETING AGENDA**

**JUNE 19, 1991**

**SPEAKERS**

- |             |   |   |
|-------------|---|---|
| <b>I.</b>   | <b>INTRODUCTION/PURPOSE</b>                                     | <b>R. ABBOTT</b>                            |
| <b>II.</b>  | <b>BACKGROUND INFORMATION</b>                                   | <b>S. DHAR</b>                              |
| <b>III.</b> | <b>FRACTURE MECHANICS ANALYSIS</b>                              | <b>M. BADLANI<br/>(SMC O'DONNELL, INC.)</b> |
| <b>IV.</b>  | <b>UNCERTAINTY IN FLAW SIZING<br/>UTILIZING UT TECHNIQUES</b>   | <b>J. SWENSZKOWSKI</b>                      |
| <b>V.</b>   | <b>UTILIZATION OF RT TECHNIQUE FOR<br/>EXAMINATION PURPOSES</b> | <b>J. SWENSZKOWSKI</b>                      |
| <b>VI.</b>  | <b>CONTINGENCY REPAIR PLAN</b>                                  | <b>S. RANGANATH<br/>(GENERAL ELECTRIC)</b>  |
| <b>VII.</b> | <b>SUMMARY</b>  | <b>R. ABBOTT</b>                            |



## BACKGROUND INFORMATION OF HPCS NOZZLE KC-32 FLAW

- (A) IN-SERVICE INSPECTION OF HIGH PRESSURE CORE SPRAY NOZZLE SAFE END TO SAFE END EXTENSION WELD KC-32 PERFORMED IN OCTOBER 1990 REVEALED A FLAW THAT EXCEEDED THE ASME CODE ACCEPTANCE STANDARDS.
  
- (B) SINCE THE FLAW HAD PROPAGATED TO ALLOY 182, WHICH IS SUSCEPTIBLE TO IGSCC, NMPC ELECTED TO UTILIZE MECHANICAL STRESS IMPROVEMENT (MSIP) AS A MEANS OF MITIGATING CRACK GROWTH DUE TO IGSCC BY IMPROVING THE RESIDUAL STRESS DISTRIBUTION AROUND THE TIP OF THE FLAW.
  
- (C) POST MSIP, THE WELD WAS RE-INSPECTED. THE RE-INSPECTION INDICATED THAT THE FLAW DEPTH WAS 0.35 INCHES (41% OF WALL THICKNESS) AND 3.4 INCHES (11.3% OF CIRCUMFERENCE) IN LENGTH.
  
- (D) NMPC PERFORMED A FRACTURE MECHANICS ANALYSIS TO SUPPLEMENT MSIP. THE FRACTURE MECHANICS ANALYSIS DISREGARDED BENEFIT OF MSIP. THE THROUGH WALL RESIDUAL WELD STRESS DISTRIBUTION REPORTED IN NUREG-0313, REVISION 2, WAS UTILIZED WHICH SHOWED THE FLAW TO GROW FROM A DEPTH OF 41% TO A DEPTH OF 59% IN ONE FUEL CYCLE OF OPERATION (12,000 HOURS).



11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100


11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

**(E) NRC SAFETY EVALUATION OF FRACTURE MECHANICS ANALYSIS FOR KC-32 REQUIRED NMPC TO:**

- **PERFORM A MID-CYCLE INSPECTION OF NOZZLE WELD KC-32 (BETWEEN THE 5TH AND 10TH MONTH OF THIS CYCLE).**
  
- **RESUBMIT FRACTURE MECHANICS ANALYSIS BASED ON MID-CYCLE INSPECTION WHICH WOULD:**
  - (i) ASSESS WELD RESIDUAL STRESSES IN 10" DIAMETER PIPE.**
  
  - (ii) ADDRESS UNCERTAINTY IN FLAW SIZING RESULTING FROM ULTRASONIC EXAMINATION.**



Figure - Nine Mile Point 2 - Core Spray Nozzle  
Safe-End to Safe-End Extension Weld





2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

11

22



NIAGARA MOHAWK POWER CORPORATION

NINE MILE POINT UNIT 2

CRACK GROWTH EVALUATION

FOR


CORE SPRAY SAFE-END-TO-EXTENSION WELDMENT

PRESENTED TO


UNITED STATES NUCLEAR REGULATORY COMMISSION


JUNE 1991





ANALYSIS FLOW CHART






CORE SPRAY NOZZLE GEOMETRY



7

1000

1000



ANSYS 4.  
 DEC 10 199  
 \*\*:59:02  
 PLOT NO.  
 POST1 STRE  
 STEP=69  
 ITER=200  
 SY (AVG)  
 S GLOBAL  
 DMX =0.040  
 SMN =-3770  
 SMX =37211  
  
 ZU =1  
 DIST=1.78E  
 \*XF =5.32E  
 \*YF =-9.7E  
 EDGE  
 -3770  
 -2938  
 -2105  
 -1273  
 -4409  
 3915  
 12239  
 20563  
 28887  
 37211

FIGURE 3.7 POST MSIP AXIAL STRESSES IN THE SACC-END-10-EXTENSION WELD (0.78% CONTRACTION)



Vertical line of noise or artifacts on the left side of the page.








FIGURE 3.11 POST MSIP AXIAL STRESSES WITH OPERATING LOADS INCLUDED FOR THE SAFE-END-TO-EXTENSION WELD (0.788% CONTRACTION)






THROUGH-WALL DISTRIBUTION OF AXIAL RESIDUAL  
STRESS FROM NUREG-0313



4

2




ASSUMED THROUGH-WALL WELDING RESIDUAL STRESS  
DISTRIBUTION IN SMALL-DIAMETER WELDMENTS  
( $< 12$  in.).

(FROM NUREG-1061)



O'Donnell & Associates, Inc.  
Pittsburgh, Pennsylvania



COMBINED AXIAL STRESS DISTRIBUTION AT OPERATING CONDITIONS

PROPRIETARY

SMC O'DONNELL INC.





## STRESS INTENSITY FACTOR

Stress Profile represented by third degree polynomial

$$\sigma_0 = A_0 + A_1X + A_2X^2 + A_3X^3$$

Stress Intensity Factor [Reference: Dedhia and Harris,

PVP Vol. 95, 1983]


$$K_1 = \sqrt{\pi a} [A_0F_0 + aA_1F_1 + a^2A_2F_2 + a^3A_3F_3]$$


$A_0$ ,  $A_1$ ,  $A_2$  and  $A_3$  = coefficients of the polynomial expression representing

the stress profile  $\sigma(x)$  in the uncracked section


$a$  = crack depth, and

$F_0$ ,  $F_1$ ,  $F_2$  and  $F_3$  = Influence function factors







INFLUENCE FUNCTIONS FOR POWER STRESSES




O'Donnell & Associates, Inc.  
Pittsburgh, Pennsylvania



STRESS INTENSITY FACTOR VERSUS CRACK DEPTH FOR  
OPERATING CONDITIONS INCLUDING AS-WELDED STRESS





COMPOSITE CRACK GROWTH RELATIONSHIP  
USED IN THE EVALUATION






CRACK GROWTH ASSESSMENT


<u>MONTH</u> <u>ENDING</u>	<u>TIME</u> <u>(hrs)</u>	<u>CRACK DEPTH</u> <u>(% Wall)</u>	<u>CRACK LENGTH*</u> <u>% Circumference</u>
	0	41.18	11.2
May 91	2920	46.59	12.7
June 91	3650	47.85	13.0
July 91	4380	49.08	13.3
August 91	5110	50.27	13.7
Sept 91	5840	51.43	14.0
Oct 91	6570	52.55	14.3
Nov 91	7300	53.63	14.6
Feb 92	9700	56.95	15.5

Threshold  $K_1 = 28.5 \text{ ksi}/\sqrt{\text{in}}$  Plateau Growth Rate =  $5.0 \times 10^{-5} \text{ in/hr}$ .


\*Assuming length grows in same ratio as depth.




O'Donnell & Associates, Inc.  
Pittsburgh, Pennsylvania




CRACK DEPTH AS A FUNCTION OF OPERATING TIME




O'Donnell & Associates, Inc.  
Pittsburgh, Pennsylvania



CRACK LENGTH AS A FUNCTION OF OPERATING TIME



O'Donnell & Associates, Inc.  
Pittsburgh, Pennsylvania



FAILURE ANALYSIS DIAGRAM



24

25



## CONCLUSIONS

- ANALYSIS BASED ON THE ACTUAL POST-MSIP DISTRIBUTION CORRESPONDING TO FIELD MEASURED PIPE CONTRACTION INDICATES THAT THE CRACK REMAINS IN THE COMPRESSIVE REGION.
- FOR THE HYPOTHETICAL CASE WITHOUT MSIP, FRACTURE MECHANICS EVALUATION BASED ON A CONSERVATIVE LINEAR AS-WELDED RESIDUAL STRESS, PREDICTS A CRACK DEPTH LESS THAN 57% OF THE WALL THICKNESS AFTER ONE FUEL CYCLE.
- PREDICTED CRACK DEPTH AFTER ONE CYCLE MEETS THE ASME CODE SECTION XI LIMIT AND THE CRACK REMAINS IN THE STABLE REGIME.
- ANALYSIS RESULTS RECONFIRM THAT SAFE OPERATION CAN BE CONTINUED THROUGH THE CURRENT CYCLE.

Vertical text on the left side of the page, possibly a page number or reference code.

## **UT UNCERTAINTY**

**PAGE 1 OF 3**


- U.T. EXAMINATIONS WERE PERFORMED TO ASME SECTION XI CODE, WITH ENHANCEMENTS ENDORSED BY THE EPRI NDE CENTER.**
- EPRI REQUIRES THAT THE TECHNIQUES EMPLOYED (PROCEDURE, EQUIPMENT, AND PERSONNEL) BE QUALIFIED BY DEMONSTRATION, ON SAMPLES WITH DEFECTS OF KNOWN QUANTITIES AND QUALITIES.**
- ALL UT EXAMINATIONS PERFORMED ON THIS WELD WERE BY PROCEDURE, EQUIPMENT, AND PERSONNEL THAT HAD BEEN QUALIFIED AT THE EPRI NDE CENTER.**

Vertical text on the left side of the page, possibly a page number or header.

## **UT UNCERTAINTY**

**PAGE 2 OF 3**

- **AUTOMATED UT EXAMINATION IDENTIFIED THE INDICATION.**
- **FOUR (4) DIFFERENT MANUAL UT TECHNIQUES WERE UTILIZED TO SIZE THE INDICATION. THE RESULTS WERE ALL CONSISTENT WITH EACH OTHER AND SUPPORTED THE AUTOMATED EXAM.**
- **AFTER A MODIFICATION ON AN ADDITIONAL AREA OF THIS SYSTEM BOTH AUTOMATED AND MANUAL UT EXAMINATIONS WERE REPERFORMED. THE RESULTS WERE ALSO CONSISTENT WITH THE PREVIOUSLY PERFORMED SIZING.**



## **UT UNCERTAINTY**

**PAGE 3 OF 3**

- **UT UNCERTAINTY SHOULD NOT BE A FACTOR AS THE TECHNIQUES THAT WERE EMPLOYED ARE STATE OF THE ART AND HAVE BEEN PROVEN BY DEMONSTRATION TO ACCURATELY MEASURE THE SIZES OF KNOWN DEFECTS.**



406

4 3 2 1

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

1

2

3


4



## **FEASIBILITY OF RADIOGRAPHY ON HPCS INDICATION**

**PAGE 1 OF 2**

- **A WATER FILLED MOCK-UP OF THE NOZZLE WAS RADIOGRAPHED IN THE SHOP USING APPROXIMATELY A 70 CURIE IR 192 SOURCE.**
- **RESULTS INDICATED THAT BY USING A STRONGER SOURCE MEANINGFUL RESULTS COULD POSSIBLY BE OBTAINED.**
- **A 200. CURIE SOURCE OF IR 192 WAS OBTAINED AND RADIOGRAPHY WAS ATTEMPTED ON THE AREA CONTAINING THE INDICATION.**
- **RESULTS OF THE RADIOGRAPHS WERE INCONCLUSIVE (RADIOGRAPHS WERE NOT OF READABLE QUALITY).**
- **ADDITIONAL RADIOGRAPHS WERE ATTEMPTED USING DIFFERENT SPEED FILMS AND WITH VARYING THE SOURCE ANGLE.**



## **FEASIBILITY OF RADIOGRAPHY ON HPCS INDICATION**

**PAGE 2 OF 2**

- THESE ALSO DID NOT PRODUCE RADIOGRAPHS OF ACCEPTABLE QUALITY.**
- TO PURSUE FURTHER RADIOGRAPHY ON THIS WELD WOULD RESULT IN UNNECESSARY EXPOSURE TO PERSONNEL AND NOT YIELD ANY MEANINGFUL INFORMATION.**



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

**WELD OVERLAY DESIGN BASIS FOR  
NINE MILE POINT 2 CORE SPRAY NOZZLE  
SAFE END TO SAFE END EXTENSION WELD**

**PRESENTED BY**


**SAM RANGANATH  
GE NUCLEAR ENERGY  
SAN JOSE, CALIFORNIA**




SECRET

## OVERLAY DESIGN BASIS

- 0 THICKNESS BASED ON IWB-3640 AND APPENDIX C OF SECTION XI
  - CONSIDERS PRESSURE, WEIGHT AND SEISMIC INERTIA LOADING
  - NO CREDIT TAKEN FOR REMAINING PIPE CROSS-SECTION; THUS INDEPENDENT OF CRACK SIZE
- 0 MINIMUM LENGTH IS  $\sqrt{RT}$ 
  - LENGTH GENERALLY GREATER FOR UT INSPECTABILITY
- 0 SHRINKAGE ANALYSIS ASSURES STRESSES ELSEWHERE IN THE PIPING SYSTEM ARE WITHIN ALLOWABLE VALUES
  - SYSTEM WELDS WITH INDICATIONS NEED TO BE REEVALUATED







Cross Sections

Stress Distributions At Net Section Collapse






Figure 2 - Weld Overlay Stress Distributions at Net-Section Collapse



## THICKNESS DESIGN FOR A FULL STRUCTURAL OVERLAY



$$P'_b = \frac{6S_m}{\pi} \left( 2 - \frac{a}{t} \right) \sin \beta$$

$$\beta = \frac{\pi}{2 - \frac{a}{t}} \left( 1 - \frac{a}{t} - \frac{P_m}{3S_m} \right)$$

$$P'_b = SF(P_m + P_b) - P_m$$

**WELD OVERLAY THICKNESS = ( t - a )**




Table 1 - Weld Overlay Thickness Calculation Summary

```


*****
*
*
*          PLANT ID:  NINE MILE POINT 2
*          WELD ID:   SAFE-END TO SAFE-END EXT
*
*
*          PIPE THICKNESS =  0.88 INCH
*          PIPE DIAMETER  = 11.38 INCH
*
*          PRIMARY STRESSES:
*          PRESSURE       =  3.66 KSI
*          DEAD WEIGHT MEMBRANE =  0.27 KSI
*          DEAD WEIGHT BENDING =  2.98 KSI
*          SEISMIC MEMBRANE  =  0.58 KSI
*          SEISMIC BENDING   =  4.13 KSI
*          SM WELD MATERIAL  = 23.30 KSI
*          SM PIPE MATERIAL  = 23.30 KSI
*
*
*
*          T          PB (KSI)          PM+PB          PM+PB/3
*          -----   - - - - -         - - - - -         - - - - -
*          WOT       T+WOT  (KSI)  REMOTE  WOT  (REMOTE)  (WOT)
*          -----   - - - - -         - - - - -         - - - - -
*          0.255    0.774    3.595    5.333  23.556    8.928    9.050
*
*
*          PRIMARY STRESSES:
*          PM          =  3.595
*          PM+PB      =  8.928
*
*          MINIMUM REQUIRED WELD OVERLAY THICKNESS =  0.255 INCH
*          MINIMUM REQUIRED WELD OVERLAY WIDTH    =  2.2  INCH
*
*****

```



Small, illegible markings or text in the top right corner.


Figure 1 - Nine Mile Point 2 - Core Spray Nozzle  
Safe-End to Safe-End Extension Weld







EXAMPLE OF HOW A WELD OVERLAY IS EXAMINED  
REQUIRED WIDTH OF OVERLAY





## CONCLUSION

THE FULL STRUCTURAL WELD OVERLAY FOR  
THE NMP 2 CORE SPRAY NOZZLE SAFE END  
TO SAFE END EXTENSION WELD, MEETS ALL  
CODE, NRC AND UT INSPECTABILITY  
CRITERIA



Vertical text or markings along the left edge of the page, possibly bleed-through from the reverse side.

## S U M M A R Y

### NMPC ACTIONS

- SUBMIT REVISED FRACTURE MECHANICS ANALYSIS TO NRC BY JUNE 28 FOR APPROVAL
- PERFORM MID-CYCLE UT INSPECTION OF WELD KC-32
- EVALUATE UT RESULTS WITH RESPECT TO THE RESULTS OF REVISED FRACTURE MECHANICS ANALYSIS.

THE FOLLOWING CRITERIA WILL BE UTILIZED:

- (i) IF FLAW LENGTH AND DEPTH FOR THE PERIOD OF EVALUATION IS WITHIN ALLOWABLE LIMITS AS ESTABLISHED BY THE ANALYSIS, NO FURTHER ACTION WILL BE TAKEN UNTIL THE REFUELING OUTAGE.
- (ii) IF FLAW LENGTH FOR THE PERIOD OF EVALUATION EXCEEDS ALLOWABLE LIMITS AS ESTABLISHED BY THE ANALYSIS BUT DEPTH REMAINS WITHIN THE LIMITS ESTABLISHED, A REVISED FRACTURE MECHANICS ANALYSIS WILL BE SUBMITTED TO NRC FOR ACCEPTANCE PRIOR TO STARTUP.
- (iii) IF FLAW DEPTH FOR THE PERIOD OF EVALUATION EXCEEDS ALLOWABLE LIMITS AS ESTABLISHED BY THE ANALYSIS, NMPC SHALL PERFORM REPAIR OF THE KC-32 WELD.

### NRC ACTIONS

- REVIEW AND APPROVE REVISED FRACTURE MECHANICS ANALYSIS
- APPROVE ASME XI REPAIR PLAN SUBMITTED ON JUNE 10, 1991



mid-cycle inspection. During the meeting, the licensee committed to submit a revised fracture mechanics analysis by June 28, 1991. The NRC staff agreed to promptly review this revised analysis as well as the proposed repair plan submitted on June 10, 1991. It was agreed that if any significant growth (to be defined by NMPC and agreed to by the NRC staff) of this flaw is detected during the mid-cycle inspection, further evaluation will be required as well as a probable repair. However, if the NRC staff determines the revised analysis to be submitted on June 28, 1991, is acceptable and there is no significant growth of the flaw, the plant may resume and continue operation without repairing the weld (KC-32) until the next refueling outage when the weld will be reinspected.

Original Signed By:

Donald S. Brinkman, Senior Project Manager  
Project Directorate I-1  
Division of Reactor Projects - I/II  
Office of Nuclear Reactor Regulation

Enclosures:

- 1. List of Attendees
- 2. Licensee Handout Material

cc w/enclosures:  
See next page

DISTRIBUTION:

Docket File	NRC & Local PDRs
FMiraglia	JPartlow
JCalvo	SVarga
PDI-1 Reading	RACapra
DBrinkman	CVogan
OGC	EJordan
NRC Participants	ACRS (10)
CCowgill	

OFC	:PDI-1:LA	:PDI-1:PM	:PDI-1:D	:	:
NAME	:CVogan <i>CV</i>	:DBrinkman <i>AB</i>	:RACapra <i>RC</i>	:	:
DATE	:6/27/91	:6/27/91	:6/27/91	:	:

OFFICIAL RECORD COPY  
Document Name: NMP2 MTG SUM

1850  
1851  
1852  
1853  
1854  
1855  
1856  
1857  
1858  
1859  
1860

1850  
1851  
1852  
1853  
1854  
1855  
1856  
1857  
1858  
1859  
1860

1850  
1851  
1852  
1853  
1854  
1855  
1856  
1857  
1858  
1859  
1860

1850  
1851  
1852  
1853  
1854  
1855  
1856  
1857  
1858  
1859  
1860

1850  
1851  
1852  
1853  
1854  
1855  
1856  
1857  
1858  
1859  
1860