

# OFFICIAL TRANSCRIPT OF PROCEEDINGS

**Agency:** Nuclear Regulatory Commission  
 Incident Investigation Team

**Title:** Nine Mile Point Nuclear Power Plant  
 Interview of: DAVID RATHBUN

**Docket No.**

**LOCATION:** Scriba, New York

**DATE:** Tuesday, August 20, 1991

**PAGES:** 1 - 31

**ANN RILEY & ASSOCIATES, LTD.**  
 1612 K St. N.W., Suite 300  
 Washington, D.C. 20006  
 (202) 293-3950.


*9305070-213*



ADDENDUM TO INTERVIEW OF DAVID A. RATHBUN CSD F Shift  
(Name/Position)

<u>Page</u>	<u>Line</u>	<u>Correction and Reason for Correction</u>
4	13+14	"full-rod display" to "four-rod display"
8	25	"read switch" to "reed switch"
9	2	"read switch" to "reed switch" (twice)
9	6	"to zero-zero" to "than zero-zero"
10	2	"read switches" to "reed switches"
28	17	"him" to "them"
28	22	"had" to "have"

Page 1 of 1 Signature *David Rathbun* Date 8/23/91



UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION  
INCIDENT INVESTIGATION TEAM

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25

-----  
Interview of :  
DAVID RATHBUN :  
(Closed) :  
-----

Conference Room B  
Administration Building  
Nine Mile Point Nuclear  
Power Plant, Unit Two  
Lake Road  
Scriba, New York 13093  
Tuesday, August 20, 1991

The interview commenced, pursuant to notice,  
at 1:25 p.m.

PRESENT FOR THE IIT:  
Michael Jordan, NRC  
Rich Conte, INPO  
PRESENT WITH MR. RATHBUN:  
Mike Colomb, Niagara Mohawk

11

12



## P R O C E E D I N G S

[1:25 p.m.]

1  
2  
3 MR. JORDAN: It's August 20, 1991. It's 1:25 p.m.  
4 We're at the Nine Mile Point Unit One nuclear power station,  
5 in the P building. We are going to cover events of a  
6 transient that occurred on August 13, 1991. My name is  
7 Michael Jordan, with the U.S. NRC, out of Region III.

8 MR. CONTE: I'm Rich Conte, Region I.

9 MR. RATHBUN: My name is David Rathbun, reactor  
10 operator at Nine Mile Point Unit Two.

11 MR. COLOMB: My name is Mike Colomb. I work for  
12 Niagara Mohawk Power Corporation. I'm the operations  
13 manager at Unit Two.

14 MR. JORDAN: We're here to interview Dave Rathbun.

15 Dave, why don't you start out and tell us what's  
16 your experience in your site here? What experience do you  
17 have? What's your background?

18 MR. RATHBUN: I was a Navy nuke for six years,  
19 reactor operator. I joined Niagara Mohawk in 1982. I  
20 licensed on Unit One, went over to Unit Two, and licensed at  
21 Unit Two, reactor operator. For the past six months or so,  
22 I've been a chief shift operator on F shift.

23 I'm not sure what else you'd like me to say.

24 MR. CONTE: When did you get your license in Unit  
25 Two?





1 MR. RATHBUN: I can't remember exactly, to be  
2 honest.

3 MR. CONTE: What year?

4 MR. RATHBUN: That's what I'm trying to remember.  
5 I can't even remember the year, to be honest. I'd say  
6 about five years ago, or so.


7 MR. JORDAN: You're currently licensed?

8 MR. RATHBUN: Yes.

9 MR. JORDAN: Okay, Dave. Why don't you go ahead  
10 and tell us in your own words, then, what you saw and how  
11 you saw the event transpire?

12 MR. RATHBUN: Okay. I was coming in to relieve  
13 the on-shift chief shift operator. I walked into the  
14 control room at approximately 6 o'clock. The incident had  
15 already started, and I arrived prior to the re-energizing of  
16 the uninterruptable power supplies.

17 Shortly after I walked into the control room, I  
18 made the SSS aware that I was available, and he requested  
19 that I use EOP 6, attachment 14, to attempt to -- I'm trying  
20 to think of the word I want to use -- locate whether or not  
21 the rods were full in or not. This was still when we had no  
22 indication of the position of rods. I looked through the  
23 procedure. At the time, I could only see one thing that  
24 might help, and that was to verify locally that the scram  
25 air-header was depressurized. I suggested that to the SSS,




1 and he agreed, and we sent a non-licensed operator out to  
2 check on that.

3           Before he could report back, we recovered power on  
4 the uninterruptable power supplies, at which time we  
5 regained some of the rod indication systems. Myself and  
6 another operator then, using both the rod sequence  
7 controller and the full core display -- some rods didn't  
8 show full in on both of those, and they weren't exactly the  
9 same, so we went through and checked the rods that weren't  
10 indicating full in on RSCS against the full-core display,  
11 and out of that came up with six rods that were not  
12 indicating full in on both of them. We selected those rods  
13 using the rod select matrix, to try to use the full-rod  
14 display to find where the rods were, and got blanks on all  
15 of them, so we still didn't know.

16           We reported that to the SSS, and at that time I  
17 suggested to the SSS that perhaps these rods are over-driven  
18 in by the scram. If we reset the scram, we may be able to  
19 let the rods settle and get good indication on them. The  
20 only problem with that was that at the time the reactor  
21 vessel level was less than level 3, which is a scram signal.

22           The assistant SSS, STA, reminded both of us that  
23 he had authorized use of attachment 14, which gives guidance  
24 for defeating RPS interlocks to allow resetting scrams to do  
25 repeated scram signals to insert rods that are not full in.




1 The SSS directed me, then, to insert those jumpers and reset  
2 the scram.

3 I used attachment 14, took it in the back of the  
4 control room with me, and inserted the jumpers in 609 panel  
5 and 611 panel. Also using the procedure, I came back out  
6 front and reset alternate rod insertion, reset the scram.  
7 At that point we got indication of all rods in on the full-  
8 core display and RSCS, and we reported that to the SSS.

9 I wasn't really given any more duties after that.  
10 I answered the phones occasionally and helped direct some of  
11 the non-LOTs on lesser tasks out in the plant, as far as  
12 trying to regain some of the things for a normal shutdown,  
13 try to get the plant back in a more normal configuration.

14 I worked with one of the oncoming STAs to try to  
15 get the plant computers back, to get help from the TSC or  
16 the OSC, whichever it was, for the computer techs. Once the  
17 SPDS computer was back, I reinitialized the EOF so that they  
18 could make use of the SPDS computer.

19 At one point in time I was asked to look at the  
20 Division 2 H2O2 monitor. Basically, all that was wrong with  
21 it was that the pump was not running, and we weren't sure at  
22 that time why it was not running. The valves were still all  
23 lined up; we had not taken the containment isolation; and  
24 the SSS wanted that on line so we could have accurate  
25 indication of if anything was going wrong in the primary



1 containment, so at his direction I restarted that pump.

2 At approximately 10:17, I relieved the CSO, who  
3 had been there. He took the log in to write in all of the  
4 things that had gone on during his time in the control room,  
5 and I had a non-LOT write down and be my scribe for a while,  
6 until I could get the log back. We just continued the cool-  
7 down, put shutdown cooling in service.


8 We attempted to put clean-up in service and  
9 encountered a problem with that, where it isolated. At that  
10 time, the SSS, which by now had also been relieved as a new  
11 SSS, made the determination that we were not going to worry  
12 about clean-up for a while, till it cooled down.

13 That's pretty much it. I left before they down-  
14 graded the emergency from a site area emergency.

15 MR. JORDAN: A couple questions.

16 You mentioned that the RSCS and the full core  
17 display and the rod worth minimizer were indicating rods not  
18 full in. Can you give me an idea of the RSCS and the full  
19 core display were indicating the same number of rods and the  
20 same rods? Or were they different rods, was the RSCS and  
21 the full core display indicating different rods?

22 MR. RATHBUN: The RSCS was indicating quite a bit  
23 more than the six rods that we ended up with -- excuse me.  
24 I don't remember exactly how many. There was one operator  
25 that was looking at that, the one that I was helping. He





1 used the RSCS as a guide.

2 He went, you know, would break down the rows on  
3 that display and when he came to a blank where there should  
4 have been a full in light. He'd read that number off and  
5 I'd check that number on the full core display, whether or  
6 not it had full in lights.

7 It seemed to me that there were other rods that  
8 had, that did not have full in lights on the full core  
9 display but that he had full in lights on the RSCS.

10 Between the two of them, there were only six that  
11 showed not full in on both of them together.

12 MR. JORDAN: How about the rod worth minimizer?

13 MR. RATHBUN: Rod worth minimizer, the new rod  
14 worth minimizer has a confirmed shutdown option or thing you  
15 can select. When power came back it was in the normal  
16 display. I had to select that confirmed shutdown and when I  
17 did, it said "shutdown, no; all rods in, no; number of rods  
18 not full in, 1" and then there is another button you can  
19 press to give a list.

20 I pressed that button and it gave me one rod  
21 number, of which I don't remember the exact number. It was  
22 1830-something I think, and anyway it said that it thought  
23 that rod was full in but it was giving it as the rod that it  
24 thought was not full in.

25 After we reset the scram and RSCS and the full



1 core display both said all rods were full in, the rod worth  
2 minimizer also agreed with that and said "shutdown, yes" and  
3 "all rods full in, yes."

4 MR. JORDAN: Was 18-whatever it is, 1830-  
5 something, was that one of the rods that --

6 MR. RATHBUN: No. That was not one of the six  
7 rods. We checked that against our list.

8 MR. JORDAN: Okay. You say you selected those  
9 rods, the six rods on the four rod display?

10 MR. RATHBUN: Uh-huh [affirmative].

11 MR. JORDAN: And they indicated?

12 MR. RATHBUN: Blanks.

13 MR. JORDAN: Just blanks?

14 MR. RATHBUN: Right.

15 MR. JORDAN: The rest of the rods on full core  
16 display, did they indicate blanks also?


17 MR. RATHBUN: I don't remember seeing any zeroes  
18 on it but I wasn't really looking for them so I am not  
19 really sure.

20 MR. CONTE: What do you normally get in the over-  
21 travel situation where it is too far in?

22 MR. RATHBUN: We've had this kind of indication  
23 before on these. That's why I --

24 MR. CONTE: Do you get blanks or xx or what?

25 MR. RATHBUN: Not blanks, xx's if the read switch



1 isn't making up and the reactor manual control system doubts  
2 the read switch or doesn't, has it open for read switch.

3           There is a read switch for overtravel in which is  
4 -- I am not exactly sure now if it picks up the green light  
5 but we've had, I have seen it before on scrams, until you  
6 reset it where they're pushed in farther to zero-zero and  
7 the zero-zero doesn't show up on the four rod display.

8           MR. CONTE: What does show up?

9           MR. RATHBUN: Just blanks, like I saw there.

10           MR. CONTE: What about the green light? What did  
11 you say about that?


12           MR. RATHBUN: The green lights would be up on the  
13 full core display.

14           MR. JORDAN: You say those are, on an overtravel  
15 they are still lit or they are not lit?

16           MR. RATHBUN: Some of them were and some of them  
17 weren't. I don't remember exactly. They came in when we  
18 reset the scram and the rods were able to settle back in the  
19 past.

20           MR. JORDAN: How about in the past, when you had  
21 indication on the four --

22           MR. RATHBUN: Well, it was pretty much kind of  
23 like this where some would and some wouldn't. It was never  
24 the whole core, never, you know, didn't show full in. It  
25 was only some of the rods.



1 MR. CONTE: How much do you know about the power  
2 supply to those read switches in terms of where they get  
3 power?

4 MR. RATHBUN: RPIS.

5 MR. CONTE: If you don't know --

6 MR. RATHBUN: I wouldn't be able to give it to you  
7 from memory. I know I have gone through the GE prints for  
8 that system looking up power supplies to make changes to our  
9 procedure because they didn't have it in it quite a while  
10 back, a year or so ago, and I was writing markups a lot and  
11 needed one of them.


12 I can't give you a definite answer but I know that  
13 it comes off, most of the stuff in that system comes off of  
14 a main breaker, one or two main breakers in the panel. Its  
15 ultimate power supply in the plant I am not really sure.

16 MR. CONTE: Was it a surprise to you based on your  
17 training here at Nine Mile that you would get a loss of  
18 annunciators and an accompanying full core display out,  
19 being black like that? Have you ever seen that before in  
20 training on the simulator or either at startup testing or--

21 MR. RATHBUN: Not to my recollection, no.

22 MR. CONTE: Okay. I had some questions as you  
23 were running down the chronology. Let's go back to the  
24 start of this thing.

25 How do you know it was six o'clock that you walked





1 into the control room? Was it before the site emergency was  
2 declared?

3 MR. RATHBUN: When I walked in, I walked in from  
4 the back of the control room, and just as I walked through  
5 into the front part of the control room between Panel 602  
6 and 601, the SSS site emergency director was announcing, you  
7 know, let me have your attention, I am going to declare a  
8 site area emergency.

9 That was just as I walked through is when he said  
10 that. I know it was a few minutes to or after 6:00 just from  
11 what time it was on my clock radio and I was in the parking  
12 lot and just ready to walk in.

13 MR. CONTE: Could you retrace the path walking in,  
14 primarily when you entered Unit Two, what areas were dark?

15 MR. RATHBUN: Sure. I didn't notice anything in  
16 the security building at all or out in the parking lot or on  
17 the way in.


18 When I walked into the CO2 room I noticed that  
19 part fo the lights, about half of the lights were off.

20 MR. CONTE: CO2 room, what building and elevation  
21 was that?

22 MR. RATHBUN: That is auxiliary service building  
23 south, elevation 261.

24 Those lights there --

25 MR. CONTE: Had some lights on.



1 MR. RATHBUN: Right. Those lights, I don't know  
2 why, but for some reason they get turned off a lot. There's  
3 like half the lights in there on a light switch and half of  
4 them are on another contactor, so I tried to turn them on  
5 and I got no response.

6 MR. CONTE: Oh, okay.

7 MR. RATHBUN: Interesting, I'll have to remember  
8 this when I go upstairs and ask about it.

9 I walked from there into the access passageway.

10 You step into it and then turn a corner and go  
11 through another door and I noticed again a lot of the lights  
12 were out. It's a very long passageway.

13 MR. CONTE: Access passageway, what building?  
14 Same building?


15 MR. RATHBUN: No, that's basically what it's  
16 called, access passageway or electric bay. It's a long  
17 passageway between Unit One heading towards Unit Two -- Unit  
18 Two going to Unit One, I'm sorry.

19 MR. CONTE: Oh, is that where we go to go to the  
20 cafeteria?

21 MR. RATHBUN: Yes, that long hallway.

22 MR. CONTE: I was wondering what you called that,  
23 okay.

24 MR. JORDAN: If I could back up just for a second.  
25 You say in the CO2 room you --



1 MR. RATHBUN: -- attempted --

2 MR. JORDAN: With the light switch?

3 MR. RATHBUN: Right.

4 MR. JORDAN: The lights did not come on or as a

5 result of operating the lights that were in there did they

6 go off?

7 MR. RATHBUN: Nothing happened.

8 MR. JORDAN: Nothing happened?

9 MR. RATHBUN: Nothing at all.

10 MR. JORDAN: Okay.

11 MR. RATHBUN: Okay, so from there I turned and --

12 MR. CONTE: What was the condition in the access

13 passageway with the lights?

14 MR. RATHBUN: A lot of the lights were out, yes.

15 MR. CONTE: A lot of the lights were out, but not

16 black?

17 MR. RATHBUN: No. There was a few lights on.

18 MR. CONTE: Any emergency lighting on?

19 MR. RATHBUN: I didn't notice any in either of

20 these two buildings.


21 I went into the door into the -- I guess it would

22 be in the turbine building where the elevator is. Again

23 about half of the lights were out. There's like three lights

24 in that area and like two of them were on and one was off.

25 MR. CONTE: I'm sorry, I missed that area again.



1 MR. RATHBUN: The turbine building, I believe it  
2 is, 261 -- where the elevator is and the stairwell.

3 Elevator arrived and the lights were all out in  
4 the elevator including the emergency lights and I rode the  
5 elevator up --

6 MR. CONTE: Did you see people coming out of that  
7 elevator?

8 MR. RATHBUN: Yes. There were a couple of non-  
9 licensed operators who came out of the elevator --

10 MR. CONTE: Do you remember their names?


11 MR. RATHBUN: -- in a little bit of a hurry --  
12 only one of them, Tom Restuccio. I don't remember who the  
13 other one was.

14 MR. CONTE: Okay.

15 MR. RATHBUN: And I asked something like "Is  
16 everything okay?" One of them said no, which I had begun to  
17 suspect already.

18 I think one of them said something about, the  
19 reactor had scrambled at that point in time. I rode the  
20 elevator up. The elevator operating lights for the floors  
21 and the buttons all worked, but the lighting in there was  
22 not working, and the emergency lights in there were not  
23 working.

24 Up to elevation 306. Again, most of the lights  
25 were out.





1 MR. CONTE: Elevation 306, what building?

2 MR. RATHBUN: Same building, turbine building.

3 This is by the RP office and the access to go into the  
4 turbine building on 306. I walked over to the doors, into  
5 the control building, carded in there. The card reader  
6 still worked.

7 MR. CONTE: Did you see anything unusual in the  
8 lighting in the control building?


9 MR. RATHBUN: Yes. Got into the control building.  
10 As I recall, the hallway in the control building looked  
11 normal. I carded into the control room, and I didn't notice  
12 anything as far as lighting out in the control room. Then I  
13 walked up between the panels and into the front, like I  
14 said before, just in time for the SED to make his emergency  
15 declaration.

16 MR. CONTE: Going further on, you said that one of  
17 the SSS sent down an RO to verify locally the scram header  
18 depressurization. Do you know who that RO was?

19 MR. RATHBUN: It was a non-licensed operator I  
20 sent out. That was Dave Brockwell.

21 MR. CONTE: Where does he have to go to see this?

22 MR. RATHBUN: That would be reactor building, 261  
23 elevation. We researched on the prints for this system and  
24 found an indicator off the scram air header that we believed  
25 was in an instrument rack down there near the CRD flow



1 control station.

2 MR. CONTE: Do you remember when he reported back?

3 MR. RATHBUN: No. I never heard a report back  
4 from him personally. Later on I had asked if anybody had  
5 seen him, because I hadn't seen him in a while, and he had  
6 been sent down to help start up the auxiliary boilers.

7 MR. CONTE: You mentioned you wanted to reset the  
8 scram; you had made a suggestion to reset the scram because  
9 you thought the scram pressure was pushing the rods too far  
10 in. You had the level 3 in, which was the low-level scram  
11 setting --

12 MR. RATHBUN: Right.


13 MR. CONTE: -- and someone reminded you -- and I  
14 didn't catch the name -- that you can defeat an RPS  
15 interlock.

16 MR. RATHBUN: That was the STA, Mike Eron.

17 MR. CONTE: Okay. What did he say? You can  
18 defeat an interlock?

19 MR. RATHBUN: Well, what he said, basically, was  
20 that Mike Conway, who was the SSS-SED, had already told me  
21 to use attachment 14 -- he had authorized the use of  
22 that -- and that one of the sections in that gives guidance  
23 for bypassing the RPS interlocks in order to reset scrams.

24 MR. CONTE: And you were basically getting ready  
25 to follow that attachment.



1 MR. RATHBUN: Right.

2 Mike took a moment to think about it and said,  
3 Yes, that's what I want to do, told me to do that.

4 MR. CONTE: Did you do that?

5 MR. RATHBUN: Yes, I did. Four jumpers in the  
6 back of the panel, and I installed them.

7 MR. CONTE: Okay.

8 MR. JORDAN: The only scram signal that was  
9 preventing you from resetting the scram that you know of was  
10 the low level?

11 MR. RATHBUN: Yes. Turbine trip, stop valve and  
12 control valve fast closures were in, but they were bypassed,  
13 and we had scram dump volume high level in at that point,  
14 which could be bypassed by the bypass switches, but the  
15 level one you can't bypass normally.

16 MR. JORDAN: And the level was --?

17 MR. RATHBUN: I'm not sure of the exact level at  
18 that time, but it was less than 159.3, the setpoint.

19 MR. JORDAN: So 159.3 is the scram setpoint?

20 MR. RATHBUN: Yes.

21 MR. CONTE: What panels -- you said the panels  
22 that you put the jumpers in were 609 and what?

23 MR. RATHBUN: 611.

24 MR. CONTE: You mentioned that Division 2 hydrogen  
25 and oxygen pumps not running. Is that a surprise to you?

10



1 MR. RATHBUN: I couldn't figure out any reason why  
2 it wouldn't have been running, nor the SSS -- or I should  
3 say SRO -- that was back looking at it with me. Nothing  
4 else on the system appeared to be other than normal  
5 operating. Like I said, there were no isolations, no valves  
6 out of position, just that the pump wasn't running.

7 MR. CONTE: Do you happen to know, based on your  
8 training and experience, whether or not those pumps are  
9 powered from vital or non-vital, or safety, sources?

10 MR. RATHBUN: They're powered from vital, safety-  
11 related -- they're a safety-related pump.

12 MR. CONTE: Okay.

13 Further on in the day, you mentioned, reactor  
14 water cleanup had isolated.


15 MR. RATHBUN: Yes.

16 MR. CONTE: What input signals indicated the  
17 isolation? What parameters caused the isolation?

18 MR. RATHBUN: The isolation occurred on the delta  
19 flow timers' timing out.

20 MR. CONTE: Could you give me a little explanation  
21 of what that's supposed to do?

22 MR. RATHBUN: Basically, it's a leak detection  
23 system looking at the flow coming into the system and the  
24 flow leaving the system, under the assumption that, if  
25 they're different, then it could indicate a leak -- more





1 flow coming in, not as much going out; the water has got to  
2 go somewhere. However, certain transients on the system can  
3 cause a difference in flow due to unstabilities and your  
4 changing the parameters of the system, the flows and what-  
5 no, so there's a timer associated with it.

6 MR. CONTE: I see. Okay.

7 When you're starting up reactor water cleanup, is  
8 that an unusual alarm, or a usual alarm?

9 MR. RATHBUN: It isn't that it necessarily happens  
10 every time, but it's not unusual, no. Usually they'll just  
11 come in and go right out.

12 MR. CONTE: I want to make sure I understand. The  
13 reactor water cleanup was on service at the time of the  
14 trip.

15 MR. RATHBUN: At the time of the trip it was in  
16 service.

17 MR. CONTE: What happened to it during the power  
18 outage time period? Do you happen to know?

19 MR. RATHBUN: Not really, no. I know that one of  
20 the immediate scram actions is to either place cleanup in  
21 the full reject mode or shut the pumps off. Most of the  
22 time we shut the pumps off because we don't have time to --  
23 it's somewhat of a lengthy process to put it into full  
24 reject mode. If there isn't time, usually, the SSS will  
25 simply say, Okay, turn it off.

010



1 MR. CONTE: So when you came up to the panels, the  
2 system was shut down.

3 MR. RATHBUN: The first time I had a chance to  
4 look at it, it was already shut down.

5 MR. CONTE: Okay. You were trying to start it up.

6 MR. RATHBUN: Yes. This was later. They wanted  
7 to put it in reject mode to aid in vessel level control

8 MR. CONTE: And when you were starting it up, you  
9 got the isolation signal.

10 MR. RATHBUN: Right.

11 MR. CONTE: You personally were doing this.

12 MR. RATHBUN: No, I was the CSO at that time. One  
13 of my control room reactor operators was doing that.

14 MR. CONTE: What's his name?

15 MR. RATHBUN: Jim Emery?


16 MR. COLOMB: He's on the list.

17 MR. CONTE: Was he following a procedure?

18 MR. RATHBUN: Yes, OP-37. I'm not entirely sure  
19 which section of it he was using.

20 MR. CONTE: Okay. So you basically abandoned  
21 trying to get it started again.

22 MR. RATHBUN: After it isolated, the SSS took a  
23 look at the system parameters and said that trying to put it  
24 in service at this point in time was not -- he didn't feel  
25 it a good idea; the system was still fairly hot, compared to



1 the reactor, and he didn't want to put it in service until  
2 it cooled down.

3 MR. CONTE: You were in the control room, I guess,  
4 from 6 o'clock on, right?

5 MR. RATHBUN: Yes.

6 MR. CONTE: Did you overhear the conversation  
7 with RCIC and what was happening with RCIC? Is there  
8 anything you remember about that? You weren't given  
9 responsibilities on that; I understand that.

10 MR. RATHBUN: Right.

11 I know that was an operator who was assigned level  
12 control using RCIC after they had determined the feed pumps  
13 had tripped and vessel level was lowering. I know later on  
14 they did have a problem with level. As pressure went down,  
15 the booster pumps -- it got down to the discharge head of  
16 the feedwater booster pumps -- condensate booster pumps, I  
17 should say -- and the feedwater level control valves were  
18 locked up in the open position. The operator at RCIC -- I  
19 was standing near him at one point in time -- was diverting  
20 flow from RCIC back to the full flow test to the CST, which  
21 cut off its contribution to the level increase, but the  
22 booster pumps were still going.

23 MR. CONTE: How was water going in from the  
24 booster pumps? The reg valves were locked up in  
25 an as-is --



1 MR. RATHBUN: Right. They were locked up open or  
2 throttled somewhere but fairly high open, probably. They  
3 locked up at 100 percent, I guess, when they lost power.  
4 I'm not real sure on that. I know they had to adjust things  
5 and reset the lock-outs on them.

6 MR. CONTE: RCIC was never tripped. He just  
7 diverted it to the suppression pool?

8 MR. RATHBUN: To the CST.

9 MR. CONTE: To the CST. I'm sorry.

10 MR. RATHBUN: When he diverted it to CST, level  
11 still rose until it reached 202.3 inches, which is the level  
12 8 setpoint, at which time the steam admission valve shut and  
13 the injection valve shut. I asked him if it was in standby,  
14 and he said basically they left it there when those two  
15 valves shut. They turned the -- what do I want to say? --  
16 test return valves closed.

17 Some time later on, probably 15 to 20 minutes  
18 later, I wandered by that panel and happened to notice that  
19 one of the testable checks was still indicating full open.  
20 I pointed that out to one of the STAs -- or SROs -- who was  
21 looking up different tech specs and what-not. I made sure  
22 they knew that. They had already known it and were looking  
23 at containment operability specs.

24 MR. CONTE: Until feed and condensate were  
25 restored, which I think was about 7:30 --





1 MR. RATHBUN: I don't remember the time, to be  
2 honest.

3 MR. CONTE: Whatever.

4 -- was RCIC the primary source of getting water  
5 into the plant? After this level transient -- for example,  
6 water came back down -- you had to keep feeding in order to  
7 maintain level; is that correct?

8 MR. RATHBUN: I'm not real sure on level. As you  
9 said, I wasn't assigned level. I remember at least one  
10 time they went low, and they started RCIC to recover level.  
11 I believe there was another time they had a lowering trend,  
12 and I'm not sure exactly what went on to recover that.

13 MR. CONTE: In this condition, to start it again  
14 you would just open the steam admission valve? Since it  
15 wasn't in a tripped condition.

16 MR. RATHBUN: I believe, unless it had got down to  
17 the initiation setpoint, you'd have to open the steam  
18 admission valve and open the injection valve.

19 MR. CONTE: But you weren't there at this point.

20 MR. RATHBUN: Right.

21 I was over trying to get how many rods were full  
22 in or weren't full in.

23 MR. CONTE: Later in the morning, I guess, a work  
24 party went out to restore some of the uninterruptable power  
25 supplies to normal.



1 MR. RATHBUN: Right.

2 MR. CONTE: From your vantage point in the control  
3 room, were you aware that that was happening? Did you hear  
4 anybody voice a concern about that?

5 MR. RATHBUN: Not really. The first thing I knew  
6 anything about it was that the full-core display came back,  
7 and a lot of annunciators came in and started flashing.

8 MR. CONTE: I'm sorry. I'm confusing you. You're  
9 back in 6:22 in the morning.

10 MR. RATHBUN: Right.

11 MR. CONTE: I'm talking about a time period later,  
12 in mid-morning.

13 MR. RATHBUN: Oh, when they put them on normal?

14 MR. CONTE: Yes.

15 MR. RATHBUN: Oh, okay.

16 MR. CONTE: Did you heard any discussion and  
17 concern about shifting back to normal?

18 MR. RATHBUN: I vaguely remember them talking  
19 about it. I don't recall what was said, to be honest. I do  
20 remember that one of the operators was directed to go out  
21 and attempt to line them back up to normal, and that they  
22 had problems with two of them and had to leave two of them  
23 on maintenance. I don't really recall the exact reasons  
24 why.

25 I do remember something being said about the order



1 that the SSS wanted them in. I don't remember what the  
2 order was exactly, except that I remember that the two that  
3 he had trouble with were the two that he wanted them to wait  
4 last on, make sure they could be reset -- I think C because  
5 it had like only communications and lighting on it, anyway;  
6 we had got them back at that point, because they were on  
7 maintenance, because if you lost it it wouldn't be too much  
8 of a problem. He wanted that to be the one that he tested,  
9 to try to put it in normal first.

10 MR. CONTE: Okay. Very good.

11 I'm all out of questions here.

12 MR. JORDAN: I've got just a couple.

13 MR. RATHBUN: Okay.

14 MR. JORDAN: When they transferred back to  
15 normal, did you see any bump, any change in any of the  
16 parameters, anything?

17 MR. RATHBUN: Nothing that I saw. I really wasn't  
18 up close to the panels at that time, monitoring. Sometime  
19 around there I was going around, trying to get a handle on  
20 what was going on, different people doing things so I could  
21 get a turnover from the off-going guys, so he could get a  
22 relief and fill his log out before he had to go home.

23 MR. JORDAN: Was there a lot of communication as  
24 far as when this was occurring? Did you get a feel so you  
25 knew whether something was going to be transferred?



1 MR. RATHBUN: I remember some communications going  
2 on, like before each UPS that he tried. It seems to me he  
3 was using the radio, and I can't remember if he was talking  
4 to the CSO or if the CSO had assigned one of the other  
5 reactor operators to stand over by the panel and monitor the  
6 electric plant. I think about that time I was walking down  
7 the back panels in the control room. This would have been  
8 out on the front panel section. But I'm not certain.

9 MR. JORDAN: You mentioned -- was it a testable  
10 check valve?

11 MR. RATHBUN: Yes.

12 MR. JORDAN: A testable check valve that was open?

13 MR. RATHBUN: Yes.

14 MR. JORDAN: And it probably should have been  
15 closed. Do you know what system that was on?

16 MR. RATHBUN: Yes. That was on RCIC. There are  
17 two testable check valves, one inside and one outside the  
18 containment, and the one outside was indicating full open.  
19 I checked the bulb, and it wasn't burned out. The one  
20 inside the containment was indicating full shut, and the  
21 injection valve was indicating full shut.

22 MR. JORDAN: Do you know how long that lasted?  
23 You were there most of the day. Was it fixed?

24 MR. RATHBUN: Sometime after I took the shift --  
25 or just before I took the shift, they had sent an operator





1 out. They put a hold-out or a mark-up on the injection  
2 valve, de-energized it shut, to comply with the tech spec  
3 for containment penetration. And they wrote a WR to get  
4 that worked. I remember seeing a reference tag hanging on  
5 it when I was doing a turnover with the offgoing CSO.

6 MR. JORDAN: Do you know about what time you  
7 identified the problem or you noticed it?

8 MR. RATHBUN: It would have been shortly after 10.  
9 I noticed it when I was walking down the panels prior to  
10 relief. I'd say someplace between 5 after and 10 after 10.

11 MR. JORDAN: When you installed the jumpers --  
12 this is going back again --

13 MR. RATHBUN: No problem.

14 MR. JORDAN: -- on the 609 and 611, is that jumper  
15 out just the level, or does that jumper all the logic?

16 MR. RATHBUN: That jumpers all the RPS logic.

17 MR. JORDAN: All the RPS logic.

18 MR. RATHBUN: Right. The four jumpers together,  
19 that is.

20 MR. JORDAN: Okay.

21 MR. CONTE: I hope I'm not repeating myself: Did  
22 you ever see this before, in terms of loss of annunciators  
23 and the full-core display going out? Did I ask that  
24 question?

25 MR. RATHBUN: Yes. You asked that. The answer



1 was no, I don't ever recall seeing it.

2 MR. CONTE: Okay. I guess I did repeat myself.

3 MR. RATHBUN: That's okay.

4 MR. CONTE: There was a report of water hammer in  
5 reactor water cleanup and the rad waste line from RHR later  
6 in the way.

7 MR. RATHBUN: Right.

8 MR. CONTE: What do you know about those? Was it  
9 just a report? Was it confirmed?

10 MR. RATHBUN: Well, on the one for RHR, that was  
11 when we were flushing to try to put shutdown cooling in  
12 service. That was after I had relieved the CSO, and I was  
13 now the active CSO. One of the operators was out in the  
14 plant. I can't remember what he was sent out to do. He  
15 heard these banging noises coming from the floor below him,  
16 and he went down to investigate and called from there. I  
17 could hear him in the background, through the phone.

18 The cleanup ones -- again, there were some  
19 operators up at the cleanup panel attempting to backflush,  
20 backwash, and precoat a filter. They heard noises again  
21 from the floor below them and went down to investigate.  
22 That particular one -- I had been out in the plant, doing  
23 the venting when restarting the cleanup system to do the  
24 warm-up and heard very loud bangs coming from the system.

25 MR. CONTE: Are you saying that the reports of the



1 water hammer are coming from the same system?

2 MR. RATHBUN: No, two separate systems.

3 MR. CONTE: Two separate systems.

4 MR. RATHBUN: Reactor water cleanup --

5 MR. CONTE: Reactor water cleanup was the  
6 backflush for precoating the demineralizers.

7 MR. RATHBUN: Right, and at the same time we were  
8 starting the pump -- this was just prior to the isolation,  
9 just after they started the pump and before the isolation  
10 occurred.

11 MR. CONTE: And the other area is the rad waste  
12 line for flushing the shutdown cooling system, or RHR.

13 MR. RATHBUN: I'm not sure which part of the  
14 system had the water hammer or banging noises, but it was  
15 the shutdown cooling system when we were doing the warm-up  
16 of it, which takes water from the reactor and flushes it  
17 through the system to rad waste.

18 MR. JORDAN: Do you know who the operators were?

19 MR. RATHBUN: For which system?


20 MR. JORDAN: For the RHR.

21 MR. RATHBUN: Pat Brennan.

22 MR. CONTE: How about reactor water cleanup?

23 MR. RATHBUN: Cleanup was two non-LOTS and I am  
24 not entirely certain who it was.

25 I can tell you who I think it was, but I am not



1 sure whether that is true or not.

2 MR. CONTE: Have you seen this before or heard  
3 this before or for both systems?

4 MR. RATHBUN: Not for shutdown cooling but for the  
5 other system, for cleanup, yes.

6 MR. CONTE: Were the people that you talked to,  
7 were they sure that this was water hammer?

8 MR. RATHBUN: I don't believe that either one of  
9 them used the term water hammer.

10 All they were saying is there is very loud banging  
11 noises. They weren't sure what we were doing or whatever  
12 but they felt we should be aware and maybe we need to do  
13 something.

14 MR. CONTE: But the noise was associated with  
15 starting a pump, doing something to assist them so the  
16 connection was obviously there?

17 MR. RATHBUN: Yes. I mean they could narrow down  
18 where the noise was coming from. In the cleanup one it was  
19 coming from the heat exchanger room. In the other case he  
20 wasn't sure exactly what it was coming from. He said it  
21 sounded like it was coming from the spent fuel pool cooling  
22 heat exchanger room, which has some piping -- what's the  
23 word I want? Pipe runs in it from that system. He knew  
24 that we were doing the warmup of the shutdown cooling lines  
25 and was wondering if that it what was causing it.





1 I don't believe either one of them I said used the  
2 term water hammer.

3 MR. CONTE: I don't have anything else. Mike?

4 MR. JORDAN: I don't have anything else.

5 MR. CONTE: We're off the record.

6 [Whereupon, at 2:08 p.m., the taking of the  
7 interview was concluded.]

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25



REPORTER'S CERTIFICATE

This is to certify that the attached proceedings before the United States Nuclear Regulatory Commission


in the matter of:

NAME OF PROCEEDING: Int. of DAVID RATHBUN

DOCKET NUMBER:

PLACE OF PROCEEDING: Scriba, N.Y.

were held as herein appears, and that this is the original transcript thereof for the file of the United States Nuclear Regulatory Commission taken by me and thereafter reduced to typewriting by me or under the direction of the court reporting company, and that the transcript is a true and accurate record of the foregoing proceedings.

  
\_\_\_\_\_  
JON HUNDLEY  
Official Reporter  
Ann Riley & Associates, Ltd.



ORIGINAL

07 -95A-91

OFFICIAL TRANSCRIPT OF PROCEEDINGS

Agency: Nuclear Regulatory Commission  
 Incident Investigation Team

Title: Nine Mile Point Nuclear Power Plant  
 Interview of: DAVID RATHBUN

Docket No.

LOCATION: Scriba, New York

DATE: Tuesday, August 20, 1991

PAGES: 1 - 31

ANN RILEY & ASSOCIATES, LTD.

1612 K St. N.W., Suite 300


Washington, D.C. 20006

(202) 293-3950.


9305070213 911031  
 PDR ADOCK 05000410  
 S PDR



305070213









UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION  
INCIDENT INVESTIGATION TEAM


1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25

-----  
Interview of :  
DAVID RATHBUN :  
(Closed) :  
-----

Conference Room B  
Administration Building  
Nine Mile Point Nuclear  
Power Plant, Unit Two  
Lake Road  
Scriba, New York 13093  
Tuesday, August 20, 1991

The interview commenced, pursuant to notice,  
at 1:25 p.m.

PRESENT FOR THE IIT:  
Michael Jordan, NRC  
Rich Conte, INPO  
PRESENT WITH MR. RATHBUN:  
Mike Colomb, Niagara Mohawk



## P R O C E E D I N G S

[1:25 p.m.]

1  
2  
3 MR. JORDAN: It's August 20, 1991. It's 1:25 p.m.  
4 We're at the Nine Mile Point Unit One nuclear power station,  
5 in the P building. We are going to cover events of a  
6 transient that occurred on August 13, 1991. My name is  
7 Michael Jordan, with the U.S. NRC, out of Region III.

8 MR. CONTE: I'm Rich Conte, Region I.

9 MR. RATHBUN: My name is David Rathbun, reactor  
10 operator at Nine Mile Point Unit Two.

11 MR. COLOMB: My name is Mike Colomb. I work for  
12 Niagara Mohawk Power Corporation. I'm the operations  
13 manager at Unit Two.


14 MR. JORDAN: We're here to interview Dave Rathbun.

15 Dave, why don't you start out and tell us what's  
16 your experience in your site here? What experience do you  
17 have? What's your background?

18 MR. RATHBUN: I was a Navy nuke for six years,  
19 reactor operator. I joined Niagara Mohawk in 1982. I  
20 licensed on Unit One, went over to Unit Two, and licensed at  
21 Unit Two, reactor operator. For the past six months or so,  
22 I've been a chief shift operator on F shift.

23 I'm not sure what else you'd like me to say.

24 MR. CONTE: When did you get your license in Unit  
25 Two?



1 MR. RATHBUN: I can't remember exactly, to be  
2 honest.

3 MR. CONTE: What year?

4 MR. RATHBUN: That's what I'm trying to remember.  
5 I can't even remember the year, to be honest. I'd say  
6 about five years ago, or so.

7 MR. JORDAN: You're currently licensed?

8 MR. RATHBUN: Yes.

9 MR. JORDAN: Okay, Dave. Why don't you go ahead  
10 and tell us in your own words, then, what you saw and how  
11 you saw the event transpire?

12 MR. RATHBUN: Okay. I was coming in to relieve  
13 the on-shift chief shift operator. I walked into the  
14 control room at approximately 6 o'clock. The incident had  
15 already started, and I arrived prior to the re-energizing of  
16 the uninterruptable power supplies.

17 Shortly after I walked into the control room, I  
18 made the SSS aware that I was available, and he requested  
19 that I use EOP 6, attachment 14, to attempt to -- I'm trying  
20 to think of the word I want to use -- locate whether or not  
21 the rods were full in or not. This was still when we had no  
22 indication of the position of rods. I looked through the  
23 procedure. At the time, I could only see one thing that  
24 might help, and that was to verify locally that the scram  
25 air-header was depressurized. I suggested that to the SSS,



1 and he agreed, and we sent a non-licensed operator out to  
2 check on that.

3           Before he could report back, we recovered power on  
4 the uninterruptable power supplies, at which time we  
5 regained some of the rod indication systems. Myself and  
6 another operator then, using both the rod sequence  
7 controller and the full core display -- some rods didn't  
8 show full in on both of those, and they weren't exactly the  
9 same, so we went through and checked the rods that weren't  
10 indicating full in on RSCS against the full-core display,  
11 and out of that came up with six rods that were not  
12 indicating full in on both of them. We selected those rods  
13 using the rod select matrix, to try to use the full-rod  
14 display to find where the rods were, and got blanks on all  
15 of them, so we still didn't know.

16           We reported that to the SSS, and at that time I  
17 suggested to the SSS that perhaps these rods are over-driven  
18 in by the scram. If we reset the scram, we may be able to  
19 let the rods settle and get good indication on them. The  
20 only problem with that was that at the time the reactor  
21 vessel level was less than level 3, which is a scram signal.

22           The assistant SSS, STA, reminded both of us that  
23 he had authorized use of attachment 14, which gives guidance  
24 for defeating RPS interlocks to allow resetting scrams to do  
25 repeated scram signals to insert rods that are not full in.





1 The SSS directed me, then, to insert those jumpers and reset  
2 the scram.

3 I used attachment 14, took it in the back of the  
4 control room with me, and inserted the jumpers in 609 panel  
5 and 611 panel. Also using the procedure, I came back out  
6 front and reset alternate rod insertion, reset the scram.  
7 At that point we got indication of all rods in on the full-  
8 core display and RSCS, and we reported that to the SSS.

9 I wasn't really given any more duties after that.  
10 I answered the phones occasionally and helped direct some of  
11 the non-LOTs on lesser tasks out in the plant, as far as  
12 trying to regain some of the things for a normal shutdown,  
13 try to get the plant back in a more normal configuration.

14 I worked with one of the oncoming STAs to try to  
15 get the plant computers back, to get help from the TSC or  
16 the OSC, whichever it was, for the computer techs. Once the  
17 SPDS computer was back, I reinitialized the EOF so that they  
18 could make use of the SPDS computer.

19 At one point in time I was asked to look at the  
20 Division 2 H2O2 monitor. Basically, all that was wrong with  
21 it was that the pump was not running, and we weren't sure at  
22 that time why it was not running. The valves were still all  
23 lined up; we had not taken the containment isolation; and  
24 the SSS wanted that on line so we could have accurate  
25 indication of if anything was going wrong in the primary



1 containment, so at his direction I restarted that pump.

2 At approximately 10:17, I relieved the CSO, who  
3 had been there. He took the log in to write in all of the  
4 things that had gone on during his time in the control room,  
5 and I had a non-LOT write down and be my scribe for a while,  
6 until I could get the log back. We just continued the cool-  
7 down, put shutdown cooling in service.

8 We attempted to put clean-up in service and  
9 encountered a problem with that, where it isolated. At that  
10 time, the SSS, which by now had also been relieved as a new  
11 SSS, made the determination that we were not going to worry  
12 about clean-up for a while, till it cooled down.

13 That's pretty much it. I left before they down-  
14 graded the emergency from a site area emergency.

15 MR. JORDAN: A couple questions.

16 You mentioned that the RSCS and the full core  
17 display and the rod worth minimizer were indicating rods not  
18 full in. Can you give me an idea of the RSCS and the full  
19 core display were indicating the same number of rods and the  
20 same rods? Or were they different rods, was the RSCS and  
21 the full core display indicating different rods?

22 MR. RATHBUN: The RSCS was indicating quite a bit  
23 more than the six rods that we ended up with -- excuse me.  
24 I don't remember exactly how many. There was one operator  
25 that was looking at that, the one that I was helping. He



1 used the RSCS as a guide.

2 He went, you know, would break down the rows on  
3 that display and when he came to a blank where there should  
4 have been a full in light. He'd read that number off and  
5 I'd check that number on the full core display, whether or  
6 not it had full in lights.

7 It seemed to me that there were other rods that  
8 had, that did not have full in lights on the full core  
9 display but that he had full in lights on the RSCS.

10 Between the two of them, there were only six that  
11 showed not full in on both of them together.

12 MR. JORDAN: How about the rod worth minimizer?

13 MR. RATHBUN: Rod worth minimizer, the new rod  
14 worth minimizer has a confirmed shutdown option or thing you  
15 can select. When power came back it was in the normal  
16 display. I had to select that confirmed shutdown and when I  
17 did, it said "shutdown, no; all rods in, no; number of rods  
18 not full in, 1" and then there is another button you can  
19 press to give a list.

20 I pressed that button and it gave me one rod  
21 number, of which I don't remember the exact number. It was  
22 1830-something I think, and anyway it said that it thought  
23 that rod was full in but it was giving it as the rod that it  
24 thought was not full in.

25 After we reset the scram and RSCS and the full



1 core display both said all rods were full in, the rod worth  
2 minimizer also agreed with that and said "shutdown, yes" and  
3 "all rods full in, yes."

4 MR. JORDAN: Was 18-whatever it is, 1830-  
5 something, was that one of the rods that --

6 MR. RATHBUN: No. That was not one of the six  
7 rods. We checked that against our list.

8 MR. JORDAN: Okay. You say you selected those  
9 rods, the six rods on the four rod display?

10 MR. RATHBUN: Uh-huh [affirmative].

11 MR. JORDAN: And they indicated?

12 MR. RATHBUN: Blanks.

13 MR. JORDAN: Just blanks?

14 MR. RATHBUN: Right.

15 MR. JORDAN: The rest of the rods on full core  
16 display, did they indicate blanks also?

17 MR. RATHBUN: I don't remember seeing any zeroes  
18 on it but I wasn't really looking for them so I am not  
19 really sure.

20 MR. CONTE: What do you normally get in the over-  
21 travel situation where it is too far in?

22 MR. RATHBUN: We've had this kind of indication  
23 before on these. That's why I --

24 MR. CONTE: Do you get blanks or xx or what?

25 MR. RATHBUN: Not blanks, xx's if the read switch





1 isn't making up and the reactor manual control system doubts  
2 the read switch or doesn't, has it open for read switch.

3           There is a read switch for overtravel in which is  
4 -- I am not exactly sure now if it picks up the green light  
5 but we've had, I have seen it before on scrams, until you  
6 reset it where they're pushed in farther to zero-zero and  
7 the zero-zero doesn't show up on the four rod display.

8           MR. CONTE: What does show up?

9           MR. RATHBUN: Just blanks, like I saw there.

10          MR. CONTE: What about the green light? What did  
11 you say about that?

12          MR. RATHBUN: The green lights would be up on the  
13 full core display.

14          MR. JORDAN: You say those are, on an overtravel  
15 they are still lit or they are not lit?

16          MR. RATHBUN: Some of them were and some of them  
17 weren't. I don't remember exactly. They came in when we  
18 reset the scram and the rods were able to settle back in the  
19 past.

20          MR. JORDAN: How about in the past, when you had  
21 indication on the four --

22          MR. RATHBUN: Well, it was pretty much kind of  
23 like this where some would and some wouldn't. It was never  
24 the whole core, never, you know, didn't show full in. It  
25 was only some of the rods.



1 MR. CONTE: How much do you know about the power  
2 supply to those read switches in terms of where they get  
3 power?

4 MR. RATHBUN: RPIS.

5 MR. CONTE: If you don't know --

6 MR. RATHBUN: I wouldn't be able to give it to you  
7 from memory. I know I have gone through the GE prints for  
8 that system looking up power supplies to make changes to our  
9 procedure because they didn't have it in it quite a while  
10 back, a year or so ago, and I was writing markups a lot and  
11 needed one of them.

12 I can't give you a definite answer but I know that  
13 it comes off, most of the stuff in that system comes off of  
14 a main breaker, one or two main breakers in the panel. Its  
15 ultimate power supply in the plant I am not really sure.

16 MR. CONTE: Was it a surprise to you based on your  
17 training here at Nine Mile that you would get a loss of  
18 annunciators and an accompanying full core display out,  
19 being black like that? Have you ever seen that before in  
20 training on the simulator or either at startup testing or--

21 MR. RATHBUN: Not to my recollection, no.

22 MR. CONTE: Okay. I had some questions as you  
23 were running down the chronology. Let's go back to the  
24 start of this thing.

25 How do you know it was six o'clock that you walked



1 into the control room? Was it before the site emergency was  
2 declared?

3 MR. RATHBUN: When I walked in, I walked in from  
4 the back of the control room, and just as I walked through  
5 into the front part of the control room between Panel 602  
6 and 601, the SSS site emergency director was announcing, you  
7 know, let me have your attention, I am going to declare a  
8 site area emergency.

9 That was just as I walked through is when he said  
10 that. I know it was a few minutes to or after 6:00 just from  
11 what time it was on my clock radio and I was in the parking  
12 lot and just ready to walk in.

13 MR. CONTE: Could you retrace the path walking in,  
14 primarily when you entered Unit Two, what areas were dark?

15 MR. RATHBUN: Sure. I didn't notice anything in  
16 the security building at all or out in the parking lot or on  
17 the way in.


18 When I walked into the CO2 room I noticed that  
19 part fo the lights, about half of the lights were off.

20 MR. CONTE: CO2 room, what building and elevation  
21 was that?

22 MR. RATHBUN: That is auxiliary service building  
23 south, elevation 261.

24 Those lights there --

25 MR. CONTE: Had some lights on.



1 MR. RATHBUN: Right. Those lights, I don't know  
2 why, but for some reason they get turned off a lot. There's  
3 like half the lights in there on a light switch and half of  
4 them are on another contactor, so I tried to turn them on  
5 and I got no response.

6 MR. CONTE: Oh, okay.

7 MR. RATHBUN: Interesting, I'll have to remember  
8 this when I go upstairs and ask about it.

9 I walked from there into the access passageway.

10 You step into it and then turn a corner and go  
11 through another door and I noticed again a lot of the lights  
12 were out. It's a very long passageway.

13 MR. CONTE: Access passageway, what building?  
14 Same building?

15 MR. RATHBUN: No, that's basically what it's  
16 called, access passageway or electric bay. It's a long  
17 passageway between Unit One heading towards Unit Two -- Unit  
18 Two going to Unit One, I'm sorry.

19 MR. CONTE: Oh, is that where we go to go to the  
20 cafeteria?

21 MR. RATHBUN: Yes, that long hallway.

22 MR. CONTE: I was wondering what you called that,  
23 okay.

24 MR. JORDAN: If I could back up just for a second.  
25 You say in the CO2 room you --





1 MR. RATHBUN: -- attempted --

2 MR. JORDAN: With the light switch?

3 MR. RATHBUN: Right.

4 MR. JORDAN: The lights did not come on or as a

5 result of operating the lights that were in there did they

6 go off?

7 MR. RATHBUN: Nothing happened.

8 MR. JORDAN: Nothing happened?

9 MR. RATHBUN: Nothing at all.

10 MR. JORDAN: Okay.

11 MR. RATHBUN: Okay, so from there I turned and --

12 MR. CONTE: What was the condition in the access

13 passageway with the lights?

14 MR. RATHBUN: A lot of the lights were out, yes.

15 MR. CONTE: A lot of the lights were out, but not

16 black?

17 MR. RATHBUN: No. There was a few lights on.

18 MR. CONTE: Any emergency lighting on?

19 MR. RATHBUN: I didn't notice any in either of

20 these two buildings.

21 I went into the door into the -- I guess it would

22 be in the turbine building where the elevator is. Again

23 about half of the lights were out. There's like three lights

24 in that area and like two of them were on and one was off.

25 MR. CONTE: I'm sorry, I missed that area again.



1 MR. RATHBUN: The turbine building, I believe it  
2 is, 261 -- where the elevator is and the stairwell.

3 Elevator arrived and the lights were all out in  
4 the elevator including the emergency lights and I rode the  
5 elevator up --

6 MR. CONTE: Did you see people coming out of that  
7 elevator?

8 MR. RATHBUN: Yes. There were a couple of non-  
9 licensed operators who came out of the elevator --

10 MR. CONTE: Do you remember their names?


11 MR. RATHBUN: -- in a little bit of a hurry --  
12 only one of them, Tom Restuccio. I don't remember who the  
13 other one was.

14 MR. CONTE: Okay.

15 MR. RATHBUN: And I asked something like "Is  
16 everything okay?" One of them said no, which I had begun to  
17 suspect already.

18 I think one of them said something about, the  
19 reactor had scrambled at that point in time. I rode the  
20 elevator up. The elevator operating lights for the floors  
21 and the buttons all worked, but the lighting in there was  
22 not working, and the emergency lights in there were not  
23 working.

24 Up to elevation 306. Again, most of the lights  
25 were out.



1 MR. CONTE: Elevation 306, what building?

2 MR. RATHBUN: Same building, turbine building.

3 This is by the RP office and the access to go into the  
4 turbine building on 306. I walked over to the doors, into  
5 the control building, carded in there. The card reader  
6 still worked.

7 MR. CONTE: Did you see anything unusual in the  
8 lighting in the control building?

9 MR. RATHBUN: Yes. Got into the control building.  
10 As I recall, the hallway in the control building looked  
11 normal. I carded into the control room, and I didn't notice  
12 anything as far as lighting out in the control room. Then I  
13 walked up between the panels and into the front, like I  
14 said before, just in time for the SED to make his emergency  
15 declaration.

16 MR. CONTE: Going further on, you said that one of  
17 the SSS sent down an RO to verify locally the scram header  
18 depressurization. Do you know who that RO was?

19 MR. RATHBUN: It was a non-licensed operator I  
20 sent out. That was Dave Brockwell.

21 MR. CONTE: Where does he have to go to see this?

22 MR. RATHBUN: That would be reactor building, 261  
23 elevation. We researched on the prints for this system and  
24 found an indicator off the scram air header that we believed  
25 was in an instrument rack down there near the CRD flow



1 control station.

2 MR. CONTE: Do you remember when he reported back?

3 MR. RATHBUN: No. I never heard a report back  
4 from him personally. Later on I had asked if anybody had  
5 seen him, because I hadn't seen him in a while, and he had  
6 been sent down to help start up the auxiliary boilers.

7 MR. CONTE: You mentioned you wanted to reset the  
8 scram; you had made a suggestion to reset the scram because  
9 you thought the scram pressure was pushing the rods too far  
10 in. You had the level 3 in, which was the low-level scram  
11 setting --

12 MR. RATHBUN: Right.


13 MR. CONTE: -- and someone reminded you -- and I  
14 didn't catch the name -- that you can defeat an RPS  
15 interlock.

16 MR. RATHBUN: That was the STA, Mike Eron.

17 MR. CONTE: Okay. What did he say? You can  
18 defeat an interlock?

19 MR. RATHBUN: Well, what he said, basically, was  
20 that Mike Conway, who was the SSS-SED, had already told me  
21 to use attachment 14 -- he had authorized the use of  
22 that -- and that one of the sections in that gives guidance  
23 for bypassing the RPS interlocks in order to reset scrams.

24 MR. CONTE: And you were basically getting ready  
25 to follow that attachment.





1 MR. RATHBUN: Right.

2 Mike took a moment to think about it and said,  
3 Yes, that's what I want to do, told me to do that.

4 MR. CONTE: Did you do that?

5 MR. RATHBUN: Yes, I did. Four jumpers in the  
6 back of the panel, and I installed them.

7 MR. CONTE: Okay.

8 MR. JORDAN: The only scram signal that was  
9 preventing you from resetting the scram that you know of was  
10 the low level?

11 MR. RATHBUN: Yes. Turbine trip, stop valve and  
12 control valve fast closures were in, but they were bypassed,  
13 and we had scram dump volume high level in at that point,  
14 which could be bypassed by the bypass switches, but the  
15 level one you can't bypass normally.

16 MR. JORDAN: And the level was --?

17 MR. RATHBUN: I'm not sure of the exact level at  
18 that time, but it was less than 159.3, the setpoint.


19 MR. JORDAN: So 159.3 is the scram setpoint?

20 MR. RATHBUN: Yes.

21 MR. CONTE: What panels -- you said the panels  
22 that you put the jumpers in were 609 and what?

23 MR. RATHBUN: 611.

24 MR. CONTE: You mentioned that Division 2 hydrogen  
25 and oxygen pumps not running. Is that a surprise to you?



1 MR. RATHBUN: I couldn't figure out any reason why  
2 it wouldn't have been running, nor the SSS -- or I should  
3 say SRO -- that was back looking at it with me. Nothing  
4 else on the system appeared to be other than normal  
5 operating. Like I said, there were no isolations, no valves  
6 out of position, just that the pump wasn't running.

7 MR. CONTE: Do you happen to know, based on your  
8 training and experience, whether or not those pumps are  
9 powered from vital or non-vital, or safety, sources?

10 MR. RATHBUN: They're powered from vital, safety-  
11 related -- they're a safety-related pump.

12 MR. CONTE: Okay.

13 Further on in the day, you mentioned, reactor  
14 water cleanup had isolated.


15 MR. RATHBUN: Yes.

16 MR. CONTE: What input signals indicated the  
17 isolation? What parameters caused the isolation?

18 MR. RATHBUN: The isolation occurred on the delta  
19 flow timers' timing out.

20 MR. CONTE: Could you give me a little explanation  
21 of what that's supposed to do?

22 MR. RATHBUN: Basically, it's a leak detection  
23 system looking at the flow coming into the system and the  
24 flow leaving the system, under the assumption that, if  
25 they're different, then it could indicate a leak -- more



1 flow coming in, not as much going out; the water has got to  
2 go somewhere. However, certain transients on the system can  
3 cause a difference in flow due to unstabilities and your  
4 changing the parameters of the system, the flows and what-  
5 no, so there's a timer associated with it.

6 MR. CONTE: I see. Okay.

7 When you're starting up reactor water cleanup, is  
8 that an unusual alarm, or a usual alarm?

9 MR. RATHBUN: It isn't that it necessarily happens  
10 every time, but it's not unusual, no. Usually they'll just  
11 come in and go right out.

12 MR. CONTE: I want to make sure I understand. The  
13 reactor water cleanup was on service at the time of the  
14 trip.

15 MR. RATHBUN: At the time of the trip it was in  
16 service.

17 MR. CONTE: What happened to it during the power  
18 outage time period? Do you happen to know?

19 MR. RATHBUN: Not really, no. I know that one of  
20 the immediate scram actions is to either place cleanup in  
21 the full reject mode or shut the pumps off. Most of the  
22 time we shut the pumps off because we don't have time to --  
23 it's somewhat of a lengthy process to put it into full  
24 reject mode. If there isn't time, usually, the SSS will  
25 simply say, Okay, turn it off.



1 MR. CONTE: So when you came up to the panels, the  
2 system was shut down.

3 MR. RATHBUN: The first time I had a chance to  
4 look at it, it was already shut down.

5 MR. CONTE: Okay. You were trying to start it up.

6 MR. RATHBUN: Yes. This was later. They wanted  
7 to put it in reject mode to aid in vessel level control

8 MR. CONTE: And when you were starting it up, you  
9 got the isolation signal.

10 MR. RATHBUN: Right.

11 MR. CONTE: You personally were doing this.

12 MR. RATHBUN: No, I was the CSO at that time. One  
13 of my control room reactor operators was doing that.

14 MR. CONTE: What's his name?

15 MR. RATHBUN: Jim Emery?


16 MR. COLOMB: He's on the list.

17 MR. CONTE: Was he following a procedure?

18 MR. RATHBUN: Yes, OP-37. I'm not entirely sure  
19 which section of it he was using.

20 MR. CONTE: Okay. So you basically abandoned  
21 trying to get it started again.

22 MR. RATHBUN: After it isolated, the SSS took a  
23 look at the system parameters and said that trying to put it  
24 in service at this point in time was not -- he didn't feel  
25 it a good idea; the system was still fairly hot, compared to





1 the reactor, and he didn't want to put it in service until  
2 it cooled down.

3 MR. CONTE: You were in the control room, I guess,  
4 from 6 o'clock on, right?


5 MR. RATHBUN: Yes.

6 MR. CONTE: Did you overhear the conversation  
7 with RCIC and what was happening with RCIC? Is there  
8 anything you remember about that? You weren't given  
9 responsibilities on that; I understand that.

10 MR. RATHBUN: Right.

11 I know that was an operator who was assigned level  
12 control using RCIC after they had determined the feed pumps  
13 had tripped and vessel level was lowering. I know later on  
14 they did have a problem with level. As pressure went down,  
15 the booster pumps -- it got down to the discharge head of  
16 the feedwater booster pumps -- condensate booster pumps, I  
17 should say -- and the feedwater level control valves were  
18 locked up in the open position. The operator at RCIC -- I  
19 was standing near him at one point in time -- was diverting  
20 flow from RCIC back to the full flow test to the CST, which  
21 cut off its contribution to the level increase, but the  
22 booster pumps were still going.

23 MR. CONTE: How was water going in from the  
24 booster pumps? The reg valves were locked up in  
25 an as-is --



1 MR. RATHBUN: Right. They were locked up open or  
2 throttled somewhere but fairly high open, probably. They  
3 locked up at 100 percent, I guess, when they lost power.  
4 I'm not real sure on that. I know they had to adjust things  
5 and reset the lock-outs on them.

6 MR. CONTE: RCIC was never tripped. He just  
7 diverted it to the suppression pool?

8 MR. RATHBUN: To the CST.

9 MR. CONTE: To the CST. I'm sorry.

10 MR. RATHBUN: When he diverted it to CST, level  
11 still rose until it reached 202.3 inches, which is the level  
12 8 setpoint, at which time the steam admission valve shut and  
13 the injection valve shut. I asked him if it was in standby,  
14 and he said basically they left it there when those two  
15 valves shut. They turned the -- what do I want to say? --  
16 test return valves closed.

17 Some time later on, probably 15 to 20 minutes  
18 later, I wandered by that panel and happened to notice that  
19 one of the testable checks was still indicating full open.  
20 I pointed that out to one of the STAs -- or SROs -- who was  
21 looking up different tech specs and what-not. I made sure  
22 they knew that. They had already known it and were looking  
23 at containment operability specs.

24 MR. CONTE: Until feed and condensate were  
25 restored, which I think was about 7:30 --



1 MR. RATHBUN: I don't remember the time, to be  
2 honest.

3 MR. CONTE: Whatever.

4 -- was RCIC the primary source of getting water  
5 into the plant? After this level transient -- for example,  
6 water came back down -- you had to keep feeding in order to  
7 maintain level; is that correct?

8 MR. RATHBUN: I'm not real sure on level. As you  
9 said, I wasn't assigned level. I remember at least one  
10 time they went low, and they started RCIC to recover level.  
11 I believe there was another time they had a lowering trend,  
12 and I'm not sure exactly what went on to recover that.

13 MR. CONTE: In this condition, to start it again  
14 you would just open the steam admission valve? Since it  
15 wasn't in a tripped condition.

16 MR. RATHBUN: I believe, unless it had got down to  
17 the initiation setpoint, you'd have to open the steam  
18 admission valve and open the injection valve.

19 MR. CONTE: But you weren't there at this point.

20 MR. RATHBUN: Right.

21 I was over trying to get how many rods were full  
22 in or weren't full in.

23 MR. CONTE: Later in the morning, I guess, a work  
24 party went out to restore some of the uninterruptable power  
25 supplies to normal.



1 MR. RATHBUN: Right.

2 MR. CONTE: From your vantage point in the control  
3 room, were you aware that that was happening? Did you hear  
4 anybody voice a concern about that?

5 MR. RATHBUN: Not really. The first thing I knew  
6 anything about it was that the full-core display came back,  
7 and a lot of annunciators came in and started flashing.

8 MR. CONTE: I'm sorry. I'm confusing you. You're  
9 back in 6:22 in the morning.

10 MR. RATHBUN: Right.

11 MR. CONTE: I'm talking about a time period later,  
12 in mid-morning.

13 MR. RATHBUN: Oh, when they put them on normal?

14 MR. CONTE: Yes.

15 MR. RATHBUN: Oh, okay.

16 MR. CONTE: Did you heard any discussion and  
17 concern about shifting back to normal?

18 MR. RATHBUN: I vaguely remember them talking  
19 about it. I don't recall what was said, to be honest. I do  
20 remember that one of the operators was directed to go out  
21 and attempt to line them back up to normal, and that they  
22 had problems with two of them and had to leave two of them  
23 on maintenance. I don't really recall the exact reasons  
24 why.

25 I do remember something being said about the order





1 that the SSS wanted them in. I don't remember what the  
2 order was exactly, except that I remember that the two that  
3 he had trouble with were the two that he wanted them to wait  
4 last on, make sure they could be reset -- I think C because  
5 it had like only communications and lighting on it, anyway;  
6 we had got them back at that point, because they were on  
7 maintenance, because if you lost it it wouldn't be too much  
8 of a problem. He wanted that to be the one that he tested,  
9 to try to put it in normal first.

10 MR. CONTE: Okay. Very good.

11 I'm all out of questions here.

12 MR. JORDAN: I've got just a couple.

13 MR. RATHBUN: Okay.

14 MR. JORDAN: When they transferred back to  
15 normal, did you see any bump, any change in any of the  
16 parameters, anything?

17 MR. RATHBUN: Nothing that I saw. I really wasn't  
18 up close to the panels at that time, monitoring. Sometime  
19 around there I was going around, trying to get a handle on  
20 what was going on, different people doing things so I could  
21 get a turnover from the off-going guys, so he could get a  
22 relief and fill his log out before he had to go home.

23 MR. JORDAN: Was there a lot of communication as  
24 far as when this was occurring? Did you get a feel so you  
25 knew whether something was going to be transferred?



1 MR. RATHBUN: I remember some communications going  
2 on, like before each UPS that he tried. It seems to me he  
3 was using the radio, and I can't remember if he was talking  
4 to the CSO or if the CSO had assigned one of the other  
5 reactor operators to stand over by the panel and monitor the  
6 electric plant. I think about that time I was walking down  
7 the back panels in the control room. This would have been  
8 out on the front panel section. But I'm not certain.

9 MR. JORDAN: You mentioned -- was it a testable  
10 check valve?

11 MR. RATHBUN: Yes.

12 MR. JORDAN: A testable check valve that was open?

13 MR. RATHBUN: Yes.

14 MR. JORDAN: And it probably should have been  
15 closed. Do you know what system that was on?

16 MR. RATHBUN: Yes. That was on RCIC. There are  
17 two testable check valves, one inside and one outside the  
18 containment, and the one outside was indicating full open.  
19 I checked the bulb, and it wasn't burned out. The one  
20 inside the containment was indicating full shut, and the  
21 injection valve was indicating full shut.

22 MR. JORDAN: Do you know how long that lasted?  
23 You were there most of the day. Was it fixed?

24 MR. RATHBUN: Sometime after I took the shift --  
25 or just before I took the shift, they had sent an operator



1 out. They put a hold-out or a mark-up on the injection  
2 valve, de-energized it shut, to comply with the tech spec  
3 for containment penetration. And they wrote a WR to get  
4 that worked. I remember seeing a reference tag hanging on  
5 it when I was doing a turnover with the offgoing CSO.

6 MR. JORDAN: Do you know about what time you  
7 identified the problem or you noticed it?

8 MR. RATHBUN: It would have been shortly after 10.  
9 I noticed it when I was walking down the panels prior to  
10 relief. I'd say someplace between 5 after and 10 after 10.

11 MR. JORDAN: When you installed the jumpers --  
12 this is going back again --

13 MR. RATHBUN: No problem.

14 MR. JORDAN: -- on the 609 and 611, is that jumper  
15 out just the level, or does that jumper all the logic?

16 MR. RATHBUN: That jumpers all the RPS logic.

17 MR. JORDAN: All the RPS logic.

18 MR. RATHBUN: Right. The four jumpers together,  
19 that is.

20 MR. JORDAN: Okay.

21 MR. CONTE: I hope I'm not repeating myself: Did  
22 you ever see this before, in terms of loss of annunciators  
23 and the full-core display going out? Did I ask that  
24 question?

25 MR. RATHBUN: Yes. You asked that. The answer



1 was no, I don't ever recall seeing it.

2 MR. CONTE: Okay. I guess I did repeat myself.

3 MR. RATHBUN: That's okay.

4 MR. CONTE: There was a report of water hammer in  
5 reactor water cleanup and the rad waste line from RHR later  
6 in the way.

7 MR. RATHBUN: Right.

8 MR. CONTE: What do you know about those? Was it  
9 just a report? Was it confirmed?

10 MR. RATHBUN: Well, on the one for RHR, that was  
11 when we were flushing to try to put shutdown cooling in  
12 service. That was after I had relieved the CSO, and I was  
13 now the active CSO. One of the operators was out in the  
14 plant. I can't remember what he was sent out to do. He  
15 heard these banging noises coming from the floor below him,  
16 and he went down to investigate and called from there. I  
17 could hear him in the background, through the phone.

18 The cleanup ones -- again, there were some  
19 operators up at the cleanup panel attempting to backflush,  
20 backwash, and precoat a filter. They heard noises again  
21 from the floor below them and went down to investigate.  
22 That particular one -- I had been out in the plant, doing  
23 the venting when restarting the cleanup system to do the  
24 warm-up and heard very loud bangs coming from the system.

25 MR. CONTE: Are you saying that the reports of the





1 water hammer are coming from the same system?

2 MR. RATHBUN: No, two separate systems.

3 MR. CONTE: Two separate systems.

4 MR. RATHBUN: Reactor water cleanup --

5 MR. CONTE: Reactor water cleanup was the  
6 backflush for precoating the demineralizers.

7 MR. RATHBUN: Right, and at the same time we were  
8 starting the pump -- this was just prior to the isolation,  
9 just after they started the pump and before the isolation  
10 occurred.

11 MR. CONTE: And the other area is the rad waste  
12 line for flushing the shutdown cooling system, or RHR.

13 MR. RATHBUN: I'm not sure which part of the  
14 system had the water hammer or banging noises, but it was  
15 the shutdown cooling system when we were doing the warm-up  
16 of it, which takes water from the reactor and flushes it  
17 through the system to rad waste.

18 MR. JORDAN: Do you know who the operators were?

19 MR. RATHBUN: For which system?

20 MR. JORDAN: For the RHR.

21 MR. RATHBUN: Pat Brennan.

22 MR. CONTE: How about reactor water cleanup?

23 MR. RATHBUN: Cleanup was two non-LOTS and I am  
24 not entirely certain who it was.

25 I can tell you who I think it was, but I am not



1 sure whether that is true or not.

2 MR. CONTE: Have you seen this before or heard  
3 this before or for both systems?

4 MR. RATHBUN: Not for shutdown cooling but for the  
5 other system, for cleanup, yes.

6 MR. CONTE: Were the people that you talked to,  
7 were they sure that this was water hammer?

8 MR. RATHBUN: I don't believe that either one of  
9 them used the term water hammer.

10 All they were saying is there is very loud banging  
11 noises. They weren't sure what we were doing or whatever  
12 but they felt we should be aware and maybe we need to do  
13 something.

14 MR. CONTE: But the noise was associated with  
15 starting a pump, doing something to assist them so the  
16 connection was obviously there?

17 MR. RATHBUN: Yes. I mean they could narrow down  
18 where the noise was coming from. In the cleanup one it was  
19 coming from the heat exchanger room. In the other case he  
20 wasn't sure exactly what it was coming from. He said it  
21 sounded like it was coming from the spent fuel pool cooling  
22 heat exchanger room, which has some piping -- what's the  
23 word I want? Pipe runs in it from that system. He knew  
24 that we were doing the warmup of the shutdown cooling lines  
25 and was wondering if that it what was causing it.



1

I don't believe either one of them I said used the



REPORTER'S CERTIFICATE

This is to certify that the attached proceedings before the United States Nuclear Regulatory Commission


in the matter of:

NAME OF PROCEEDING: Int. of DAVID RATHBUN

DOCKET NUMBER:

PLACE OF PROCEEDING: Scriba, N.Y.

were held as herein appears, and that this is the original transcript thereof for the file of the United States Nuclear Regulatory Commission taken by me and thereafter reduced to typewriting by me or under the direction of the court reporting company, and that the transcript is a true and accurate record of the foregoing proceedings.

  
\_\_\_\_\_  
JON HUNDLEY,  
Official Reporter  
Ann Riley & Associates, Ltd.



1 2 3 4 5 6 7 8 9 10

1 2 3 4 5 6 7 8 9 10



1 2

1 2 3 4 5 6 7 8 9 10

