Docket File



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

June 21, 1993

Docket No. 50-410

LICENSEE: Niagara Mohawk Power Corporation

FACILITY: Nine Mile Point Nuclear Station, Unit 2

SUBJECT: SUMMARY OF JUNE 10, 1993, MEETING TO DISCUSS THE INSPECTION AND

POSSIBLE REPAIR OF A FLAW IN HIGH PRESSURE CORE SPRAY NOZZLE

WELD KC-32 AT NINE MILE POINT NUCLEAR STATION, UNIT 2

A meeting was held in the NRC One White Flint North Office in Rockville, Maryland, with Niagara Mohawk Power Corporation (NMPC) and NRC staff representatives to discuss the inspection and possible repair of a flaw in the weld (KC-32) joining the high pressure core spray nozzle safe end to safe end extension at Nine Mile Point Unit 2 (NMP-2). The licensee had requested this meeting. Enclosure 1 is a list of meeting attendees. Enclosure 2 is a copy of the handout material provided by NMPC.

<u>BACKGROUND</u>

The flaw in weld KC-32 was discovered during the first NMP-2 refueling outage in October 1990 and subsequently treated with the Mechanical Stress Improvement Process (MSIP). Ultrasonic examination (UT) after MSIP showed an indication depth of 41 percent of the wall thickness and a length that was 11.3 percent of the weld circumference. Ultrasonic reexaminations midway through the second operating cycle and during the second refueling outage revealed no growth in the flaw. The staff has reviewed and approved NMPC submittals that provided justification for continued operations since discovery of the flaw. The staff's most recent letter regarding operations with the flaw was dated May 6, 1992.

In the letter of May 6, 1992, the staff agreed with NMPC's proposal to operate NMP-2 for up to 9700 hours during the current (third) operating cycle. Operations beyond 9700 hours required NMPC to either justify such operations prior to exceeding 9700 hours of operation or to repair or replace the weld prior to exceeding 9700 hours of operation. The staff's letter of May 6, 1992, noted that NMPC had committed to repair or replace weld KC-32 during the third refueling outage if it is not repaired or replaced during the third operating cycle.

By letter dated March 16, 1993, NMPC provided the staff with the results of a fracture mechanics analysis that provided a basis for operations beyond 9700 hours during the third operating cycle. The staff is currently evaluating this NMPC proposal for continued operations. The NMPC letter of March 16, 1993, also advised the staff that NMPC was reevaluating the merits of replacing the safe end extension during the third refueling outage. NMPC

9304290199 930421 PDR ADDCK 05000410

NAC FILE GENTICA GOPY

67.00TA

1

.

.

expressed concern at that time that replacement of the safe end extension, without fully evaluating other possible options, could result in excessive costs, significant radiation exposure, and extension of the refueling outage with no net safety gain. NMPC committed to provide additional information to the staff regarding these evaluations in the near future.

MEETING DISCUSSIONS

The NMPC representatives initially indicated that they intended to provide the staff with NMPC's assessment of the flaw in weld KC-32 and to discuss their commitment to replace the safe end during the third refueling outage. NMPC then reviewed the history of the flaw, including the UT examinations that have been performed. NMPC indicated that the weld was ultrasonically scanned many times during each examination and that both automated and manual UT data indicate that the flaw depth is no greater than 41 percent of the wall thickness, and not growing in length.

NMPC then discussed the results of a finite element inelastic analysis that considered welding residual stresses, MSIP application, and operating loads. The results of this analysis indicated that the flaw in weld KC-32 remains in the compressive stress region and that no further fracture mechanics analysis is necessary. NMPC stated that they intended to propose to the staff that the weld not be repaired during the third refueling outage if examination of the flaw shows no increase in length or depth. If any growth is observed, NMPC would then implement a weld overlay repair plan.

NMPC reviewed some of its incentives for repairing weld KC-32 instead of replacing it. For instance, repair would involve approximately 4.3 person rem of exposure, and replacement would involve about 43.75 person rem. Repair would increase critical path outage time by about 7 days and replacement would involve an increase of approximately 21 critical path days. NMPC also indicated that repair would not require cutting into the reactor coolant pressure boundary, and that the risks associated with implementing a repair are lower than those associated with replacement.

NMPC summarized their position relative to inspection and repair of the flaw near the conclusion of the meeting. Specifically, results of the finite element inelastic analysis and UT examinations indicate the flaw growth has been arrested. Based on mitigation of flaw growth, NMPC has reassessed its commitment to replace the safe end extension and will propose to repair the weld with an overlay during the third refueling outage if examination of the

•

.

:


flaw reveals growth in length or depth. No repair would be performed if the examination shows no increase in length or depth. NMPC indicated that a written submittal for the staff's consideration would likely be forwarded in 3 to 4 weeks.

John E. Menning, Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Enclosures:

- 1. List of Attendees
- 2. Licensee Handout Material

cc w/enclosures: See next page



Niagara Mohawk Power Corporation

cc:

Nine Mile Point Nuclear Station Unit No. 2

Mark J. Wetterhahn, Esquire Winston & Strawn 1400 L Street, NW. Washington, DC 20005-3502

Mr. Richard Goldsmith Syracuse University College of Law E. I. White Hall Campus Syracuse, New York 12223

Resident Inspector Nine Mile Point Nuclear Station P. O. Box 126 Lycoming, New York 13093

Gary D. Wilson, Esquire Niagara Mohawk Power Corporation 300 Erie Boulevard West Syracuse, New York 13202

Mr. David K. Greene Manager Licensing Niagara Mohawk Power Corporation 301 Plainfield Road Syracuse, New York 13212

Ms. Donna Ross New York State Energy Office 2 Empire State Plaza 16th Floor Albany, New York 12223

Supervisor Town of Scriba Route 8, Box 382 Oswego, New York 13126 Regional Administrator, Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Charles Donaldson, Esquire Assistant Attorney General New York Department of Law 120 Broadway New York, New York 10271

Mr. Richard M. Kessel Chair and Executive Director State Consumer Protection Board 99 Washington Avenue Albany, New York 12210

Mr. Martin J. McCormick Jr.
Plant Manager, Unit 2
Nine Mile Point Nuclear Station
Niagara Mohawk Power Corporation
P. O. Box 32
Lycoming, New York 13093

Mr. Neil S. Carns
Vice President - Nuclear Generation
Nine Mile Point Nuclear Station
Niagara Mohawk Power Corporation
P. O. Box 32
Lycoming, New York 13093

Mr. B. Ralph Sylvia Executive Vice President, Nuclear Niagara Mohawk Power Corporation 301 Plainfield Road Syracuse, New York 13212 •

June 10, 1993

Inspection and Possible Repair of a Flaw

in a High Pressure Core Spray Nozzle Weld

at Nine Mile Point Unit 2

ATTENDANCE LIST

| Name | |
|------|--|
| | |

Robert Capra John Menning Jack Strosnider Robert Hermann William Koo Robert McBrearty Carl Terry

Keith Ward

David Greene
W. David Baker
S. K. Dhar
Gary Wilson
Kenneth Korcz
John Swenskowski
Manu Badlani
Mark Wetterhahn
Michael Heath

<u>Position</u>


Project Director Project Manager Branch Chief Section Chief Sr. Materials Engineer Reactor Engineer Vice President -Nuclear Engineering Manager - Nuclear Engineering for Unit 2 Licensing Manager Program Director Engineer Attorney Licensing Engineer NDE Lead Consultant | Attorney ISI Project Manager

<u>Organization</u>

NRC/NRR/PDI-1 NRC/NRR/PDI-1 NRC/NRR/EMCB NRC/NRR/EMCB NRC/NRR/EMCB NRC/Region I Niagara Mohawk

Niagara Mohawk

Niagara Mohawk
Niagara Mohawk
Niagara Mohawk
Niagara Mohawk
Niagara Mohawk
Niagara Mohawk
A.A. O'Donnell
Winston and Strawn
General Electric



NIAGARA MOHAWK POWER CORPORATION


NINE MILE POINT NUCLEAR STATION

UNIT 2

HIGH PRESSURE CORE SPRAY SAFE END TO SAFE END EXTENSION WELD 2-RPV-KC32

JUNE 10, 1993





NIAGARA MOHAWK POWER CORPORATION HPCS CORE SPRAY NOZZLE MEETING AGENDA

JUNE 10, 1993

| | | SPEAKERS |
|------|---|------------------------------------|
| ¸I. | INTRODUCTION/PURPOSE | K. D. WARD |
| п. | BACKGROUND INFORMATION | K. D. WARD |
| III. | ULTRASONIC TESTING | M. HEATH (GENERAL ELECTRIC) |
| IV. | MECHÁNICAL STRESS IMPROVEMENT ANALYSIS | M. BADLANI (AEA O'DONNELL, INC) |
| V. | CONTINGENCY REPAIR PLAN | K. D. WARD |
| VI. | SUMMARY | K. D. WARD |


, ę W Å

PURPOSE

PURPOSE

TO PROVIDE NMPC'S ASSESSMENT OF THE HPCS SAFE END TO SAFE END EXTENSION WELD FLAW AND DISCUSS OUR COMMITMENT TO REPLACE THE SAFE END AT REFUEL OUTAGE 3:

- ◆ FLAW HAS BEEN ARRESTED BY MECHANICAL.
 STRESS IMPROVEMENT PROCESS
- ◆ REPAIR OR REPLACEMENT IS NOT REQUIRED PROVIDING THE PROPOSED INSPECTION ACCEPTANCE CRITERIA ARE MET
- ♦ REPAIR BY WELD OVERLAY IS ACCEPTABLE ALTERNATIVE TO REPLACEMENT SHOULD ACCEPTANCE CRITERIA NOT BE MET



BACKGROUND INFORMATION ON HPCS NOZZLE KC-32 FLAW

- ◆ FLAW WAS DISCOVERED DURING FIRST REFUELING OUTAGE IN-SERVICE INSPECTIONS (OCTOBER 1990). MECHANICAL STRESS IMPROVEMENT PROCESS (MSIP) WAS APPLIED TO MITIGATE CRACK GROWTH.
- ♦ INITIAL FRACTURE MECHANICS ANALYSIS SUBMITTED TO NRC ON DECEMBER 28, 1990. REVISED ANALYSIS SUBMITTED ON JUNE 28, 1991 TO:
 - ASSESS FLAW WITH AS-WELDED RESIDUAL STRESS FOR SMALL DIAMETER PIPE AS SPECIFIED IN NUREG 1061
 - INCREASE MAXIMUM UT INDICATION SIZE BY 5% IN DEPTH AND LENGTH TO ADD ADDITIONAL MARGIN
- ◆ RESPONSE TO NMPC IN NRC LETTER OF MAY 6, 1992, INDICATED NMPC'S COMMITMENT TO REPLACE SAFE END EXTENSION IN THE THIRD REFUELING OUTAGE
- ♦ NMPC HAS REEVALUATED REPLACEMENT OF SAFE END EXTENSION BASED ON SAFETY, EXPOSURE AND COST CONSIDERATIONS

z.


•

•

•


,

(HIGH PRESSURE CORE SPRAY)



6 3 • • • •

ULTRASONIC TESTING



ULTRASONIC EXAMINATIONS OF WELD 2-RPV-KC32


- ◆ UT EXAMINATIONS WERE PERFORMED IN ACCORDANCE WITH THE ASME SECTION XI CODE, WITH ENHANCEMENTS ENDORSED BY THE EPRI NDE CENTER
- ◆ ALL OF THE EXAMINERS, EQUIPMENT, AND PROCEDURES WERE QUALIFIED AT THE EPRINDE CENTER ON SAMPLES WITH ACTUAL CRACKS OF KNOWN DEPTHS
- ♦ IN ADDITION TO THE ABOVE, ALL (4) OF THE EXAMINERS OF RECORD WERE CERTIFIED LEVEL III'S IN THE ULTRASONIC METHOD

| | MAXIMUM RECORDED | | | | |
|---|------------------|--------------|--|--|--|
| INSPECTION | CRACK DEPTH | CRACK LENGTH | | | |
| 1ST REFUEL OUTAGE - POST MSIP (1990) | 41% (.35") | 11.3% (3.4") | | | |
| MID-CYCLE (1991) | 38% (.32") | 11.0% (3.3") | | | |
| 2ND REFUEL OUTAGE (1992) | 29% (.25") | 11.0% (3.3") | | | |

| | | | , ´ , |
|---|---|--|-------|
| | • | | - |
| | • | | |
| | • | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| • | | | |
| | | | |
| | | | |

ULTRASONIC EXAMINATIONS OF WELD 2-RPV-KC32 (Cont'd)

- ◆ VARIATIONS IN MAXIMUM DEPTH OF .1 INCH ARE NOT UNEXPECTED FOR A NARROW FLAW
- ♦ IN ADDITION TO THE SIZING EXAMINATIONS, OVER 30 AUTOMATED UT SCANS HAVE BEEN PERFORMED ON THIS WELD TO DATE
- ◆ NO TRANSDUCER READINGS HAVE SHOWN THIS INDICATION TO BE DEEPER THAN 41%T, AND (9) SEPARATE TRANSDUCER READINGS HAVE INDICATED THIS FLAW TO BE SHALLOWER
- ◆ EPRI PERSONNEL HAVE REVIEWED ALL OF THE COLLECTED DATA TO DATE, AND THEY CONCUR THAT THE VARIATION NOTED IS REASONABLE
- ♦ BOTH AUTOMATED AND MANUAL DATA INDICATE THE FLAW DEPTH TO BE NO DEEPER THAN 41%T, AND NOT GROWING IN THE LENGTH DIRECTIONS



ULTRASONIC EXAMINATIONS OF WELD 2-RPV-KC32 (Cont'd)


♦ BASED ON THE ABOVE, WE ARE CONFIDENT THAT THIS INDICATION IS NO DEEPER THAN 41%T AND IS NOT GROWING IN EITHER THE LENGTH OR DEPTH DIRECTIONS

| | • | • | , ^{, ,} , |
|--|---|---|--------------------|
| | | | - |
| | | | |
| | | , | |
| | | • | |
| | , | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

MSIP ANALYSIS

FOR

CORE SPRAY SAFE-END-TO-EXTENSION WELDMENT



VERIFICATION

ANALYSES

FINITE ELEMENT INELASTIC ANALYSIS

TESTS


- MgCl₂ TEST
 EPRI
- RESIDUAL STRESS MEASUREMENTS
 ARGONNE NATIONAL LABORATORY FOR NRC
 EPRI FOR BWR OWNERS GROUP

OPERATION

 PROCESS APPLIED FOR WELDMENTS WITH AND WITHOUT CRACKS FOR ABOUT 1,000 JOINTS

TESTS & OPERATION EXPERIENCE QUALIFIED THE METHOD OF ANALYSIS USED FOR INDIVIDUAL WELDMENTS

MARTIN MARIETTA KNOLLS & WESTINGHOUSE BETTIS VERIFICATION OF MECHANICAL STRESS IMPROVEMENT PROCESS FOR NAVY SPECIFICATION




USE OF MECHANICAL STRESS IMPROVEMENT PROCESS IN NUCLEAR PLANTS

| Utility | Plant | Year | Pipe & Fittings | Nozzles and S.E.s | Total | i Notes |
|--------------------------|-----------------------|---------|-----------------|----------------------|-------|---------|
| CECo | Dresden 3 | 1986 | 50 | 1 2 | 52 | ! |
| CECo | LaSalle 2 | 1987 | 1 25 | 29 | 54 | l |
| CECo | Quad Cities 1 | 1987 | ı 36 | 1 2 | 38 | i |
| CP&L | Brunswick 2 | 1988 | 1 0 | 15 | 15 | 1 |
| CECo | Quad Cities 2 | 1988 | 43 | 4 | 47 | Ī |
| Nuclenor | Santa Maria de Garona | 1988 | 24 | 0 | 24 | 1 |
| OKG Aktiebolag | Oskarshamn | 1988 | 1 | 0 | 1 | i 1 |
| CP&L | Brunswick 1 | 1988 | 1 0 | 10 | 10 | ! |
| CECo | LaSalle 1 | 1988 | 15 | 15 | 30 | ľ |
| CECo | LaSalle 2 | 1988 | 8 | 0 | 8 | |
| CECo | Dresden 2 | 1988 | 82 | 22 | 104 | 1 |
| PECo | Limerick 2 | 1989 | 2 | 16 | 18 | |
| Northeast | Millstone 1 | 1989 | 0 | 22 | 22 | |
| Detroit Edison | Fermi 2 | 1989 | 6 | 21 | 27 | |
| CECo | Quad Cities 1 | 1989 | 28 | 12 | 40 | |
| CP&L | Brunswick 2 | 1989/90 | 16 | 20 | 36 | 2 |
| CECo | Quad Cities 2 | 1990 | 30 | 14 | 44 | 2 |
| Teollisuuden Voima Oy | TVO | 1990 | 5 | 0 | 5 | |
| Niagara Mohawk | Nine Mile Pt 2 | 1990 | 0 | 1 | 1 | 1 |
| Taiwan Power Co | Kuosheng 2 | 1990 | 2 | 0 | 2 | 1 |
| CP&L | Brunswick 1 | 1990/91 | 10 | 24 | 34 | |
| Northeast | Millstone 1 | 1991 | 34 | 9 | 43 | |
| Iberdrola | Cofrentes | 1991 | 0 | 42 | 42 | |
| Boston Edison | Pilgrim 1 | 1991 | 16 | 0 | 16 | 2 |
| PECo | Peach Bottom 3 | 1991 | 10 | 0 1 | 10 | |
| PECo | Limerick 1 | 1992 | 0 | 7 | 7 | |
| Cleveland Elec | Perry 1 | 1992 | 0 | 27 | 27 | 1 |
| TVA | Browns Ferry 3 | 1992 | 81 | 29 | 110 | 2 |
| GPU | Oyster Creek | 1992 | 70 | 0 | 70 | 2 |
| Georgia Power | Hatch 1 | 1993 | 11 | 18 | 29 | |
| TVA | Browns Ferry 2 | 1993 | 12 | 0 | 12 | 2 |
| | Totals | 1 | 617 | 361 | 978 | |

Recent Application for PWR Inconel 600 Nozzles and Small Diameter Piping

Notes:


1) Some weldments with preexisting cracks
2) Weldments for replacement piping made of SCC immune materials





CRACKS ARRESTED BY MSIP

| NOMINAL PIPE SIZE | FLA LENGTH | AW SIZE DEPTH | CYCLES OF OPERATION |
|----------------------|---------------|------------------|---------------------------|
| 10" | 0.5" | .09" (15%) | 1 |
| 20" | 2.1" | 0.25" (20%) | 1 |
| 10" | 5.5" | 0.11" (16%) | 3 |

 $1^n = 25.4$ mm








ANALYSIS

INELASTIC FINITE ELEMENT ANALYSIS INCLUDING

- WELDING RESIDUAL STRESSES
- MSIP APPLICATION
- OPERATING LOADS

| | • | | • | , w , |
|---|-----|---|---|-------|
| • | | | | - |
| | | , | | |
| | | | | |
| , | | | | |
| • | | | | |
| | | | | |
| | | | | |
| | | | | |
| • | | | | 1 |
| | | | | |
| | | | | |
| • | · · | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | ÷ | |
| | | | | |








FIGURE 3.7 POST MSIP AXIAL STRESSES IN THE SAFE-END-TO-EXTENSION WELD (0.788% CONTRACTION)

• T .






FIGURE 3.11 POST MSIP AXIAL STRESSES WITH OPERATING LOADS INCLUDED FOR THE SAFE-END-TO-EXTENSION WELD (0.788% CONTRACTION)

• • , • • μ •




FAILURE ANALYSIS DIAGRAM




CONCLUSIONS

- INELASTIC ANALYSIS BASED ON THE ACTUAL POST-MSIP DISTRIBUTION CORRESPONDING TO FIELD MEASURED PIPE CONTRACTION INDICATES THAT THE CRACK REMAINS IN THE COMPRESSIVE REGION. NO FURTHER FRACTURE MECHANICS EVALUATION NECESSARY
- UT INSPECTIONS CONFIRM THAT CRACK HAS BEEN ARRESTED
- ANALYSIS RESULTS RECONFIRM THAT SAFE OPERATION CAN BE CONTINUED




INSPECTION CRITERIA



INSPECTION CRITERIA

- PROPOSING INSPECTION OF FLAW AT THE NEXT OUTAGE
 - ◆ IF DEPTH ≤ .41T AND LENGTH ≤ .113L, THEN NO FURTHER ACTION
 - ◆ IF DEPTH > .41T OR LENGTH > .113L, IMPLEMENT REPAIR PLAN
- COMPLETION OF THE CURRENT CYCLE WILL ENCOMPASS APPROXIMATELY 22,000 HOURS OF OPERATION

ı . •



•

.

•

•

COMPARISON OF REPLACEMENT AND REPAIR PLANS

| | REPLACEMENT | REPAIR |
|--|-------------|-------------|
| Exposure (manrem) | 43.75 | 4.3 |
| Increase in Critical Path Days During a Typical Refueling Outage | 21 | 7 |
| Cost (dollars)* | 1.5 million | 0.6 million |

- * Cost does not include loss of power generation revenue; due to increase in outage duration
- REPLACEMENT OPTION IS MUCH MORE SIGNIFICANT EVOLUTION THAN REPAIR
- THE REPLACEMENT REQUIRES COMPLETE DEFUELING AND DEWATERING OF VESSEL
- REPAIR PLAN DOES NOT REQUIRE CUTTING INTO REACTOR COOLANT PRESSURE BOUNDARY
- ASSOCIATED RISKS OF REPAIR PLAN ARE LOWER THAN REPLACEMENT PLAN

1 (1 tam) 0 0

•

e ·

la .

,

.

REPAIR PLAN

e De dam y

.

1

•

•

φ

W

REPAIR PLAN PROVIDES PRESSURE BOUNDARY COMPARABLE TO REPLACEMENT PLAN

- ◆ NMPC SUBMITTED WELD OVERLAY REPAIR PLAN JUNE 10, 1991, (NMP2L 1303) AND ADDRESSED STAFF'S CONCERNS IN MARCH 3, 1992, LETTER (NMP2L 1341)
- ♦ WELD OVERLAY IS LONG-TERM REPAIR
 - REPAIR WILL MEET DESIGN CRITERIA IN NUREG-0313, REV. 2
 - Crack Depth Assumed Through Wall
 - Crack Length Assumed to be 360° Circumference
 - Overlay Thickness has Factor of Safety of 3.0 Against Net Section Collapse for Normal and Upset Conditions
 - Factor of Safety of 1.5 is Maintained for Emergency and Faulted Conditions
 - Weld Design is a Full Structural Overlay
 - CERTIFIED DESIGN REPORT WILL DEMONSTRATE NEW CONFIGURATION MEETS FLAW EVALUATION CRITERIA OF 1986 ASME CODE, SECTION XI, IWB-3640, FOR CLASS 1 COMPONENTS

mes of 2

•

9

•

r.

•

.

SUMMARY

A CONTRACTOR OF THE PROPERTY O The first program of the second secon 1

•

CONCLUSIONS

- ◆ ANALYSIS BASED ON THE ACTUAL POST MSIP DISTRIBUTION CORRESPONDING TO FIELD MEASURED PIPE CONTRACTION INDICATES THAT THE CRACK REMAINS IN THE COMPRESSIVE REGION
- ♦ UT INSPECTIONS CONFIRM THAT CRACK HAS BEEN ARRESTED
- ♦ BASED ON MITIGATION OF CRACK GROWTH, NMPC HAS REASSESSED ITS COMMITMENT TO REPLACE THE SAFE END EXTENSION
- ◆ PROPOSING INSPECTION OF FLAW AT THE NEXT OUTAGE
 - IF DEPTH ≤.41T AND LENGTH ≤.113L, THEN NO FURTHER ACTION
 - IF DEPTH > .41T OR LENGTH > .113L, PROVIDE OVERLAY TO THE PIPE
- ♦ WELD OVERLAY IS AN ACCEPTABLE ALTERNATIVE TO REPLACEMENT

,

•

,

.

.

•

•

flaw reveals growth in length or depth. No repair would be performed if the examination shows no increase in length or depth. NMPC indicated that a written submittal for the staff's consideration would likely be forwarded in 3 to 4 weeks.

Original signed by:

John E. Menning, Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Enclosures:

- 1. List of Attendees
- 2. Licensee Handout Material.

cc w/enclosures: See next page

Distribution: w/handouts: Docket File NRC & Local PDRs PDI-1 Reading CCowgill, RGN-I JMenning ·

w/o handouts:

T. Murley/F. Miraglia, 12/G/18 J. Partlow, 12/G/18

S. Varga

J. Calvo

R. A. Capra

J. Menning C. Vogan

OGC

E. Jordan, MNBB 3701 J. Strosnider, 7/D/4

R. Hermann, 7/D/4

W. Koo, 7/D/4

R. McBrearty, RGN-I

ACRS (10)

V. McCree, EDO, 17/G/21

C. Cowgill, RGN-I

| LA:PDI-1MA | PM:PDI-1 | D:PDI-1 | | | |
|---------------|--------------|------------|-----|-----|-----|
| CVogan MV 105 | JMenning:smm | RACapra Ru | | | |
| 10 /21/93 | 6/21/93 | 6/21/93 | / / | / / | / / |

OFFICIAL RECORD COPY

Document Name: NM250410.MTS

, * ti . . . d 1 . •