

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9509280076 DOC. DATE: 95/09/22 NOTARIZED: NO DOCKET #
FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410
AUTH. NAME AUTHOR AFFILIATION
TERRY, C.D. Niagara Mohawk Power Corp.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards results of insps performed since mechanical stress improvement process applied in first refueling outage at facility for indication in weld joining HPCS nozzle safe end to safe-end extension (KC-32).

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
TITLE: OR Submittal: General Distribution

NOTES:


	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	PD1-1 LA		1	1	PD1-1 PD		1	1
	EDISON, G		1	1				
INTERNAL:	ACRS		6	6	<u>FILE CENTER</u> 01		1	1
	NRR/DE/EMCB		1	1	NRR/DRCH/HICB		1	1
	NRR/DSSA/SPLB		1	1	NRR/DSSA/SRXB		1	1
	NUDOCS-ABSTRACT		1	1	OGC/HDS3		1	0
EXTERNAL:	NOAC		1	1	NRC PDR		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 18 ENCL 17

MP



CARL D. TERRY
Vice President
Nuclear Engineering

September 22, 1995
NMP2L 1572

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

RE: Nine Mile Point Unit 2
Docket No. 50-410
NPF-69

*Subject: High Pressure Core Spray (HPCS) Nozzle Safe-End Extension (KC-32) Weld
Inspection Frequency*

Gentlemen:


During the first refueling outage at Nine Mile Point Unit 2 (NMP2), Niagara Mohawk Power Corporation (NMPC) identified an indication in the weld joining the High Pressure Core Spray (HPCS) nozzle safe end to the safe-end extension (KC-32) utilizing UT inspection techniques. After evaluating the indication, NMPC applied Mechanical Stress Improvement Process (MSIP) to improve the residual stress distribution in the region of the flaw to eliminate the potential for flaw growth. Subsequent to the application of MSIP, UT inspections were again performed during the first refueling outage, at a mid-cycle outage during the second fuel cycle and at the second, third, and fourth refueling outages. No growth in the flaw has been identified by these inspections as compared with the first post-MSIP UT inspection. NMPC has determined that the stabilization of the flaw is due to the application of MSIP which has maintained the flaw in compression.

By letter dated July 8, 1993, Niagara Mohawk committed to conduct a UT reinspection of the flaw at each subsequent refueling outage. NMP2 Technical Specification 4.0.5.f states that an inservice inspection program for piping identified in Generic Letter (GL) 88-01 shall be performed in accordance with Staff positions. In accordance with Generic Letter 88-01, "NRC Position on IGSCC in BWR Austenitic Stainless Steel Piping," KC-32 was categorized as an IGSCC Category "F" weld which, consistent with our commitment, requires that all indications be inspected every refueling outage. Welds that have been treated by stress improvement that are classified as IGSCC Category "F" because they do not meet the applicable Staff positions may be upgraded to Category "E" if no adverse change in crack condition is found after four successive examinations. Category "E" welds are examined once every other outage. Normally, the four successive exams would be conducted on a refueling outage cycle frequency.

230605

9509280076 950922
PDR ADCK 05000410
PDR

ADD 1/1



As indicated above, Niagara Mohawk has performed four successive examinations which indicate no adverse change in the cracking condition. One of the exams was performed at a mid-cycle frequency (as mandated by the Staff) and, consequently, only three of four exams were conducted during a refuel outage. However, Niagara Mohawk contends that the four exams indicate that MSIP has been effective in mitigating any crack growth and the intent of GL 88-01 has been met. Further exams will result in unnecessary radiation exposure while inspecting KC-32 at each outage. Accordingly, Niagara Mohawk requests Staff approval to recategorize KC-32 as a category "E" weld. Assuming Staff approval, the next scheduled exam will be refueling outage six. Attachment A provides the results of inspections performed since MSIP was applied in the first refueling outage.

Very truly yours,



C. D. Terry
Vice President - Nuclear Engineering

CDT/JMT/kap
Attachment

xc: Regional Administrator, Region I
Mr. L. B. Marsh, Director, Project Directorate I-1, NRR
Mr. G. E. Edison, Senior Project Manager, NRR
Mr. B. S. Norris, Senior Resident Inspector
Records Management



Handwritten scribbles and marks in the top right corner, possibly including the number '1'.

ATTACHMENT A

KC-32 Inspection Results

Inspection	Length/% of Internal Circumference		Depth/% of Wall Thickness
*Post-MSIP (RF01) (December 1990)	3.40" (11.3%)		0.35" (41%)
Midcycle (August 1991)	3.3" (10.9%)		0.32" (38%)
RFO-2 (April 1992)	2.6" Automated (8.6%)	3.3" Manual (10.9%)	0.25" (29%)
RFO-3 (October 1993)	2.5" Automated (8.3%)	3.0" Manual (9.9%)	0.25" (29%)
RFO-4 (May 1995)	2.5" Automated (8.3%)	3.0" Manual (9.9%)	0.30" (35%)

* Cannot be counted toward four successive examinations (i.e., the weld experienced no service).



Handwritten scribbles and marks in the top right corner.