

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO: 50-220

UNIT NAME: NMP#1

DATE: 6/4/96

PREPARED BY: D. E. Coleman

TELEPHONE: (315) 349-2558

REPORT MONTH - April 1996

| No. | Date | Type ¹ | Duration (Hours) | Reason ² | Method of Shutting Down Reactor ³ | Licensee Event Report # | System Code ⁴ | Component Code ⁵ | Cause & Corrective Action to Prevent Recurrence |
|-----|--------|-------------------|------------------|---------------------|--|-------------------------|--------------------------|-----------------------------|--|
| 3 | 960520 | F | 68.2 | A | 3 | 96-02 | | | The reactor scrammed on turbine trip due to high water level which was caused by failure of #13 feedwater flow control valve. The apparent cause of the failure of this valve is improper operation of the volume air booster resulting from accumulation of grease and residue on a needle valve and bypass port. |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

- | | | | | |
|--|--|---|---|---------------------------------------|
| <p>1</p> <p>F: Forced S: Scheduled</p> | <p>2</p> <p>Reason: A-Equipment Failure (Explain) B-Maintenance or Test C-Refueling D-Regulatory Restriction E-Operator Training & License Exam F-Administrative G-Operational Error (Explain) H-Other (Explain)</p> | <p>3</p> <p>Method: 1-Manual 2-Manual Scram 3-Automatic Scram 4-Other (Explain)</p> | <p>4</p> <p>Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)</p> | <p>5</p> <p>Exhibit I-Same Source</p> |
|--|--|---|---|---------------------------------------|

9606180528 960611
PDR ADOCK 05000220
R PDR

SECRET