

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO: 50-220

UNIT NAME: NMP#1

DATE: 6/4/96

PREPARED BY: D. E. Coleman

TELEPHONE: (315) 349-2558

REPORT MONTH - April 1996

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
3	960520	F	68.2	A	3	96-02			The reactor scrammed on turbine trip due to high water level which was caused by failure of #13 feedwater flow control valve. The apparent cause of the failure of this valve is improper operation of the volume air booster resulting from accumulation of grease and residue on a needle valve and bypass port.

<sup>1</sup>  
F: Forced  
S: Scheduled

<sup>2</sup>  
Reason:  
A-Equipment Failure (Explain)  
B-Maintenance or Test  
C-Refueling  
D-Regulatory Restriction  
E-Operator Training & License Exam  
F-Administrative  
G-Operational Error (Explain)  
H-Other (Explain)

<sup>3</sup>  
Method:  
1-Manual  
2-Manual Scram  
3-Automatic Scram  
4-Other (Explain)

<sup>4</sup>  
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

<sup>5</sup>  
Exhibit I-Same Source

9606180528 960611  
PDR ADOCK 05000220  
R PDR

SECRET