		CATE	GORY 1		
	REGULATORY	INFORMATION	DISTRIBUTION	EM (RIDS)	
ACCESSIO FACIL:5 AUTH.N BOSNIC, DAHLBER RECIP.	N NBR:9710030161 0-410 Nine Mile Po AME - AUTHOR D. Niagara G,K.A. Niagara NAME RECIPIE	DOC.DATE: 9 int Nuclear 9 AFFILIATION Mohawk Power Mohawk Power NT AFFILIATIO	97/09/26 NOTARIZED Station, Unit 2, Ni Corp. Corp. DN): NO .agara Moha	DOCKET # 05000410
SUBJECT	: LER 97-009-00:on control bldg rel technical review of control bldg	970827,deten ay room in su .Revised surv relay room &	mined failure to i rveillance.Caused eillance procedure completed testing.	nclude by inadequat re testing W/970926 ltr	e C
DISTRIB TITLE:	UTION CODE: IE22T 50.73/50.9 License	COPIES RECE e Event Repor	VED:LTR ENCL	SIZE: 5 Rpt, etc.	T
NOTES:					G
	RECIPIENT ID CODE/NAME PDI-1 PD	COPIES LTTR ENCL 1 1	RECIPIENT ID CODE/NAME HOOD,D	COPIES LTTR ENCL , 1 l	O
INTERNAL:	ACRS AEOD/SPD/RRAB NRR/DE/ECGB	1 1 .1 1 x	AEOD/SPD/RAB FILE CENTER NRR/DE/EELB	2 2 1 1 1 1	Y
	NRR/DE/EMEB NRR/DRCH/HICB NRR/DRCH/HQMB	$\begin{array}{ccc} 1 & 1 \\ 1 & 1 \\ 1 & 1 \\ 1 & 1 \end{array}$	NRR/DRCH/HHFB NRR/DRCH/HOLB NRR/DRPM/PECB		1
	RES/DET/EIB	1 1	RGN1 FILE 01		ס
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1	•

5

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS, OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

1

1

1

1.

NOAC POORE, W.

NRC PDR

,

AOY

0

C

U

M

Ε

N

т

1

1

1

1

NOAC QUEENER, DS

NUDOCS FULL TXT

· · ·

.

·

•

NIAGARA MOHAWK

GENERATION **BUSINESS GROUP**

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

September 26, 1997 NMP2L 1728

United States Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

RE: Docket No. 50-410 LER 97-09

Gentlemen:

In accordance with 10CFR50.73 (a)(2)(i)(B), we are submitting LER 97-09, "Missed Technical Specification Surveillance of the Control Room Envelope."

Very truly yours,

KA Jallber

Kim A. Dahlberg Plant Manager - NMP2

KAD/GJG/cmk Attachment

Mr. H. J. Miller, Regional Administrator, Region I
 Mr. B. S. Norris, Senior Resident Inspector
 Records Management

TExal,

030:59

9710030161 970926 PDR ADOCK 05000410 S PDR

. • • •

•

4

, • -*

• • • .

•

.

I

•

		_												· · · · ·			
NRC FORM 366 U.S. NUCLEAK REGULATORY COMMISSION						ATTROVED OMB NO. 3150-0104 EXPIRES: 4/30/92											
LICENSEE EVENT REPORT (LER)							ESTIMAT REQUES RECORD COMMIS (0150-010	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-S30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20235, AND TO THE PAPERWORK RESULTION PROJECT 01300100, OFFRED PM MANAGEMENT AND BUDGET, WASHINGTON, DC 20200									
PACILITY	NAME (I)	••				•		DOCKE	T NUMBER	<i>(</i> 2)				•	PAGE	3)	
Nine M	ile Poi	nt Uni	it 2					050	0041	0					1 OF	4	
TITLE (4) Missed Technical Specification Surveillance of the Control Room Envelope																	
EVE	NT DATE	ເທ			LER NUMBE	ж(б)			REPO	RT DA			OTHE	R FACILI	TES INVO	LVED (T)
MONTH	DAY	YEAI	r year	NAR H	SEQUENTIA NUMBER	L	REVIS NUME	ION M	юнтн	DAY	YEAR	FACIL	ITY NAME	s	DOCKET NUMBER(3)		
08	27	97	97		009		00		09	26	97	N/A		05000)	
					ι							N/A			0500	0	
0	PERATIN	O MODE	(9)	1	TH	IS REPOI	RT IS SUE	MITTED	PURSUANT	то тн	E REQUIREM	ENTS OF 10 C	FR f: (Chr	ck one or n	iore of the	following)	(11)
POWER	POWER LEVEL (10) Image: 20.402(b) Image: Image: 20.405(c) 95 Image: 20.405(a)(1)(i) Image: 20.405(c)					□ 50.73(a)(2)(iv) □ 73.71(b) □ 50.73(a)(2)(v) □ 73.71(c) □ 60.73(a)(2)(v) □ 73.71(c)											
			□ 20.405(□ 20.405(□ 20.405(□ 20.405(=)(1) n)(1) n)(1)	(ii) (iv) (v)		0.73(a)(0.73(a)(0.73(a)(0.73(a)((2)(i) (2)(ii) (2)(iii)			□ 50.73(a)(2)(vii) □ 50.73(a)(2)(viii)(A) □ 50.73(a)(2)(viii)(B) □ 50.73(a)(2)(x)			Greec(fr in Abstract below and in Text, N Form 366A)			d in Text, NRC
						•	LICENSE	E CONTA	CT FOR TI	AS LER	. (12)			1			
NAME										T			TELEPH	ONE NUM	BER		
Don Bosnic - Manager Operations Unit 2						Ī	(315) 349-7952										
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																	
CAUSE	573	TEM	COMPONEN	т	MANUFAC- TURER	REPOI TO I	RTABLE NPRDS	<u> Est</u>	СЛИ	SE SYSTEM COMPONENT MANUFA TURER		PAC-	REP	ORTABLE D NPRDS			
									×.				T				
			SUPPLEMENT	L RE	PORT EXPECT	ED (14)					EXPECT		MONTH		DAY YE		YEAR
U YES (V)	res, comple	u EXPE	CTED SUBMISSI	ON D.		NO				SUBMISSION DATE (15)							

1

ABSTRACT (Limit to 1400 spaces, Le., approximately fifteen single space typewritten lines) (16)

On August 27, 1997, Niagara Mohawk (NMPC) determined that the surveillance test which had been performed to meet Surveillance Requirement (SR) 4.7.3.e.2 of the Nine Mile Point Unit 2 (NMP2) Technical Specifications (TS) did not appropriately include testing of the control building relay room, which is included in the control room envelope as described in the NMP2 Updated Safety Analysis Report (USAR) Section 6.4.2. In addition, it was determined that the procedure did not test the redundant air conditioning units (ACU) in the required lineups.

The cause of failure to include the control building relay room in the surveillance and not test the system in the required ACU alignments has been determined to be inadequate technical review.

Both divisions of the control room outside air special filter train were declared inoperable. TS limiting condition for operations (LCO) 3.0.3 was entered but actions were delayed based upon TS SR 4.0.3. The surveillance procedure was revised to incorporate testing of the control building relay room and verification of ACU alignments. Testing was completed and the control room outside air special filter trains were declared operable.

, ,

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION			20VED OMB NO. 3130-0104 EXPIRES: 4/30/92									
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (I-S30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.									
FACILITY NAME (I) DOCKET NUMBER (2)			LER NUMBER (6)						PAGE ()			
			YEAR		SEQUENTIAL NUMBER	18. A.S.	REVISION NUMBER					
Nine Mile Point Unit 2	05000410		97	-	09	-	00	02	OF	04		
	NRC FORM 366A LICENSEE E TEXT C FACILITY NAME (I) Nine Mile Point Unit 2	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION FACILITY NAME (I) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATI REQUEST RECORDS COMMISS (0150-0104) FACILITY NAME (I) DOCKET NUMBER (2) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN REQUEST: 50.0 HRS. F RECORDS AND REPOR COMMISSION, WASHE (150-0104), OFFICE OF FACILITY NAME (I) DOCKET NUMBER (2) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN PER R REQUEST: 50.0 HRS, FORW/ RECORDS AND REPORTS M/ COMMISSION, WASHINGTON (150-0104), OFFICE OF MAN. FACILITY NAME (I) DOCKET NUMBER (2) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION ROUTED ON EXPIRE LICENSEE EVENT REPORT (LER) ESTIMATED BURDEN PER RESPONSE TO COMMENTS IN REQUEST: 50.0 HRS, FORWARD COMMENTS IN RECORDS AND REPORTS MANAGEMENT BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION, WASHINGTON, DC 20555, AND TO (150-0104), OFFICE OF MANAGEMENT AND BRACOMMISSION FACILITY NAME (I) DOCKET NUMBER (2) LER NUMBER Nine Mile Point Unit 2 0 5 0 0 0 4 1 0 9 7 0 9	NRC FORM 366A U.S. NUCLEOR REGULATORY COMMISSION ROVED OMB NO EXPRESS 4200 LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN PER RESPONSE TO COMPLY W REQUEST: 500 HBS. FORWARD COMMENTS REDAR RECORDS AND REPORTS MANAGEMENT BRANCH () COMMISSION, WASHINGTON, DC 2000, AND THE (1500 HOM, OFFICE OF MANAGEMENT AND BUDGET FACILITY NAME (I) PACELITY NAME (I) DOCKET NUMBER (2) VIEAR SEQUENTIAL NUMBER (9) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLESER REGULATORY COMMISSION COVED OMB NO. 3150-0104 LICENSEE EVENT REPORT (LER) ESTIMATED BURDEN PER RESIDENSE TO COMPLY WITH THIS INFOR REQUEST: 500 HRS. FORWARD COMMENTS RECARDING BURDEN FRECORDS AND REPORTS MANAGEMENT BRANCH (P-S30), U.S. NUCL COMMISSION, WASHENGTON, DC 20355, AND TO THE PAPERWORK R PACELITY NAME (I) DOCKET NUMBER (2) VEAR YEAR SEQUENTIAL Nine Mile Point Unit 2 0 5 0 0 0 4 1 0	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION Reversion LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN MER RESPONSE TO COMMENTS REGARDING BURDEN ESTIMATION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATION RECORDS AND REPORTS MANAGEMENT BRANCH (P-S30), U.S. NUCLEAR REPORTS MANAGEMENT AND BUDGET, WASHINGTON, DC 2005 (150-0104), OFFICE OF MANA	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION ROVED 0MB NO. 3150-0104 EXPIRES: 473092 LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLEC REQUEST: 50.0 HRS, FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (*530), U.S. NUCLEAR REGULATOR COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROTE (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503. FACILITY NAME (I) DOCKET NUMBER (2) LER NUMBER (6) PAGE (1) Nine Mile Point Unit 2 0 5 0 0 0 4 1 0 9 7 0 9 0 0 02 OF		

TEXT (If more space is required, use additional NRC Form 3664's) (17)

I. DESCRIPTION OF EVENT

On August 27, 1997, Niagara Mohawk determined that the surveillance test which had been implemented to meet Surveillance Requirement (SR) 4.7.3.e.2 of the Nine Mile Point Unit 2 (NMP2) Technical Specifications (TS) had not appropriately included testing of all areas considered to be within the control room envelope. Operations surveillance procedure N2-OSP-HVC-R001 (Control Room Outside Air Special Filter Train Functional Test) only verified that a positive 0.125 inch water gauge (WG) pressure was maintained in the control room. The control building relay room differential pressure had not been verified. In addition, since the ACUs provide some of the driving force to pressurize the Control Building, the surveillance did not demonstrate operability for all possible ACU alignments.

Immediately upon discovery of the missed surveillance, operations entered TS LCO 3.0.3. TS SR 4.0.3 was applicable, which allows actions to be delayed 24 hours for completion of the surveillance. Procedure N2-OSP-HVC-R001 was revised to include verification of the relay room differential pressure. The surveillance was performed on both divisions of control room outdoor air special filter trains. Division II successfully met the SR, but Division I failed to meet the SR. Since one control room filter train was operable, TS 3.0.3 and SR 4.0.3 were exited and TS 3.7.3 Action Statement "a" was entered, which allows seven days for repair. A one time only procedure change was then made to adjust balancing damper 2HVC*DMPV84. Surveillance procedure N2-OSP-HVC-R001 was reperformed on the Division I control room filter train which then successfully met the SR. The Division II control room filter train was then retested to verify that the SR was still met. On September 1, 1997, both trains were declared operable.

ļ

4

II. CAUSE OF EVENT

The cause of the failure to include the control building relay room in procedure N2-OSP-HVC-R001 has been determined to be inadequate technical review. A contributing factor is that NMP2 TS SR 4.7.3.e.2 requires that the "control room is maintained at a positive pressure of 0.125 inch WG relative to the outside atmosphere during subsystem operation at an outside air intake flow rate less than or equal to 1500 cfm." Previous reviewers did not interpret this to mean "control room envelope."

The failure to test all possible ACU alignments has also been determined to be inadequate technical review. When N2-OSP-HVC-R001 was developed and revised, personnel did not understand that the ACUs provide some of the pressurization to meet SR 4.7.3.e.2. Previously, personnel believed that pressurization was provided by the special filter train fans alone, and that the operation of the ACU was therefore not critical to demonstrating compliance with this SR.

• ·

.

•

ς.

. •

·

· · · .

· · · · ·

. * * *

1	***								_					
-	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION			OVED OMB NO. 3150-0104 EXPIRES: 4/30/92										
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (#-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.										
	FACILITY NAME (I)	DOCKET NUMBER (2)				LER NUMBER	ത്ര			PAGEO)			
	•			YEAR		SEQUENTIAL NUMBER	13. SE	REVISION NUMBER						
	Nine Mile Point Unit 2	05000410		97	-	09		00	03	OF	04			
ł		•			<u>, </u> ,		<u></u>		.					

TEXT (If more space is required, use additional NRC Form 366A's) (17)

III. ANALYSIS OF EVENT

This event is reportable in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation or condition prohibited by the plant's Technical Specifications". TS SR 4.7.3.e.2 requires that at least once per 18 months, operability of the control room outdoor air special filter trains be demonstrated by verifying that the filter trains automatically switch to the emergency pressurization mode of operation and the control room is maintained at a positive pressure of 0.125 inch WG relative to the outside atmosphere during subsystem operation at an outside air intake flow rate less than or equal to 1500 cfm. This SR had not been demonstrated for the control building relay room.

The results of the initial surveillance performed on August 27, 1997 for the combined control room and relay room were as follows:

· .	Control Room (inches WG)	Relay Room (inches WG)
Fan 2A (Division I)	0.25	0.10
Fan 2B (Division II)	0.30	0.15 - 0.175

As can be seen from these results, the control room and relay room were both at a positive pressure for both divisions. However, the relay room did not meet the acceptance criteria of 0.125 inch WG for Division I.

The purpose of maintaining the control room envelope at a positive pressure is to prevent infiltration of radioactivity or other harmful gases into the control room environment. Even though the Division I control room filter train did not meet the acceptance criteria, the initial surveillance demonstrated that a positive pressure was attained which would have prevented infiltration. Therefore, this missed SR did not pose a threat to the health and safety of the public or NMP2 plant personnel.

IV. CORRECTIVE ACTIONS

- 1. TS 3.0.3 was entered, but actions were delayed as allowed by SR 4.0.3. Procedure N2-OSP-HVC-R001 was revised to include verification of the relay room differential pressure and assure that required ACU lineups are verified. Adjustments were made to balancing damper 2HVC*DMP8A and both divisions of the control room special filter trains were successfully tested and declared operable.
- 2. This event will be reviewed in operator requalification training by February 28, 1998.

• •

• ~ *

.

ι.

•.. . ·•

.

.

• . . .

•

۹ ۱ .

· • ,

1												
•	NRC FORM 366A	KOVED OMB NO. 3150-0104 EXPIRES: 4/30/92										
	LICENSEE EV TEXT.Co	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (#530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.										
	FACILITY NAME (I)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE ()					
			Ŧ	YEAR	26×	SEQUENTIAL NUMBER	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	REVISION NUMBER				
	Nine Mile Point Unit 2	05000410		97	-	09	-	00	04	OF	04	
ł		<u></u>		L	- <u>L</u> _		<u> </u>					

TEXT (If more space is required, use additional NRC Form 3664's) (17)

IV. <u>CORRECTIVE ACTIONS</u> (cont'd)

In addition, since the deficiencies which initiated this event occurred prior to 1994, previously implemented actions to address instances of inadequate managerial methods, relative to technical procedure preparation and review, are also applicable to this event. Specifically, a corrective action described in LER 94-003:

An inadequate technical review has been recognized in the past as being one of the major reasons for violating specific requirements. Niagara Mohawk has upgraded specific programs whose purpose is not only to ensure that adequate procedures are written, but also to ensure the review of these procedures is carried out in a manner that should eliminate events such as these. These include, but are not limited to, the following procedurally controlled programs:

- NIP-SEV-01, Applicability Reviews and Safety Evaluations
- NIP-PRO-03, Preparation and Review of Technical Procedures
- PWM-PRO-0105, Technical Procedure Verification and Validation

V. ADDITIONAL INFORMATION

- A. Failed components: none.
- B. Previous similar events: NMP2 has had a number of instances where inadequate procedure preparation or review caused missed or inadequately performed surveillance tests. As a result of previous events, enhancements were made to the procedure preparation, review, and issue process with the implementation of Nuclear Division Interface Procedure, NIP-PRO-03, "Preparation and Review of Technical Procedures." This event and those discussed in LERs 94-05, 96-01, 96-02, 96-07, 97-01, and 97-07 involved problems with past-practice identified by personnel involved in procedure review activities. Since this event occurred prior to the corrective actions taken for these similar events, it could not have been prevented by these corrective actions. In addition, in a letter from Mr. R. B. Abbott dated November 22, 1996 in response to Inspection Report 96-07, NMPC provided a status of NMP2 surveillance procedure review efforts. The attachment to that letter outlined our efforts to convert the NMP2 TS to the Improved Standard Technical Specifications. The missed SR reported in this LER was identified by the NMPC staff preparing those amendments.
- C. Identification of components referred to in this LER:

COMPONENT	IEEE 803 FUNCTION	IEEE'805 SYSTEM ID
2HVC*DMPV84	DMP .	VI

, , ,

۰ ۰ ۰

ş