

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9808240020 DOC.DATE: 98/08/14 NOTARIZED: NO DOCKET #  
 FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moho 05000410  
 AUTH.NAME AUTHOR AFFILIATION  
 BOSNIC,D. Niagara Mohawk Power Corp.  
 DAHLBERG,K.A. Niagara Mohawk Power Corp.  
 RECIPIENT NAME RECIPIENT AFFILIATION

SUBJECT: LER 98-002-01:on 980115,violation of TS 6.2.2.b occurred.  
 Caused by inappropriate behavior of licensed operator who  
 violated TS & procedure requirements.Licensed operator has  
 been removed from all station duties.W/980817 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 PD	1 1	HOOD,D	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<del>FILE CENTER</del>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOHB	1 1	NRR/DRCH/HQMB	1 1
	NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
	RES/DET/EIB	1 1	RGNI FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE,J H	1 1
	NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST.  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

AD4



2



NIAGARA MOHAWK

GENERATION  
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

August 17, 1998  
NMP2L 1816

United States Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-410  
LER 98-02, Supplement 1

Gentlemen:

In accordance with 10CFR50.73 (a)(2)(i)(B), we are submitting LER 98-02, Supplement 1, "Violation of Technical Specification 6.2.2.b." There is substantial doubt as to the Licensed Operator's capability to knowingly violate Technical Specifications. Therefore, the cause of this event has been revised.


Very truly yours,

Kim A. Dahlberg  
Plant Manager - NMP2

KAD/GJG/lmc  
Attachment

xc: Mr. H. J. Miller, Regional Administrator, Region I  
Mr. B. S. Norris, Senior Resident Inspector  
Records Management

9808240020 980814  
PDR ADOCK 05000410  
S PDR



## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-330), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Nine Mile Point Unit 2				DOCKET NUMBER (2) 05000410				PAGE (3) 1 OF 3				
TITLE (4) Violation of Technical Specification 6.2.2.b												
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE(7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)	
01	15	98	98	02	01	08	14	98	N/A		05000	
									N/A		05000	
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 095		<input type="checkbox"/> 20.402(b) <input type="checkbox"/> 20.405(a)(1)(i) <input type="checkbox"/> 20.405(a)(1)(ii) <input type="checkbox"/> 20.405(a)(1)(iii) <input type="checkbox"/> 20.405(a)(1)(iv) <input type="checkbox"/> 20.405(a)(1)(v)			<input type="checkbox"/> 20.405(c) <input type="checkbox"/> 50.36(e)(1) <input type="checkbox"/> 50.36(e)(2) <input checked="" type="checkbox"/> 50.73(a)(2)(i) <input type="checkbox"/> 50.73(a)(2)(ii) <input type="checkbox"/> 50.73(a)(2)(iii)			<input type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(x)			<input type="checkbox"/> 73.71(b) <input type="checkbox"/> 73.71(c) <input type="checkbox"/> OTHER <small>(Specify in Abstract below and in Text, NRC Form 366A)</small>	
LICENSEE CONTACT FOR THIS LER (12)												
NAME Don Bosnic - Manager Operations NMP2						TELEPHONE NUMBER (315) 349-7952						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)												
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS			
SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION DATE (15)			MONTH	DAY	YEAR	
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)						<input checked="" type="checkbox"/> NO						

ABSTRACT (Limits to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On January 15, 1998, Niagara Mohawk Power Corporation (NMPC) discovered that on December 24, 1997, for approximately six minutes, a Licensed Operator was not "at the controls" of Nine Mile Point Unit 2 (NMP2) as required by Technical Specification (TS) 6.2.2.b. This violation was discovered by NMPC during an investigation into missing Operations personnel files. A Licensed Senior Operator and the Licensed Operator were in the control room and both could have immediately responded to plant transients. At the time, the plant was operating with all Emergency Core Cooling Systems available for automatic response to a plant transient.

The apparent cause of the event is the inappropriate behavior of the Licensed Operator who violated the TS and procedure requirements. Based on the nature of the behavior of the individual, NMPC Employee Assistance Program professionals have concluded that Operations Management had no substantial behavioral observation information that could have been used to predict or prevent this event.

The licensed operator has been removed from all station duties.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Nine Mile Point Unit 2	05000410	98	- 02	- 01	02 OF 03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

## I. DESCRIPTION OF EVENT

On January 15, 1998, Niagara Mohawk Power Corporation (NMPC) discovered that on December 24, 1997 for approximately six minutes, a Licensed Operator was not "at the controls" of Nine Mile Point Unit 2 (NMP2). Technical Specification (TS) 6.2.2.b requires "at least one Licensed Operator shall be in the control room when fuel is in the reactor. In OPERATIONAL CONDITIONS 1, 2 or 3, at least one Licensed Senior Operator or Licensed Operator shall be at the controls of the unit." Contrary to this requirement, the Licensed Operator, who was assigned to the "at the controls" area, left the controls area. The "at the controls" area is defined by Figure 13.5-1 of the NMP2 Updated Safety Analysis Report.

As required by TS 6.2.2.e, a Licensed Senior Operator (Assistant Station Shift Supervisor (ASSS)) was in the control room during this period. However, the Licensed Senior Operator was in the area of the control room back panels (not in the view of the "at the controls" area) and was thus unaware of this TS violation. The Station Shift Supervisor (SSS) was performing tasks outside the control room.

NMPC discovered this violation while performing an investigation into missing Operations personnel files. In the course of the investigation, it became evident that the Licensed Operator left the controls area to remove the personnel files. The Licensed Operator entered the glass enclosed SSS office and an area behind a control panel. Both areas are in the control room, but outside the "at the controls" area.

## II. CAUSE OF EVENT

The apparent cause of the event is the inappropriate behavior of the Licensed Operator who violated the TS and procedure requirements. Based on the nature of the behavior of the individual, NMPC Employee Assistance Program professionals have concluded that Operations Management had no substantial behavioral observation information that could have been used to predict or prevent this event.

NMPC has performed an investigation and concluded that this violation was isolated to the Licensed Operator on this one occasion. Other licensed personnel were interviewed, and all interviewed knew the "at the controls" requirements and assured that they met those requirements.

## III. ANALYSIS OF EVENT

The event is reportable in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation or condition prohibited by the plant's Technical Specifications," since a Licensed Operator was not "at the controls".





LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20535, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (3)			PAGE (4)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Nine Mile Point Unit 2	05000410	98	02	01	03 OF 03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

### III. ANALYSIS OF EVENT (cont'd)

As noted above, the Licensed Senior Operator (ASSS), and the Licensed Operator were in the control room and both could have immediately responded to plant transients. At the time, the plant was operating with all Emergency Core Cooling Systems available for automatic response to a plant transient. Therefore, this event did not pose a threat to the health and safety of the public or plant personnel.

### IV. CORRECTIVE ACTIONS

1. The Licensed Operator has been removed from all station duties: Prior to the discovery of this event, the individual had his unescorted access removed for medical reasons on January 2, 1998.
2. An investigation was performed and concluded that this was an isolated incident involving this Licensed Operator on this one occasion. Other licensed personnel were interviewed, and all interviewed knew the "at the controls" requirements and assured that they met those requirements.
3. A sampling of surveillances involving the Licensed Operator within the last six months were compared against Security records. The available records indicated that the Operator was in the area needed to perform the surveillances. Additionally, surveillance procedures are reviewed by two operations management staff personnel prior to closing out the procedures.
4. A sampling of rounds performed by the Licensed Operator in the last six months were reviewed against Security records. It was determined that on July 21, 1997, one required area was not entered. This was a general area requiring entry on shiftly rounds. Subsequent rounds verified that there were no anomalies in that area. Therefore, there are no adverse consequence of the missed rounds. An additional sampling was performed with no further discrepancies and thus, the single instance is considered an anomaly.

### V. ADDITIONAL INFORMATION

- A. Failed components: none.
- B. Previous similar events: none.
- C. Identification of components referred to in this LER: none.

