

50-410



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

October 15, 1998

Mr. John H. Mueller
Chief Nuclear Officer
Niagara Mohawk Power Corporation
Nine Mile Point Nuclear Station
Operations Building, Second Floor
Lycoming, NY 13093

SUBJECT: CORE SHROUD INSPECTION AND FLAW EVALUATION FOR OPERATION
AFTER REFUELING OUTAGE 6, NINE MILE POINT NUCLEAR STATION,
UNIT NO. 2 (TAC NO. MA2286)

Dear Mr. Mueller:

By letter dated July 9, 1998, as supplemented September 21, 1998, Niagara Mohawk Power Corporation (NMPC) submitted results of the ultrasonic inspection of core shroud welds during the 1998 refueling outage (RFO6) at Nine Mile Point Nuclear Station, Unit 2 (NMP2), and provided a flaw evaluation for the continued operation of NMP2 for one operating cycle.

Following the detection of significant cracking (i.e., in excess of 10 percent of the inspected length) in horizontal weld H4, NMPC inspected accessible areas of all horizontal welds in accordance with the Boiling Water Reactor Vessel and Internals Project's (BWRVIP's) "BWR Core Shroud Inspection and Flaw Evaluation Guidelines" (BWRVIP-01), Revision 2. These additional inspections revealed significant cracking in welds H5 and H7; minor cracking in welds H1, H2, H3, and H8; and no cracking in weld H6. NMPC also inspected accessible areas of vertical welds V12, V13, V14, V15, V16, and V17 and found no evidence of cracking. NMPC's letter of July 9, 1998, included a report by General Electric Nuclear Energy, GENE-B13-01920-63, Revision 2, "The Evaluation Of Nine Mile Point Unit 2 Shroud Cracking For At Least One Fuel Cycle Of Operation Following RFO6," dated June 1998, which describes the observed cracking in the horizontal shroud welds and presents the results of a structural margin evaluation.


The NRC staff has completed its review of your submittals. In the enclosed safety evaluation, the NRC staff concludes that the flaw evaluation meets the rules of the American Society of Mechanical Engineers Boiler and Pressure Vessel Code (ASME Code), Section XI, "Rules for In-Service Inspection of Nuclear Power Plant Components." Since the predicted final flaw depth at the end of the operating cycle has a calculated safety factor that exceeds the safety factor required by the ASME Code, the NRC staff concludes that continued operation, without repair or intermediate inspection of the NMP2 core shroud, is acceptable for at least the operating cycle that follows RFO6.

The NRC staff acknowledges that you believe the current analysis, which is based upon the bounding crack growth rate of 5×10^{-5} inch/hour specified in BWRVIP-01, is conservative and that you plan to submit a revised analysis in the future that may justify operations for two cycles. The revised analysis will be based upon the NRC staff's recent approval of BWRVIP-14, "Evaluation of Crack Growth in BWR Stainless Steel Reactor Pressure Vessel Internals." The NRC staff also acknowledges that NMPC will submit its NMP2 core shroud reinspection plan to the NRC staff at least 3 months before the RFO7 reinspection is performed, and will provide the results of the RFO7 reinspection to the NRC staff within 30 days of its completion.

9810200030 981015
PDR ADDCK 05000410
P PDR

SEARCHED INDEXED SERIALIZED FILED
OCT 15 1998
FBI - ALBANY

1/1
D10
MAY



J. Mueller

- 2 -

This completes our review under TAC No. MA2286. If you have questions regarding this letter or the enclosure, contact me by phone at (301) 415-3049 or by electronic mail at dsh@nrc.gov.

Sincerely,



Darl S. Hood, Senior Project Manager
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket No. 50-410

Enclosure: Safety Evaluation

cc w/encl: See next page



This completes our review under TAC No. MA2286. If you have questions regarding this letter or the enclosure, contact me by phone at (301) 492-3049 or by electronic mail at dsh@nrc.gov.

Sincerely,

Original signed by:

Darl S. Hood, Senior Project Manager
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket No. 50-410

Enclosure: Safety Evaluation

cc w/encl: See next page

Distribution:

Docket File
PUBLIC
PDI-1 R/F
OGC
ACRS
CCowgill, RI

DHood
SBajwa
MBanic
KWichman
CCarpenter
JStrosnider

RHermann
CSheng

DOCUMENT NAME: G:\NMP2\NM2A2286.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	PM:PDI-1	LA:PDI-1	D:PDI-1					
NAME	DHood/rs1 DS/H	SLittle	SBajwa					
DATE	10/14/98	10/14/98	10/15/98					

OFFICIAL RECORD COPY



1111111111

John H. Mueller
Niagara Mohawk Power Corporation

cc:

Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Resident Inspector
Nine Mile Point Nuclear Station
P.O. Box 126
Lycoming, NY 13093

Mr. Jim Rettberg
NY State Electric & Gas Corporation
Corporate Drive
Kirkwood Industrial Park
P.O. Box 5224
Binghamton, NY 13902-5224

Mr. John V. Vinqvist, MATS, Inc.
P.O. Box 63
Lycoming, NY 13093

Supervisor
Town of Scriba
Route 8, Box 382
Oswego, NY 13126

Mr. Richard Goldsmith
Syracuse University
College of Law
E.I. White Hall Campus
Syracuse, NY 12223

Nine Mile Point Nuclear Station
Unit No. 2

Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, NY 10271

Mr. Timothy S. Carey
Chair and Executive Director
State Consumer Protection Board
5 Empire State Plaza, Suite 2101
Albany, NY 12223

Mark J. Wetterhahn, Esquire
Winston & Strawn
1400 L Street, NW.
Washington, DC 20005-3502

Gary D. Wilson, Esquire
Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, NY 13202

Mr. F. William Valentino, President
New York State Energy, Research,
and Development Authority
Corporate Plaza West
286 Washington Avenue Extension
Albany, NY 12203-6399



Small, faint, illegible marks or characters in the top right corner.