CATEGORY

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

DOC.DATE: 97/09/25 NOTARIZED: NO

DOCKET #

ACCESSION NBR:9901190210 FACIL:50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220 AUTHOR AFFILIATION AUTH.NAME Region 1 (Post 820201) DOERFLEIN, L. Region 1 (Post 820201) BELTZ, T. RECIP.NAME RECIPIENT AFFILIATION SUBJECT: PNO-I-97-062:on 970916, one inch "fish-mouth" break was identified on one condenser inlet tube in emergency cooling condenser. Repairs required cutting of inlet & outlet endbells of condenser. DISTRIBUTION CODE: 1E34F COPIES RECEIVED:LTR U ENCL TITLE: 50 Docket & Vendors PNO/Non-Routine Event/Safeguards Event (PN) NOTES: (0 COPIES COPIES RECIPIENT RECIPIENT ID CODE/NAME LTTR ENCL ID CODE/NAME LTTR ENCL FILE CENTER INTERNAL: ACRS 1 NUDOCS FULL TXT NRR/DRPM/PERB 1 RES/DET/EIB 1 OE DIR 1 RES/DRA/DEPY 1 RES/DST

1 RGN1 FILE 01 EXTERNAL: LITCO BRYCE, J H 1 NOAC


1

1 NRC PDR

RES/RPHEB

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

RES/DST DEPY



-1-

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-I-97-062

This preliminary notification constitutes EARLY notice of events of POSSIBLEsafety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that isknown by Region I staff in King of Prussia, Pennsylvania on this date.

Facility

Licensee Emergency Classification

Niagara Mohawk Power Corp.

Notification of Unusual Event

Nine Mile Point 1

Alert

Lycoming, New York

Site Area Emergency

Dockets: 50-220

General Emergency

X Not Applicable

Subject: FORCED OUTAGE TO REPAIR EMERGENCY CONDENSER TUBE LEAKS On September 15, 1997, Nine Mile Point Unit 1 commenced a reactor shutdown to evaluate and repair an apparent tube leak in one of four emergency cooling (EC) condensers.

On September 16, using a boroscope, a 1-inch "fish-mouth" break was identified on one condenser inlet tube in the EC condenser. The repairs require the licensee to remove by cutting the inlet and outlet endbells of the condenser. Subsequently, on September 22, during a pressure test of the redundant train, the licensee identified tube leaks in two other EC condensers.

To inspect and repair all the EC condensers, the licensee currently anticipates the forced outage duration to be approximately four to seven weeks.

The resident staff is following the outage and monitoring licensee activities.

The licensee has issued a press release.

The Region I Office of Public Affairs is prepared to respond to media inquiries.

The State of New York has been notified.

The information is current as of 9:00 a.m., September 25, 1997.

Contact:

Lawrence Doerflein

Terry Beltz

(610)337-5378

(315)342-4041

9901190210 970925 PDR I&E PNO-I-97-062 PDR

IE34 0|1

• .