

June 21, 1999

Mr. John H. Mueller  
Chief Nuclear Officer  
Niagara Mohawk Power Corporation  
Nine Mile Point Nuclear Station  
Operations Building, 2nd Floor  
P.O. Box 63  
Lycoming, NY 13093

**SUBJECT: NRC INTEGRATED INSPECTION REPORT NOS. 50-220/99-04  
AND 50-410/99-04**

Dear Mr. Mueller:

This report transmits the findings of safety inspections conducted by NRC inspectors at the Nine Mile Point Nuclear Station, Units 1 and 2, from March 28, through May 8, 1999. At the conclusion of the inspection, the findings were discussed with members of your staff.

During the six-week inspection period covered by this report, operation of the Nine Mile Point Nuclear Station reflected an acceptable safety focus. The Unit 1 outage was well managed with appropriate emphasis on shutdown risk. At Unit 2, a few performance shortcomings in the areas of maintenance and engineering surfaced as a result of the automatic reactor shutdown which occurred on April 24. For example, maintenance on the reactor core isolation cooling system resulted in its failure to operate on demand and an inadequate design review of a modification to the uninterruptible power supply system contributed to its failure. Additionally, we observed that your staff's troubleshooting and analysis of the Unit 2 equipment problems were not methodical or well coordinated. However, we noted that you and your staff recognized these performance shortcomings and were developing actions to improve.

Effective programs were maintained for radioactive material waste management and transportation of radioactive materials. Radiological controls for the Nine Mile Point Unit 1 refuel outage were effectively planned and implemented and were focused on jobs with elevated exposure estimates, high dose rates, and radiologically complex work.

Based on the results of this inspection, the NRC has determined that six Severity Level IV violations of NRC requirements occurred. These violations are being treated as Non-Cited Violations (NCVs), consistent with Appendix C of the Enforcement Policy. These NCVs are described in the subject inspection report. If you contest the violation or severity level of these NCVs, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001, with copies to the Regional Administrator, Region I; and the Director, Office of Enforcement, Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Senior Resident Inspector at the Nine Mile Point facility.

9907010028 990621  
PDR ADOCK 05000220  
G PDR

OFFICIAL RECORD COPY

IE:01

John H. Mueller

2

In accordance with 10CFR2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Sincerely,

Original Signed by:

Michele G. Evans, Chief  
Projects Branch 1  
Division of Reactor Projects

Docket Nos. 50-220, 50-410  
License Nos. DPR-63, NPF-69

Enclosure: NRC Inspection Report Nos. 50-220/99-04 and 50-410/99-04

cc w/encl:

G. Wilson, Esquire

M. Wetterhahn, Winston and Strawn

J. Rettberg, New York State Electric and Gas Corporation

P. Eddy, Electric Division, Department of Public Service, State of New York

C. Donaldson, Esquire, Assistant Attorney General, New York Department of Law

J. Vinqvist, MATS, Inc.

F. Valentino, President, New York State Energy Research  
and Development Authority

J. Spath, Program Director, New York State Energy Research  
and Development Authority

John H. Mueller

3

Distribution w/encl:

H. Miller, RA/J. Wiggins, DRA (1)  
Region I Docket Room (with concurrences)  
Nuclear Safety Information Center (NSIC)  
PUBLIC  
NRC Resident Inspector  
M. Evans, DRP  
W. Cook, DRP  
R. Junod, DRP

Distribution w/encl: (VIA E-MAIL)

J. Shackelford, Acting RI EDO Coordinator  
G. Hunegs - Nine Mile Point  
E. Adensam, NRR  
D. Hood, NRR  
M. Campion, RI  
Inspection Program Branch (IPAS)  
R. Correia, NRR  
DOCDESK

DOCUMENT NAME: G:\BRANCH1\NMP9904.WPD

To receive a copy, indicate in the box: "C" = Copy w/ attachment/enclosure "E" = Copy w/ attachment/enclosure  
"N" = No copy

OFFICE	RI/DRP	E	RI/DRP	E
NAME	GHunegs	<i>WJE jr</i>	MEvans	<i>WJE</i>
DATE	06/21/99		06/21/99	

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION

REGION I

Docket/Report Nos.: 50-220/99-04  
50-410/99-04

License Nos.: DPR-63  
NPF-69

Licensee: Niagara Mohawk Power Corporation  
P. O. Box 63  
Lycoming, NY 13093

Facility: Nine Mile Point, Units 1 and 2

Location: Scriba, New York

Dates: March 28, 1999 - May 8, 1999

Inspectors: G. K. Hunegs, Senior Resident Inspector  
R. A. Fernandes, Resident Inspector  
R. A. Skokowski, Resident Inspector  
F. J. Arner, III, Reactor Engineer  
A. L. Della Greca, Senior Reactor Engineer  
K. S. Kolaczyk, Operations Engineer  
G. W. Morris, Senior Reactor Engineer  
R. C. Ragland, Radiation Specialist

Approved by: Michele G. Evans, Chief  
Projects Branch 1  
Division of Reactor Projects

9907010035 990621  
PDR ADOCK 05000220  
G PDR

## EXECUTIVE SUMMARY

Nine Mile Point Units 1 and 2  
50-220/99-04 & 50-410/99-04  
March 28, 1999 - May 8, 1999

This inspection report included aspects of licensee operations, engineering, maintenance, and plant support. The report covered a six-week period of resident inspection. The results of an occupational radiation exposure and radwaste management and transportation inspection from April 7 - 16, an inservice inspection program review from April 19 - 23, and an engineering inspection from April 12 - 16 were also included in this inspection report.

### Operations

The April 24 Unit 2 automatic reactor shutdown from 100 percent power was characterized by the licensee and NRC staffs as a risk significant transient. The cause was determined to be a generator protection circuit relay failure which also resulted in a residual (slower) transfer to off-site power. The slow transfer caused large motor loads such as reactor feedwater pumps, reactor recirculation pumps, and condensate booster pumps to trip. Operator performance with respect to procedure use, communications, and control of plant equipment was good. Senior management oversight of scram recovery efforts was appropriate. Major equipment failures included the reactor core isolation cooling system and a partial loss of the uninterruptible power supply system. These equipment failures and other minor equipment problems did not significantly impact recovery efforts. (O1.2)

The Unit 1 outage shutdown risk program was well implemented. The communication of plant protected equipment and safety system status was good. (O1.3)

Overall, NMPC's approach to identifying and resolving equipment performance problems following the April 24 Unit 2 reactor scram was acceptable. Positive aspects of NMPC's post-scram evaluation process included the establishment of multi-discipline teams to review equipment performance, the conduct of periodic status briefs, and the use of vendor services. Senior management effectively challenged their staff's post-scram analysis which contributed to a more rigorous evaluation and the re-creation of the event using the plant simulator. However, a few performance shortcomings related to the scram evaluation process were apparent. Although the overall process was thorough, equipment troubleshooting and failure analysis were not methodical. NMPC management recognized these shortcomings and was developing methods to improve its staff's problem solving skills. (O7.1)

Between March 5 and March 12, 1999, Unit 2 experienced two events where the automatic depressurization system nitrogen storage tanks had excessive leakage. NMPC failed to recognize that the leakage exceeded the allowed limit, and therefore, did not take the required limiting condition of operation actions. This was a non-cited violation of Unit 2 Technical Specification 3.5.1. (O8.2)

## Executive Summary (cont'd)

### Maintenance

The Unit 1 fuel off-load was well controlled. Communications between the operators on the refuel bridge, as well as between the refuel bridge and the control room were observed to be good. (M1.2)

The installation of the emergency core cooling system torus suction strainers was well controlled. The work environment was clean, organized and good foreign material exclusion controls were in place. (M1.3)

During the Unit 2 scram, the reactor core isolation cooling (RCIC) system failed to operate as required and was manually tripped. This RCIC system failure was attributed to an inadequate maintenance procedure and the licensee's over-reliance on vendor support for a 1998 RCIC turbine trip throttle valve rebuild. The failure to ensure an adequate maintenance procedure was prepared and used to perform work on the RCIC system was a non-cited violation. Based on recent operating history, the RCIC system has exceeded its Maintenance Rule performance criteria. (M2.1)

On April 24, a Unit 2 generator protection circuit relay failed which caused a reactor scram. NMPC effectively evaluated the cause and consequences of the relay failure and implemented acceptable corrective action. (M2.2)

Non-destructive examination personnel were qualified, and adhered to procedures while performing examinations. The core shroud and reactor vessel weld inspection plans were in accordance with the requisite NRC safety evaluation. Deficiencies identified during inspection activities were properly documented. A new surveillance program provided enhanced oversight of vendor activities. (M3.1)

### Engineering

During the Unit 2 reactor scram transient, one of the two reactor protection system uninterruptible power supplies (UPS) failed. Excessive currents, which caused the inverter DC power supply fuse to blow, were the result of a UPS design deficiency involving a newly installed maintenance bypass switch. NMPC identified that this vendor supplied UPS design change received an inadequate engineering design review. (E1.1)

Unit 1 design changes that were reviewed, correctly addressed the concerns for which the modifications and been developed. Typically, the analyses accurately described the purpose of the modification and the intended results; the calculation and safety evaluations satisfactorily supported the design changes; and the design change process was acceptably implemented. (E1.2)

In the case of the Emergency Core Cooling System (ECCS) strainer modification, the technical scope of the design change was comprehensive, but the licensee's original review of an ECCS pump air ingestion calculation lacked thoroughness regarding a small break loss of coolant

## Executive Summary (cont'd)

accident (LOCA) scenario and required a more detailed analysis and a revision of the supporting calculation. Additionally, the safety evaluation required revision to provide stronger bases for the conclusions contained therein regarding a large break LOCA. The licensee's review of air ingestion phenomena associated with the large break LOCA resulted in the conservative decision to declare inoperable, in the future, any ECCS pump placed in operation for surveillance testing or torus cooling. (E2.1)

From March 20 to March 23, 1999, Unit 1 operated with a maximum average planar heat generation rate (APLHGR) exceeding the limits specified by the technical specifications. This technical specification violation was non-cited. NMPC determined that the cause was the inadvertent processing of traverse in-core probe (TIP) data, due to inadequate computer system security on the 3D-Monicores system. Specifically, TIP data could be processed without authorization or operator knowledge from uncontrolled locations. Additionally, the oversight by station personnel with regards to reactivity management and core performance monitoring was poor, in that this discrepancy was not recognized for three days. (E4.1)

The failure to conduct the required ASME Code inservice inspections of the reactor recirculation pump seal housing bolts and flange surfaces during the first and second ten-year inspection intervals was non-cited. (E8.1)

NMPC self-identified and promptly corrected a condition which could have adversely affected the ability of the unit to achieve safe-shutdown, involving the Unit 2 service water intake de-icing heater control circuits which were not protected against a control room fire. This violation of License Condition 2.G was non-cited. (E8.3)

### Plant Support

Radioactive material/waste management and transportation programs were effectively implemented as evidenced by use of up-to-date regulations and facility licenses, appropriately trained personnel, proper procedural guidance and adequate maintenance of procedures, appropriate use of scaling factors to estimate isotopic content of radioactive material/waste packages, and proper shipping records. (R1.1)

Radiological controls for the Unit 1 refuel outage were effectively planned and implemented and focused on jobs with elevated exposure estimates, high dose rates, and radiologically complex work. (R1.2)

Radiological posting practices for access to radiation areas, high radiation areas, and airborne radioactivity areas were effective as evidenced by well defined boundaries and clear radiological postings. Some opportunities to enhance informational postings on the refuel floor that required "health physics notification prior to entry" beneath the drywell dome and reactor head insulation were identified. (R1.2)

Contamination monitoring requirements for access to the Turbine Building 305' Green Area (clean area within the radiologically controlled area [RCA]) did not include an entire whole body

## Executive Summary (cont'd)

frisk similar to the requirements for RCA exit. However, they were adequate to minimize the risk for the spread and ingestion of significant amounts of radioactive contamination based on use of detailed procedures, restrictions on personnel that could use the facility, and close health physics oversight. (R1.2)

Effective high radiation area controls were implemented as evidenced by clear radiological postings, use of locked doors when required, use of "Alarming" dosimetry, use of radiation work permits (RWPs), use of remote door alarms, requirements for a minimum available exposure for access, and increased health physics oversight and monitoring for high radiation area entry. (R1.2)

Material conditions were good and housekeeping practices were effective as evidenced by clear aisles and walkways, neatly stored tools and equipment, and painted floor and wall surfaces. (R2.1)

Self-assessments, audits, and the deficiency/event reporting system were effectively used to identify, evaluate, and resolve radiological control issues as evidenced by the conduct of multiple self-assessments and audits to satisfy the radiation protection program review requirements in 10CFR20.1101(c) and use of the DER system to implement appropriate corrective actions and controls to prevent unplanned exposures. (R7.1)

One non-cited violation was identified associated with the failure to maintain access restrictions in the upper elevation of the drywell during movement of an irradiated core component on March 15, 1997. (R7.1)



# TABLE OF CONTENTS

	page
EXECUTIVE SUMMARY .....	ii
TABLE OF CONTENTS .....	vi
Summary of Plant Status .....	1
I. Operations .....	1
O1 Conduct of Operations .....	1
O1.1 General Comments .....	1
O1.2 Automatic Reactor Shutdown (Unit 2) .....	1
O1.3 Outage Shutdown Safety (Unit 1) .....	3
O7 Quality Assurance in Operations .....	4
O7.1 Assessment of Post-Scram Troubleshooting Efforts (Unit 2) .....	4
O8 Miscellaneous Operations Issues .....	5
O8.1 (Closed) Licensee Event Report (LER) 50-410/98-26 .....	5
O8.2 (Closed) LER 50-410/99-03 .....	6
II. Maintenance .....	7
M1 Conduct of Maintenance .....	7
M1.1 General Comments (61726, 62707) .....	7
M1.2 Fuel Off-load Activities (Unit 1) .....	8
M1.3 Installation of Core and Containment Spray Strainer Assemblies (Unit 1) .....	8
M2 Maintenance and Material Condition of Facilities and Equipment .....	9
M2.1 Reactor Core Isolation Cooling (RCIC) System Failure During Reactor Scram Transient (Unit 2) .....	9
M2.2 Generator Protection Relay Failure Resulted in Scram (Unit 2) .....	10
M3 Maintenance Procedures and Documentation .....	11
M3.1 Inservice Inspection (Unit 1) .....	11
M8 Miscellaneous Maintenance Issues .....	13
M8.1 (Closed) LER 50-410/99-02 .....	13
M8.2 (Closed) VIO 50-410/98-05-02 .....	13
M8.3 (Closed) VIO 50-220/98-02-05 .....	13
III. Engineering .....	14
E1 Conduct of Engineering .....	14
E1.1 Uninterruptible Power Supply (UPS) Failure During Reactor Scram Transient (Unit 2) .....	14
E2 Engineering Support of Facilities and Equipment .....	15
E2.1 Design Modifications (Unit 1) .....	15
E4 Engineering Staff Knowledge and Performance .....	17
E4.1 (Closed) LER 50-220/99-03 .....	17
E8 Miscellaneous Engineering Issues .....	19

Table of Contents (cont'd)

E8.1	(Closed) LER 50-220/98-19 .....	19
E8.2	(Closed) VIO 50-410/98-05-03 .....	20
E8.3	(Closed) LER 50-410/99-04 .....	20
E8.4	(Closed) IFI 50-410/98-19-03: Leakage of contaminated water following a scram reset .....	21
E8.5	(Closed) Violation 50-220/98-16-02 .....	22
IV.	Plant Support .....	23
R1	Radiological Protection & Chemistry Controls .....	23
R1.1	Unit 1 and Unit 2 Solid Radioactive Waste Management and Transportation of Radioactive Materials .....	23
R1.2	Refuel Outage Radiological Controls (Unit 1) .....	24
R2	Status of RP&C Facilities and Equipment .....	27
R2.1	Radiological Housekeeping (Units 1 and 2) .....	27
R7	Quality Assurance in RP&C Activities .....	28
R7.1	Radiological Control Program Corrective Actions (Units 1 and 2) .....	28
V.	Management Meetings .....	30
X1	Exit Meeting Summary .....	30

**ATTACHMENTS**

- Attachment 1- Partial List of NMPC Persons Contacted
- Inspection Procedures Used
  - Items Opened, Closed, and Updated
  - List of Acronyms Used

## Report Details

### Summary of Plant Status

Nine Mile Point Unit 1 (Unit 1) began the inspection period at 100 percent reactor power. On April 11, Unit 1 was shutdown to begin a scheduled refueling outage (RFO15) and remained shutdown through the end of the inspection period. Significant outage activities included inspection of core shroud vertical welds and reactor vessel longitudinal welds, and installation of new emergency core cooling system suction strainers.

Nine Mile Point Unit 2 (Unit 2) began the inspection period at 100 percent reactor power. Unit 2 automatically shutdown on April 24 due to the malfunction of an electrical relay associated with the generator protection circuit. Maintenance activities completed during the shutdown included: reactor core isolation cooling system troubleshooting and repair; uninterruptible power supply system modifications; and recirculation system flow control valve (FCV) maintenance. Following the forced maintenance outage, Unit 2 was returned to service on May 4. Due to recirculation system flow control valve fluctuations, Unit 2 was placed in single-loop operation on May 6. After FCV adjustments were made, Unit 2 was returned to two-loop operation on May 9 and was returned to 100 percent power on May 11.

### I. Operations

#### **O1 Conduct of Operations<sup>1</sup>**

##### **O1.1 General Comments (71707)**

Using NRC Inspection Procedure 71707, the resident inspectors conducted frequent reviews of ongoing plant operations. The reviews included tours of accessible areas of both units, verification of engineered safeguards features (ESF) system operability, verification of adequate control room and shift staffing, verification that the units were operated in conformance with Technical Specifications (TSs), and verification that logs and records accurately identified equipment status or deficiencies. In general, the conduct of operations was professional and safety-conscious.

##### **O1.2 Automatic Reactor Shutdown (Unit 2)**

###### **a. Inspection Scope (71707)**

On April 24, at 4:19 a.m., Unit 2 experienced an automatic reactor shutdown (scram) from 100 percent power. The inspectors responded to the site and observed portions of the scram recovery process. The inspectors also reviewed the operator logs, post-scram review documentation, and the sequence of events. Additionally, the event was discussed with Unit 2 operations and management personnel.

---

<sup>1</sup> Topical headings such as O1, M8, etc., are used in accordance with the NRC standardized reactor inspection report outline. Individual reports are not expected to address all outline topics. The NRC inspection manual procedure or temporary instruction that was used as inspection guidance is listed for each applicable report section.

b. Observations and Findings

The cause of the reactor shutdown was the failure of a relay in the generator protection circuitry (see section M2.2). The relay failure caused a turbine trip and subsequent automatic reactor shutdown. Because of the particular relay failure and design of the generator protection circuit, instead of a fast transfer of electrical loads to off-site power, a residual (slower) transfer occurred which caused all feedwater, condensate booster, and recirculation pumps to trip. All control rods fully inserted on the automatic shutdown and vessel level control was maintained by automatic initiation and injection of the high pressure core spray (HPCS) system. The reactor core isolation cooling (RCIC) system also initiated, but failed to come up to speed and was tripped by the control room operators (see section M2.1). All five turbine bypass valves opened to control reactor pressure below the main steam safety relief valve setpoint. Plant cool-down was commenced on natural circulation using the turbine bypass valves. By late evening on April 24, the plant was in cold shutdown.

Coincident with the reactor shutdown, there was a trip of the uninterruptible power supply (UPS) which provides a portion of the power to the reactor protection system (see section E1.1). The partial loss of UPS resulted in several primary containment isolation valve group isolations. The partial loss of UPS had negligible impact on scram recovery efforts.

The Updated Safety Analysis Report (USAR) classifies this event as an incident of moderate frequency. Notwithstanding the equipment problems, plant response was in accordance with the USAR. Because of the residual transfer of power, and notable equipment failures, the NRC staff performed an initiating event risk assessment. The NRC staff's assessment showed that the event was risk significant, in that, the total conditional core damage probability had increased and exceeded the accident sequence precursor threshold value used by the NRC staff for assessing significance. The licensee's risk assessment of this event was consistent with the NRC staff's assessment.

The inspectors evaluated operator performance with respect to emergency operating procedure use, emergency plan use, communications and control of the plant. Based on interviews of operators and operations management and review of operator logs and plant sequence of event information, the inspectors determined that operators responded appropriately to the event. Reactor vessel level and pressure were well controlled. Subsequent re-creation of the event on the simulator also showed that operator response was appropriate. The inspectors noted that Niagara Mohawk Power Corporation (NMPC) senior managers responded to the site and provided appropriate oversight. Additional operators were made available to provide assistance, as necessary. The inspectors observed good communications and good procedure use by operators during the post-scram recovery period. With the exception of the RCIC and UPS system failures, other major equipment operated as designed. A few minor system discrepancies were appropriately documented in the corrective action program for follow-up evaluation and repair.

c. Conclusions

The April 24 Unit 2 automatic reactor shutdown from 100 percent power was characterized by the licensee and NRC staffs as a risk significant transient. The cause was determined to be a generator protection circuit relay failure which also resulted in a residual (slower) transfer to off-site power. The slow transfer caused large motor loads such as reactor feedwater pumps, reactor recirculation pumps, and condensate booster pumps to trip. Operator performance with respect to procedure use, communications; and control of plant equipment was good. Senior management oversight of scram recovery efforts was appropriate. Major equipment failures included the reactor core isolation cooling system and a partial loss of the uninterruptible power supply system. These equipment failures and other minor equipment problems did not significantly impact recovery efforts.

O1.3 Outage Shutdown Safety (Unit 1)

a. Inspection Scope (71707)

The inspectors reviewed the methods used by Unit 1 personnel to monitor shutdown safety as outlined in station procedures.

b. Observations and Findings

Procedure N1-ODG-11, "Shutdown Operations Protection Guideline," is used to monitor plant status during shutdown conditions. NMPC uses an attachment to the procedure for tracking the status of plant equipment important to shutdown safety associated with decay heat removal, inventory control, electrical power availability, secondary containment, and reactivity control. The attachment is updated each shift by control room operators and is used to brief station personnel at various meetings throughout the day. The inspector observed several briefings and noted good communication from station personnel with respect to emphasizing safety system status and protected components. The inspector noted that visual aides were used on control panels and in equipment rooms to warn personnel of the protected status of safety significant equipment.

c. Conclusions

The Unit 1 outage shutdown risk program was well implemented. The communication of plant protected equipment and safety system status was good.

## O7 Quality Assurance in Operations

### O7.1 Assessment of Post-Scram Troubleshooting Efforts (Unit 2)

#### a. Inspection Scope (71707)

NMPC appointed a post-scrum review team to investigate the cause of the Unit 2 scram (see section O1.2). The inspectors attended post-scrum review team and site operations review committee (SORC) meetings, observed NMPC troubleshooting efforts and discussed the scram evaluation activities with several members of the Unit 2 management staff. Additionally, the inspectors reviewed the post-scrum review procedure. The inspectors assessed NMPC's overall performance in identifying the causes of the equipment deficiencies.

#### b. Observations and Findings

A post-scrum review team was appointed to investigate the cause of the scram and to determine corrective action. The technical services department had the lead on identifying the causes and equipment performance issues and were assisted by design engineering. Several teams were formed to focus on individual equipment performance problems including the RCIC, UPS, and generator protection relay failure. The teams used Procedure N2-REP-6, "Post-Scram Review," which provided an overall approach to evaluate the causes of a reactor scram and to review plant equipment performance. The teams held periodic briefs and formal SORC reviews were conducted. Senior management challenged the preliminary and apparent causes of equipment malfunctions during the review process:

The inspector noted that the operators that were involved in the transient prepared critique sheets listing their recollection of the event and actions taken, but a formal method to evaluate operator performance was not evident. Station practice has been to rely on the self-evident nature of operator errors to determine if a more rigorous review is warranted. In the case of this transient, the operations manager determined that it would be beneficial to re-create the event on the simulator to more thoroughly evaluate operator performance and learn from the event. As a result, some minor simulator fidelity issues were identified and additional operator performance insights were gained.

The evaluation of the cause of the scram and equipment performance was particularly challenging because of the complexity of the transient. Additionally, data was not available from the transient analysis recorder following the event, since it had not been properly aligned to automatically trigger the recording of data because of an earlier operator error. NMPC documented this problem in deviation/event report (DER) 2-99-1260. Based on the inspectors' observations, NMPC's approach to the troubleshooting and analysis of the transient and equipment problems was not methodical. For example, the troubleshooting efforts to identify the cause of the RCIC trip were extensive and drawn out. The eventual identification that tolerances for the trip and throttle valves were incorrect was the result of additional trip throttle valve agitation, late in the troubleshooting process, rather than the conduct of a formal root cause analysis. NMPC

management attributed their staff's problem resolution weaknesses to the absence of necessary skills and training. The inspectors learned that NMPC was developing methods and training to improve performance in this area, including increased formal root cause analysis training.

c. Conclusions

Overall, NMPC's approach to identifying and resolving equipment performance problems following the April 24 Unit 2 reactor scram was acceptable. Positive aspects of NMPC's post-scram evaluation process included the establishment of multi-discipline teams to review equipment performance, the conduct of periodic status briefs, and the use of vendor services. Senior management effectively challenged their staff's post-scram analysis which contributed to a more rigorous evaluation and the re-creation of the event using the plant simulator. However, a few performance shortcomings related to the scram evaluation process were apparent. Although the overall process was thorough, equipment troubleshooting and failure analysis were not methodical. NMPC management recognized these shortcomings and was developing methods to improve its staff's problem solving skills.

08 **Miscellaneous Operations Issues (92700)**

- 08.1 (Closed) Licensee Event Report (LER) 50-410/98-26: Seismic Monitor Inoperable for More Than Thirty Days and Special Report Not Submitted. On October 9, 1998, NMPC discovered that a reactor building triaxial response spectrum recorder (TRSR) was not properly oriented which rendered the seismic monitor inoperable. The seismic monitoring instrumentation is installed to monitor and record data in the event of an earthquake. This data would be used following an earthquake to verify that the event was bounded by the analytical model provided in the USAR. NMPC determined that the monitor had been inoperable since at least May 1997, when the equipment was last tested, and was potentially inoperable since initial installation. On October 23, 1998, NMPC corrected the orientation of the TRSR and verified proper orientation of the other accessible seismic monitoring equipment.

NMPC concluded that station personnel who developed and revised the seismic monitor surveillance procedures were not aware of the importance and precise tolerances required for the orientation of the seismic monitor instruments. Consequently, the instruments were improperly positioned and rendered inoperable for greater than thirty days. NMPC's failure to maintain the seismic monitors in an operable status and submit a Special Report, as required by TS 3.3.7.2, constitutes a violation of minor significance and is not subject to formal enforcement action.

The inspectors completed an on-site review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions, as described in the LER, were reasonable. This LER is closed.

08.2 (Closed) LER 50-410/99-03: Automatic Depressurization System (ADS) Nitrogen Leakage in Excess of Unit 2 Technical Specifications Surveillance Limits

a. Inspection Scope (92700)

Between March 5 and March 12, 1999, Unit 2 experienced two events where the leakage from the ADS nitrogen storage tanks exceeded the design basis leak rate. The inspectors reviewed the associated DERs, attended pertinent SORC meetings, reviewed the subsequent LER, and discussed related issues with NMPC personnel.

b. Observations and Findings

The nitrogen system supplies high pressure nitrogen to the ADS valves. The system consists of high pressure storage tanks located outside the reactor building, which supply nitrogen to tank Nos. 4 and 5, located within the reactor building, which in turn supply nitrogen to the ADS accumulators. Tank No. 4 supplies three ADS valves, while tank No. 5 supplies four ADS valves. The tanks are normally isolated from the outside storage tanks and are periodically re-pressurized to make-up for normal leakage.

Event 1

On March 5, Unit 2 completed a surveillance test on the ADS nitrogen system. The test exercised various valves within the system and required operators to remove the blank flange on the nitrogen emergency fill connection and attach a test assembly. Following the test, operators removed the test assembly, re-installed the flange and verified acceptable tank pressures. Over the next day, operators re-pressurized tank No. 5 several times. Subsequently, operators identified a leak at the blank flange. The gasket was replaced and the pressure in the tank was stabilized. DER 2-1999-0682 was written to evaluate the event, and the subsequent review showed that the leak rate from tank No. 5 exceeded the TS allowed value.

Event 2

On March 9, 1999, operators responded to a low nitrogen pressure alarm on tank No. 4 and manually re-pressurized the tank. From March 9 to March 12, operators re-pressurized the tank five more times while searching for leaks. Initially, the station shift supervisor (SSS) considered the leakage to be of a similar magnitude as past leaks and concluded that the TS leakage limit was not exceeded. However, on March 12, the SSS determined that Unit 2 may have exceeded the TS limit and initiated DER 2-1999-0749. Later that day, NMPC identified and repaired a few small nitrogen system leaks. The leak rate decreased to below the TS limit. Subsequently, NMPC found the normally closed valve 2GSN\*V73A slightly open, and difficult to operate. NMPC concluded that since the first re-pressurization of tank No. 4, on March 9, that valve 2GSN\*V73A had permitted leakage.



In addition to the two events described in the LER, NMPC believes that excessive nitrogen leakage occurred at other times and it was not recognized that the TS limit or the design basis was exceeded.

As described in the LER, NMPC determined that, based on the maximum observed leakage during these two events, approximately 1.68 and 1.86 days of nitrogen for tank Nos. 4 and 5 would have been available. Although, this was less than the design basis of five days, NMPC concluded that 1.5 days was sufficient to allow for a nitrogen truck to arrive on site to resupply the nitrogen tanks. The inspectors considered this to be reasonable. Nonetheless, the failure to take the actions required by TS 3.5.1.e.2 during the period when the ADS tanks leakage rate exceeded the TS allowed limits is a violation. This Severity Level IV violation is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy (NCV 50-410/99-04-01). This violation is in the licensee's corrective action program as DERs 2-1999-0682 and 2-1999-0749.

The inspectors completed an on-site review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions as described in the LER were reasonable. This LER is closed.

c. Conclusion

Between March 5 and March 12, 1999, Unit 2 experienced two events where the automatic depressurization system nitrogen storage tanks had excessive leakage. NMPC failed to recognize that the leakage exceeded the allowed limit, and therefore, did not take the required limiting condition of operation actions. This was a non-cited violation of Unit 2 Technical Specification 3.5.1.

## II. Maintenance

### **M1 Conduct of Maintenance**

#### **M1.1 General Comments (61726, 62707)**

Using NRC Inspection Procedures 61726 and 62707, the resident inspectors periodically observed various maintenance activities and surveillance tests. As part of the observations, the inspectors evaluated the activities with respect to the requirements of the Maintenance Rule, as detailed in 10CFR50.65. In general, maintenance and surveillance activities were conducted professionally, with the work orders (WOs) and necessary procedures in use at the work site, and with the appropriate focus on safety. Specific activities and noteworthy observations are detailed in the inspection report. The inspectors reviewed procedures and observed all or portions of the following maintenance/surveillance activities:

- WO 99-08109, Hydraulic control unit post maintenance testing.
- WO 99-06450, Uninterruptible power supply inverter cleaning and inspection.
- N2-OSP-ICS-R002, Reactor core isolation cooling.
- WO 98-03424, Feedwater heater replacement.
- RFMSHRD30, Electric discharge machine shroud weld V9 and V10 activities.

## **M1.2 Fuel Off-load Activities (Unit 1)**

### **a. Inspection Scope (60710)**

The inspectors observed portions of Unit 1 fuel off-load activities using the guidance provided in NRC Inspection Procedure 60710, "Refueling Activities."

### **b. Observations and Findings**

The inspectors observed fuel off-load activities from the control room and from the refueling bridge. The off-load was performed in accordance with approved procedures, and was well controlled. The inspectors considered the communications by the operators on the refuel bridge and between the refuel bridge and the control room operators to have been good. The inspectors independently verified installation of the refueling interlock jumper and that a sample of the fuel moves were correct.

### **c. Conclusions**

The Unit 1 fuel off-load was well controlled. Communications between the operators on the refuel bridge, as well as between the refuel bridge and the control room were observed to be good.

## **M1.3 Installation of Core and Containment Spray Strainer Assemblies (Unit 1)**

### **a. Inspection Scope**

The inspector reviewed work order packages for installing the emergency core cooling system (ECCS) torus strainers to ensure the installation was being conducted in accordance with station drawings and work instructions.

### **b. Observations and Findings**

The inspector utilized work order packages 98-03314-05,06,07, and 08 to verify that the core spray and containment spray systems' strainer assemblies were properly installed. The packages included quality assurance hold points, foreign material exclusion signatures, as well as signatures for verification of component fit-up. The inspector verified that welders were utilizing approved welding procedures and welding material. Additionally, the inspector verified the welder's qualifications were current and compatible for the weld procedure and process being utilized on the modification.

The inspector toured the torus and work site and observed that the work areas were clean and organized and that waste materials were kept to a minimum to reduce the challenges to foreign material exclusion controls. In addition, the inspector noted that quality assurance personnel were assigned to the project and were conducting routine surveillance activities.

c. Conclusions

The installation of the emergency core cooling system torus suction strainers was well controlled. The work environment was clean and organized and good foreign material exclusion controls were in effect.

**M2 Maintenance and Material Condition of Facilities and Equipment**

**M2.1 Reactor Core Isolation Cooling (RCIC) System Failure During Reactor Scram Transient (Unit 2)**

a. Inspection Scope (62707, 37551)

During the April 24 reactor scram transient, the RCIC system failed (see section O1.2). The inspectors reviewed applicable sections of the USAR, RCIC operating procedures, and the DER disposition. The inspectors walked down portions of the system, observed system troubleshooting efforts, and interviewed the operator who was responsible for the operation of the RCIC system at the time of its failure.

b. Observations and Findings

During the reactor scram, reactor low water level was reached and the RCIC system received an automatic start signal. The RCIC injection valve opened and the trip throttle valve indicated that it was open. However, the maximum RCIC turbine speed observed by operators was 200 rpm with zero discharge flow indicated. Based on these control room indications, the control room operator manually secured the RCIC turbine. Based on the observed system operating parameters, the inspector concluded the operator's action to trip the RCIC turbine was appropriate.

Subsequent troubleshooting showed that the RCIC system had received a valid initiation signal and that the steam admission and outboard injection valves had opened. Data recorders confirmed that the RCIC turbine speed had increased to 200 rpm, at which point the turbine trip valve was tripped.

NMPC conducted extensive troubleshooting and determined that the latching mechanism for the trip throttle valve was not sufficiently engaged. NMPC determined that the set-up of the overspeed trip linkage and associated valve components was not correct. The inspectors determined that the RCIC turbine trip throttle valve had been disassembled and rebuilt during the 1998 outage. NMPC obtained vendor assistance to complete the work and had relied upon the vendor's expertise. Licensee review determined that the overspeed trip linkage tolerances were not described in the work

package and consequently the linkage was re-assembled with incorrect tolerances. The failure to provide an adequate work procedure is a violation of 10 CFR 50 Appendix B Criterion V, "Instruction, Procedures, and Drawings." This severity level IV violation is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy (NCV 50-410/99-04-02). This procedural adequacy violation is in the licensee's corrective action program as Deficiency Event Report (DER) 1099-1254. Corrective actions included revising the maintenance procedure and providing additional training for maintenance personnel. The licensee also determined that additional industry operating experience was available, but not used, concerning RCIC system trip throttle valve maintenance.

The Maintenance Rule performance criteria for the RCIC system is two functional failures over a two-year period. This failure was classified as a maintenance preventable functional failure and actual performance shows three functional failures during the previous two-year period. At the end of the inspection period, NMPC was evaluating the RCIC system for classification in Maintenance Rule category (a)(1).

c. Conclusions

During the Unit 2 scram, the reactor core isolation cooling (RCIC) system failed to operate as required and was manually tripped. This RCIC system failure was attributed to an inadequate maintenance procedure and the licensee's over-reliance on vendor support for a 1998 RCIC turbine trip throttle valve rebuild. The failure to ensure an adequate maintenance procedure was prepared and used to perform work on the RCIC system was a non-cited violation. Based on recent operating history, the RCIC system has exceeded its Maintenance Rule performance criteria.

M2.2 Generator Protection Relay Failure Resulted in Scram (Unit 2)

a. Inspection Scope

The Unit 2 reactor scram was caused by the failure of a generator protection circuit relay. The inspector observed and reviewed NMPC's troubleshooting and evaluation methods used to determine the cause of the relay failure.

b. Observations and Findings

NMPC troubleshooting effort showed that the volts/hertz relay associated with the generator protection circuit had failed. The circuit design was such that the relay failure caused the turbine trip (and reactor scram) and caused a residual (slower) transfer of electrical loads to offsite power sources.

No apparent cause for the relay failure was identified. Inspection of the relay did not reveal any physical characteristics for the failure mode. Bench testing showed that the relay was defective and that the malfunction would provide a spurious trip signal with an outcome the same as the event that was experienced. To obtain more specific information concerning the failure mode, the failed relay was shipped to an independent

laboratory for failure analysis. The relay was replaced and calibrated satisfactorily. Other similar relays in use were recalibrated and tested satisfactorily.

The inspector reviewed the failed volt/hertz relay work history which showed that this relay was replaced during outages in 1996 and 1998. The failed relay and similar relays used in the generator protection circuit fall under the Unit 2 preventive maintenance program and are calibrated every refuel outage. These relays were included within the scope of the Maintenance Rule and this event was classified by NMPC as a functional failure.

c. Conclusions

On April 24, a Unit 2 generator protection circuit relay failed which caused a reactor scram. NMPC effectively evaluated the cause and consequences of the relay failure and implemented acceptable corrective action.

**M3 Maintenance Procedures and Documentation**

**M3.1 Inservice Inspection (Unit 1)**

a. Inspection Scope (73753)

The inspectors reviewed the inservice inspection (ISI) activities that were part of Refueling Outage (RFO) 15. The review involved performing a walkdown of portions of the core spray system piping and verifying piping welds were reflected in the ISI program manual and system isometric drawings. Non-destructive examination (NDE) activities were observed, and the qualifications of NDE personnel verified. Additionally, the inspectors assessed NMPC's oversight of contractor NDE activities.

b. Observations and Findings

ISI Program Manual

No deficiencies were noted in the ISI program manual during the field walkdown of the core spray system. The list and location of core spray system piping welds contained in the manual, matched the as-built system configuration. However, during the field walkdown the inspectors identified errors in the core spray system weld map isometric drawing F-45183-C. Specifically, the ISI program manual indicated welds 81-WD-128 and 81-WD-183-A were located downstream of core spray pumps 11 and 12. The inspectors confirmed the welds were located in the correct location on the core spray piping. However, they were not shown on the corresponding weld map drawing. NMPC documented this drawing error in DER 1-99-1225.

Both welds were located in ASME Code Class 2 piping and were not among the population of welds that NMPC had selected for NDE activities. This approach was in accordance with ASME Code requirements, which indicate only 25% of the

applicable welds in ASME Code Class 2 piping need be examined over the 10-year inspection interval. Accordingly, the weld map error did not result in an ASME Code violation and this ISI Program administration oversight was of minor safety consequence not subject to formal enforcement action.

#### Observation of NDE Activities

The inspectors witnessed several NDE field inspections, including an ultrasonic (UT) examination performed by NMPC personnel on a recirculation system piping weld, and a visual examination of a service water system piping hanger conducted by a contractor. The individuals who performed the examinations met the training and experience requirements outlined in procedure SNT-TC-1A "Recommended Practice, Personnel Qualification and Certification of Non-Destructive Testing."

While observing the UT examination, the inspectors verified the UT test equipment was calibrated in accordance with industry and NMPC standards. Further, the inspectors verified that deficiencies uncovered during the visual and UT examinations were documented as required in DERs.

#### Core Shroud and Beltline Weld Inspection Activities

NMPC had made arrangements with two vendors, General Electric and Framatone, to perform NDE activities on the horizontal welds in the reactor vessel and core shroud, respectively. By review of vendor inspection plans and interviews with NDE personnel, the inspectors verified the inspection scope for the shroud and reactor vessel welds were in accordance with the NRC approved inspection plans described in NRC correspondence to NMPC, dated March 24 and April 7, 1999, respectively. To minimize the possibility that relevant indications would be overlooked, both vendors had at least two individuals who independently review the NDE data.

#### Oversight of NDE Activities

During this outage, NMPC changed its philosophy regarding oversight of contracted NDE activities. Prior to the change, NMPC NDE personnel provided little formal oversight of contracted NDE activities. Instead, oversight was provided on an informal basis, whereby NMPC personnel would observe contractor activities on a time-available basis. Formal oversight was limited to yearly audits of the ISI program.

During this outage, NMPC developed a formalized ISI surveillance schedule that outlined which NDE activities would be monitored. Most monitoring was conducted by NMPC NDE personnel. However, contract personnel were scheduled to oversee some NDE activities where NMPC did not have the necessary in-house experience to adequately observe and evaluate. Surveillance plan observations were to be documented and forwarded to management for review.

The inspectors did not have the opportunity to review any completed surveillance reports or observe performance of surveillance in the field, so it was not possible to comment on

the quality of the effort. However, the new surveillance program does provide NMPC additional assurance that contracted activities will be properly conducted.

c. Conclusions

Non-destructive examination personnel were qualified, and adhered to procedures while performing examinations. The core shroud and reactor vessel weld inspection plans were in accordance with the requisite NRC safety evaluation. Deficiencies identified during inspection activities were properly documented. A new surveillance program provided enhanced oversight of vendor activities.

**M8 Miscellaneous Maintenance Issues (37551, 92700, 90712, 92903)**

- M8.1** (Closed) LER 50-410/99-02: Missed Technical Specification Channel Functional Test of the Recirculation Flow Upscale Rod Block. The technical details associated with this LER were discussed in NRC Inspection Report (IR) 50-410/99-03, Section M1.2. The inspectors completed an in-office review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions as described in the LER were reasonable. This LER is closed.
- M8.2** (Closed) VIO 50-410/98-05-02: Failure to conduct surveillance test on batteries. Specifically, during Refueling Outages (RFOs) 4 and 5, credit was inappropriately taken for the battery performance test, in lieu of the battery service test for the Division I 125 volt battery. Subsequently, NMPC issued LER 50-410/98-09 "Missed Battery TSSR [technical specification surveillance report] Due to Inappropriate Interpretation." This LER was reviewed and closed in NRC IR 50-410/98-05. Based on the review of the LER, which provided the root cause and corrective actions regarding the event, NMPC was not required to provide a separate response to the violation. The inspectors verified implementation of the corrective actions associated with this event. Violation 50-410/98-05-02 is closed.
- M8.3** (Closed) VIO 50-220/98-02-05: Inadequate plant impact in Work Order (WO) package. Specifically, during the development of a troubleshooting WO associated with a control room chilled water temperature control valve, the impact of removing two leads was not adequately evaluated. As a result, removing these leads caused an unanticipated opening of the control room ventilation outside air and return air dampers. The inspectors confirmed the completion of the corrective actions associated with the event as described in NMPC's June 26, 1998, response to the violation. Violation 50-220/98-02-05 is closed.

### III. Engineering

#### E1 **Conduct of Engineering**

##### E1.1 Uninterruptible Power Supply (UPS) Failure During Reactor Scram Transient (Unit 2)

###### a. Inspection Scope (37551)

During the reactor scram transient, one of the two reactor protection system uninterruptible power supplies (2VBB-UPS3B), failed. The inspector reviewed applicable sections of the USAR, UPS operating procedures, and the DER disposition.

###### b. Observations and Findings

The power supply for the reactor protection system (RPS) consists of two UPS systems. Each UPS has three power sources: the preferred alternating current (AC) source, the direct current (DC) source, and the maintenance AC source. Upon loss of the preferred AC source, the UPS automatically switches to the DC source. Each UPS is connected to its RPS through two redundant electrical protection assemblies (EPAs). The EPAs are designed to protect the RPS circuits from voltage or frequency deviations.

During the event, power was lost to the preferred UPS power supply causing the UPS to transfer to the battery. Upon re-energizing the AC switchgear, the UPS DC source fuse blew. Also, the voltage had lowered sufficiently enough to cause the EPAs to trip on undervoltage, resulting in a loss of power to the RPS. The impact of the loss was limited because the plant was already shutdown.

NMPC performed a formal event and causal factor analysis to determine the root cause of the UPS failure. It was determined that, excess current caused the DC power supply fuse to blow. The excess current was the result of a design deficiency with the control circuit board for the maintenance bypass switch. The specific design deficiency was incorrect grounding of a control circuit board. NMPC determined that the design deficiency was created during the installation of the UPS maintenance bypass switch. The maintenance bypass switch for the failed system was a vendor supplied modification which was installed during the 1998 refueling outage and for the other train of UPS, in 1996. During the modification review process, NMPC did not recognize that the grounding circuit for the maintenance bypass switch was incorrect. Contributing to NMPC's oversight was the absence of appropriate vendor supplied design change drawings. As documented in DER 2-1999-1707, corrective actions included a review of the engineering design change process. In addition, NMPC's interim corrective action included the installation of a temporary modification to remove the motor-operated feature of the maintenance bypass switch, effectively removing the circuit card design deficiency.

NMPC classified the UPS failure as a Maintenance Rule functional failure. The inspector determined that this was the only functional failure for the UPS system during the previous two-year period.



c. Conclusions

During the Unit 2 reactor scram transient, one of the two reactor protection system uninterruptible power supplies (UPS) failed. Excessive currents, which caused the inverter DC power supply fuse to blow, were the result of a UPS design deficiency involving a newly installed maintenance bypass switch. NMPC identified that this vendor supplied UPS design change received an inadequate engineering design review.

**E2 Engineering Support of Facilities and Equipment**

**E2.1 Design Modifications (Unit 1)**

a. Inspection Scope (37700)

The inspectors reviewed selected Unit 1 design change packages (DCPs) to assess the quality of engineering analyses and to verify that the design change process complied with plant administrative procedures and regulatory requirements. The inspection addressed temporary and permanent design changes and included a review of the background information, applicable analyses, calculations, safety evaluations, internal review process, and post-modification testing activities. The inspectors also conducted walkdowns of selected installations to verify their conformance with applicable documents.

b. Observations and Findings

The inspectors determined that the reviewed system and component changes correctly addressed the concerns for which the design modifications had been prepared and that the applicable analyses accurately described the purpose of the modification and the intended results. Except as described below, the analyses, calculations, and safety evaluations were detailed, supported the design changes, and had been appropriately reviewed. The inspectors identified no concerns with the installed equipment or post-modification testing performed.

ECCS Suction Strainer Replacement

This modification pertained to the installation of new horizontal stacked disc strainers in the torus and was initiated to address strainer plugging concerns raised by NRC Bulletin 96-03, "Potential Plugging of Emergency Core Cooling Suction Strainers by Debris in Boiling-Water Reactors." Besides the installation of the strainers, the modification package addressed other needed changes, including: (1) the addition of new spectacle flanges and a strainer between the condensate storage tanks and the core spray pumps; and (2) the removal of retired-in-place hydrogen-oxygen monitoring tubing in the torus to eliminate a potential direct debris source. The inspectors found the technical scope of the design changes to be comprehensive and the licensee's review of the procedures requiring revision due to the design changes to be thorough.

In vendor calculation No. S14STRAINERM002, "ECCS System Strainer Air/Steam Ingestion Analysis," the licensee evaluated whether the air bubbles that formed in the Unit 1 torus during a loss of coolant accident (LOCA) or a safety-relief valve (SRV) discharge presented a challenge to the operation of the core spray and containment spray systems. The inspectors found that, although the licensee had performed the required independent review of the calculation, the review lacked thoroughness in certain areas. For instance, based on the results of the calculation, the licensee had concluded that an SRV actuation while the containment spray pumps were operating, such as in response to a small break LOCA, would result in air being ingested into the containment spray pump strainers and cause degradation of the pumps. However, the licensee did not address this potential condition in the unreviewed safety question determination section of the safety evaluation. As a result of the inspectors' questions in this area, the licensee asked the vendor to perform a more detailed analysis of this specific scenario and subsequently determined that air ingestion and, hence, pump degradation would not occur.

During a large break LOCA, the vendor calculation indicated that the time lapse between the onset of the LOCA and the start of the pumps would prevent air ingestion into the new ECCS suction strainers and would not challenge the operability of the pumps. In the calculation, the vendor concluded that a pump, which was already running at the onset of a large break LOCA may be momentarily degraded due to air ingestion; however, the pumps would still be able to achieve the flow rates assumed in the accident analysis. The licensee accepted the calculation results, but conservatively decided that, whenever a core or containment spray pump was placed in operation for testing or torus cooling, they would declare that loop of the system not operational and follow the TS requirements regarding the limiting condition for operation (LCO) of that system. As in the case of the small break LOCA, the licensee had not specifically addressed in the safety evaluation the potential degraded condition of the pump for which the LCO was necessary. The licensee explained that the potential for air ingestion by the pumps was a pre-existing unrecognized condition that was being alleviated by the new strainers and that the LCO was a conservative measure to assure the reliability of the affected system. The inspectors determined that the two conditions described above should have been included in the licensee's unreviewed safety question review. Upon further review of the issue, the licensee determined that the safety evaluation should be revised to provide stronger bases for the conclusions reached. Accordingly, the licensee initiated Deviation/Event Report (DER) 1-1999-1480.

c. Conclusions

Unit 1 design changes that were reviewed, correctly addressed the concerns for which the modifications had been developed. Typically, the analyses accurately described the purpose of the modification and the intended results; the calculation and safety evaluations satisfactorily supported the design changes; and the design change process was acceptably implemented.

In the case of the Emergency Core Cooling System (ECCS) strainer modification, the technical scope of the design change was comprehensive, but the licensee's original

review of an ECCS pump air ingestion calculation lacked thoroughness regarding a small break loss of coolant accident (LOCA) scenario and required a more detailed analysis and a revision of the supporting calculation. Additionally, the safety evaluation required revision to provide stronger bases for the conclusions contained therein regarding a large break LOCA. The licensee's review of air ingestion phenomena associated with the large break LOCA resulted in the conservative decision to declare inoperable, in the future, any ECCS pump placed in operation for surveillance testing or torus cooling.

#### **E4 Engineering Staff Knowledge and Performance**

##### **E4.1 (Closed) LER 50-220/99-03: NMP1 Thermal Limit Exceeded the Requirements of Technical Specifications**

###### **a. Inspection Scope (37551, 92700)**

On February 19, 1999, the Unit 1 3D-Monicores system was mistakenly updated with a traverse in-core probe (TIP) power distribution from February 4, 1999. This action resulted in the plant being operated with the average planar heat generation rate (APLHGR) exceeding the limits specified in the Technical Specifications. The inspector reviewed the LER and the documentation associated with NMPC's corrective action program.

###### **b. Observations and Findings**

3D-Monicores is a system of computer programs designed to monitor and predict important core parameters. The programs calculate reactor power, moderator void and flow distributions in the core. This information is used to determine other core parameters such as margins to thermal limits, and fuel exposure. The programs are designed to track current reactor parameters automatically (usually once per hour) or on demand. The computer program accuracy is enhanced by making use of in-core neutron flux measurements. NMPC utilizes the TIP system for in-core flux measurements and inputs this data to the 3D-Monicores. On March 23, NMPC completed a routine TIP data collection run and subsequently transferred the new data to the 3D-Monicores system. The new TIP data correctly updated the computer's calculated core power distribution and following the printout of the core parameters the operators determined that the APLHGR value for one area of the core was 2.2 percent above TS limits. Operators immediately reduced power to restore the APLHGR within TS limits.

NMPC's investigation into the event determined that an inadvertent "Process TIPs" command was entered into the 3D-Monicores system. This action essentially put old in-core flux measurements into the program. During the investigation, NMPC determined that the action had a discernable effect on the computer printout of the core parameters, but was not identified by the operators or the reactor engineering group at the time of the error. NMPC's investigation also determined that the error did not cause any adverse effects until after a control rod pattern adjustment was made on March 20, 1999. Had the proper TIP case been in the computer program at that time, there is a high probability that the particular rod adjustment would not have been done. Evaluation by NMPC

determined that an APLHGR of 2.2 % above the limit would not have exceeded any of the 10 CFR 50.46 licensing criteria, and therefore, had minimal safety consequences.

NMPC determined that the cause of inadvertent processing of TIP data was inadequate computer system security on the 3D-Monicores system. The system was not protected, in that the design allowed TIP data to be processed without authorization and without warning from uncontrolled locations. The inspectors determined that additional information and follow-up was required in the area of computer security (IFI-50-220/99-04-03). NMPC determined that the reactor engineering group failed to recognize the corruption of the system due to insufficient analysis of daily 3D-Monicores data, in that the discrepancy was not recognized for three days. Corrective actions in the LER included disabling the ability to process TIPs from uncontrolled locations. The NMPC root cause evaluation identified several other corrective actions including developing tools to aid in monitoring the accuracy of 3D-Monicores and tracking key core thermal limit parameters for trending and analysis purposes.

As discussed above, NMPC determined that the actual impact of exceeding the thermal limit was small. Nonetheless, the failure to maintain core thermal limits as required by TS 3.1.7.a is a violation. This severity level IV violation is being treated as a Non-Cited Violation (NCV), consistent with Appendix C of the NRC Enforcement Policy (NCV 50-220/99-04-04). This violation is in the licensee's corrective action program as DER 1-1999-0837.

The inspectors completed an on-site review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions as described in the LER were reasonable. This LER is closed.

c. Conclusions

From March 20 to March 23, 1999, Unit 1 operated with a maximum average planar heat generation rate (APLHGR) exceeding the limits specified by the technical specifications. This technical specification violation was non-cited. NMPC determined that the cause was the inadvertent processing of traverse in-core probe (TIP) data, due to inadequate computer system security on the 3D-Monicores system. Specifically, TIP data could be processed without authorization or operator knowledge from uncontrolled locations. Additionally, the oversight by station personnel with regards to reactivity management and core performance monitoring was poor, in that this discrepancy was not recognized for three days.

**E8 Miscellaneous Engineering Issues (92700)****E8.1 (Closed) LER 50-220/98-19: Missed ASME Section XI Inservice Inspection Due to Cognitive Error.****a. Inspection Scope**

On November 13, 1998, while reviewing an issue associated with a contingency work package, NMPC discovered certain visual inspections had not been performed on plant components as required by the ASME Code. The missed inspections concerned the failure to perform visual examinations of the reactor recirculation pump seal housing bolts and flange surfaces, during the first and second ten year inspection intervals.

**b. Observations and Findings**

NMPC determined the inspections were missed since the reactor recirculation pumps bolts had not been classified as pressure retaining components in design documents. The recirculation pump flanges were not examined, because ISI personnel overlooked an ASME Code requirement that stated, if any of the five recirculation pumps are disassembled during an interval, one pump flange surface inspection must be performed. During the first and second ten year intervals, several recirculation pumps were disassembled.

Niagara Mohawk corrective action included revising the ISI inspection plan to incorporate the required inspections. A review of the ISI plan was conducted to ensure ASME Code and regulatory requirements were identified in the plan. No other missed inspections were identified. Finally, an inspection of the recirculation pump seal housing bolts was scheduled for completion during refuel outage (RFO) 15.

The inspectors reviewed the ISI program plan and self assessment reports, and verified the plan had been modified. The failure to conduct the required ASME code inspections is a severity level IV violation and is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy (NCV 50-220/99-04-05). This violation is in the licensee's corrective action program as LER 50-220/98-19.

The inspectors completed an on-site review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions as described in the LER were reasonable. This LER is closed.

c. Conclusion

The failure to conduct the required ASME Code inservice inspections of the reactor recirculation pump seal housing bolts and flange surfaces during the first and second ten-year inspection intervals was non-cited.

E8.2. (Closed) VIO 50-410/98-05-03: Failure to perform adequate design for emergency diesel generator (EDG) modification on fuel line. Specifically, the installation of a 1993 modification to the EDG fuel lines failed to include a rubber grommet at the piping support to compensate for system vibration. As a result, vibration of the fuel line pipe caused fretting of the pipe at the location of the pipe support and on April 14, 1998, during surveillance testing of the Division II EDG, a fuel leak developed. NMPC issued DER2-98-0891 to address this issue. The root cause and corrective actions associated with this DER were reviewed in NRC IR 50-410/98-05. Based on this review, NMPC was not required to provide a separate response to the violation. The inspectors verified completion of the corrective actions associated with this event. Violation 50-410/98-05-03 is closed.

E8.3. (Closed) LER 50-410/99-04: NMP2 Service Water Intake De-Icing Heater Control Circuits do not Meet Fire Protection Program Requirements

a. Inspection Scope (92700)

On March 18, 1999, during a review of the Safe Shutdown Analysis for a control room fire, Unit 2 personnel determined that the service water intake de-icing heater control circuits were not included in the analysis. The inspectors reviewed the associated DER, attended pertinent SORC meetings, reviewed the subsequent LER, and discussed related issues with NMPC personnel.

b. Observations and Findings

The Unit 2 service water intake structure openings are equipped with bar rack heaters to eliminate the potential for frazil ice adhesion. Frazil ice formation can occur when the intake structure temperature drops near freezing. Therefore, TS require the heaters to be operable whenever the intake tunnel water temperature is below 39 degrees F. As part of the corrective actions for LER 50-410/99-01, "NMP2 Outside the Design Basis Due to Safe Shutdown Service Water Pump Bay Unit Coolers Being Out-of-Service," Unit 2 determined that a control room/relay room fire that renders the service water intake de-icing heaters inoperable, coincident with service water temperatures that approach freezing, could lead to a complete loss of service water. This condition was not in accordance with the Safe Shutdown Analysis as described in the Unit 2 UFSAR, and this condition has existed since the initial operation of the plant.

Upon identification, NMPC established a fire watch for the control room/relay room fire area, which will be in place until a design change to correct the deficiency is implemented. NMPC expects to complete the design change by November 30, 1999. In

addition, NMPC is continuing their review of the safe-shutdown capability as described in LER 50-410/99-01. The inspectors considered this actions to be appropriate.

NMPC Licensee Condition 2.G requires implementation of the fire protection program described in the UFSAR. The fire protection program includes an analysis of the ability to achieve safe-shutdown of the unit in the case of a control room fire. The failure to ensure that the service water intake de-icing capability is available during a control room fire, could impair the ability to achieve safe-shutdown, and is a violation of this licensee condition. This Severity Level IV violation is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy (NCV 50-410/99-04-06). This violation is in the licensee's corrective action program as LER 50-410/99-04.

The inspectors completed an on-site review of the LER and verified that it was completed in accordance with the requirements of 10CFR50.73. Specifically, the description and analysis of the event, as contained in the LER, were consistent with the inspectors' understanding of the event. The root cause and corrective and preventive actions as described in the LER were reasonable. This LER is closed.

c. Conclusion

NMPC self-identified and promptly corrected a condition which could have adversely affected the ability of the unit to achieve safe-shutdown, involving the Unit 2 service water intake de-icing heater control circuits which were not protected against a control room fire. This violation of License Condition 2.G was non-cited.

- E8.4 (Closed) IFI 50-410/98-19-03: Leakage of contaminated water following a scram reset. Draining evolutions of the scram discharge volume (SDV) have resulted in the contamination of a small area of the reactor building floor. The contamination is caused by steam condensing into and leaking from a ventilation duct to which the equipment drain cooler and the SDV vent piping are connected. NMPC compensated for this by ensuring that applicable procedures incorporate a plant announcement to stand clear of the area during SDV venting and draining. The NRC originally became aware of this issue in 1997 (NRC inspection report 97-11). Later, the NRC opened the IFI to conduct further review of the issue. The purpose of this inspection was to review the system design and to evaluate the safety implications.

The potential for the leakage was created in the 1994-1995 time frame, after the licensee implemented a design change that relocated the reactor building equipment drain header piping. Before the implementation of this change, the hot, pressurized drain lines from the reactor core isolation cooling and the residual heat removal steam condensing systems shared a common header with the cool, gravity equipment drain lines. This common header provided a path for the fluid from the pressurized sources to flash into steam, through the gravity drains, into the reactor building. The relocation of the piping to separate the high pressure drain header from the gravity drain header was successful in eliminating steam from the gravity drains. However, an associated change that tied the SDV vent piping into the equipment drain cooler vent line, effectively created a path

of less resistance to a connected ventilation duct allowing leaks from the duct onto the floor during scram reset.

The inspectors' review of the design implications determined that the small amount of contaminated water emitted from the ventilation duct was controlled and contained in accordance with approved site radiation protection procedures. The inspectors also determined that within the affected area there was no safety equipment which could be adversely impacted by the water spillage. Based on this review, the inspectors did not consider the small amount of water spillage to be safety significant but noted that, although the licensee had implemented several design changes in the equipment drain system during the last five years, they had not implemented an acceptable piping configuration that resolved the original system interaction and the venting contamination concerns. The water spillage also constituted an operator work-around in that it required additional operator actions during the drain evolution of the SDV.

NMPC had proposed and was evaluating alternatives to eliminating the inadvertent contamination experienced during SDV draining. The proposed actions included the rerouting of the SDV vent line and the use of a check valve. Based on the licensee actively pursuing the resolution of this low safety significant issue, this item is closed.

- E8.5 (Closed) Violation 50-220/98-16-02: Failure to identify and promptly correct a condition adverse to quality. On August 20, 1998, NMPC determined that they had failed to recognize, in 1996 and 1997, a low cooling water flow to the motor bearing of core spray pump No. 122. The licensee reported the finding in LER 98-16. At the time of the finding, the NRC reviewed the issue and was satisfied that the licensee had developed a comprehensive corrective action plan to resolve the discrepancy. Nonetheless, the licensee's failure to evaluate and correct their finding was a violation of the Appendix B, corrective action program.

During the current follow up review, the inspectors confirmed that the actions described in the LER and the subsequent engineering evaluation had been satisfactorily completed. Specifically, the inspectors verified that: (1) the repair of the affected pump had been satisfactorily completed; (2) the extent of condition had been addressed; (3) the applicable maintenance procedures had been revised; and (4) the lesson learned from the event had been discussed with responsible personnel from engineering, operations, and maintenance. This item is closed.



#### IV. Plant Support

### R1 Radiological Protection & Chemistry Controls

#### R1.1 Unit 1 and Unit 2 Solid Radioactive Waste Management and Transportation of Radioactive Materials

##### a. Inspection Scope (86750)

A selective review was performed to evaluate NMPC's basis for certifying that radioactive materials and wastes intended for disposal were properly classified, described, packaged, marked and labeled and that radioactive material/waste shipments were made in accordance with applicable shipping regulations. Information was gathered by a review of the following: possession or access to applicable federal regulations; maintenance of licenses for facilities that radioactive materials or wastes were shipped; training records; procedural guidance and procedural maintenance; use of scaling factors to infer the concentration of difficult-to-measure radio nuclides; methods used to classify radioactive wastes; shipping records; and through interviews with cognizant personnel and tours through the plant.

##### b. Observations and Findings

A review of records verified that NMPC had ready access to up-to-date copies of federal regulations including 49 CFR Parts 100-179 and 10 CFR Parts 20, 61, and 71. A review of selected records verified that up-to-date copies of licenses were maintained for facilities to which radioactive materials and wastes were shipped. A selected review of training records showed that members of the Radwaste organization responsible for preparing radioactive waste shipments had received current training on regulations and computer programs used to prepare shipments. An interview with a training specialist revealed that initial training and periodic training were provided on equipment and processes that generate radioactive waste. A review of selected procedures verified that detailed instructions were provided for personnel involved with the transfer, packaging and transport of radioactive wastes. Procedural guidance was adequately maintained and several procedures were in the process of being revised to incorporate recent changes to the regulations and to make needed improvements.

The Radwaste group primarily used computer programs to classify and prepare radioactive material and waste shipments. A selected review of shipping records showed that waste classifications were accurate and no discrepancies were identified. Shipping records were prepared in accordance with procedural guidance and included appropriate information such as radiation and contamination surveys, emergency response information, and shippers certification of the adequacy of the shipment.

##### c. Conclusions

Radioactive material/waste management and transportation programs were effectively implemented as evidenced by use of up-to-date regulations and facility licenses,

appropriately trained personnel, proper procedural guidance and adequate maintenance of procedures, appropriate use of scaling factors to estimate isotopic content of radioactive material/waste packages, and proper shipping records.

## R1.2 Refuel Outage Radiological Controls (Unit 1)

### a. Inspection Scope (83750)

A review was performed of radiological controls implemented for outage work. Information was gathered by a review of radiation exposure goals, selected licensee initiatives to maintain radiation exposures as low as is reasonably achievable (ALARA), through discussions with cognizant personnel, through a review of radiological posting practices, by a review of administrative controls for the Unit 1 Turbine Building "Green Area," a review of high radiation area access controls, and a review of the following documents:

1. ALARA Review 99-12, "Drywell In-Service Inspections (ISI), Erosion/Corrosion (E/C) Exams and Support Work"
2. ALARA Review 99-10, "Dewater and Desludge Torus, Replace ECCS Suction Strainers"
3. ALARA Review 99-06, "Replace Thirty-Seven Control Rod Drives (CRDs)"
4. ALARA Review 99-11, "Disassembly/Reassembly of Reactor Vessel, Fuel Movements and Decontamination"
5. ALARA Review 99-03, "Drywell - Repack Valves - All Elevations"
6. ALARA Review 99-17, "Drywell Floor Drain Sump and Associated Work"
7. GAP-RPP-08, Rev 5, "Control of High, Locked High, and Very High Radiation Areas"
8. S-RAP-RPP-0801, Rev. 8, "High Radiation Area Monitoring and Control"
9. S-RAP-RPP-0103, "Posting Radiological Areas"
10. 10CFR61.55 data for NMP1 dry active waste (DAW)
11. Safety Evaluation 96-102, "Safety Evaluation for Turbine Building Green Area"
12. Deviation/Event Report No. 1-1999-1106, "Unlocked Source Storage Locker - Turbine Building 261' - Condenser Bay."
13. N1-RSP-1Q, "Accountability of Calibration and Check Sources at NMP Unit 1, Rev. 0."

### b. Observations and Findings

An ALARA exposure goal of 280 person rem was set for RFO15. The majority of dose (more than 200 person-rem) was estimated to be received from drywell work. Significant dose jobs included 70 person-rem for drywell ISI, 25 person-rem for torus desludging and ECCS suction strainer replacement, 23 person-rem for CRD exchanges, 20 person-rem for refuel floor activities, 18 person-rem for drywell valve repacks, and 17 person-rem for miscellaneous drywell inspections. Interviews with cognizant personnel and reviews of documentation revealed that the radiological controls organization was staffed with trained and qualified personnel and there was early involvement in planning for jobs with elevated exposure estimates, high dose rates, and radiologically complex work.

ALARA reviews were thorough and provided details of applicable industry events. Examples of radiological controls and ALARA/initiatives included the following:

- Significant amounts of temporary shielding were installed in the Unit 1 drywell to reduce general area and job specific dose rates;
- Floor and equipment drain lines were flushed to reduce general area dose rates in the radwaste building, reactor building, and drywell and allowed the drywell to be down posted from a locked high radiation area to a high radiation area;
- Detailed component and equipment locations were included on drywell briefing maps;
- The torus was desludged with a back-flushable filter skid which reduced the need for filter handling and disposal; and
- Cameras were stationed in key work areas for remote monitoring of work.

#### RFO15 Handbook

An outage handbook was distributed to plant personnel to communicate important outage information such as responsible contacts and telephone numbers, meeting times, and plant maps. However, the inspector noted that the handbook included information regarding the expected response to an alarming dosimeter that was inconsistent with procedural guidance and general employee training. The handbook stated that if an individual received a dose rate alarm on their alarming dosimetry they should move to a lower dose rate area. Procedural guidance and general employee training instructed personnel that if an electronic dosimeter alarm occurs, personnel shall leave the work area and report to radiological protection. NMPC issued a DER and distributed a correction to the RFO15 Handbook. No known examples of improper response to alarming dosimetry occurred as a result of this temporary inconsistency and no violations of NRC requirements were identified.

#### Radiological Boundaries

Overall, radiological boundaries were clearly defined and posted. However, several opportunities for improving radiological postings were identified on the Unit 1 refueling floor. For example, during reactor vessel disassembly, the drywell dome and the reactor vessel head insulation were stored on the refueling floor. General contamination beneath these components was approximately 10,000 - 60,000 dpm/100 cm<sup>2</sup> and areas on the bottom of the insulation package had levels up to 24 mrad/hr/100 cm<sup>2</sup>. Access to these components was restricted with several signs indicating "Contact Health Physics Prior to Entry." During a tour of the refuel floor, several locations that provided access to areas beneath the drywell dome and reactor head insulation did not have readily observable radiological postings. Upon notification by the inspector, health physics staff members immediately posted the identified areas. The improvements in radiological posting were considered an enhancement to existing postings and no violations of NRC requirements were identified.

### Administrative Controls For the Unit 1 Turbine Building "Green Area"

A clean area ("Green Area") was setup within the radiologically controlled area (RCA) on Unit 1 Turbine Building 305 foot elevation to allow turbine building workers to eat, drink, and use sanitation facilities. A safety evaluation was used as the basis for establishing the area and administrative controls for setup, use, and health physics oversight of the facility were included in procedure S-RAP-RPP-0103, Rev. 9, "Posting Radiological Area." Controls for "Green Area" access included continuous health physics oversight; requirements and provisions for contamination monitoring of hands, feet, and face prior to entry; frequent contamination and radiation surveys; and special provisions for the transport of food and other clean items within the RCA.

The radiation protection manager acknowledged that personal contamination surveys for "Green Area" access did not include a whole-body frisk. However, he pointed out that the risk for the spread of contamination and potential ingestion of significant amounts of contamination were minimized by limiting use of the facility to individuals that were briefed on use of the facility and who worked in areas with relatively low contamination levels and lower risk of hot particles (i.e., turbine building workers); contamination monitoring was performed for body parts with the highest probability of contamination (hands, feet, and face); and the health physics staff maintained close oversight and monitoring of the facility. Additionally, all RCA workers were required to receive a whole-body frisk prior to exiting the RCA and experience gained during the previous outage demonstrated that radiological controls implemented for the "Green Area" were effective in controlling contamination.

### High Radiation Area Access Controls

Controls for high radiation area access included detailed procedural guidance; radiological postings; frequent use of locked doors and required use of locked access controls for areas that could result in an individual receiving a dose equivalent in excess of 1000 mrem per hour at 30 centimeters; radiation work permit (RWP) controls; use of "alarming" dosimetry; requirements for a minimum available exposure for access; use of remote door alarms; and increased health physics oversight and monitoring. Two health physics technicians and two health physics supervisors selected for interviews demonstrated thorough knowledge of high radiation area controls. Tours of the plant confirmed that high radiation and locked high radiation areas were appropriately posted and doors that were required to be locked were found locked or appropriately controlled by health physics staff. A review of DERs for the last year showed no negative trends in high radiation area postings or high radiation area access controls.

DER 1-1999-1106 dated April 15, 1999, was written to document and investigate the discovery of an unlocked radioactive source cabinet by a health physics supervisor during a routine tour. The source cabinet was used to store radioactive sources used for instrument source checks and was posted as a high radiation area. The maximum dose rate found in the cabinet was 80 mrem per hour at 30 cm from a source. Upon identification, a source inventory was conducted which showed that all sources were accounted for and the cabinet was locked. Actions taken to identify and correct the

deficient condition and to place the issue into the corrective action system were appropriate. The failure to maintain the posted high radiation area storage cabinet locked was contrary to radioactive source storage requirements in N1-RSP-1Q, "Accountability of Calibration and Check Sources at NMP Unit 1," Rev. 0. This violation is minor in nature and is not subject to formal enforcement action.

c. Conclusions

Radiological controls for the Unit 1 refuel outage were effectively planned and implemented and focused on jobs with elevated exposure estimates, high dose rates, and radiologically complex work.

Radiological posting practices for access to radiation areas, high radiation areas, and airborne radioactivity areas were effective as evidenced by well defined boundaries and clear radiological postings. Some opportunities to enhance informational postings on the refuel floor that required "health physics notification prior to entry" beneath the drywell dome and reactor head insulation were identified.

Contamination monitoring requirements for access to the turbine building "Green Area" (clean area within the radiologically controlled area {RCA}) did not include an entire whole body frisk similar to the requirements for RCA exit. However, they were acceptable to minimize the risk for the spread and ingestion of significant amounts of radioactive contamination based on use of detailed procedures, restrictions on the personnel that could use the facility, and close health physics oversight.

Effective high radiation area controls were implemented as evidenced by clear radiological postings, use of locked doors when required, use of "Alarming" dosimetry, use of radiation work permits, use of remote door alarms, requirements for a minimum available exposure for access, and increased health physics oversight and monitoring for high radiation area entry.

**R2 Status of RP&C Facilities and Equipment**

**R2.1 Radiological Housekeeping (Units 1 and 2)**

a. Inspection Scope (83750 and 86750)

Plant tours were conducted to evaluate housekeeping and cleanliness and material conditions. Information was gathered through tours of Unit 1 and Unit 2 radwaste buildings and through the Unit 1 drywell, reactor and turbine building.

b. Observations and Findings

Housekeeping practices were effective as evidenced by clear isles and walkways, neatly stored tools and equipment, and well illuminated work areas. Material condition for the reactor and radwaste buildings were generally very good with painted floor and wall surfaces.

c. Conclusion

Material conditions were good and housekeeping practices were effective as evidenced by clear aisles and walkways, neatly stored tools and equipment, and painted floor and wall surfaces.

**R7 Quality Assurance in RP&C Activities**

**R7.1 Radiological Control Program Corrective Actions (Units 1 and 2)**

a. Inspection Scope (86750)

A review was performed of the use of audits, appraisals, and DERs for the identification and resolution of deficiencies in the area of radiological controls and radwaste management and transportation. Information was gathered through discussions with cognizant personnel and selected reviews of quarterly self-assessments, audits, and DERs.

b. Observations and Findings

A combination of self-assessments and quality assurance audits were performed to meet the requirements for an annual review of radiation protection program content and implementation as required by 10CFR20.1101(c). Quarterly self-assessments were performed at each unit to identify trends in program areas. Self-assessments included a review of radiation exposure, radiological safety indicators, and radiation worker performance. Semi-annual self-assessments in radiological controls were performed to review common elements of Unit 1 and Unit 2 radiological controls programs. Quality assurance audits of radiological controls and radwaste management were often performed with the assistance of industry peers. Deficiencies arising from self-assessments and audits were addressed through the DER system and opportunities for improvement were maintained on an "Action Item List" for evaluation and review.

Two significant deficiencies were selected to evaluate the effectiveness of corrective actions:

DER 1-97-0762 dated March 16, 1997, was written during the previous refuel outage at NMP1 (RFO14) after an irradiated core component (tie-rod mid-support piece) was placed on the reactor cavity seal plate which resulted in elevated dose rates and an audible indication of increased dose rates on the upper drywell radiation monitor system. Two individuals who were or may have been in the upper drywell at the time of the event were alerted by the audible indication of increased dose rates (increased chirping rate) and exited the drywell without receiving a significant exposure. Dose rates on the mid-support piece were subsequently measured to be 200 rem per hour on contact. Immediate corrective actions included restriction of personnel access to the upper elevations of the drywell; relocation of the mid-support piece to the equipment pit; and issuance of a stop work order on the fuel floor. A root cause analysis identified multiple barrier failures which resulted in the event including the failure to recognize and

communicate that the mid-support piece was an irradiated core component. Preventative actions included revision of multiple procedures to include appropriate communications and radiological controls for restriction of personal access during movement of the mid-support piece and other irradiated core components.

Radiological control barriers that were in place at the drywell included 1) use of electronic alarming dosimetry, 2) use of a remote radiation monitoring system with detector probes in the upper drywell, and 3) the health physics staff had a policy to evacuate the upper drywell if elevated radiation readings/alarms were received by the upper drywell radiation monitoring system. Total dose to the individuals electronic dosimetry for the drywell entry was 10.7 mrem and 29.5 mrem and the maximum dose rates measured by the worker's electronic dosimetry was 145.9 mrem per hour and 174.9 mrem per hour. These readings were typical for routine drywell entries. Maximum dose rates measured by the radiation monitoring system averaged 159.3 mrem per hour. Conservative exposure calculations estimated that the maximum dose rate to the head of an individual standing in the upper drywell would have been 978 mrem per hour.

A selected review of procedures verified that appropriate revisions had been made and interviews with cognizant personnel confirmed that personnel were knowledgeable of the event and actions to take for the movement of irradiated core components.

Technical Specification 6.11, "Radiation Protection Program" states that "procedures for personnel radiation protection shall be prepared consistent with the requirements of 10 CFR 20 and shall be approved, maintained and adhered to for all operations involving personnel radiation exposure." Procedure S-RAP-RPP-0801, "High Radiation Area Monitoring and Control" step 3.8.1 required the drywell 259 foot elevation ladder to be in place and locked to control access to the upper elevations of the drywell during the movement of an irradiated core component. Contrary to this requirement access restrictions to the upper elevations of the drywell were not maintained on March 15, 1997 during movement of a tie rod mid-support piece. This Severity Level IV violation is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy (NCV 50-220/99-04-07). This violation was in the licensee's corrective action program as DER 1-97-0762.

DER 1-97-1346, dated April 29, 1997, was also written during the previous refuel outage at Unit 1 after irradiated fuel was placed in the 198 cell rack adjacent to the spent fuel pool gate, resulting in unexpected elevated dose rates after drain down of 70 Rem per hour at contact with the bottom of the gate and 700 mrem per hour immediately above the spent fuel pool gates. Access to areas with elevated dose rates were appropriately controlled prior to and after the discovery of the elevated dose rates, no uncontrolled exposures resulted from the event, corrective and preventative actions were determined to be appropriate and no violations of NRC requirements were identified. An apparent cause evaluation determined that this event occurred because of a mis-communication or understanding between engineering and reactor engineering personnel regarding precautions for moving spent fuel within six feet of the spent fuel gate. Additionally, there were no procedures which specifically prevented the storage of fresh spent fuel adjacent to the spent fuel gate. Immediate corrective actions included restriction of access to the

area, establishing the area above the spent fuel gate as a high radiation area, and flooding the area between the spent fuel pool gates which dropped dose rates to 7 mrem per hour. Preventive actions included revision of procedures to require health physics notification prior to movement of the lower spent fuel gate shield plug (No. 9); to require shield plug No. 9 to be in-place for cavity work or to control the area as a locked high radiation area when the shield plug was not in-place; and a revision of fuel handling procedures to limit the storage of fuel in the 198 cell to only new fuel or spent fuel greater than one year old. A selected review of procedures during the inspection verified that appropriate revisions had been made and interviews confirmed that health physics personnel assigned to the refuel floor were knowledgeable of the event and actions to take when the lower spent fuel gate was moved.

c. Conclusions

Self-assessments, audits, and the deficiency/event reporting system were effectively used to identify, evaluate, and resolve radiological control issues as evidenced by the conduct of multiple self-assessments and audits to satisfy the radiation protection program review requirements in 10CFR20.1101(c). Appropriate corrective actions and controls to prevent unplanned exposures were implemented as a result of previous deficiencies.

One non-cited violation was identified associated with the failure to maintain access restrictions to the upper elevation of the drywell during movement of an irradiated core component on March 15, 1997.

V. Management Meetings

**X1 Exit Meeting Summary**

The inspectors presented the inspection results to members of the licensee management at the conclusion of the inspection on May 27, 1999. The licensee acknowledged the findings presented.



## ATTACHMENT 1

### PARTIAL LIST OF PERSONS CONTACTED

#### Niagara Mohawk Power Corporation

D. Bosnic	Manager, Operations, Unit Two
S. Doty	Manager, Maintenance, Unit One
N. Paleologos	Plant Manager, Unit Two
F. Fox	Acting Manager, Maintenance, Unit Two
R. Smith	Plant Manager, Unit One
N. Rademacher	Manager, Quality Assurance
D. Topley	Manager, Operations, Unit One

#### INSPECTION PROCEDURES USED

IP 37550	Engineering
IP 37551	On-Site Engineering
IP 61726	Surveillance Observations
IP 62707	Maintenance Observations
IP 71707	Plant Operations
IP 71750	Plant Support
IP 73753	Inservice Inspection
IP 83750	Occupational Radiation Exposure
IP 86750	Solid Radwaste Management and Transportation of Materials
IP 90712	In-Office Review of Written Reports of Non-Routine Events at Power Reactor Facilities
IP 92700	Onsite Follow-up of Written Reports of Non-Routine Events at Power Reactor Facilities
IP 92904	Followup - Plant Support

#### ITEMS OPENED, CLOSED, AND UPDATED

##### OPENED

50-410/99-04-01	NCV	Automatic Depressurization System Nitrogen Leakage in Excess of NMP2 Technical Specifications Surveillance Limits.
50-410/99-04-02	NCV	Unit 2 Reactor Core Isolation Cooling System Failure During Reactor Scram Transient.
50-220/99-04-03	IFI	Computer Security for 3D Monicore.
50-220/99-04-04	NCV	Failure to Maintain Core Thermal Limits as Required by Technical Specifications.

50-220/99-04-05	NCV	Failure to Conduct the Required ASME Code Inspections.
50-410/99-04-06	NCV	Failure to Ensure that the Service Water Intake De-icing Capability is Available During a Control Room Fire.
50-220/99-04-07	NCV	Radiological Control Program Correction Actions.
<b><u>CLOSED</u></b>		
50-410/99-04-01	NCV	Automatic Depressurization System Nitrogen Leakage in Excess of NMP2 Technical Specifications Surveillance Limits.
50-410/99-04-02	NCV	Unit 2 Reactor Core Isolation Cooling System Failure During Reactor Scram Transient.
50-410/98-05-02	VIO	Failure to Conduct Surveillance Test on Batteries.
50-220/98-02-05	VIO	Inadequate Plant Impact in Work Order Package.
50-220/99-04-04	NCV	Failure to Maintain Core Thermal Limits as Required by Technical Specifications.
50-220/99-04-05	NCV	Failure to Conduct the Required ASME Code Inspections.
50-410/98-05-03	VIO	Failure to Perform Adequate Design for Emergency Diesel Generator Modification on Fuel Line.
50-410/99-04-06	NCV	Failure to Ensure that the Service Water Intake De-icing Capability is Available During a Control Room Fire.
50-410/98-19-03	IFI	Leakage of Contaminated Water Following a Scram Reset.
50-220/98-16-02	VIO	Failure to Identify and Promptly Correct a Condition Adverse to Quality.
50-220/99-04-07	NCV	Radiological Control Program Correction Actions.
50-410/98-26	LER	Seismic Monitor Inoperable for More than Thirty Days and Special Reports Not Submitted.
50-410/99-03	LER	ADS Nitrogen Leakage in Excess of Unit 2 Technical Specifications Surveillance Limits.
50-220/99-03	LER	NMP1 Thermal Limit Exceeded the Requirements of Technical Specifications.

- 50-220/98-19 LER Missed ASME Section XI Inservice Inspection Due to Cognitive Error.
- 50-410/99-02 LER Missed Technical Specification Channel Functional Test of the Recirculation Flow Upscale Rod Block.
- 50-410/99-04 LER NMP2 Service Water Intake De-Icing Heater Control Circuits do Not Meet Fire Protection Program Requirements.

LIST OF ACRONYMS USED

AC	Alternating Current
ADS	Automatic Depressurization System
ALARA	As Low As is Reasonably Achievable
APLHGR	Average Planar Heat Generation Rate
APRM	Average Power Range Monitor
ASME	American Society of Mechanical Engineers
BWRVIP	Boiling Water Reactor Vessel and Internals Project
CDF	Core Damage Frequency
CFR	Code of Federal Regulations
CRD	Control Rod Drives
DAW	Dry Active Wastes
DC	Direct Current
DCP	Design Change Package
DER	Deviation/Event Report
DOT	Department of Transportation
dpm	Disintegration Per Minute
EC	Emergency Condenser
E/C	Erosion/Corrosion
ECCS	Emergency Core Cooling System
ECS	Emergency Cooling System
EDG	Emergency Diesel Generators
EP	Emergency Preparedness
EPA	Electric Protection Assemblies
ESA	Engineering Supporting Analysis
ESF	Engineered Safeguards Feature
ESL	Equipment Status Log
FCV	Flow Control Valve
FWBP	Feedwater Booster Pump
GAP	Generation Administration Procedure
HPCI	High Pressure Core Injection
HPCS	High Pressure Core Spray
IFI	Inspector Followup Item
IGSCC	Intergranular Stress Corrosion Cracking
IR	Inspection Report
ISEG	Independent Safety Engineering Group
ISI	In-Service Inspection
LCO	Limiting Condition for Operation
LER	Licensee Event Report
LOCA	Loss of Coolant Accident
LPRM	Local Power Range Monitor
LSFT	Logic System Functional Test
APRM	Local Power Range
NCV	Non Cited Violation
NDE	Nondestructive Examination
NMPC	Nine Mile Point Corporation

NRC	Nuclear Regulatory Commission
PRA	Probability Risk Analysis
PRNM	Power Range Neutron Monitor
QA	Quality Assurance
RCA	Radiological Controlled Area
RCIC	Reactor Core Isolation Cooling
RFO15	Refueling Outage
RPS	Reactor Protection System
RWP	Radiation work Permit
SDV	Scram Discharge Valve
SORC	Station Operating Review Committee
SRV	Safety Relief Valve
SSS	Station Shift Supervisor
TIP	Traverse Incore Probe
TS	Technical Specification
USAR	Updated Safety Analysis Report
Unit 1	Nine Mile Point Unit 1
Unit 2	Nine Mile Point Unit 2
UPS	Uninterruptible Power Supply
UT	Ultrasonic
WO	Work Order

