



FirstEnergy Nuclear Operating Company

5501 North State Route 2  
Oak Harbor, Ohio 43449

Brian D. Boles  
Vice President, Nuclear

419-321-7676

February 27, 2017

L-16-280

10 CFR 50.73

ATTN: Document Control Desk  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

Subject:  
Davis-Besse Nuclear Power Station, Unit 1  
Docket Number 50-346, License Number NPF-3  
Licensee Event Report 2016-008-01

Enclosed is Revision 01 to Licensee Event Report (LER) 2016-008-00, "Application of Technical Specification for the Safety Features Actuation System Instrumentation" to provide additional information subsequent to completion of the evaluation. The changes are marked with a revision bar in the margin. This event is being reported pursuant to 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by Technical Specifications.

There are no regulatory commitments contained in this letter or its enclosure. The actions described represent intended or planned actions and are described for information only. If there are any questions or if additional information is required, please contact Mr. Patrick J. McCloskey, Manager – Site Regulatory Compliance, at (419) 321-7274.

Sincerely,

Brian D. Boles

vaw

Enclosure: LER 2016-008-001

cc: NRC Region III Administrator  
NRC Resident Inspector  
NRR Project Manager  
Utility Radiological Safety Board

IEZZ  
NRR



**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Davis-Besse Nuclear Power Station, Unit 1	<b>2. DOCKET NUMBER</b> 05000 346	<b>3. PAGE</b> 1 OF 7
--	--------------------------------------	--------------------------

**4. TITLE:**  
Application of Technical Specification for the Safety Features Actuation System Instrumentation

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
06	30	2016	2016	008	01	02	27	17		05000
										05000

**9. OPERATING MODE**      **11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)**

<b>1</b>	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<b>100</b>	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> 73.77(a)(1)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 73.77(a)(2)(i)
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 73.77(a)(2)(ii)
		<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> OTHER	Specify in Abstract below or in NRC Form 366A

**12. LICENSEE CONTACT FOR THIS LER**

LICENSEE CONTACT: Vicki Wadsworth, Senior Nuclear Engineering Specialist – Regulatory Compliance	TELEPHONE NUMBER (Include Area Code) (419) 321-7690
---	--

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

**14. SUPPLEMENTAL REPORT EXPECTED**      **15. EXPECTED SUBMISSION DATE**

YES (If yes, complete 15. EXPECTED SUBMISSION DATE)       NO

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 30, 2016, at 0829, with the Davis-Besse Nuclear Power Station in Mode 1 and at approximately 100 percent power, a level transmitter for Safety Features Actuation System (SFAS) Channel 1 was declared inoperable for scheduled maintenance and Technical Specification (TS) Limiting Condition of Operation (LCO) 3.3.5 Condition A was entered. At 2342 hours a power supply in SFAS Channel 2 failed and a separate TS LCO 3.3.5 Condition A was entered. Upon recognition that two channels of SFAS were inoperable, TS LCO 3.3.5 Condition B was entered at 0245 and then exited at 0330 with the use of compensatory actions to restore SFAS Channel 1 operability. After further review, it was determined the compensatory actions could not be credited and TS LCO 3.3.5, Condition B was re-entered at 1325. SFAS Channel 1 was restored and declared operable at 1351 hours.

Causes of the event were the Shift Manager failed to initially recognize that TS LCO Conditions A and B had been met; followed by Station Personnel failing to effectively implement required processes. The root cause was that Station Management failed to recognize that a normalized deviation had occurred that resulted in TS noncompliance. Corrective Actions include specific refresher training to all applicable personnel, revising relevant documents, and developing an event Case Study for training purposes. This condition is being reported in accordance with 10 CFR 50.73(a)(2)(i)(B) as an operation or condition prohibited by the plant's Technical Specifications.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

**DESCRIPTION OF OCCURRENCE:**

**System Description:**

The Safety Features Actuation System (SFAS) [JE] at the Davis-Besse Nuclear Power Station (DBNPS) is designed to automatically prevent or limit fission product and energy release from the core, to isolate the containment vessel and to initiate the operation of Engineered Safety Features equipment in the event of a loss of coolant accident and main steam line break. The SFAS operates in a distributed manner to initiate the appropriate systems. The SFAS does this by determining the need for actuation in each of four channels monitoring each actuation parameter. Once the need for actuation is determined, the condition is transmitted to automatic actuation logics, which perform the two-out-of-four logic to determine the actuation of each end device. Four plant parameters are used for automatic SFAS actuation. The fifth parameter, the Borated Water Storage Tank (BWST) [BP-T] Level – Low Low, is used to provide a permissive to allow manual transfer from the BWST to the containment emergency sump.

The SFAS consists of four identical redundant instrument (sensing) and logic channels and two identical redundant actuation channels, and each instrument channel includes trip bistable modules with digital isolation devices. The isolated output of the trip bistable module is used to comprise coincidence matrices with the terminating relays within the actuation channel of the SFAS. The trip bistables monitor the station variables and normally feed continuous electrical (fail-safe) signals into two-out-of-four coincidence matrices. Should any of the station variables exceed their trip setpoints, the corresponding bistables in each of the four channels will trip and cease sending output signals. If two of the four channel bistables monitoring the same station variable cease to send output signals, the corresponding normally-energized terminating relays on all channels will trip.

The SFAS is a fail-safe, de-energize to trip, system. Therefore, if the power supply to a channel is lost, that channel will trip, reducing the system coincidence matrices from two-out-of-four to one-out-of-three mode. The terminating relays of sensing and logic channels 1 and 3 must both be de-energized to activate safety actuation channel 1. Similarly, sensing and logic channels 2 and 4 must both be de-energized to activate safety actuation channel 2. The terminating relays (also known as output relays) [JE-RLY] act on the actuation control devices such as motor controllers and solenoid valves.

The BWST supplies borated water for emergency core cooling via the Decay Heat Removal/Low Pressure Injection (LPI) System [BP] and High Pressure Injection (HPI) System [BJ], and as a source of borated water for the Containment Spray System [BE]. During accident conditions, the BWST provides containment cooling and depressurization, core cooling, and replacement inventory and is a source of negative reactivity for reactor shutdown. The BWST ensures that an adequate supply of borated water is available to cool and depressurize the containment in the event of a Design Bases Accident (DBA); to cool and cover the core in the event of a Loss of Coolant Accident (LOCA.), and to ensure an adequate level exists in the containment sump to support ECCS and containment spray pump operation in the recirculation mode.

The BWST level is monitored by four independent level transmitters. Each of the differential pressure signals generated by these transmitters is monitored by a bistable to provide a trip signal at a low low level. The BWST allowable value of greater than or equal to 101.6 inches of water and less than or equal to 115.4



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

**DESCRIPTION OF OCCURRENCE: (continued)**

inches of water was chosen to provide the operator with an alarm and a permissive to allow timely operation of the BWST outlet and containment emergency sump valves to the long term recirculation position. This is to protect the pumps from cavitation for lack of proper net positive suction head and allow transfer of ECCS suction to the containment emergency sump from the BWST during the recirculation mode of operation before the inventory of the BWST is depleted.

**Technical Specification(s):**

Technical Specification (TS) Limiting Condition for Operation (LCO) 3.3.5 requires four channels of SFAS instrumentation for each parameter to be operable in each SFAS train. Failure of any instrument renders the affected channel(s) inoperable and reduces the reliability of the affected parameter and affected systems or components. With one or more parameters with one channel inoperable, Condition A requires one channel be placed in trip in one hour. With one channel placed in trip in an hour and Condition A not met, or one or more parameters with two or more channels rendered inoperable, Condition B requires the unit to be in Mode 3 in 6 hours and Mode 5 within 36 hours.

**DESCRIPTION OF EVENT:**

On June 30, 2016, at 0829, with the DBNPS operating in Mode 1 at approximately 100 percent power, BWST SFAS Channel 1 Level Transmitter LT1525A was taken out of service for maintenance to replace the enclosure box and for calibration activities. SFAS Channel 1 was declared inoperable and TS LCO 3.3.5, Condition A was entered and the associated bistable for BWST Level was tripped. At 2342 hours with LT1525A still out of service, a failure of SFAS Channel 2 +15 Volt Power Supply occurred, rendering the SFAS Channel 2 inoperable, including SFAS Channel 2 BWST level instrument LT1525B. BWST Level Transmitters for SFAS Channel 3 (LT1525C) and SFAS Channel 4 (LT1525D) remained operable. A separate entry into TS LCO 3.3.5 Condition A was made at 2342 hours, but no entry into TS LCO 3.3.5 Condition B was made. At approximately 0140 hours on July 1, 2016, the Operations Crew became aware that TS LCO 3.3.5 Condition B should have been entered and various members of the Duty Team organization were contacted to discuss applicability of TS LCO 3.3.5 Conditions A and B.

On July 1, 2016, at 0245 hours following a plant Duty Team discussion where the condition was re-assessed, the proper additional TS LCO 3.3.5, Condition B was entered as required for two channels of BWST level functions inoperable, which requires a plant shutdown to Mode 3 in 6 hours. Following further discussions, between Operations and select Duty Team personnel, it was believed that SFAS Channel 1 could be considered operable with compensatory actions due to the BWST Level - Low Low level being a transfer permissive that allows transfer to the Emergency Sump with less than nine feet of level in the BWST. The compensatory actions were specific to SFAS Channel 1. Therefore, Operations exited TS LCO 3.3.5 Condition B at 0330 hours.

After further review, it was determined the compensatory actions associated with BWST Level - Low Low level transmitter could not be credited and the previous operability determination for SFAS Channel 1 was invalid. Operations re-entered TS LCO 3.3.5, Conditions A and B at 1325 hours.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

**DESCRIPTION OF EVENT: (continued)**

Upon completion of maintenance and successful testing, SFAS Channel 1 BWST Level Transmitter (LT1525A) was declared operable at 1351 hours and TS LCO 3.3.5 Condition B was exited. Upon replacement and testing of the +15 Volt power supply, SFAS Channel 2 was declared operable and TS LCO 3.3.5 Condition A was exited at 1800 hours on July 1, 2016.

**CAUSE OF EVENT**

The direct cause for the failure to properly apply TS 3.3.5 was determined to be that the Shift Manager failed to initially recognize that entry conditions for TS LCO 3.3.5 Condition B had been met following a loss of power to SFAS Channel 2. The TS was not reviewed in its entirety and provided peer checks were not performed independently.

A contributing cause of the improper application of TS 3.3.5 was determined to be that station personnel failed to use or rigorously implement required processes and procedures involving the conduct of operations, event reporting, operability determination, and regulatory communications and interface.

The root cause for the failure to properly apply TS 3.3.5 was determined to be that station management failed to recognize in a timely manner that a normalized deviation in organizational behaviors has occurred surrounding the accountability for critical performance standards and expectations. Additionally, organizational biases such as maintaining an unrealistic optimism towards an outcome, technical arrogance, overconfidence in knowledge and expertise, and the failure to seek or respond effectively to challenges, have resulted in the tendency to rationalize behaviors.

**ANALYSIS OF EVENT**

The BWST Level Transmitters monitor the BWST Level and initiate an SFAS Level 5 signal on BWST Level - Low Low. This output signal provides a passive permissive interlock to allow operators the ability to shift ECCS suction from the BWST to the Emergency Sump by allowing operators to open the Decay Heat Pump Suction From Emergency Sump Valves and close the associated BWST Isolation Valves. The transfer of suction source from the BWST to the Emergency Sump is a manual transfer. The Probabilistic Risk Analysis (PRA) models failure of the SFAS Level 5 permissive signal, as well as failure of the valves to be repositioned (or failure of the human action to manually transfer the suction), which could result in the inability of the plant to shift ECCS suction from the BWST to the Emergency Sump.

The four-channel SFAS system is a 2-out-of-four circuit, such that any two level instruments which sense a BWST Level - Low Low will actuate the permissive interlock for both trains. With both LT1525A and LT1525B out of service, the SFAS BWST Level - Low Low passive permissive transfer was active (i.e., the valves could be repositioned to shift from the BWST to the Emergency Sump) as indicated by Annunciator 5-3-A, BWST LO-LO LVL XFER TO EMER SUMP. Since the permissive interlock was met, a failure of this SFAS Level 5 permissive signal is not possible.

Having the transfer permissive interlock active while the BWST was still full could permit operators to inadvertently transfer suction from the BWST to the Emergency Sump (violating procedure guidance) before there was adequate volume in the Emergency Sump. Additionally, having the transfer permissive annunciator 5-3-A lit significantly prior to reaching the BWST Level procedurally directing the transfer to the



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

**ANALYSIS OF EVENT: (continued)**

Emergency Sump could potentially increase the probability that the Operators would not take the action to transfer suction when the appropriate level was reached. However, by procedure and by training, Operators would monitor, log, and trend BWST level, so they would be aware when the proper time to transfer occurred, and there would be minimal increase in the failure to perform the required action.

Based on the above, the condition of having two BWST Level Transmitters out of service does not result in an increase in CDF, as calculated by the PRA model, and this condition would be considered to have a very low safety significance.

**Reportability Discussion:**

On June 30, 2016, at 2342 hours, with the failure of SFAS Channel 2 Power supply, and SFAS Channel 1 BWST Level Transmitter previously declared inoperable for maintenance, TS 3.3.5, Condition B should have been entered due to the BWST parameter being inoperable for two channels of SFAS, requiring a 6-hour shutdown of the unit. However, as described above, while Condition B was entered on July 1, 2016 at 0245 hours, it was inappropriately exited at 0330 hours, and no shutdown initiated. Because the unit continued to operate after July 1, 2016, at 0542 hours with two channels of SFAS inoperable, this represents continued operation or condition prohibited by the plant's Technical Specifications, which is reportable per 10 CFR 50.73(a)(2)(i)(B). On July 10, 2016, a retrospective notification was made to the NRC (Event Number 52079) for initiation of a plant shutdown as required by the TS that should have been made in accordance with 10 CFR 50.72(b)(2)(i). All safety systems performed as required in response to the event, and no loss of safety function occurred.

**CORRECTIVE ACTIONS:**

**Immediate and Completed Actions:**

Upon completion of maintenance and successful testing, SFAS Channel 1 BWST Level Transmitter (LT1525A) was declared operable at 1351 hours on July 1, 2016. Upon replacement and testing of the +15 Volt power supply, SFAS Channel 2 was declared operable at 1800 hours on July 1, 2016.

The individual human performance issues by station personnel determined to have been in responsible decision making roles during the events were addressed in accordance with the company performance management process.

Station Leadership sought support of independent observers from the First Energy Nuclear Operating Company (FENOC) fleet to monitor activities in the control room during plant start-up from the most recent forced outage. An intended focus was to observe TS implementation.

Site Leadership conducted an All-Hands session with station personnel emphasizing the series of significant events in 2016 which resulted from gaps in performance standards. The Site Vice-President communicated that culpability for the deficiencies was shared among all station organizations. As such, it was emphasized that all personnel must internalize the need to modify behaviors to achieve event free operation.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

**CORRECTIVE ACTIONS (continued):**

Site Leadership issued a site-wide communication reaffirming the strict commitment to literal compliance with DBNPS TSs. The communications identifies Senior Reactor Operators (SROs) as having primary responsibility for TS compliance. Expected behaviors for the review and independent peer check of license conditions was also emphasized. The communication also establishes the role of other Station and Fleet personnel who may provide support to the SROs in assessing plant conditions, as having a shared responsibility for understanding TS and assuring literal compliance.

As an immediate action, a Standing Order was issued on July 6, 2016, to reinforce the expectations for review of TS and Operability Determinations, and Duty Team and Licensed Operator standards and expectation. Subsequently, Fleet Operations Procedure, "Conduct of Operations", and Operations Business Practice, "Conduct of Operations Handbook" was revised to improve Operator understanding and implementation of the TS. Specifically, a thorough review of the entire TS LCO and TS Bases shall be reviewed by both the reviewer and peer checker. An independent check shall be performed by a Licensed Operator. Both of these documents include direction for conducting briefs for equipment challenges to safety, risk, or reliability where no transient has occurred.

The standing order guidance has also been institutionalized in Fleet Operations Business Practice, "Operations Briefings and Challenge Calls". This business practice was revised to include a review of each Condition in its entirety for current license requirements. The review focuses on the potential for entry/escalation into additional Conditions due to subsequent determination on an inoperable System, Structure, or Component (SSC).

Additionally, Fleet Operations Business Practice, "First Energy Nuclear Operating Company (FENOC), Duty Teams", has been revised to include the following:

- Expectations for Shift Manager communications to the Duty Team regarding unplanned Technical Specification entries and/or emergent issues
- Expectations for Duty Team members regarding decision-making and any subsequent changes to a decision or course of action requires consultation of the full Duty Team and other affected stakeholders
- An expectation to consider staffing the Outage Control Center in the event of an unplanned TS LCO less than 72 hours is entered
- Include the use of the R.E.A.D.E (Recognize, Express, Appraise, Decide, Evaluate) Tool when addressing emergent equipment issues

Refresher training on TS has been provided to a targeted audience of key station stakeholders including select SROs (a Shift Manager, a Shift Engineer, a Unit Supervisor, and a Licensed Operator Training instructor at a minimum), a Duty Team Leader, a Duty Operations Manager, and a Duty Regulatory Compliance Manager.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
Davis-Besse Nuclear Power Station Unit 1	05000 - 346	2016	- 008	- 01

**NARRATIVE**

**CORRECTIVE ACTIONS (continued):**

A case study was developed to include the applicable lessons learned regarding; literal compliance with TS, TS vulnerability awareness, applicability of the Operability Determination process, applicability of Surveillance Requirement (SR) 3.0.1, and inappropriate bias and group think tools.

The Operations Manager shall develop and communicate a new expectation for Duty Directors, Duty Team Leads, Duty Operations, and Duty Regulatory Compliance Managers to conduct weekly observations of licensed operators implementing and applying TS.

The Davis-Besse Leadership Performance Improvement Commitment Plan, which recognizes leadership's contribution to the decline in performance involving the erosion of standards and expectations, has been implemented to provide for achieving Leadership and Team Effectiveness.

**Scheduled Actions:**

Based on the initial refresher training on TS provided to a targeted audience of key stakeholders, the training will be further customized and be presented to all Licensed Operators along with applicable Duty Team members. The curricula shall include, at a minimum, complex TS case studies, Operability Determination and Functionality Assessment including case studies and application of station procedures, case studies involving the use of compensatory measures, insights to regulatory positions, and Notices of Enforcement Discretion (NOED).

The case study that was developed to include the applicable lessons learned regarding; literal compliance with TS, TS vulnerability awareness, applicability of the Operability Determination process, applicability of Surveillance Requirement (SR) 3.0.1, and inappropriate bias and group think tools will be presented to the Supervisor Curriculum Review Committee for incorporation into the Supervisor Continuing Training Program for 2017. Training shall include all licensed reactor operators.

**PREVIOUS SIMILAR EVENTS**

DBNPS LER 2015-001 documents that the seismic BWST had been aligned in the past to the non-seismic Spent Fuel Pool system for purification. This rendered the BWST inoperable for periods of time longer than allowed per Technical Specification 3.5.4 while the plant was operating in Modes 1 through 4. However, this previous condition was not associated with the SFAS transfer permissive on BWST Level - Low Low, and the corrective actions taken for the previous event are not applicable to the current event.