

REGULATOR INFORMATION DISTRIBUTION ITEM (RIDS)

ACCESSION NBR: 8404190224 DOC. DATE: 84/04/05 NOTARIZED: NO DOCKET #  
 FACIL: 50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Gas 05000275  
 50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Gas 05000323

AUTH. NAME AUTHOR AFFILIATION  
 SCHUYLER, J.O. Pacific Gas & Electric Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Forwards response to issues identified during 840228-29  
 audit exit interview re analysis & qualification of annulus  
 structure framing sys. Ack of receipt of matl requested.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 12  
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES: J Hanchett 1cy PDR Documents. 05000275  
 J Hanchett 1cy PDR Documents. 05000323

|           | RECIPIENT<br>ID CODE/NAME | COPIES<br>L TTR ENCL | RECIPIENT<br>ID CODE/NAME | COPIES<br>L TTR ENCL |
|-----------|---------------------------|----------------------|---------------------------|----------------------|
|           | NRR/DL/ADL                | 1 0                  | NRR LB3 BC                | 1 0                  |
|           | NRR LB3 LA                | 1 0                  | SCHIERLING, H 01          | 1 1                  |
| INTERNAL: | ELD/HDS2                  | 1 0                  | IE FILE                   | 1 1                  |
|           | IE/DEPER/EPB 36           | 3 3                  | IE/DEPER/IRB 35           | 1 1                  |
|           | IE/DQASIP/QAB21           | 1 1                  | NRR/DE/AEAB               | 1 0                  |
|           | NRR/DE/CEB 11             | 1 1                  | NRR/DE/EHEB               | 1 1                  |
|           | NRR/DE/EQB 13             | 2 2                  | NRR/DE/GB 28              | 2 2                  |
|           | NRR/DE/MEB 18             | 1 1                  | NRR/DE/MTEB 17            | 1 1                  |
|           | NRR/DE/SAB 24             | 1 1                  | NRR/DE/SGEB 25            | 1 1                  |
|           | NRR/DHFS/HFEB40           | 1 1                  | NRR/DHFS/LQB 32           | 1 1                  |
|           | NRR/DHFS/PSRB             | 1 1                  | NRR/DL/SSPB               | 1 0                  |
|           | NRR/DSI/AEB 26            | 1 1                  | NRR/DSI/ASB               | 1 1                  |
|           | NRR/DSI/CPB 10            | 1 1                  | NRR/DSI/CSB 09            | 1 1                  |
|           | NRR/DSI/ICSB 16           | 1 1                  | NRR/DSI/METB 12           | 1 1                  |
|           | NRR/DSI/PSB 19            | 1 1                  | NRR/DSI/RAB 22            | 1 1                  |
|           | NRR/DSI/RSB 23            | 1 1                  | <u>REG FILE</u> 04        | 1 1                  |
|           | RGNS                      | 3 3                  | RM/DDAMI/MIB              | 1 0                  |
| EXTERNAL: | ACRS 41                   | 6 6                  | BNL (AMDTs ONLY)          | 1 1                  |
|           | DMB/DSS (AMDTs)           | 1 1                  | FEMA-REP DIV 39           | 1 1                  |
|           | LPDR 03                   | 2 2                  | NRC PDR 02                | 1 1                  |
|           | NSIC 05                   | 1 1                  | NTIS                      | 1 1                  |
| NOTES:    |                           | 1 1                  |                           |                      |

TOTAL NUMBER OF COPIES REQUIRED: L TTR 55 ENCL 48

... ..  
... ..  
... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..  
... ..

... ..

... ..

| ... | ... | ... | ... | ... | ... |
|-----|-----|-----|-----|-----|-----|
| X   | R   | ... | A   | R   | ... |
| X   | R   | ... | B   | R   | ... |
| X   | R   | ... | C   | R   | ... |
| X   | R   | ... | D   | R   | ... |
| X   | R   | ... | E   | R   | ... |
| X   | R   | ... | F   | R   | ... |
| X   | R   | ... | G   | R   | ... |
| X   | R   | ... | H   | R   | ... |
| X   | R   | ... | I   | R   | ... |
| X   | R   | ... | J   | R   | ... |
| X   | R   | ... | K   | R   | ... |
| X   | R   | ... | L   | R   | ... |
| X   | R   | ... | M   | R   | ... |
| X   | R   | ... | N   | R   | ... |
| X   | R   | ... | O   | R   | ... |
| X   | R   | ... | P   | R   | ... |
| X   | R   | ... | Q   | R   | ... |
| X   | R   | ... | R   | R   | ... |
| X   | R   | ... | S   | R   | ... |
| X   | R   | ... | T   | R   | ... |
| X   | R   | ... | U   | R   | ... |
| X   | R   | ... | V   | R   | ... |
| X   | R   | ... | W   | R   | ... |
| X   | R   | ... | X   | R   | ... |
| X   | R   | ... | Y   | R   | ... |
| X   | R   | ... | Z   | R   | ... |

# PACIFIC GAS AND ELECTRIC COMPANY

PG&E + 77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

J. O. SCHUYLER  
VICE PRESIDENT  
NUCLEAR POWER GENERATION

April 5, 1984

PGandE Letter No.: DCL-84-133

Mr. George W. Knighton, Chief  
Licensing Branch No. 3  
Division of Licensing  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington D.C. 20555


Re: Docket No. 50-275, OL-DPR-76  
Docket No. 50-323  
Diablo Canyon Units 1 and 2  
Audit of Unit 2 Annulus Design

Dear Mr. Knighton:

The NRC Staff performed an audit of the Diablo Canyon Unit 2 annulus design on February 28 and 29, 1984. Enclosed are PGandE responses to issues identified during the audit exit interview pertaining to analysis and qualification of the annulus structure framing system in Units 1 and 2.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,



Enclosure

cc: D. G. Eisenhut  
J. B. Martin  
H. E. Schierling  
Service List

3001  
11

8404190224 840405  
PDR ADOCK 05000275  
P PDR



## ENCLOSURE

PGandE RESPONSE TO ISSUES IDENTIFIED DURING  
NRC TECHNICAL AUDIT OF UNIT 2 ANNULUS DESIGN  
ON FEBRUARY 28-29, 1984

ISSUE 1


To address the issues raised in recent anonymous allegations, the NRC Staff suggested that the following items be considered by the Diablo Canyon Project (by generic calculations or example). The items pertain to the analysis and qualification of the annulus structure framing system in Units 1 and 2.

- a. Temperature differentials that occur in the transient conditions during plant startup and shutdown
- b. Local temperature differentials in supporting structural members of the framing system caused by the thermal environment in the supported pipe
- c. Local temperature effects due to jet impingement

RESPONSE 1a. Startup and Shutdown Conditions

The temperature variation in the annulus area during startup and shutdown was reviewed for Diablo Canyon and other comparable operating plants. During operation, the design temperature inside the containment is 1200F. Based on the fan cooler capacity of Diablo Canyon and operating experience at other plants, it is likely that during refueling the temperature in the annulus area will be between 80 and 900F. Considering the time between heating and cooling the annulus steel and the concrete crane wall (thermal inertia), a conservative estimate of the temperature differential between the two structural elements would be 400F. If a steel member is restrained axially by infinitely rigid supports, the induced axial stress due to a uniform temperature change of 400F over the entire length of the member would be 7.54 ksi ( $\sigma = \alpha E \Delta T = (6.5)(10)^{-6}(29)(10)^6(40) = 7.54$  ksi).

If the flexibility of restraining supports or members is considered, the induced axial stress in the restrained member would be reduced. For example, if the stiffness of the supports is twice the stiffness of the restrained member, the resulting stress would be 2/3 of the fully restrained case, or 2/3 (7.54) = 5.03 ksi. Considering the actual geometry of the annulus structure and the crane wall, this latter condition would be an upper limit on the



incremental axial stresses in the annulus steel resulting from the transient thermal differential between the annulus structure and the crane wall.

The self-limiting characteristics of secondary stresses are recognized by the prevalent industry codes, such as ANSI and ASME, which permit higher stress allowables when load combinations include thermal effects. Specifically, the ANSI Code allows the stresses to be increased over normal limits by a factor of 1/3 to 1/2. The FSAR does not mention the specific loading condition involving transient thermal effects during plant startup and shutdown. However, if the FSAR loading combination applicable to the containment's internal structure during normal operating conditions is considered, the condition only includes DE and not DDE or Hosgri. For axial loads where the normal allowable stress for A-36 material is 0.6 fy, or 21.6 ksi, the permissible 1/3 increase is, therefore, 7.2 ksi. This is greater than the computed maximum incremental stress due to a 40°F differential temperature. The inclusion of the transient thermal effect and simultaneous increase in stress allowable will, therefore, result in a stress condition that is less restrictive than the loading condition which ignores the transient effect.

#### b. Local Pipe Effects

The air temperature in the annulus area is controlled by the HVAC system. With a conservative estimate of 7.6 air changes per hour and circulation in the annulus area equal to or greater than the average circulation inside the containment structure, there is sufficient mixing of air so that the temperature will be nearly uniform. The only deviation would be localized in the vicinity of a hot pipe attachment.

The temperature of structural members in the vicinity of hot pipe attachments decreases very rapidly within a short distance from the pipe. Examples of this are shown in the Attachment. Even though the temperatures in the annulus area are somewhat different from temperatures under which these data were gathered, several important points are applicable. First, the temperature of steel attachments to the piping at the outer surface of the insulation indicates that about half of the temperature differential between the pipe surface and the air takes place in the insulation. In the annulus area, a similar reduction would be expected. Second, the temperature reduces very rapidly beyond the insulation. As indicated in the earlier discussion associated with the temperature differential between the annulus steel and the crane wall, a 40°F differential over the entire length of a structural framing member causes an increase in stress of less than 1/3 of the allowable working level stresses. Considering the rapid reduction in temperature of the steel attachments beyond the insulation, and the further temperature reduction in the cooler ambient air, the average temperature change over the entire length of a structural framing member is expected to be considerably less than 40°F. This is particularly true for the rigid structural steel pipe supports which are efficient conductors of heat and which, in turn, are attached to major structural steel members of considerable length (17 ft. long or more). Therefore, the inclusion of this condition with other normal operating loads with the attendant increase in stress allowables does not produce a more restrictive load combination.





### c. Jet Impingement Thermal Effects

From previous investigations, it has been determined that there are only two locations where jets can strike structural members of the annulus framing system Unit 1. The Unit 2 evaluation is still in progress. At one of these locations, the postulated jet is far enough away from the impacted member (column 8) such that the surface temperature of the member is only about 170°F. As discussed in the previous items, such a localized rise in temperature will not result in a controlling condition.

In the second location, the postulated jet is potentially very close to the member (column 6, approximate elevation 111'). Considering the worst scenario of a continuous jet spraying directly on the member, rather than the more realistic case of an intermittent jet spray, the surface temperature of the member would be approximately 500°F. This condition will cause axial growth and some bowing of the column.

The axial growth can take place virtually unrestrained. The only members attached to this column are in horizontal planes at elevations 101', 106', 117', and 140'. The members at the lower three elevations are steel members which have very small resistance to vertical movement at the column location. Therefore, these members move with the column and induce virtually no load in the column or in themselves. The column supports a 20-in. thick concrete slab at elevation 140'. This slab offers very little resistance to the vertical growth of the column (approximately 1/4 to 3/8 in.) since it is simply supported at the crane wall. The minor resistance that does exist results from the slab being supported by adjacent columns not subjected to the jet. The flexural stiffness of the slab spanning between these columns is negligible compared to the axial stiffness of the column, thereby allowing the column to move vertically. This mode of behavior (axial growth), therefore, is not a design controlling condition.

The bowing behavior has also been investigated for this very conservative case of the jet spraying directly on the column. For this relatively simple case, definition of the temperature gradient is very difficult. Rudimentary calculations indicate that there is a possibility of some local yielding at two support points of the column at elevations 106' and 117'. Excluding the bowing behavior, the stress in the column at these points is relatively low. The combined effect of axial and bending stresses, including the jet pressure as expressed by the AISC interaction equation, produces a stress ratio of only 0.62 compared with the allowable limit of 1.0. When the bowing effect is included, this ratio may exceed 1.0, but the conditions are still acceptable from an engineering point of view and still meet the requirements in the FSAR as discussed below. In actual behavior, some local yielding may develop from the imposition of the thermally induced stresses with the other stresses, but this yielding will simply relieve the thermal stresses. The column will continue to perform its function of providing vertical support for all attached members. This is true since the column is adequately braced by the annulus structure at elevations 106' and 117', and the axial stress in the column, excluding thermal loads, is only 14.3 ksi.



1000

1000

1000

1000

1000

1000

The FSAR states that for the load combinations which involve thermal loads associated with postulated pipe break, "Thermal loads are neglected when it can be shown that they are secondary and self-limiting in nature and where the material is ductile." The above discussion describes a condition where the thermal loads are secondary and self-limiting. Since the columns in the annulus structure are fabricated from low carbon steel, the material is ductile. This satisfies the requirements in the FSAR to neglect the thermal loads.

## ISSUE 2

One connecting bolt was identified as having been qualified by using the 8th Edition of the AISC Code, whereas the licensing criterion specifies the use of the 7th Edition.

## RESPONSE 2

During the technical audit, the NRC Staff observed that the 8th Edition of AISC Code was used in qualifying one of the annulus steel brace connections. This was found in calculation 2123C-5. The case was discovered during an attempt to compare the qualification methods of member connections adopted by Unit 1 with those used by Unit 2.

It was noted during the audit that:

- a. Use of the AISC Code, 8th Edition, was an isolated case.
- b. Calculation 2123C-5 is based upon the very conservative assumptions that bolt threads are included in the shear plane and that the connection was a friction type.

However, a field walkdown conducted on March 2, 1984, revealed that the threads are excluded from the shear plane. Also, the as-built drawing indicates that the bolts are A325-X, and thus, a bearing type connection. Based on the above data, the brace connection is also qualified to the AISC Code, 7th Edition. The changes have been incorporated in the calculations.

A further investigation was conducted to determine how extensively the AISC Code, 8th Edition, was used in the annulus steel evaluation. A complete review was performed of the Unit 1 annulus steel calculations pertaining to final qualification analysis. From this investigation, it was found that no other calculations contained the AISC Code, 8th Edition, as a reference. Calculation 2123C-5 has been corrected to indicate the proper reference.

## ISSUE 3

The following QA issues were identified in Unit 2 annulus calculations:

- a. A single originator's name was on certain calculation sheets that appeared (based on distinct differences in handwriting) to have been prepared by



11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200

201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300

301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400

401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500

501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600

601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700

701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800

801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
841  
842  
843  
844  
845  
846  
847  
848  
849  
850  
851  
852  
853  
854  
855  
856  
857  
858  
859  
860  
861  
862  
863  
864  
865  
866  
867  
868  
869  
870  
871  
872  
873  
874  
875  
876  
877  
878  
879  
880  
881  
882  
883  
884  
885  
886  
887  
888  
889  
890  
891  
892  
893  
894  
895  
896  
897  
898  
899  
900

two different individuals. It also appeared that the name of the other originator was erased. The original checker's date also appeared to have been erased and new dates entered.

- b. A few calculation sheets updated to Rev. 1 showed evidence of voiding the sheet by drawing an "X" across the sheet and writing "void." However, the "X" and "void" notations were subsequently erased, returning the calculation sheet to a valid status.

### RESPONSE 3

- a. The sheets in question were part of a calculation which was started by one engineer and only partially completed before the engineer was temporarily transferred to a different assignment. To complete the task, a second engineer continued the calculations. This engineer reviewed the partially completed work by the previous engineer and, upon agreeing with it, decided to adopt that work as his own and entered his name as the originator. This is consistent with Diablo Canyon engineering procedures. He then completed the calculation and gave it to the original checker. When the checker reviewed the entire calculation, including the previous work, to make sure it was acceptable for any changes made, he signed the new sheets with the appropriate date and also revised the dates on the earlier partially completed sheets to indicate that the entire calculation was checked again. This is also consistent with Diablo Canyon engineering procedures. The NRC Staff auditors reviewed the final calculation and found it to be acceptable in its present form.
- b. PGandE has investigated the situation and, based on a discussion with the originator and checker, found the following:

The originator and the checker said that the calculation under consideration was made early in the annulus verification analysis (Phase I). However, when the final qualification analyses of the annulus were made, following the development of the final vertical floor response spectra (Phase II), the checker reviewed the Phase I calculations and concluded that they could not be used for all of the Phase II work. Therefore, he decided to void them and have the originator generate a new calculation. Upon consultation between the originator and the checker, the originator pointed out that the original calculation should not be voided since it was applicable to all Phase I work and also to some of the special cases in Phase II work. Also, since new calculations were made for Phase II where Phase I calculations could not be used, it was correct not to void the original calculation. Therefore, based on the agreement between both the originator and the checker, the calculations were reinstated to a valid status.



Attachment

TEMPERATURE DISTRIBUTION DATA

The following report describes a survey made to determine temperature distribution on various types of Grinnell-engineered pipe supports.

The temperatures of the supports were measured with iron-constantan thermocouples.

The insulation, 4-in. thick combination, in two layers and covered with canvas, was removed to permit the tack welding of the thermocouples to the pipe supports. All insulation was replaced 20 hours before any readings were taken.

The following pages present the results of this survey, with a sketch of the assembly and a temperature differential chart.





## SINGLE ROD ASSEMBLY


Sixteen (16) thermocouples were tack welded to a Grinnell Fig. 224 Forged Alloy Pipe Clamp at the positions indicated in Figure #1.


Because of the irregular sections of this assembly, the temperatures cannot be conclusively plotted against the distance from the pipe; hence, no graph showing differentials is included.

The average temperatures in degrees Fahrenheit were:

|                           |           |            |
|---------------------------|-----------|------------|
| Steam temperature - 905°  |           |            |
| Ambient Temperature - 90° |           |            |
| Thermocouple #1 - 888°    | #6 - 736° | #11 - 255° |
| 2 - 858                   | 7 - 745   | 12 - 310   |
| 3 - 792                   | 8 - 655   | 13 - 132   |
| 4 - 803                   | 9 - 575   | 14 - 272   |
| 5 - 749                   | 10 - 508  | 15 - 113   |
|                           |           | 16 - 90    |

Figure #1





## RISER CLAMP

One (1) thermocouple was attached to the pipe, nine (9) to the clamp (one of these tacked close to the one on the pipe), one (1) on the nut of one of the clamp bolts, and one (1) on the eye rod. The positions were as indicated in Fig. #1. Figure #2 shows temperature differentials.

The average temperatures in degrees Fahrenheit were:

|                           |           |           |
|---------------------------|-----------|-----------|
| Steam temperature - 900°  |           |           |
| Ambient temperature - 83° |           |           |
| Thermocouple #1 - 885°    | #5 - 451° | #9 - 257° |
| 2 - 857                   | 6 - 349   | 10 - 211  |
| 3 - 664                   | 7 - 306   | 11 - 219  |
| 4 - 573                   | 8 - 269   | 12 - 115  |

Figure #1






Figure #2





TRAVEL STOP

Two (2) thermocouples were tack welded to the pipe, seven (7) to one of the side plates, one (1) to the eye bolt nut, one (1) on the outside edge of the bottom plate, one (1) on the eye of the eye bolt, and two (2) on the supporting rod, at the distances indicated on Figure #1. Temperature differentials are shown in Figure #2.

The average temperatures in degrees Fahrenheit were:

|                           |           |            |
|---------------------------|-----------|------------|
| Steam temperature - 890°  |           |            |
| Ambient temperature - 90° |           |            |
| Thermocouple #1 - 885°    | #6 - 361° | #11 - 167° |
| 2 - 873                   | 7 - 279   | 12 - 167   |
| 3 - 818                   | 8 - 238   | 13 - 145   |
| 4 - 682                   | 9 - 214   | 14 - 108   |
| 5 - 477                   | 10 - 183  | 15 - 97    |

Figure #1






Figure #2





## TRAPEZE ASSEMBLY

This support consists of a pipe covering protection saddle and two channels, as shown in Figure #1.

Two (2) thermocouples were tacked on the pipe, four (4) on the protection saddle, four (4) on the channel, one (1) on a rod nut, and three (3) on one rod, at the distances indicated. Figure #2 represents the temperature differential.

The average temperatures in degrees Fahrenheit were:

|                           |           |           |  |
|---------------------------|-----------|-----------|--|
| Steam temperature - 900°  |           |           |  |
| Ambient temperature - 90° |           |           |  |
| Thermocouple #1 - 897°    | #6 - 386° | #11 - 94° |  |
| 2 - 872                   | 7 - 259   | 12 - 94   |  |
| 3 - 736                   | 8 - 180   | 13 - 90   |  |
| 4 - 681                   | 9 - 147   | 14 - 90   |  |
| 5 - 542                   | 10 - 93   |           |  |

Figure #1






Figure #2







GUIDE

Two (2) thermocouples were tack welded to the pipe, four (4) to the protection saddle, and one (1) to the adjacent beam. The positions of the thermocouples were as indicated in Figure #1. Figure #2 is the temperature differential chart.

The average temperatures in degrees Fahrenheit were:

|                     |   |      |           |
|---------------------|---|------|-----------|
| Steam temperature   | - | 900° |           |
| Ambient temperature | - | 88°  |           |
| Thermocouple #1     | - | 897° | #5 - 553° |
| 2                   | - | 888  | 6 - 453   |
| 3                   | - | 799  | 7 - 148   |
| 4                   | - | 703  |           |

Figure #1




Figure #2

