



Dennis R. Madison
Vice President – Plant Farley

Southern Nuclear
Operating Company
Farley Nuclear Plant
Post Office Drawer 470
Ashford, AL 36312

Tel 334.814.4511
Fax 334.814.4575

April 13, 2017

Docket Nos.: 50-348

NL-17-0539

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant
Special Report 2017-001-00, Nonfunctional Radiation Monitor R-60D

Ladies and Gentlemen:

In accordance with the requirements of Technical Requirements Manual (TRM) 13.3.4, the enclosed Special Report No. 2017-001-00 (Unit 1) is submitted.

This letter contains no NRC commitments. If you have any questions, please contact Elizabeth Williford at (334) 814-4765.

Respectfully submitted,

D. R. Madison
Vice President – Farley

DRM/JAC

Enclosure: Special Report 2017-001-00

cc: Southern Nuclear Operating Company
Mr. S. E. Kuczynski, Chairman, President & CEO
Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer
Mr. M. D. Meier, Vice President – Regulatory Affairs
Mr. R. D. Gayheart, Fleet Operations General Manager
Mr. B. J. Adams, Vice President – Engineering
Mr. J. J. Hutto, Regulatory Affairs Director
Ms. B. L. Taylor, Regulatory Affairs Manager – Farley
RTYPE: CFA04.054

U. S. Nuclear Regulatory Commission
Ms. C. Haney, Regional Administrator
Mr. S. A. Williams, NRR Project Manager – Farley
Mr. P. K. Niebaum, Senior Resident Inspector – Farley

Joseph M. Farley Nuclear Plant Unit 1

Enclosure

Special Report 2017-001-00, Nonfunctional Radiation Monitor R-60D

**Joseph M. Farley Nuclear Plant, Unit 1
Special Report 2017-001-00, Nonfunctional Radiation Monitor R-60D**

This Special Report is being submitted due to the Unit 1 radiation monitor R-60D (Auxiliary Feedwater Pump Turbine Exhaust) not being restored to functional status within the time required by Technical Requirements Manual (TRM) section 13.3.4. The TRM requires that the monitor be restored to functional status within 7 days or submit a Special Report within the following 14 days.

At 1235 on March 26, 2017, with Unit 1 in Mode 1 and operating at 100 percent power, radiation monitor R-60D was declared nonfunctional due to an erratic signal. A mandatory TRM Required Action was entered and a work order was generated to repair R-60D.

Troubleshooting of the loop failure isolated the problem to the detector. Due to the detector's location on the main steam valve room roof being in close proximity to steam generator safety relief valve exhaust piping, repair of the monitor is a personnel safety concern should any relief valve lift during the repair effort. Therefore, repair of the monitor should be performed only under cold shutdown conditions to ensure personnel safety. A work order is in place to be worked during the next refueling outage, or at the next available opportunity. In addition, a design change is scheduled to replace R-60D with a new radiation monitor. Compensatory measures have been established and TRM Required Actions are being met for radiation monitor R-60D nonfunctionality.