

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **Susquehanna Steam Electric Station - Unit 2** DOCKET NUMBER (2) **0 5 0 0 0 3 8 8** PAGE (3) **1 OF 0 1**

TITLE (4) **Fire Barrier Wrap Missing**

EVENT DATE (6)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)															
1	0	2	6	8	4	8	4	0	2	7	0	0	1	1	3	0	8	4	0	5	0	0	0	0	0	0

OPERATING MODE (9) **4** THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)
20.406(a)(1)(i)	50.38(a)(1)	50.73(a)(2)(v)	73.71(c)
20.406(a)(1)(ii)	50.38(a)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 308A)
20.406(a)(1)(iii)	X 50.73(a)(2)(ii)	50.73(a)(2)(vii)(A)	
20.406(a)(1)(iv)	50.73(a)(2)(iii)	50.73(a)(2)(vii)(B)	
20.406(a)(1)(v)	50.73(a)(2)(iv)	50.73(a)(2)(viii)	

LICENSEE CONTACT FOR THIS LER (12)

NAME **T. P. Baileys** TELEPHONE NUMBER **711 17 514 21-1312 1411**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
B	*	C N D	X 9 9 9	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15) **0 1 1 5 8 4**

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)


Three conduits were discovered on October 15, 1984, which had not been coated with fire barrier coating as required by the Fire Hazards Analysis. A nonconformance report was generated and routed to Plant Engineering for evaluation. On November 1, 1984, Plant Engineering determined that the condition affected the operability of the conduit fire barrier and notified operations to implement Technical Specification Action Statement 3.7.7.a and a fire watch was assigned to the area.

The cause of the lack of fire barrier wrap on these conduits could not be determined. The conduits appear to have never been wrapped with the fire barrier material although the surveillance procedure records imply they were found satisfactory on February 9, 1984. The documentation for the surveillance procedure cannot be located; however, the computerized tracking system indicates that it was completed on February 9, 1984. Due to the lack of documentation, the surveillance procedure will be performed again as soon as practical.

The three conduits will be coated with the fire barrier material as required. Due to an administrative error the fire watch was mistakenly assigned to area 30-672' rather than area 30-762'. This error was discovered on November 30, 1984 and corrected. Additional information regarding this error will be submitted in a supplement to this LER.

~~8412110208~~
Time

* Fire Barrier





SUSQUEHANNA STEAM ELECTRIC STATION
PO BOX 467, BERWICK, PA 18603


November 30, 1984

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 84-027-00
ER 100450 FILE 841-23
PLAS- 017

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 84-027-00. This event was determined reportable per 10CFR50.73(a)(2)(i)(B), in that three conduits were discovered missing their fire barrier wrapping.


H.W. Keiser
Superintendent of Plant-Susquehanna

TPB/pjg

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R.H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

Re-issued with Corrected Attachments

IE32
11

