ACCE (LE RATED DIST REGULATOR	RIBU'	TION IATION	DEMONSTRATION DISTRIBUTION)N·S M (RIDS	SYST 3)	EM	
ACCESSION FACIL:50 AUTH.N/ CRIST:M. BYRAM,R. RECIP.N	N NBR:8903210249 D-388 Susquehanna S AME AUTHOR A L. Pennsylva G. Pennsylva NAME RECIPIEN	DOC.L team E FFILIA nia Pc nia Pc T AFFI	ATE: 8 Lectri TION Wer & Wer & LIATIO	89/03/13 NOTARIZED c Station, Unit 2, Light Co. Light Co. N	: NO Pennsy	ylva	DOCKET # 05000388	
SUBJECT	: LER 89-002-00:on	881215	,inadv	vertent reactor cor	e isola	ation		F
μ.	cooring sys aucom	atical	.ту тпл	trated a injected.	W/8	lt	r.	្រ
DISTRIBU	JTION CODE: IE22D	COPIES	RECEI	VED:LTR ENCL	SIZE	:4	2	D
TITLE: S	50.73 Licensee Even	t Repo	ort (LE	ER), Incident Rpt,	etc.			S
NOTES:LI	PDR 1 cy Transcrip	ts.					05000388	
-	RECIPIENT	COPIE	S	RECIPIENT	COP:	IES		Å
	ID CODE/NAME ·	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL		_
	PD1-2 LA	l	ŀ	PD1-2 PD	1	1		D
	THADANI, M	1	1					D
INTERNAL:	ACRS MICHELSON	l	l	ACRS MOELLER	2	2		-
	ACRS WYLIE	1	1	AEOD/DOA	1	l		5
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2	r	
	ARM/DCTS/DAB	1	1	DEDRO	1	1		
	NRR/DEST/ADE 8H	1	1	NRR/DEST/ADS 7E	1	0		
	NRR/DEST/CEB 8H	1	1	NRR/DEST/ESB 8D	1	1		
	NRR/DEST/ICSB 7	1	1	NRR/DEST/MEB 9H	1	1		
I	NRR/DEST/MTB 9H	1	1	NRR/DEST/PSB 8D	1	1		
	NRR/DEST/RSB 8E	1	1	NRR/DEST/SGB 8D	1	l		
	NRR/DLPQ/HFB 10	1	1	NRR/DLPQ/QAB 10	1	l		
	NRR/DOEA/EAB 11	1	1	NRR/DREP/RAB 10	1	1		
	NRR/DREP/RPB 10	2	2	NRR/DRIS/SIB 9A	1	1		
	NUDOCS-ABSTRACT	1	1	REG_FILE 02	1	1		R
	RES/DSIR/EIB	1	1	RES/DSR/PRAB	1	1		
	RGN1 FILE 01	1	1	,				I
EXTERNAL:	EG&G WILLIAMS,S	4	4	FORD BLDG HOY,A	1	1		D
	H ST LOBBY WARD	1	1	LPDR	1	1		-
	NRC PDR	1	1	NSIC MAYS,G	1	1		S
	NSIC MURPHY, G.A	1	l					1
NOTES:	•	2	2					

NOTE TO ALL "RIDS" RECIPIENTS:

£

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

فالانجار ويوني المراجع

TOTAL NUMBER OF COPIES REQUIRED: LTTR 47 ENCL 46

- John a second and the

pla

A

D

D

S

(RC Form 366 9-83)			-	LIC	ENSE	E EVENT	REPO	ORT	(LER)	U.S. NU	CLEAR REGULATORY COMA APPROVED OMB NO. 3150-0 EXPIRES: 8/31/88	KISSION 104
Susqueha	nna St	eam I	Electric	Ŝtation	– Ur	uit 2			D C	OCKET NUMBER	12) PAC 0 3 8 8 1 OF	1E (3)
Tradavort	ont Po	acto	r Core Te	ation	്നി	ing Init	iati	ion a	and Inject	ion		
EVENT DATE		accu	LER NUMBER	(6)		PORT DATE (7)			OTHER F	ACILITIES INVO	LVED (8)	
MONTH DAY	NTH DAY YEAR YEAR SEQUENTIAL REVISION MONTH DAY YEAR FACILITY NAMES DOCK											
1 2 1 5	88	8 9 -	002	00	0 3	1 3 8	9			/	0 15 0 0 0	
OPERATING MODE (9)	1	20.40	DAT IS SUBMITTI	DPURSUANT	20,405	(c)	OF 10 C	FH 9: 70	50,73(a)(2)(iv)	r the following) (1	73,71(b)	
POWER		20.40	26(a)(1)(i)		50.38(:)(1)			50.73(e)(2)(v)		73.71(c)	
<u>(10)</u>		20.40	05(e){1)(ii)		50.36(:)(2)			50.73(a)(2)(vii)		X OTHER (Specify in Ab	strect C Form
	-	20.40	25(a)(1)(iii) 05(a)(1)(iv)		50.730)(2)(0))(2)(0)			60,73(s)(2)(viii)(A)	Voluntary	
		20.40	05(a)(1)(v)		50.734)(2)(III)			50.73(s)(2)(x)		voluntary	
NAME					LICENSEE	CONTACT FOR	THIS LE	ER (12)			TELEPHONE NUMBER	
Mi ob		~~i		lianco	Errali	ator				AREA CODE		
MICO	aer r.			JIIaice					·	7117		181
		<u> </u>	COMPLETE	ONE LINE FOR	R EACH C	OMPONENT FAIL	URE DI	ESCRIBE	D IN THIS REPOR	r (13) *		
CAUSE SYSTEM	COMPON	ENT	MANUFAC- TURER	TO NPRDS		c/	USE S	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	
<u> </u>	11								_ 1 _ 1 _ 1			<u></u>
<u>, </u>		1										
		-	SUPPLEM	ENTAL REPOR	T EXPECT	'ED (14)				EXPECT SUBMISS DATE (1	ED ION IS)	YEA
YES (If yes, c ABSTRACT (Limit)	omplete EXP to 1400 spece	ECTED S 11, 1.4., 401	DBMISSION DAT	E) I single-space typ	ewritten li	X NO (nes) (16)				<u> </u>		
On December 15, 1988 Unit 2 was operating in Condition 1 at 100% power. At 0841 hours the Reactor Core Isolation Cooling (RCIC) system automatically initiated on a false low reactor water level signal and injected to the reactor vessel. The false reactor level signal was the result of a pressure transient induced on the 2C004 instrument rack due to the mispositioning of an isolation valve by an I&C tecnician. The RCIC system injected to the vessel for approximately 29 minutes until it was manually shutdown. Reactor power increased to 101% during the event. No degradation of fuel was evident. An investigation of the event determined the plant's response to the transient was acceptable. I&C personnel have reviewed this event, and the necessity of accessing and evaluating unexpected conditions when they												
r s r F I	revise tatus adiat The RC Ceatur	d to of ion CIC e, 50.7	o requi affect monito System therefo 3. The	re tha ed sys r annu at Sus re thi repor	t co tem(ncia queh s ev t is	ntrol r s) shou te. anna is ent is being	not pro	a Re a Re ot an rep vide	erators eactor B n Engine portable ed on a	review uilding ered Sa per volunta	the area afety ary	2J 1
		1	8000	010040	~~~						ł	

¥ 9.84 4.1 ۰,

¥

:

.

, en 14

•

.

-,

.

٠,*

.

.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION											
FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 2	DOCKET NUMBER (2)	LE YEAR	R NUMBER (6)	MEVISION NUMBER	ра 0 2	GE (3)					

TEXT (If more space is required, use additional NRC Form 305A's) (17)

EVENT_DESCRIPTION

At 0800 hours on December 15, 1988 with Unit 2 operating in Condition 1 at 100% power, I&C personnel began performing surveillance SI-280-206. The surveillance is a monthly functional test of Primary Containment Isolation (EIIS Code: JM) System level transmitters, LITS-B21-2N026A, B, C, D. The I&C technicians (utility/non-licensed) had completed testing of LITS-B21-2N026A, and were preparing to test LITS-B21-To isolate 2N026B, the I&C technician closed the 2N026B. reference leg isolation valve, then opened the equalization As the technician began closing the variable leg valve. isolation valve a packing leak developed. The technician stopped closing the variable leg isolation valve, and tightened the packing nut to stop the leak. The valve was in mid-position. While focusing his attention on insuring that the leak was stopped, the technician inadvertently re-opened the valve instead of closing the valve. A test pressure source was then connected across the equalizing valve. When the technician began opening the first test connection isolation valve, at approximately 0841 hours, he noticed level indication on the other in-service instrumentation on the 2C004 rack change, including level transmitters LIS-B21-2N031A and C which cause an automatic initiation of the Reactor Core Isolation Cooling (RCIC) (EIIS Code: BN) System. He immediately closed the test connection valve, rechecked the valve position, and discovered that the variable leg isolation valve was open. The I&C technician at the the instrument rack contacted the I&C technician in the control room and informed him of the transient. The control room technician did not observe any alarms and concluded that the transient had no adverse affect on the plant. As such, he did not inform the Plant Control Operator (PCO) (utility/licensed). The valve line-up was corrected and the technicians proceeded with the surveillance.

Approximately two minutes (0843 hours) later a Reactor Building area radiation monitor (ARM) alarm was received in the control room. No other alarms were received. As required by Alarm Response procedure, AR-201-001, the PCO determined that the ARM in the RCIC turbine room had caused the alarm and was indicating approximately 4 to 5 mr/hr. In accordance with AR-201-001, the PCO dispatched a Health Physics technician to perform a survey of the RCIC turbine room to verify the ARM reading. An attempt to reset the alarm was unsuccessful. The PCO then investigated the alarm setpoint to determine if the indicated readings would cause the alarm. He confirmed that they would. The setpoint of the monitor was 4 mr/hr. Following this confirmation, Health Physics personnel had completed surveying the RCIC turbine area and had verified the ARM reading. The PCO then

والوجعانية ومرجز الرواد معرواهم والطامحة أخوها الراجي مراري مراريا المارا ووريكار والا

:

فستعصيفه والمعالية والعالي والمتعالية والاستهما

¥RC Form 366A (9-83)		ULATORY COMMISSION MB NO, 3150-0104 /88		
Susquehanna Steam Unit 2	Electric Station -	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
	te/ ta page ∸t-orang	0 5 0 0 0 3 8 8	819 - 0 0 2 - 010	03 05 0 5

TEX I (If more spece is required, use additional NRC Form 305A's) (17)

determined that RCIC was in operation. After verifying that no valid initiation signal was present, the system was shutdown (0910 hours). At 0915 hours the RCIC system was declared inoperable and Limiting Condition of Operation 3.7.3 was entered.

An investigation was conducted, including why no alarms were received for the RCIC initiation. A reactor vessel high/low level alarm was not received during the event since this alarm is generated by the reactor level channel selected for feedwater level control. At the time of the transient, the B channel was selected which originates from the 2C005 A RCIC instrument rack and was unaffected by the transient. Division II reactor low level initiation alarm does exist, however this alarm is generated by LIS-B21-2N031B and D which are mounted on the 2C005 rack. There is no comparable Division I alarm. A RCIC low flow alarm was not received during the RCIC initiation since this alarm is defeated for 15 seconds following a system initiation. RCIC flow was verified to be greater than the low flow setpoint within 15 seconds using historical computer data. Thus, it was concluded that the RCIC system's response was per design and the system was declared operable at 1245 hours.

CAUSE OF EVENT

The event was caused by the I&C technician's failure to close the variable leg isolation valve prior to connecting the test pressure source and opening the test connection valve. As a result, the valving error caused a pressure perturbation on the 2C004 instrument rack simulating a -30 inch reactor level condition at level switches LIS-B21-2N031A and C, resulting in an automatic initiation of the RCIC System.

Secondly, had the I&C technician informed the PCO of the transient at the instrument rack, the PCO would have discovered that the RCIC system was injecting water into the vessel. The knowledge of a transient on the rack, on which Emergency Core Cooling System initiation instrumentation is mounted, coupled with the higher than normal radiation level in the RCIC room being alarmed in the control room, would have given the operator sufficient cause to review the control room panels. Upon review of the panels, the PCO would have observed that RCIC was in operation.

EVENT ANALYSIS

The RCIC system injected to the vessel for 29 minutes. Reactor power increased to 101% power during this time due to :

U.S. NUCLEAR REGULATORY COMM (1983) LICENSEE EENT REPORT (LER) TEXT CONTINUAEN LICENSEE EENT REPORT (LER) TEXT CONTINUAEN APPROVED OMB NO. 3150-010 EXPIRES: 8/31/88											
FACILITY NAME (1)	DOCKET NUMBER (2)	[ĻE	R NUMBI	ER (6)				PAGE	(3)	
Susquehanna Steam Electric Station - Unit 2		YEAR		SEQUEN NUMB	ER		REVISION NUMBER		Τ		
	0 5 0 0 0 3 8 8	8 9	_	0 0	2		0 0	0 4	OF	0	5

TEXT (If more space is required, use eddk.":nel NRC Form 305A's) (17)

increased core inlet subcooling. While RCIC was injecting to the 'A' Feedwater Header the temperature of the feedwater injecting to the vessel decreased approximately 12 degrees F. Operation at 101% power for 29 minutes was within the allowable deviation limits of the licensed power level. No fuel thermal limits were exceeded and no fuel preconditioning guidelines were exceeded. No changes in offgas pretreatment radiation levels occurred. A conservative analysis of the injection, performed by Nuclear Plant Engineering, indicates that the current fatigue usage factor for all affected injection nozzles is less than 0.70. As of December 15, 1988, the total number of RCIC injections, for all reasons, for Unit 2 is 59. Based on the above, this event did not pose any significant safety consequences.

REPORTABILITY

Per Section 6.0 of the Final Safety Analysis Report, the Reactor Core Isolation Cooling System is not an Engineered Safety Feature. Thus, the event is not reportable per 10CFR50.73. This report is being submitted on a voluntary basis.

CORRECTIVE ACTIONS

Procedure SI-280-206 was reviewed and found to be accurate and easily followed. The failure to close the isolation valve is attributed to the I&C technician's attention being diverted by the packing leak on the valve. I&C personnel have reviewed this event, and the necessity of accessing and evaluating unexpected conditions when they occur. The training also emphasized the importance of notifying Operations personnel of any system perturbations.

In addition, the installation of an audible alarm in the control room to alert the control room operator of a RCIC system initiation was investigated and found to be not Adequate control room instrumentation exists to justifiable. alert the control room operator and allow him to diagnose inadvertent initiations. At power, whenever the RCIC system actuates, the representative room area radiation monitor trips, and produces an alarm in the control room as happened in this event. To modify the plant for the addition of other alarms is redundant and unnecessary. A revision to the alarm response procedures requiring the operator to review the control room panels, should a Reactor Building area radiation monitor annunciate, will achieve the identical results as an alarm which specifically annunciates on the initiation of RCIC. The alarm response procedures have been revised.

TIRC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION													SION			
Susquehanna Steam Electric Station -		DOCKET, NUMBER (2)							YEAR	LE	R NUMBER (6	UMBER (6)			PAGE (3)		
Unit 2	age 11 - 1 - 10 - 21 102 01000000000000000000000000000000000	0	5	0	0	0	3 8	8	8 9	_			0 0	0 5	OF	0	5
TEXT (If more space is required, up	additional NRC Form 3954's) (17)			_					· · · · · · · · · · · · · · · · · · ·								

ADDITIONAL INFORMATION

Previous License Event Reports from both units were reviewed to identify any similar events, none were found.



March 13, 1989.

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

Mr. W.T. Russell Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION SPECIAL REPORT - RCIC INJECTION LICENSEE EVENT REPORT 89-002-00 FILE R41-2 PLAS - 356

Docket No. 50-388 License No. NPF-22

Dear Mr. Russell:

In pursuant of Technical Specification 4.7.3.d, a Special Report documenting a Reactor Core Isolation Cooling (RCIC) System injection to Unit 2 on December 15, 1988 is provided. The RCIC System automatically initiated due to a false low reactor water level signal and injected to the reactor vessel.

As of December 15, 1988, the total number of RCIC System injections for Unit 2 is 59. A conservative analysis, performed by Nuclear Plant Engineering, indicates the current usage factor for the affected nozzles is less than 0.70.

In addition, Licensee Event Report 89-002-00, outlining the event, is being provided on a voluntary basis. The RCIC System at Susquehanna is not an Engineered Safety Feature, therefore this event is not reportable per 10CFR50.73.

R.G.Byram Superintendent of Plant - Susquehanna

MLC/mjm

Cessel G. Machean Regulatory Completion Document Control Desk Washington, DC 20555

> Mr. F. I. Young Sr. Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 35 Berwick, PA 18603-0035