

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8906200359 DOC. DATE: 89/06/14 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 AUTH. NAME AUTHOR AFFILIATION
 RUSANOWSKY, P.P. Pennsylvania Power & Light Co.
 BYRAM, R.G. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-014-00: on 890514, spurious neutron monitor signal causes RPS actuation.

W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: LPDR 1 cy Transcripts. 05000387 /

	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL
	PD1-2 LA	1				1	PD1-2 PD	1				1
	THADANI, M	1				1						
INTERNAL:	ACRS MICHELSON	1				1	ACRS MOELLER	2				2
	ACRS WYLIE	1				1	AEOD/DOA	1				1
	AEOD/DSP/TPAB	1				1	AEOD/ROAB/DSP	2				2
	DEDRO	1				1	IRM/DCTS/DAB	1				1
	NRR/DEST/ADE 8H	1				1	NRR/DEST/ADS 7E	1				0
	NRR/DEST/CEB 8H	1				1	NRR/DEST/ESB 8D	1				1
	NRR/DEST/ICSB 7	1				1	NRR/DEST/MEB 9H	1				1
	NRR/DEST/MTB 9H	1				1	NRR/DEST/PSB 8D	1				1
	NRR/DEST/RSB 8E	1				1	NRR/DEST/SGB 8D	1				1
	NRR/DLPQ/HFB 10	1				1	NRR/DLPQ/PEB 10	1				1
	NRR/DOEA/EAB 11	1				1	NRR/DREP/RPB 10	2				2
	NUDOCS-ABSTRACT	1				1	REG FILE 02	1				1
	RES/DSIR/EIB	1				1	RES/DSR/PRAB	1				1
	RGN1 FILE 01	1				1						
EXTERNAL:	EG&G WILLIAMS, S	4				4	FORD BLDG HOY, A	1				1
	L ST LOBBY WARD	1				1	LPDR	1				1
	NRC PDR	1				1	NSIC MAYS, G	1				1
	NSIC MURPHY, G.A	1				1						
NOTES:		2				2						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 45 ENCL 44

R
I
D
S

A
D
D
S

R
I
D
S

A
D
D
S

Handwritten initials/signature

Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

June 14, 1989

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 89-014-00
FILE R41-2
PLAS - 370

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 89-014-00. This event was determined reportable under 10CFR50.73(a)(2)(iv) in that it resulted in the unplanned actuation of the Reactor Protection System.



R.G. Byram
Superintendent of Plant - Susquehanna

PPR/mjm

cc: Mr. W.T. Russell
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. G.S. Barber
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 35
Berwick, PA 18603-0035

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 8 7	PAGE (3) 1 OF 0 3
------------------------------------------------------------------	--------------------------------------	----------------------

TITLE (4)
Spurious Neutron Monitor Signal Causes RPS Actuation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																				
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)																	
0	5	1	4	8	9	8	9	0	1	4	0	0	0	6	1	4	8	9				0	5	0	0	0			

OPERATING MODE (9) 5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)										
POWER LEVEL (10) 0 0 0	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)						
	20.405(a)(1)(i)	50.38(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)						
	20.405(a)(1)(ii)	50.38(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	20.405(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)							
	20.405(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)							
20.405(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)

NAME P.P. Rusanowsky - Power Production Engineer	TELEPHONE NUMBER AREA CODE: 7 1 7 5 4 2 - 1 3 7 5 1 9
-----------------------------------------------------	----------------------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)	EXPECTED SUBMISSION DATE (15)	MONTH DAY YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO		

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On May 14, 1989, with Unit 1 in its fourth refueling outage and Unit 2 at 100% power, a Unit 1 Reactor Protection System (RPS) actuation occurred at 1023. Since all reactor control rods were fully inserted at the time, no control rod motion occurred. The RPS actuation was initiated by the "D" channel of the Intermediate Range (Neutron) Monitoring (IRM) System which spiked upscale momentarily as a result of induced electrical noise. No control rods or fuel bundles were being moved when the scram occurred. The IRM upscale trip was reset at approximately 1027 and the RPS actuation signal was reset at 1029. The source of the induced noise could not be determined. The IRM "D" channel was confirmed to be operating properly prior to and after the event. Since the Reactor Protection System functioned properly and per design by initiating an RPS actuation when it received the IRM upscale trip signal, there was no compromise to the health or safety of the public.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 7 8 9	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 1 4	- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 365A's) (17)

DESCRIPTION OF EVENT

On May 14, 1989, with Unit 1 in its fourth refueling outage and Unit 2 at 100% power, a Unit 1 Reactor Protection System (RPS, EIIS Code: JC) actuation occurred at 1023. The RPS actuation signal was initiated by the "D" Channel of the Intermediate Range (Neutron) Monitoring (IRM) System (EIIS Code: IG) which spiked upscale momentarily. Since all control rods were fully inserted at the time, no control rod motion occurred. No control rods or fuel bundles were being moved when the RPS actuation occurred (fuel reload had been completed on 5/12/89). Other neutron monitoring system channels exhibited similar, erratic, but smaller spikes during the same time frame. The erratic behavior, which started about one hour prior to the RPS actuation, was observed to continue for approximately two hours after the event.

CAUSE OF EVENT

This type of erratic behavior of the neutron monitoring system has been observed on numerous occasions during refueling outages when neutron flux levels are low. During these periods when the neutron signal levels are low, the instrumentation is more susceptible to induced electrical noise. On a significant number of the past occurrences, the source of the induced noise was identified to be either welding in the vicinity of the nuclear instrumentation components and cables or work activities which physically perturbed the instrumentation cables. However, the source of the induced noise for this event could not be determined.

During normal plant operation, the trip of on IRM Channel would only result in a half scram signal which does not initiate an RPS actuation. However, under certain circumstances while in Operational Condition 5 (Refueling), the RPS is configured such that any, one neutron monitoring system channel trip will initiate a (full) RPS actuation. The RPS was in this configuration when the event occurred and hence functioned per design.

REPORTABILITY/ANALYSIS

This event was determined to be reportable under 10CFR50.72(b)(2)(ii) and 10CFR50.73(a)(2)(iv) in that it resulted in the unplanned actuation of the RPS. An Emergency Notification System (ENS) call was made at 1257 on 5-14-89. Since the RPS functioned per design by initiating an RPS actuation on a noncoincident trip signal from the neutron monitoring system when configured to do so, there was no compromise to the health or safety of the public.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 7 8 9 - 0 1 4 - 0 0 0 3 OF 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 303A's) (17)

CORRECTIVE ACTIONS

Operations personnel, after confirming that all systems had responded properly and that no abnormal conditions appeared to exist, reset the "D" IRM upscale trip at approximately 1027 and the RPS actuation signal at 1029. Operations personnel attempted to identify the source of the induced noise (e.g. welding, testing or other work activities in the vicinity of the IRM components) but were unsuccessful. I&C personnel satisfactorily performed the weekly surveillance functional test after the event and confirmed that the surveillance conducted prior to the event was also satisfactory. Although we currently don't anticipate any further corrective actions, we will continue to monitor the situation and reassess it as necessary.

ADDITIONAL INFORMATION

A review of past IER's for the Station revealed the following similar events.

- Unit 1: 85-009
- 85-018
- 86-008
- 86-011

Unit 2 (Docket No. 50-388; License No. NPF-22): 84-003