REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8910160246 DOC.DATE: 89/10/06 NOTARIZED: NO DOCKET # FACIL:50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388 AUTH.NAME AUTHOR AFFILIATION

KEISER,H.W. Pennsylvania Power & Light Co.

RECIP.NAME RECIPIENT AFFILIATION

BUTLER, W.R. Project Directorate I-2

SUBJECT: Forwards response to request for addl info re pump seizure analysis.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR _ ENCL _ SIZE:_______
TITLE: OR Submittal: General Distribution

NOTES:LPDR 1 cy Transcripts.

05000388

R

1

D

D

S

R

D

D

	RECIPIENT ID CODE/NAME PD1-2 LA THADANI,M	COPIE LTTR 1 5		RECIPIENT ID CODE/NAME PD1-2 PD	COPI LTTR 1	
INTERNAL:	ACRS NRR/DEST/ESB 8D NRR/DEST/MTB 9H NRR/DOEA/TSB 11 OC/LFMB REG FILE 04	6 1 1 1	6 1 1 0 ·	NRR/DEST/ADS 7E NRR/DEST/ICSB NRR/DEST/RSB 8E NUDOCS-ABSTRACT OGC/HDS2 RES/DSIR/EIB	1 , 1 , 1 1	1 1 1 0 1
EXTERNAL:	LPDR NSIC	1	1	NRC PDR	1	1
NOTES:		2	2			•

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION TOTAL NUMBER OF COPIES REQUIRED: LITTR 29 ENCL 27



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

Harold W. Kelser Senior Vice President-Nuclear 215/770-4194

OCT 0 6 1989

Director of Nuclear Reactor Regulation Attention: Dr. W. R. Butler, Project Director Project Directorate I-2 Division of Reactor Projects U.S. Nuclear Regulatory Commission Washington, D.C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION: U2C4 SINGLE LOOP PUMP SEIZURE ANALYSIS PLA-3271 FILES A7-8C/A17-2/R41-2

Docket Nos. 50-388

References: 1.

- 1. PLA-3209, H.W. Keiser to W.R. Butler, "Proposed Amendment 74 to License No. NPF-22: Unit 2 Cycle 4 Reload", dated June 16, 1989.
- 2. XN-NF-86-146, "Susquehanna Unit 2 Cycle 2 Single Loop Operation Analysis," November, 1986.

Dear Dr. Butler:

The following information is provided in response to a request by Mr. H. Richings of the NRC staff for PP&L to provide further justification that the radiological consequences of a recirculation pump seizure accident during single loop operation are a small fraction of 10CFR100 guidelines. This information is intended to support the staff's review of Reference 1.

A pump seizure accident was analyzed for Susquehanna Unit 2 Cycle 4 to confirm the insignificance of this event relative to the 10CFR100 guidelines. As in the Single Loop Pump Seizure (SLPS) analysis reported in Reference 2, this analysis demonstrated that the radiological consequences of a pump seizure accident during single loop operation (less than 80% power) are a small fraction of the 10CFR100 guidelines. Furthermore, during Cycle 4, the delta CPR of a pump seizure accident during single loop operation was determined to be 0.29 and to be less severe than the delta CPR of 0.31 of a feedwater controller failure transient initiated from 80% power during two loop operation. The reduced power feedwater controller failure transient delta CPR, which sets the Technical Specification MCPR Operating Limit for power levels less than 80%, increases as power decreases. Therefore, the Cycle 4 power dependent MCPR operating limits would protect the MCPR safety limit during a SLPS.

8910160246 891006 PDR ADOCK 05000388 P PDC A001

=

The Company of the Co

Section for the section of the secti

4

4

• •

į.

Protection of the MCPR safety limit means that less than 0.1% of the fuel rods in the core would be expected to experience Boiling Transition (BT). The core remains covered during the SLPS accident and any fuel rods which experience BT would be expected to be in the film boiling mode for a short period. Because of the short duration of the accident, the number of fuel rods that would fail would be significantly less than the number of fuel rods calculated to experience BT. However, even if all of the rods which are calculated to experience BT were assumed to fail, the number of rods failing will be less than 0.1% of the rods in the core. The radiological consequences of 0.1% fuel failure resulting from a SLPS accident are only a small fraction of the 10CFR100 guidelines, especially since no uncontrolled release path to the environment is created during the SLPS accident.

Any questions on this response should be directed to Mr. R. Sgarro at 215-770-7916.

Very truly yours,

H. W. Keiser

cc: NRC Document Control Desk (original)

NRC Region I

Mr. M. C. Thadani, NRC Project Manager-Rockville Mr. G. S. Barber, NRC Sr. Resident Inspector-SSES

Mr. T. M. Gerusky, Pennsylvania DER

* ,