

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8912130002      DOC. DATE: 89/12/07      NOTARIZED: NO      DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv      05000387  
       50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv      05000388  
 AUTH. NAME      AUTHOR AFFILIATION  
 KEISER, H.W.      Pennsylvania Power & Light Co.  
 RECIPIENT NAME      RECIPIENT AFFILIATION  
 BUTLER, W.R.      Project Directorate I-2

SUBJECT: Part 21 rept re cold formed welded structural tubing supplied by Hub, Inc & mfg by Welded Tube Co of America.

DISTRIBUTION CODE: IE19D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 2  
 TITLE: Part 21 Rept (50 DKT)

NOTES: LPDR 1 cy Transcripts.      05000387  
       LPDR 1 cy Transcripts.      05000388

|           | RECIPIENT ID CODE/NAME | COPIES | L | T | R | ENCL | RECIPIENT ID CODE/NAME | COPIES | L | T | R | ENCL |
|-----------|------------------------|--------|---|---|---|------|------------------------|--------|---|---|---|------|
|           | PD1-2 LA               | 1      |   |   |   | 0    | PD1-2 PD               | 1      |   |   |   | 1    |
|           | THADANI, M             | 1      |   |   |   | 1    |                        |        |   |   |   |      |
| INTERNAL: | AEOD/DOA               | 1      |   |   |   | 1    | AEOD/DSP/TPAB          | 1      |   |   |   | 1    |
|           | IRM TECH ADV           | 1      |   |   |   | 1    | NRR CRUTCHFIELD        | 1      |   |   |   | 1    |
|           | NRR VARGA, S           | 1      |   |   |   | 1    | NRR/DLPQ/LPEB10        | 1      |   |   |   | 1    |
|           | NRR/DOEA/OGCB11        | 1      |   |   |   | 1    | NRR/DRIS/RVIB9D        | 1      |   |   |   | 1    |
|           | <del>NRR/DST-8E2</del> | 1      |   |   |   | 1    | NUDOCS-ABSTRACT        | 1      |   |   |   | 1    |
|           | <del>REG-ELLE</del> 01 | 1      |   |   |   | 1    | RES/DSIR/EIB           | 1      |   |   |   | 1    |
|           | RGN1                   | 1      |   |   |   | 1    | RGN2                   | 1      |   |   |   | 1    |
|           | RGN3                   | 1      |   |   |   | 1    | RGN4                   | 1      |   |   |   | 1    |
|           | RGN5                   | 1      |   |   |   | 1    |                        |        |   |   |   |      |
| EXTERNAL: | INPO RECORD CTR        | 1      |   |   |   | 1    | LPDR                   | 1      |   |   |   | 1    |
|           | NRC PDR                | 1      |   |   |   | 1    | NSIC SILVER, E         | 1      |   |   |   | 1    |
| NOTES:    |                        | 2      |   |   |   | 2    |                        |        |   |   |   |      |

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 25

7A-1

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S

4  
.  
G  
.  
.  
.  
G  
G  
B

F  
i  
G  
.  
.  
A  
G  
H  
3

... ..  
... ..  
... ..



**Pennsylvania Power & Light Company**

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

DEC 07 1989

Harold W. Keiser  
Senior Vice President-Nuclear  
215/770-4194

Director of Nuclear Reactor Regulation  
Attention: Dr. W. R. Butler, Project Director  
Project Directorate I-2  
Division of Reactor Projects  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
PART 21 REPORT  
PLA-3308 FILE R41-2

Dear Dr. Butler:

Pursuant to 10CFR21, attached is PP&L's report concerning cold formed welded structural tubing supplied by Hub, Inc. and manufactured by Welded Tube Company of America.

This condition was initially identified on September 15, 1989, and determined to be reportable on December 1, 1989. Telephone notification was made the same day to Mr. Jim Stair, Resident Inspector at Susquehanna SES.

Very truly yours,

H. W. Keiser

Attachment

cc: ~~NRC Document Control Desks~~ (original)  
NRC Region I  
Mr. M. C. Thadani, NRC Project Manager  
Mr. G. S. Barber, NRC Sr. Resident Inspector


Mr. Stanley J. Laskowski  
Manager of Quality Assurance  
& Technical Services  
Welded Tube Company of America  
1855 East 122nd Street  
Chicago, IL 60833

Mr. Ed. Thornton  
Quality Assurance Manager  
Hub, Inc.  
2146 Flinstone Drive  
Tucker, Georgia 30084

INPO  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

8912130002 891207  
PDR ADOCK 05000387  
PDC  
S

DEC 9  
11



## PART 21 REPORT

### COLD FORMED WELDED STRUCTURAL TUBING

#### Problem

During fabrication of an inverter rack at susquehanna SES, a crack was discovered in the longitudinal butt welded joint of a section of tube steel. Further inspection showed that incomplete welds existed in this material. The material had been used in a number of recent installations at Susquehanna SES.

#### Source of Material

The suspect material is cold formed welded structural tubing manufactured by Welded Tube Company of America, Chicago, Illinois. It was purchased from Hub, Inc., Tucker, Georgia. Nineteen 20-foot lengths (380 ft.) were purchased. The suspect material is all 4" x 4" x 1/4" ASTM A500 Gr. B, Q, galvanized per ASTM A153, Heat No. Y65143. To the best of our knowledge, this problem is limited to Heat No. Y65143.

#### Safety Hazard

The safety impact of incomplete welds in tube steel is a significant reduction in its strength. The affect on axial strength is minimal. However, the affect on torsional and bending strength can be significant. The material is used as structural support for safety-related components. The actual safety significance of the defect depends on its ultimate use.

#### Corrective Action

Of the 380 linear feet of suspect tube steel purchased, 183 ft. has been placed on hold for return to the supplier. The supplier and manufacturer were notified that PP&L was evaluating this material for reportability under Part 21. The supplier indicated that all remaining suspect material was being held pending PP&L's determination. PP&L has no specific information on the use of this suspect material at other facilities.

The suspect material had been installed in six recent modifications. Calculations show that the material strength is adequate for use-as-is. However, PP&L plans to repair 21 conduit supports in three of these installations to assure that full rated capacity is available in the event additional loads are ever added to these supports. As of December 1, 1989, repairs were complete on seven of the supports. Repairs to the remaining 14 are expected to be completed by mid-December. Disposition is provided in NCR's 89-0498 and 89-0487. No further action is required.