### APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

## LICENSEE EVENT REPORT (LER)

PAGE (3)																											
FACILITY											<b>^</b>											۵.۵					
		IANI	IA .	STE	AM	ELI	EC?	rR.	IC S	TATI	<u> </u>	U	LTM	. 2			10	5	101	0	0 3	8 8	1 OF	0.13			
OPERABILITY TESTING FOLLOWING INSTRUMENT LEAK REPAIR REQUIRED ENTRY INTO LCO 3.0.3																											
OPE	RABII	TTY	TES	MITS	<b>G</b> ]	FOLIC	IVC	NG	INSI					AIR F	ν	UIR	ED E	4TK		ITO	<u>тсо</u>	3.0.	<u>ა</u>				
EVE	NT DATE	(5)				R NUMB				REI	PORT DAT	TE (7	)				OTHER F		TIES IN								
MONTH	DAY	YEAR	YE	AR 🖇	₩ S	EQUENT NUMBE	IAL R	₩	REVISION NUMBER	HTMOM	DAY	YE	EAR			FACIL	ITY NAM	ES		١		NUMBER					
			1		T															<u> </u>	0 [5]	0 1 0	<u> </u>	<u> </u>			
			1	.  _	_		. [			١.			[							- I.	-			i			
0 5	2 4	9 3	9	3	7	0 0 1	4		0 0	0 6	2 3	9	3								0 [5]	0 0	${\color{red} {\sf L}}^{\color{blue} {\sf L}}$				
OPF	RATING		THI	S REPO	RT I	IS SUBMI	TTEC	) PUI	RSUANT '	TO THE R	LQUIREM	ENT	S OF 10	CFR §: /	Chec	k one e	or more of	the fo	llowing	/ (11)							
	DE (9)	-   1	.	20.40	2(b)					20,405(	c)				6	0,73(*)	(2)(iv)				73.	,71(b)					
POWE			7	20,40	5(*)(	(1)(i)				50,38(c	(1)				] 5	0,73(a)	(2)(v)			L	73.	.71{c}					
LEVE!	۱   L <sub>I</sub>	010		20.40	5(=)(	(1)(A)				50.36(c	)(2)				] 5	(0.73(a)	(2)(vii)					HER (Spe	cify in Ab Text, NR	trect C Form			
			8	20,40	5(0)	(1)(iii)			X	50,73(a	)(2)(i)				] 6	0,73(e)	(2)(viii)(A	)	,	- 1		SAI					
			I	20.40	5(a)(	(1)((v)	•			50,73(e	}(2}(#)				5	i0.73(a)	(3)(AIR)(B	) `									
			<b>.</b> .	20.40	5 (a) l	(1)(v)	*			50.73(a	)(2)(iii)				5	i0.73(a)	(2)(x)							-			
				`					1	LICENSEE	CONTAC	T FO	R THIS	LER (12)													
NAME		, -							1	•								<u> </u>			ELEPHO	NE NUMI	BER				
	1	~ .	.7_1		<b>-</b>	T	D			. The ext	inaan		~~~		~			. [	IEA CO	-							
Ric	nard	K. I	wenn	cy,	50	wer i	PIC	xıu	CLLOI	Eng:	пкег		- CO11	фттат	100	- 		7	<u>' </u> ]	7	5 <sub>1</sub> 4	<u> 2 – </u>	<u> 1316</u>	1614			
						COMPL	ETE (	BNC	LINE FOR	R EACH CO	OMPONEN	IT F/	AILURE	DESCRIB	ED I	N THIS	REPOR	Γ (13)					•••••	********			
CAUSE	SYSTEM	COM	PONE	NENT		ANUFAC-				REPORTABLE				CAU	CAUSE	SE SYSTEM		COMPONENT					REPOR	TABLE S			
CAUSE	31316					TURER		TO NPROS										<u>                                     </u>	TURER		10 8	PHUS 18					
												▓┃		1	1		-	l			1						
			1		_1	_11						<b>X</b>			丄			Ш	L_		<del> </del>						
										l		▓		i				1									
										]		<b>%</b> [		<u> </u>	L		Ш	Ш	L_		1		**************************************				
SUPPLEMENTAL REPORT EXPECTED (14)										ļ	EXPECTED			MONTH	DAY.	YEAR											
YES (If yes, complete EXPECTED SUBMISSION DATE)  NO										115510 E (15	N )	١.	١.	١.													
											X NO							<u> </u>				<u> </u>					
ABSTRAC	T (Limit	to 1400	speces,	1.e., app	roxi	imately fil	fteen .	singie	space typ	ewritten lii	nes) (16)						ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (18)										

On May 24, 1993, at 2305 hours, with Unit 2 in Condition 1 at 100% power, repairs were completed on a leaking fitting on the reference leg of reactor vessel level switch LIS-24221C. This level switch provides signals to the containment isolation logic for Drywell Cooling, Reactor Building Closed Cooling Water and Containment Instrument Gas systems. In order to perform the required functional and operability testing, the affected trip system was taken out of the tripped condition required by Technical Specification 3.3.2 ACTION b. With the trip system out of the tripped condition, ACTION b. was no longer met and Technical Specification 3.0.3 was entered. Entry into Technical Specification 3.0.3 constitutes an operation prohibited by the Technical Specifications and is reportable per 10CFR50.73(a)(2)(i)(B). Since redundant instrumentation for Drywell Cooling Isolation Logic remained operable, there were no safety consequences or compromise to public health or safety as a result of the entry into LCO 3.0.3. This condition was cleared following return of the switch to operable status. Changes with respect to Technical Specification 3.0.3 are being pursued as part of the NRC generic Technical Specification Improvement Program.

9306290315 930623 PDR ADDCK 05000388 S PDR



NRC	FORM	366A
16 80	١ .	

### U.S. NUCLEAR REGULATORY COMMISSIS

### APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

	·						
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)				
SUSQUEHANNA STEAM ELECTRIC STATION -		YEAR SEQUENTIAL REVISION NUMBER					
UNIT 2	0  5  0  0  0  3   8  8	9 3 - 0 0 4 - 0 0	012 OF 013				

TEXT (If more space is required, use additional NRC Form 366A's) (17)

## DESCRIPTION OF EVENT

On May 24, 1993 at 2305 hours, with Unit 1 in Condition 2 at 100% power, repairs were completed on a leaking fitting on the reference leg of reactor vessel water level switch LIS-24221C (EIIS Code: JM). This level switch provides signals to the containment isolation logic for Drywell Cooling (EIIS Code: VB), Reactor Building Closed Cooling Water (EIIS Code: CC), and Containment Instrument Gas (EIIS Code: LD) systems. In order to perform the required functional and operability testing, the affected trip system was taken out of the tripped condition required by Technical Specification 3.3.2 ACTION b. for performing the repairs. With the trip system out of the tripped condition, ACTION b. was no longer met and Technical Specification Limiting Condition for Operation (LCO) 3.0.3 was entered. Entry into LCO 3.0.3 constitutes an operation prohibited by the plant's Technical Specifications and is reportable per 10CFR50.73(a)(2)(i)(B).

# CAUSE OF EVENT

The cause for entry into LCO 3.0.3 ACTION was the inability to meet Technical Specification 3.3.2 ACTION b. when the affected trip system had to be taken out of the tripped condition to perform the required functional and operability testing following leak repairs. The leak was at an elbow fitting on the reference leg of reactor vessel water level switch LIS-24221C. Because of heightened awareness of the potential effects of reference leg leaks on reactor water level instrumentation signals (Generic Letter 92-04 and NRC Bulletin 93-03), the need to repair the leak and enter the LCO 3.0.3 ACTION for operability testing was reinforced.

## REPORTABILITY/ANALYSIS

This event was determined reportable per 10CFR50.73(a)(2)(i)(B), in that Susquehanna Unit 2 was in an operating condition prohibited by the plant's Technical Specifications (LCO 3.0.3) while functional and operability testing was performed on reactor vessel water level switch LIS-24221C following the repair of a leaking fitting on the switch's reference leg side. LIS-24221C provides signals to the containment isolation logic for Drywell Cooling (EIIS Code: VB), Reactor Building Closed Cooling Water (EIIS Code: CC), and Containment Instrument Gas (EIIS Code: LD) systems.

LCO ACTION 3.0.3 was entered at 2305 hours on May 24, 1993 and was cleared at 0002 hours on May 25, 1993, following successful functional and operability testing.

NRC FORM 366A (6-89) U.S. NUCLEAR REGULATORY COMMISSIS

### APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

24.05.(2)		
PAGE (3)		
)   3 OF   0  3		
)		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

There were no safety consequences or compromise to public health or safety as a result of the entry into LCO 3.0.3. Redundant instrumentation for Drywell Cooling Isolation remained operable during the time that LIS-24221C was being tested for restoring it to operable status. The time that the unit was in LCO ACTION 3.0.3 was minimized to the extent practicable.

In accordance with the guidance provided in NUREG 1022, Supplement 1, item 14.1, the required submission date for this report was determined to be June 23, 1993.

# CORRECTIVE ACTION

Following functional and operability testing of level switch LIS-24221C, the switch was declared operable at 0002 hours on May 25, 1993, and LCO ACTION 3.0.3 was cleared. The leak at the elbow fitting was considered to be an isolated incident.

PP&L is pursuing changes with respect to Technical Specification 3.0.3 as part of the NRC generic Technical Specification Improvement Program.

## ADDITIONAL INFORMATION

Failed Component Identification: Not applicable.

Previous Similar Events: LER 50-387/93-002-00.

	•		
,			•
	bcc:	R.G. Byram	TW-16
		G.T. Jones	A6-2
		J.R. Miltenberger	A6-1
	*	J.M. Kenny	A2-4
	ŧ	H.D. Woodeshick	SSES
		M.T. McGann	STC
		R.J. Prego	SB-2
		SRC(Attn: W.R. Licht)	A6-1
		G.J. Kuczynski	SSES
•		PORC Secretary	SSES
		DCS File	SSES
•	F	D. Dyckman	
1		Allegheny Electric (	Cooperative
		P.O. Box 1266	
	•	Harrisburg, PA 1710	)8-1266 ·
		M. M. Urioste	
z		<b>GE</b> Company	
		640 Freedom Business	s Center
	•	P.O. Box 1561	
•	* _	King of Prussia, PA	19406
		Institute of Nuclear Power	r Operation
		700 Galleria Parkway	
E		Atlanta, GA 30339-	5957
		•	
	•	•	
		И	
		-	

•

•

•

.