

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9309280142    DOC. DATE: 93/09/20    NOTARIZED: NO    DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania    05000387  
 AUTH. NAME    AUTHOR AFFILIATION  
 WEHRY, R.R.    Pennsylvania Power & Light Co.  
 STANLEY, H.G.    Pennsylvania Power & Light Co.  
 RECIP. NAME    RECIPIENT AFFILIATION

SUBJECT: LER 93-009-00: on 930825, determined that an unplanned ESF actuation occurred resulting in drywell vent PCIIV closure. Caused by failure of solenoid on valve actuator. Failed solenoid replaced & successfully tested. W/930920 ltr.

DISTRIBUTION CODE: IE22T    COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.


NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-2 LA CLARK, R	1 1	PD1-2 PD	1 1
INTERNAL:	ACRS	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
	NRR/DORS/OEAB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRIL/RPEB	1 1	NRR/DRSS/PRPB	2 2
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	<del>REG FILE</del> 02	1 1	RES/DSIR/EIB	1 1
	RGNI FILE 01	1 1		
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

*A04*

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!





**Pennsylvania Power & Light Company**

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

September 20, 1993


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 93-009-00  
FILE R41-2  
PLAS - 574

---

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 93-009-00. This report is being made pursuant to 10CFR50.73(a)(2)(iv), in that an unplanned Engineered Safety Feature actuation occurred when a Drywell Vent Isolation Valve failed to the closed position due to a failure of its actuator solenoid. The solenoid was replaced.

  
H.G. Stanley  
VP - Nuclear Operations

RRW/mkf

cc: Mr. T. T. Martin  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. G. S. Barber  
Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 35  
Berwick, PA 18603-0035

9309280142 930920  
PDR ADOCK 05000387  
S PDR



*JE22*

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) <b>SUSQUEHANNA STEAM ELECTRIC STATION - UNIT 1</b>	DOCKET NUMBER (2) <b>0 5   0 0   0 3   8   7</b>	PAGE (3) <b>1 OF 03</b>
---	---	----------------------------

TITLE (4)  
**UNPLANNED ESF ACTUATION - PRIMARY CONTAINMENT ISOLATION VALVE CLOSURE**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																																								
08	25	93	93	009	00	09	20	93			05000																																								
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:15%;">OPERATING MODE (9) <b>4</b></td> <td colspan="11">THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)</td> </tr> <tr> <td rowspan="6">POWER LEVEL (10) <b>0100</b></td> <td>20.402(b)</td> <td><input checked="" type="checkbox"/></td> <td>50.73(a)(2)(iv)</td> <td><input type="checkbox"/></td> <td>73.71(b)</td> </tr> <tr> <td>20.405(a)(1)(i)</td> <td><input type="checkbox"/></td> <td>50.73(a)(2)(v)</td> <td><input type="checkbox"/></td> <td>73.71(c)</td> </tr> <tr> <td>20.405(a)(1)(ii)</td> <td><input type="checkbox"/></td> <td>50.73(a)(2)(vii)</td> <td><input type="checkbox"/></td> <td rowspan="4">OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td> </tr> <tr> <td>20.405(a)(1)(iii)</td> <td><input type="checkbox"/></td> <td>50.73(a)(2)(viii)(A)</td> <td><input type="checkbox"/></td> </tr> <tr> <td>20.405(a)(1)(iv)</td> <td><input type="checkbox"/></td> <td>50.73(a)(2)(viii)(B)</td> <td><input type="checkbox"/></td> </tr> <tr> <td>20.405(a)(1)(v)</td> <td><input type="checkbox"/></td> <td>50.73(a)(2)(ix)</td> <td><input type="checkbox"/></td> </tr> </table>												OPERATING MODE (9) <b>4</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)											POWER LEVEL (10) <b>0100</b>	20.402(b)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)	20.405(a)(1)(i)	<input type="checkbox"/>	50.73(a)(2)(v)	<input type="checkbox"/>	73.71(c)	20.405(a)(1)(ii)	<input type="checkbox"/>	50.73(a)(2)(vii)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)	20.405(a)(1)(iii)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	<input type="checkbox"/>	20.405(a)(1)(iv)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	<input type="checkbox"/>	20.405(a)(1)(v)	<input type="checkbox"/>	50.73(a)(2)(ix)	<input type="checkbox"/>
OPERATING MODE (9) <b>4</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																																																		
POWER LEVEL (10) <b>0100</b>	20.402(b)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)																																														
	20.405(a)(1)(i)	<input type="checkbox"/>	50.73(a)(2)(v)	<input type="checkbox"/>	73.71(c)																																														
	20.405(a)(1)(ii)	<input type="checkbox"/>	50.73(a)(2)(vii)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)																																														
	20.405(a)(1)(iii)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	<input type="checkbox"/>																																															
	20.405(a)(1)(iv)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	<input type="checkbox"/>																																															
	20.405(a)(1)(v)	<input type="checkbox"/>	50.73(a)(2)(ix)	<input type="checkbox"/>																																															

LICENSEE CONTACT FOR THIS LER (12)

NAME <b>R. R. Wehry, Power Production Engineer - Compliance</b>	TELEPHONE NUMBER AREA CODE: <b>717</b>   <b>542-3664</b>
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)


CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
B	NIH	SIOI	C101014	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
--	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

At 0015 hours on August 25, 1993, with Unit 1 in condition 4 at 0% power, a Drywell Vent primary containment isolation valve failed closed. Investigation revealed the cause of the event to be a failed solenoid on the valve actuator. The event was determined to constitute an unplanned ESF actuation and is reportable per 10CFR50.73(a)(2)(iv). No ESF logic was involved or challenged. The valve failed to the closed position which is the position required for it to fulfill its design safety function, had it been needed. Thus, there were no safety consequences or compromise to public health or safety. Further laboratory analysis was performed on the failed solenoid. The analysis concluded that the solenoid coil wire insulation had failed, resulting in the turns of the coil wire shorting together. This was the only such failure of a solenoid coil of this model installed at Susquehanna. The solenoid was replaced.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  SUSQUEHANNA STEAM ELECTRIC STATION -  UNIT 1	DOCKET NUMBER (2)  0   5   0   0   0   3   8   7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9   3	-   0   0   9	-   0   0	0   2	OF	0   3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

At 0015 hours on August 25, 1993, with Unit 1 in Condition 4 at 0% power, a Drywell Vent primary containment isolation valve (EIIS Code: NH) failed closed while a nitrogen purge of the Drywell (EIIS Code: VB) was underway. This closure constituted an unplanned Engineered Safety Feature (ESF) actuation.

CAUSE OF EVENT

Investigation revealed the cause of the event to be failure of a solenoid on the valve actuator. Indications of elevated temperatures in the solenoid coil area were observed as well as a failed solder joint between a wire lead and an electrical connection post on the coil. This solenoid had been installed just five days prior to the event.

Further laboratory analysis was performed on the failed solenoid. The analysis concluded that the solenoid coil wire insulation had failed, resulting in the turns of the coil wire shorting together. This was the only such failure of a solenoid coil of this model installed at Susquehanna.

REPORTABILITY/ANALYSIS

This event was determined reportable per 10CFR50.73(a)(2)(iv), in that an unplanned Engineered Safety Feature (ESF) actuation occurred when the Drywell Vent containment isolation valve failed closed due to failure of a solenoid on the valve actuator. No ESF logic was involved or challenged and no other valves were affected. The subject valve is used for primary containment isolation in the event of an accident. The valve failed to the closed position, which is the position required for it to fulfill its design safety function, had it been needed. Thus, there were no safety consequences or any compromises to public health or safety. This event would not have been more significant at any other operating condition.

In accordance with the guidance provided in NUREG 1022, item 14.1, the required submission date for this report was determined to be September 24, 1993.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  SUSQUEHANNA STEAM ELECTRIC STATION -  UNIT 1	DOCKET NUMBER (2)  0 5 0 0 0 3 8 7 9 3 - 0 0 9 - 0 0 0 3 OF 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTION

The failed solenoid was replaced and successfully tested. The replacement solenoid was observed to operate at a lower temperature than the solenoid which failed.

Further laboratory analysis was performed on the failed solenoid. The analysis concluded that the solenoid coil wire insulation had failed, resulting in the turns of the coil wire shorting together. This was the only such failure of a solenoid coil of this model installed at Susquehanna.

ADDITIONAL INFORMATION

Failed Component Identification:

Valve:	Solenoid
Model:	NP30-2
Manufacturer:	Circle Seal Controls, Inc.

Previous Similar Events:

LER 50-387/90-011-00 described an event in which failure of a solenoid valve resulted in closure of a Reactor Building exhaust fan supply damper (unplanned ESF actuation).





bcc: R.G. Byram TW-16  
G.T. Jones A6-2  
J.R. Miltenberger A6-1  
J.M. Kenny A2-4  
H.D. Woodeshick SSES  
M.T. McGann STC  
R.J. Prego SB-2  
SRC(Attn: W.R. Licht) A6-1  
G.J. Kuczynski SSES  
PORC Secretary SSES  
DCS File SSES  
D. Dyckman  
Allegheny Electric Cooperative  
P.O. Box 1266  
Harrisburg, PA 17108-1266  
M. M. Urioste  
GE Company  
640 Freedom Business Center  
P.O. Box 1561  
King of Prussia, PA 19406  
Institute of Nuclear Power Operation  
700 Galleria Parkway  
Atlanta, GA 30339-5957