

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9406080006 DOC. DATE: 94/05/27 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388 R
 AUTH. NAME AUTHOR AFFILIATION
 STANLEY, H.G. Pennsylvania Power & Light Co. I
 RECIP. NAME RECIPIENT AFFILIATION
 MARTIN, T.T. Region 1 (Post 820201) D

SUBJECT: Special rept: on 940421, documents an occurrence where in
 Seismic Monitoring Instrumentation, specifically Seismic
 Monitor Analyzer, was inoperable for greater than thirty
 days. S

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. /

NOTES:

	RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL	
	PD1-2 PD		1	1	D
INTERNAL:	ACRS		1	1	S
	AEOD/DSP/TPAB		1	1	
	NRR/DE/EELB		1	1	
	NRR/DORS/OEAB		1	1	
	NRR/DRCH/HICB		1	1	
	NRR/DRIL/RPEB		1	1	
	NRR/DSSA/SPLB		1	1	
	<u>REG FILE</u> 02		1	1	
	RGNI FILE 01		1	1	
EXTERNAL:	EG&G BRYCE, J.H		2	1	R
	NRC PDR		1	1	
	NSIC POORE, W.		1	1	I
		POS LUSNY, C	1	1	D
		AEOD/DOA	1	1	S
		AEOD/ROAB/DSP	2	1	
		NRR/DE/EMEB	1	1	
		NRR/DRCH/HHFB	1	1	
		NRR/DRCH/HOLB	1	1	
		NRR/DRSS/PRPB	2	1	
		NRR/DSSA/SRXB	1	1	
		RES/DSIR/EIB	1	1	
		L ST LOBBY WARD	1	1	R
		NSIC MURPHY, G.A	1	1	I
		NUDOCS FULL TXT	1	1	D

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 280

JA2

Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

May 27, 1994

Mr. T. T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
SPECIAL REPORT - SEISMIC MONITORING
INSTRUMENTATION INOPERABLE FOR
GREATER THAN THIRTY DAYS
PLAS-603 FILE R41-2

Docket No. 50-387/50-388
License No. NPF-14/NPF-22

Dear Mr. Martin:

This Special Report, required by Unit 1 and Unit 2 Technical Specification 3.3.7.2 Action a., documents an occurrence wherein Seismic Monitoring Instrumentation, specifically a Seismic Monitor Analyzer, was inoperable for greater than thirty days.

Upon investigating a spurious seismic trigger from the Unit 1 Reactor Building Containment Foundation transducer on April 21, 1994, an unexpected acceleration was observed as having been processed by Seismic Monitor Analyzer VRS-05703 (RSA-50). It was determined that any negative DC offset voltage from the accelerometers (input signal from the field) yielded improper data analysis by the RSA-50.

Further investigations by Engineering and Instrument and Controls personnel, as well as analysis of tape data by the vendor have concluded that a computer software - related problem exists in the RSA-50 analyzer.

060092

9406080006 940527
PDR ADOCK 05000387
S PDR

TELL
1/0

Since final corrective actions have not yet been developed at this time to resolve the software problem, a supplement to this Special Report will be submitted to detail the corrective action plan.

H. G. Stanley
H. G. Stanley
Vice President - Nuclear Operations

RRW/mjm

cc: U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Mr. G. S. Barber
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 35
Berwick, PA 18603-0035