1	<b>,</b>	REGULA	ACCELEN INFORM	<b>OF</b> RATED H LATION	KILLY L RIDS PROCESSING DISTRIBUTIO	A (RIDS)		
; ; ; ; ;	ACCESSION FACIL:50 AUTH.NA METER,J STANLEY, RECIP.N	N NBR:9408090475 D-387 Susquehanna AME AUTHOR J. Pennsylv H.G. Pennsylv NAME RECIPIE	DOC.I Steam H AFFILIA ania Po ania Po NT AFFI	ATE: Clectr ATION ower & ower & LIATI	94/08/04 NOTARIZED ic Station, Unit 1, Light Co. Light Co. ON	: NO Pennsylva	DOCKET # 05000387	P
SUBJECT: LER 94-011-00:on 940707,RWCU containment isolation valves isolated on high differential flow due to leakage past work boundary valve & out of sys drains.Affected drain valves closed & leakage from sys stopped.W/940804 ltr.						brk	R I	
	DISTRIBU TITLE: 9 NOTES:	UTION CODE: IE22T 50.73/50.9 License	COPIES e Event	S RECE : Repo	IVED:LTR _ ENCL rt (LER), Incident	SIZE: Rpt, etc.	<u> </u>	O R
		RECIPIENT . ID CODE/NAME PD1-2 PD	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME POSLUSNY,C	COPIES LTTR ENC l l	CL.	і _ т
	INTERNAL:	ACRS AEOD/ROAB/DSP NRR/DE/EMEB	1 2 1	1 2 1	AEOD/DSP/TPAB NRR/DE/EELB NRR/DORS/OEAB	1.1 1.1 1.1		Y
		NRR/DRCH/HHFB NRR/DRCH/HOLB NRR/DSSA/SPLB NRR/DSSA/SPLB	1 1 1	1 1 1	NRR/DRCH/HICB NRR/DRSS/PRPB NRR/DSSA/SRXB	1 1 2 2 1 1		1
		RES/DSIR/EIB	1	1	RGN1 FILE 01	ī ī		D
	EXTERNAL:	EG&G BRYCE,J.H NRC PDR	2 1	2 1	L ST LOBBY WARD NSIC MURPHY,G.A	1 1 1 1		0

NOTE TO ALL "RIDS" RECIPIENTS:

•

NSIC POORE, W.

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 504-2083 ) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

1

1

NUDOCS FULL TXT

\*

1

,

x

1

FULL TEXT CONVERSION REQUIRED 27 27 ENCL TOTAL NUMBER OF COPIES REQUIRED: LTTR

Ο С U Μ Ε Ν Т





Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

August 4, 1994

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 94-011-00 FILE R41-2 PLAS -609

Docket No. 50-387 License No. NPF-14

Attached is Licensee Event Report 94-011-00. This report is being made pursuant to 10CFR50.73(a)(2)(iv), in that an unplanned actuation of an Engineered Safety Feature occurred when the Reactor Water Cleanup System primary containment isolation valves closed due to a high differential flow signal.

H.G. Stanley

VP - Nuclear Operations

JJM/mjm

cc: Mr. T. T. Martin Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

> Mr. D. J. Mannai Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 35 Berwick, PA 18603-0035

9408090475 940804 PDR ADDCK 05000387 5 PDR

2	FORM 366 U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104								
	ESTIMA LICENSEE EVENT REPORT (LER) AND R REGUL THE P OF MAI				ESTIMATED INFORMATIC COMMENTS I AND REPOR REGULATOF THE PAPER OF MANAGE	EXPIRES: 4/30/92 IMATED BURDEN PER RESPONSE TO COMPLY WTH THIS DRMATION COLLECTION REQUEST: 50.0 HRS. FORWARD IMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS D REPORTS MANAGEMENT BRANCH (P\$300, U.S. NUCLEAR ULLATORY COMMISSION, WASHINGTON, DC 20555, AND TO : PAPERWORK REDUCTION PROJECT (3150.0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.			
	FACILITY NAME (1)					DOG	CKET NUMBER (	2) PAGE (3)	
	Susquehanna Steam Electric St	ation -	Unit 1			0	5 0 0	0  3  8  7   1   OF  0  3	
	TITLE (4)	lvos Ter	olated on	Hiah	Differ	ential Fl	ow		
	EVENT DATE (5) LER NUMBER (6)		REPORT DATI	E (7)		OTHER FA	CILITIES INVOL	VED (8)	
	MONTH DAY YEAR YEAR WEAR		MONTH DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)	
								0   5   0   0   0   1	
	0 7 0 7 9 4 9 4 0 1 1	00	0 8 0 4	94				0   5   0   0   0	
	OPERATING MODE (9) 7 Las Market	PURSUANT TO	THE REQUIREME	NTS OF 10	CFR §: (Chec	k one or more of t	the following) (11)		
ł	20,402(5)		20.405(c) 50.38(c)(1)			),73(4)(2)(1V) ) 73(4)(2)(v)	ŀ	73,71(0) 73,71(e)	
ł		H	50.36(c)(2)			).73(s)(2)(vii)	ŀ	OTHER (Specify in Abstract	
	20,405(a)(1)(iii)		50.73(e)(2)(i)		64	),73(s)(2)(viii)(A)	ľ	below and in Text, NRC Form 366A)	
	20.405(a)(1)(iv)		50,73(a)(2)(ii)		64	),73(s)(2)(viii)(8)		•	
	20,405(a)(1)(v)		50,73(a)(2)(iii)		54	),73(e)(2)(x)			
	MANE	LIC	CENSEE CONTACT	FOR THIS	LER (12)		1		
							AREA CODE		
	Joseph J. Meter - Po	wer Pro	duction E	nainee	er		7 11 7	5   4   2   -   1   8   7   3	
	COMPLETE O	NE LINE FOR E	EACH COMPONENT	FAILURE	DESCRIBED I	THIS REPORT	(13)		
	CAUSE SYSTEM COMPONENT MANUFAC-	TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	
						1 1 1	111		
	SUPPLEMEN	TAL REPORT E	EXPECTED (14)	<u> </u>	LII	┸╼┅┸╾╼┾		MONTH DAY YEAR	
							SUBMISSIC DATE (15		
	YES (If yes, complete EXPECTED SUBMISSION DATE)								
	ABSTRACT (Limit to 1000 usees, Le. exproximative (lifet pices typewritten limit (10) On July 7, 1994, at 0947 hours with Unit 1 in Condition 1 at 100% power, an Engineered Safety Feature (ESF) actuation occurred when the Reactor Water Cleanup (RWCU) System's containment isolation valves automatically closed due to a high differential flow signal. The high differential flow signal was attributed to leakage past a work boundary valve (air operated - failed closed) and then out of system drains. The leakage was subsequently collected in the Reactor Building floor drain system. The leakage into the isolated section of the RWCU system and out of the drain valves was sufficient to isolate the entire system on high differential flow. Upon discovery of the condition, Operations closed the affected drain valves and leakage from the system was stopped. The RWCU was subsequently returned to service. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. There were no safety consequences or compromise to the public health or safety as a result of this event. The RWCU containment isolation valves performed as expected during the event. Corrective actions include changing the applicable procedure to show that involved valves should not be used as work boundaries and to review the acceptability of other station air operated - fail closed valves as a work boundary.								
						,		24T	

¥

-

1

NRC Form 366 (6-89)

,

11,1

8	LICENSEE EVENT REPORT ( TEXT CONTINUATION	APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 DIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.			
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) P/	AGE (3)	
			YEAR SEQUENTIAL REVISION		
	Unit l				
	Susquehanna Steam Electric Station	0 5 0 0 0 3 8 7	7 9 4 - 0 1 1 - 0 0 0 2	OF 03	
1	TEXT (If more spece is required, use additional NRC Form 366A's) (17)				

## DESCRIPTION OF EVENT

On July 7, 1994, at 0947 hours with Unit 1 in Condition 1 at 100% power, an Engineered Safety Feature (ESF) actuation occurred when the Reactor Water Cleanup (RWCU, EIIS Code: CE) System's containment isolation valves (EIIS Code: JM) automatically closed due to a high differential flow signal. The high differential flow signal was attributed to leakage past a work boundary valve and then out of system drains. The leakage was subsequently collected in the Reactor Building floor drain system. The leakage into the isolated section of the system and out of the drain valves was sufficient to isolate the entire system on high differential flow. Upon discovery of the condition, Operations (Utility, non-licensed) closed the affected drain valves and leakage from the system was stopped. The RWCU system was subsequently returned to service at 1615 hours. The RWCU containment isolation valves performed as expected during the event. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. There were no safety consequences or compromise to the public health or safety as a result of this event.

## CAUSE OF EVENT

The high differential flow signal was attributed to leakage past a work boundary valve and then out of system drains. The leakage into the isolated section of the system and out of the drain valves was sufficient to isolate the entire system on high differential flow. The leakage past the work boundary valve (air operated-failed closed) was due to the valve disc lifting from its seat due to system pressure. The valves in question are air operated valves with spring assist closure. The assumption with using the valves for work boundary purposes was that their design was such that when the air was removed from the valves they would fail closed and stay closed at maximum system operating pressures. The manufacturer of the valves was contacted and the design of the valves in question was that air to the valve operators in conjunction with the spring force is needed to keep the valves closed at maximum operating pressure.

## <u>REPORTABILITY / ANALYSIS</u>

This event was determined to be reportable per 10CFR50.73(a)(2)(iv), in that an unplanned ESF actuation occurred when the RWCU system's primary containment isolation valves automatically closed following receipt of a high differential flow signal. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. The leakage was subsequently collected in the Reactor Building floor drain system. There were no safety consequences or compromise to the public health or safety as a result of this event. The RWCU containment isolation valves performed as expected during the event.

In accordance with guidance provided in 10CFR50.4(d), the required submission date for this report was determined to be 08/08/94.



•

ş

		<u>محمد معرف المتحدين و بربار من ا</u>					
	NRC FORM 366A U.S. 1 (6.89)	APPROVED OMB NO. 3150-0104					
100	LICENSEE EVENT REPORT ( TEXT CONTINUATION	LER)	EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS, FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.				
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)				
	Imit 1		YEAR SEQUENTIAL REVISION NUMBER				
	Susquehanna Steam Electric Station	0 5 0 0 0 3 8 7	9   4   0   1   1   0   0   0   3   OF   0   3				
	TEXT (IT more space is required, use additional NRC Form 366A's) (17) <u>CORRECTIVE_ACTIONS</u>						
Upon discovery of the condition, Operations closed the affected drain valves and leakage from the system was stopped. The RWCU was subsequently returned to servi 1615 hours. Corrective actions include changing the applicable procedure to show involved valves should not be used as work boundaries and to review the acceptabi of other station air operated - fail closed valves as a work boundary.							
	ADDITIONAL_INFORMATION						
	Failed Component Identification: N	lot Applicable					
Past Similar Events: Although the causes for the previous events were different than this case, a review past Licensee Event Reports (LERs) for the station identified fifteen events where isolated on high flow or high differential flow signals.							
	84-047-00 85-007-00 85-017-00 85-032-00 87-001-00 89-011-00 89-016-00 91-008-00 92-003-00	84-015-01 85-024-00 86-006-00 86-017-00 89-004-00 92-009-00					