

**PRIORITY 1**  
 (ACCELERATED RIDS PROCESSING)  
 REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9408090475      DOC. DATE: 94/08/04      NOTARIZED: NO      DOCKET #  
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania      05000387  
 AUTH. NAME      AUTHOR AFFILIATION  
 METER, J.J.      Pennsylvania Power & Light Co.  
 STANLEY, H.G.      Pennsylvania Power & Light Co.  
 RECIP. NAME      RECIPIENT AFFILIATION

SUBJECT: LER 94-011-00: on 940707, RWCU containment isolation valves isolated on high differential flow due to leakage past work boundary valve & out of sys drains. Affected drain valves closed & leakage from sys stopped. W/940804 ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-2 PD	1 1	POSLUSNY, C	1 1
INTERNAL:	ACRS	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DORS/OEAB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOLB	1 1	NRR/DRSS/PRPB	2 2
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	NRR/PMAS/IRCB-E	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGNI FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

P  
R  
I  
O  
R  
I  
T  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T



**Pennsylvania Power & Light Company**

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

August 4, 1994

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 94-011-00  
FILE R41-2  
PLAS -609

---

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 94-011-00. This report is being made pursuant to 10CFR50.73(a)(2)(iv), in that an unplanned actuation of an Engineered Safety Feature occurred when the Reactor Water Cleanup System primary containment isolation valves closed due to a high differential flow signal.

H.G. Stanley  
VP - Nuclear Operations

JJM/mjm

cc: Mr. T. T. Martin  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. D. J. Mannai  
Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 35  
Berwick, PA 18603-0035

9408090475 940804  
PDR ADDCK 05000387  
S PDR

*Handwritten initials/signature*

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) <b>Susquehanna Steam Electric Station - Unit 1</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 3 8 7</b>	PAGE (3) <b>1 OF 0 3</b>
---	---	-----------------------------

TITLE (4)  
**RWCU Containment Isolation Valves Isolated on High Differential Flow**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
0 7	0 7	9 4	9 4	0 1 1	0 0	0 8	0 4	9 4			
									DOCKET NUMBER(S) 0 5 0 0 0		

OPERATING MODE (9) <b>1</b>	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) <b>1 0 0</b>	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)					
	20.405(a)(1)(i)	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)					
	20.405(a)(1)(ii)	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)					
	20.405(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	60.73(a)(2)(viii)(A)						
	20.405(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	60.73(a)(2)(viii)(B)						
	20.405(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(x)						

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME <b>Joseph J. Meter - Power Production Engineer</b>	AREA CODE <b>7 1 7</b>	NUMBER <b>5 4 2</b>	EXTENSION <b>- 1 8 7 3</b>

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		

SUPPLEMENTAL REPORT EXPECTED (14)			EXPECTED SUBMISSION DATE (15)		
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)			<input checked="" type="checkbox"/> NO		

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On July 7, 1994, at 0947 hours with Unit 1 in Condition 1 at 100% power, an Engineered Safety Feature (ESF) actuation occurred when the Reactor Water Cleanup (RWCU) System's containment isolation valves automatically closed due to a high differential flow signal. The high differential flow signal was attributed to leakage past a work boundary valve (air operated - failed closed) and then out of system drains. The leakage was subsequently collected in the Reactor Building floor drain system. The leakage into the isolated section of the RWCU system and out of the drain valves was sufficient to isolate the entire system on high differential flow. Upon discovery of the condition, Operations closed the affected drain valves and leakage from the system was stopped. The RWCU was subsequently returned to service. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. There were no safety consequences or compromise to the public health or safety as a result of this event. The RWCU containment isolation valves performed as expected during the event. Corrective actions include changing the applicable procedure to show that involved valves should not be used as work boundaries and to review the acceptability of other station air operated - fail closed valves as a work boundary.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2)  0   5   0   0   0   3   8   7	LER NUMBER (6)			PAGE (3)		
		YEAR 9   4	SEQUENTIAL NUMBER —   0   1   1	REVISION NUMBER —   0   0			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

On July 7, 1994, at 0947 hours with Unit 1 in Condition 1 at 100% power, an Engineered Safety Feature (ESF) actuation occurred when the Reactor Water Cleanup (RWCU, EIIS Code: CE) System's containment isolation valves (EIIS Code: JM) automatically closed due to a high differential flow signal. The high differential flow signal was attributed to leakage past a work boundary valve and then out of system drains. The leakage was subsequently collected in the Reactor Building floor drain system. The leakage into the isolated section of the system and out of the drain valves was sufficient to isolate the entire system on high differential flow. Upon discovery of the condition, Operations (Utility, non-licensed) closed the affected drain valves and leakage from the system was stopped. The RWCU system was subsequently returned to service at 1615 hours. The RWCU containment isolation valves performed as expected during the event. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. There were no safety consequences or compromise to the public health or safety as a result of this event.

CAUSE OF EVENT

The high differential flow signal was attributed to leakage past a work boundary valve and then out of system drains. The leakage into the isolated section of the system and out of the drain valves was sufficient to isolate the entire system on high differential flow. The leakage past the work boundary valve (air operated-failed closed) was due to the valve disc lifting from its seat due to system pressure. The valves in question are air operated valves with spring assist closure. The assumption with using the valves for work boundary purposes was that their design was such that when the air was removed from the valves they would fail closed and stay closed at maximum system operating pressures. The manufacturer of the valves was contacted and the design of the valves in question was that air to the valve operators in conjunction with the spring force is needed to keep the valves closed at maximum operating pressure.

REPORTABILITY / ANALYSIS

This event was determined to be reportable per 10CFR50.73(a)(2)(iv), in that an unplanned ESF actuation occurred when the RWCU system's primary containment isolation valves automatically closed following receipt of a high differential flow signal. There was no significant loss of coolant inventory nor was there any damage or degradation of the RWCU system during the event. The leakage was subsequently collected in the Reactor Building floor drain system. There were no safety consequences or compromise to the public health or safety as a result of this event. The RWCU containment isolation valves performed as expected during the event.

In accordance with guidance provided in 10CFR50.4(d), the required submission date for this report was determined to be 08/08/94.



5  
4

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2)  0   5   0   0   0   3   8   7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9   4	—   0   1   1	—   0   0	0   3	OF	0   3

TEXT (if more space is required, use additional NRC Form 368A's) (17)

CORRECTIVE ACTIONS

Upon discovery of the condition, Operations closed the affected drain valves and leakage from the system was stopped. The RWCU was subsequently returned to service at 1615 hours. Corrective actions include changing the applicable procedure to show that involved valves should not be used as work boundaries and to review the acceptability of other station air operated - fail closed valves as a work boundary.

ADDITIONAL INFORMATION

Failed Component Identification: Not Applicable

Past Similar Events:

Although the causes for the previous events were different than this case, a review of past Licensee Event Reports (LERs) for the station identified fifteen events where RWCU isolated on high flow or high differential flow signals.

Unit (NPF-14, Docket 387)

Unit 2 (NPF-22, Docket 388)

- 84-047-00
- 85-007-00
- 85-017-00
- 85-032-00
- 87-001-00
- 89-011-00
- 89-016-00
- 91-008-00
- 92-003-00

- 84-015-01
- 85-024-00
- 86-006-00
- 86-017-00
- 89-004-00
- 92-009-00