

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9610230080 DOC.DATE: 96/10/15 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 AUTH.NAME AUTHOR AFFILIATION
 WEHRY, R.R. Pennsylvania Power & Light Co.
 KUCZYNSKI, G.J. Pennsylvania Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 96-010-00: on 960915, determined main steam line
 penetration leakage rate exceeded TS limit. Caused by normal
 wear of "D" inboard MSIV. Restroked "C" inboard MSIV &
 reworked "D" inboard & outboard MSIV. W/961015 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

05000387

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-2 PD	1 1	POSLUSNY, C	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	2 2	<u>FILE CENTER</u>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EEB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DSIR/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 27



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101-1179 • 610/774-5151

October 15, 1996

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387/96-010-00
PLAS - 683 FILE R41-2

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 96-010-00. This event was determined to be reportable per 10CFR50.73(a)(2)(ii) in that the Main Steam Line penetration leakage exceeded the Technical Specification limit during regularly scheduled Local Leak Rate Testing.



G. J. Kuczyński

Plant Manager - Susquehanna SES

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Kenneth M. Jenison
Sr. Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9610230080 961015
PDR ADOCK 05000387
S PDR

IE22/1

NRC FORM 366a (6-89)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3159-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION										
FACILITY NAME (1) Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2) <div style="border: 1px solid black; padding: 2px; text-align: center;"> 0 5 0 0 0 3 8 7 </div>	LER NUMBER (6)				PAGE (3)				
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER						
		9 6 —	0 1 0 —	0 0				2	OF	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

At 0715 hours on September 15, 1996, with Unit 1 in its ninth refueling and inspection outage (Condition 5, Refueling, 0% power), an evaluation of data from the scheduled Main Steam Line (MSL; EISS Code: SB) penetration Local Leak Rate Testing (LLRT) determined that the "as found" leakage through both the inboard and outboard Main Steam Isolation Valves (MSIV; EISS Code: BD) was in excess of the limit of Technical Specification 3.6.1.2.c for the total MSL containment penetration leakage of 21.7 standard liters per minute (slm) (46.0 standard cubic feet per hour (SCFH)). The total "as found" minimum pathway leakage rate was 96.1 slm (203.6 SCFH). The evaluation determined that the MSIV LLRT excess leakage was reportable pursuant to 10CFR50.72(b)(2)(i) and 10CFR50.73(a)(2)(ii).

CAUSE OF EVENT

The "as found" leakage was attributed to the combined performance of the MSIVs. Upon restroking of the "C" inboard MSIV and retesting, the leak rate results for the "C" MSL penetration fell within the "as left" acceptance criteria and no additional rework was necessary. It is theorized that inadequate seating of the "C" inboard MSIV prior to the "as found" testing was caused by closing the MSIV at low pressure and low steam flow conditions. Therefore, it would fully seat in an accident. The cause of the failure of the "D" inboard MSIV was determined to be indentations and scratches in the poppet and poppet seat from normal wear. The cause of the failure of the "D" outboard MSIV was determined to be leakage through the pilot/pilot seat interface, also attributed to normal wear.

REPORTABILITY / ANALYSIS

This event was determined to be reportable per 10CFR50.72(b)(2)(i) as a condition found while the reactor was shutdown; and per 10CFR50.73(a)(2)(ii) in that the MSL containment penetration leakage through both the inboard and outboard MSIVs was in excess of the plant's Technical Specification limits.

The MSIV leakage was found during scheduled testing with the unit in Condition 5, Refueling. If the MSIVs had been challenged to perform their safety function when the unit had been operating, it is assumed that the measured leakage of 203.6 SCFH would have passed through the MSIVs. Although leakage design assumptions were exceeded by the "as found" testing leakage results, a dose estimate employing realistic assumptions as described in the Final Safety Analysis Report, Section 15.6.5, determined that offsite and control room doses would remain significantly below the current licensing basis analysis limits. As such, there were no safety consequences or compromises to public health and safety as a result of this event. A final dose calculation is being performed.

NRC FORM 366a (6-89)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3159-0104 EXPIRES: 4/30/92	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION		ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.			
FACILITY NAME (1) Unit 1 Susquehanna Steam Electric Station	DOCKET NUMBER (2) <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 5 0 0 0 3 8 7 9 6 — 0 1 0 — 0 0 </div>	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		9 6 —	0 1 0 —	0 0	3 OF 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

In accordance with the guidelines provided in NUREG-1022, Supplement 1, Item 14.1, the required submission date for this report was determined to be October 15, 1996.

CORRECTIVE ACTIONS

The "C" inboard MSIV was restroked, the MSIV LLRT reperformed and the "C" MSL penetration leak rate test results fell within the "as left" acceptance criteria. The "D" inboard and outboard MSIVs were reworked, the MSIV LLRT was reperformed and the leak rate test results fell within the "as left" acceptance criteria. The total "as left" MSL containment penetration minimum pathway leakage was measured to be 6.3 slm (13.4 SCFH) and the "as left" maximum pathway leakage was measured to be 28.2 slm (59.7 SCFH). In addition, a review of MSIV trends and rework history will be performed to determine if there is an ability to predict failures of these valves.

ADDITIONAL INFORMATION

Past similar events: LER 86-007-00, Docket No. 50-388
 LER 89-010-01, Docket No. 50-388
 LER 90-020-00, Docket No. 50-387
 LER 92-005-00, Docket No. 50-387
 LER 95-006-00, Docket No. 50-387
 LER 95-011-00, Docket No. 50-388

Failed Component: MSIVs HV-141F022C, D, HV-141F028D

Manufacturer: Atwood and Morrill Co., Inc.

Model: 21190-H