

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Medi-Physics, Inc. d/b/a GE Healthcare 4380 Brockton SE, Suite 3 Kentwood, MI 49512 REPORT NUMBER(S) 2017001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-34090	4. LICENSE NUMBER(S) 21-26707-01MD	5. DATE(S) OF INSPECTION May 26, 2017
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87127	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02500	2. PRIORITY 2	3. LICENSEE CONTACT Stephen M. Williams, R.Ph. - RSO	4. TELEPHONE NUMBER (616) 554-5717
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: 05/26/2019

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an unannounced routine inspection of a radiopharmacy in Kentwood, Michigan. The pharmacy operated Monday through Friday from 12:45 am to 4:00 pm, with limited hours on weekends. The pharmacy distributed 220-230 doses each weekday, primarily on one of two runs. The pharmacy's first run began around 2:00 am with deliveries out by 4:00 am. The second run began around 7:00 am with deliveries out by 8:30 am. In addition to unit and bulk doses of technetium-99m, the pharmacy also compounded indium-111 and thallium-201 when necessary, as well as approximately 500-1000 mCi of iodine-131 monthly using an automated capsule fill system. The pharmacy also re-distributed xenon-133 gas vials and iodine-123 capsules without alteration to its clients.

PERFORMANCE OBSERVATIONS

The inspector toured the facility in Kentwood to evaluate the licensee's measures for materials security, hazard communication and exposure control. The inspector conducted independent surveys of restricted and unrestricted areas, and found no residual contamination or exposures to members of the public in excess of regulatory limits. The inspector observed a variety of activities on the pharmacy's second run, including molybdenum breakthrough evaluation, dose drawing, client package preparation and vehicle loading, client package return and waste sorting. The licensee's staff also demonstrated the implementation of procedures for generator receipt and use, area surveys, and decay-in-storage waste handling, and discussed with the inspector the only radiological incident since the last inspection, involving a minor needle stick. The inspector had no concerns regarding the licensee's dose assessment or its corrective actions.

The inspector reviewed a selection of records, including daily surveys, weekly air monitoring evaluations and area contamination surveys, dose calibrator quality control documentation, monthly internal audits, annual corporate audits, weekly bioassay results, hazmat training, and dosimetry reports, which indicated maximum exposures in 2016 of 124 mrem whole-body / 8502 mrem extremity, and 35 mrem whole-body / 2515 mrem extremity in 2017 through March 31.

No violations of NRC requirements were identified as a result of this inspection.