

Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

October 2, 1978

BBS Ltr #78-1313

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Regional Directorate of Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #78-051/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

B. R. Shelton for 10/3

Station superintendent
Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

REGULATORY DOCKET FILE COPY.

78/0130165

A002/5 \*

## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [ ] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
	I L D R S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 5 EICENSE CODE 14 15 - LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'I	REPORT L 6 0 5 0 0 0 2 3 7 7 0 9 0 7 7 8 8 1 0 0 2 7 8 9 SOURCE 60 61 - DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [ While performing surv. DIS 1600-11 (Press. Suppression Air Oper. Vlv. press sw. setpt]
0 3	ck.) valve 2-1601-24 failed to operate in the specified time limit required by T.S.
04	4.7.D.l.a, Table 3.7.1. Safety significance minimal because redundant (inboard) iso-
0 5	lation valve was operable and would have provided containment integrity within spec-
0 6	ified times as required. This is the first occurrence of this type at Dresden.
07	
0 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	S D 11 X 12 Z 13 V A L V O P 14 E 15 Z 16
•	17 REPORT NUMBER 7 8 21 22 23 24 26 27 28 29 30 31 NO.
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER    X   18   Z   19   Z   20   Z   21   0   0   0   0   N   23   N   24   N   25   P   3   4   0   26     33   34   35   36   37   40   41   31   42   43   43   44   47   47   47   47   47
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Probable cause-foreign matter lodged in solenoid operated 4 way valve thereby pre-
11	venting proper bleed off. Subsequent testing and external inspection revealed no
12	abnormalities. With exception to the initial valve operation all subsequent operations
13	were well within the specified times setforth in the Tech. Specs. Because of the
4	singular nature of the event no further actions are deemed necessary.
5	FACILITY STATUS
	CTIVITY CONTENT  ELEASED OF RELEASE AMOUNT OF ACTIVITY 35  Z 33 Z 34 NA
7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  10 0 0 37 Z 38 NA  9 11 12 13
3]	PERSONNEL INJURIES NUMBER DESCRIPTION 41  O 0 0 40 NA
֓֞֞֟֞֝֟֝֟֝֟	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
8	PUBLICITY SSUED DESCRIPTION 45 78/0/30/70  NRC USE ONLY
. لا	IN (42) NA