

ATTACHMENT TO LICENSEE EVENT REPORT 78-039/03L-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT-3 (ILDRS-3)
DOCKET #050-249

During routine startup on 9/22/78 and during normal operation on 9/23/78, the Containment Cooling Service Water (CCSW) LPCI heat exchanger valve MO 3-1501-3A failed to operate in automatic mode while attempting to start torus cooling. The safety implications were minimal because the redundant CCSW loop was operable and sufficient time exists to operate the valve manually during any condition requiring its use.

The design of this system calls for the differential pressure between the LPCI and CCSW outlet lines be controlled by a motor operated valve in the CCSW outlet line. With the controller in the automatic mode, frequent fluctuations of the differential pressure across the heat exchanger cause excessive cycling of the valve. The open and close contactors then began to "chatter" causing the thermal overload to trip. Manual operation of the valve has been proven to be adequate in controlling the heat exchanger differential pressure. An on-site review will be conducted to determine if the containment cooling heat exchanger differential pressure controller can be normally operated manually.