

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: I L D R S 3; LICENSE NUMBER: 00-000000-000; LICENSE TYPE: 41111; CAT 58: 4

REPORT SOURCE: L; DOCKET NUMBER: 05000249; EVENT DATE: 7102078; REPORT DATE: 8111778

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During routine inspection, small leak was discovered on 3D2 feedwater heater drain line (3-3508B-10"). Leak located at hanger weld on bottom of pipe just below condenser. Similar occurrences reported in RO 75-043/03L-0, Docket #050-249. No adverse effects on public health or safety since minimal leakage was contained in turbine building floor drain system.

SYSTEM CODE: CH; CAUSE CODE: E; CAUSE SUBCODE: C; COMPONENT CODE: PIPEXX; COMP. SUBCODE: D; VALVE SUBCODE: Z

EVENT YEAR: 78; SEQUENTIAL REPORT NO.: 051; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: BZ; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRD-4 FORM SUB.: N; PRIME COMP. SUPPLIER: N; COMPONENT MANUFACTURER: K055

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Leak caused by cracked support to pipe weld, resulting from vibration at support location. Leak repaired by grinding out crack and rewelding. Brace also installed at this location to further minimize vibration. No further corrective action deemed necessary.

FACILITY STATUS: E; % POWER: 096; OTHER STATUS: NA; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Routine Inspection

ACTIVITY CONTENT RELEASED OF RELEASE: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES NUMBER: 000; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES NUMBER: 000; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY TYPE: Z; DESCRIPTION: NA

PUBLICITY ISSUED DESCRIPTION: N; NRC USE ONLY

NAME OF PREPARER: T. Jansen; PHONE: X-265

7811280/99



Commonwealth Edison

DEVIATION REPORT

DVR NO.	STA	UNIT	YEAR	NO.
D-12-3-78-78				

PART 1 TITLE OF DEVIATION		OCCURRED	
Leak in line #3-3508B, Drain 3 D2 htr to 3 C2 htr.		10-20-78	9:00PM
SYSTEM AFFECTED	PLANT CONDITIONS	DATE	TIME
3500 Feedwater Heater Sys.	MODE Run PWR(MWT) 2416 LOAD(MWE) 809		
DESCRIPTION OF EVENT		TESTING	
Found drain line from 3 D2 htr to 3 C2 htr. (under hotwell) has a leak at weld of pipe support.		YES	<input checked="" type="checkbox"/> NO
DESCRIPTION OF CAUSE			
Vibration of piping			
OTHER APPLICABLE INFORMATION			
Has happened before on other pipe supports			
EQUIPMENT FAILURE	DR NO.	WR NO.	RESponsible SUPERVISOR
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	NA	8358	Victor R. Rockovski 10-20-78

PART 2 OPERATING ENGINEERS COMMENTS
Safety significance minimal. All leakage contained within the floor drain system.

TYPE OF DEVIATION REPORTABLE OCCURRENCE	EVENT OF POTENTIAL PUBLIC INTEREST	TECH SPEC VIOLATION	NON-REPORTABLE OCCURRENCE	ANNUAL REPORTING	SAFETY-RELATED WR ISSUED
<input type="checkbox"/> 14 DAY <input checked="" type="checkbox"/> 30 DAY NOTIFICATION 6.6.B.2.d.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
REPORTABLE OCCURRENCE NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICATION			
50 XXX 78 - 51 - 03L-0	NA	A. Roberts Asst. Supt. 10/23/78 0900 TITLE DATE TIME NA TITLE DATE TIME			
24-HOUR NRC NOTIFICATION		PROMPT OFF-SITE NOTIFICATION			
<input type="checkbox"/> TPH NA REGION III DATE TIME	F.A. Palmer 10/23/78 1:13 TITLE DATE TIME				
<input type="checkbox"/> TGM NA REGION III & DOL DATE TIME	J.R. Gilliom 10/23/78 1:13 TITLE DATE TIME				
RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21 CONDITIONS AND THEIR REPORT TO NRC		TITLE DATE TIME			

REVIEW AND COMPLETED	C.E. Sargent OPERATING ENGINEER	10/23/78
ACCEPTANCE BY STATION REVIEW AS REQUIRED	<i>[Signature]</i> C.E. Sargent	
DATE	11/16/78	
RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION	<i>[Signature]</i> STATION SUPERINTENDENT	11/27/78
		DATE

NOV 24 1978