



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

DSB

April 30, 1979

BBS LTR #79-320

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #79-23-03L-0 Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in item B.1.e. above designed to contain radioactive material resulting from the fission process.

B. B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:lbg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

79 0508 0540 Y 7 1979  
A002  
5/11

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	0	1	I	L	D	R	S	2	②	0	0	0	0	0	0	0	0	0	0	0	0	③	4	1	1	1	1	④	5
	LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE					57	58		

CON'T:

7	0	L	⑥	0	5	0	0	0	0	2	3	7	⑦	0	4	0	6	7	9	⑧	0	4	2	6	7	9	⑨
	REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE									

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩**

0 2 | During radiographic inspection of 4 inch reactor head vent line (2-0215-4) lack of  
 0 3 | fusion noted in weld 4-4. Comparison of recent radiograph and the original acceptance  
 0 4 | radiograph showed indication present in both and geometry of indication had not changed  
 0 5 | during operation. Event does not represent a service degradation of a primary pressure  
 0 6 | boundary, but rather an unacceptable indication in the weld.  
 0 7 |  
 0 8 |

7	0	9	C	A	⑪	A	⑫	F	⑬	P	I	P	E	X	X	⑭	B	⑮	Z	⑯						
			SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE								
7	0	9	7	9	⑰	—	—	0	2	3	⑱	0	3	⑲	L	—	0	⑳								
			EVENT YEAR		LER/RO REPORT NUMBER			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO.											
7	0	9	B	⑱	Z	⑲	Z	⑳	Z	㉑	0	0	0	0	⑳	N	㉓	N	㉔	N	㉕	G	0	8	0	㉖
			ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS			ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳**

1 0 | Weld was cutout and rewelded in accordance with the ASME Boiler and Pressure Vessel  
 1 1 | Code. ASME Hydrostatic Test and radiography completed satisfactorily.  
 1 2 |  
 1 3 |  
 1 4 |

7	1	5	H	⑳	0	0	0	⑳	N/A	⑳	C	㉑	Weld Radiograph					⑳
			FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
7	1	6	Z	㉓	Z	㉔	N/A					N/A					㉕	
			ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE							
7	1	7	0	0	0	㉗	Z	㉘	N/A							㉙		
			PERSONNEL EXPOSURES NUMBER		TYPE			DESCRIPTION										
7	1	8	0	0	0	㉚	N/A							㉛				
			PERSONNEL INJURIES NUMBER		DESCRIPTION													
7	1	9	Z	㉜	N/A							㉝						
			LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION													
7	2	0	N	㉞	N/A							㉟						
			PUBLCITY ISSUED		DESCRIPTION													

Type 7905080535A