

0 1 | L | D | R | S | 3 | 2 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 4 | 9 | 7 | 0 | 5 | 1 | 1 | 7 | 9 | 8 | 0 | 5 | 2 | 4 | 7 | 9 | 9

7 8 9 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During review required by I.E. Bulletin 79-01 records indicate that valves 1402-9 A and

0 3 | 1402-9B inside containment on both units 2 and 3 have limit switches that are not

0 4 | qualified for use in a LOCA environment. Switches do not affect the safety of the

0 5 | plant or the operation of any system important to the safety of the public because

0 6 | the limit switches are used for valve position indication only and this indication is

0 7 | not mandatory for proper operator action during a LOCA.

0 9 | S | F | 11 | B | 12 | Z | 13 | I | N | S | T | R | U | 14 | X | 15 | Z | 16

7 8 9 10 11 12 13 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | LER/RO REPORT NUMBER | 7 | 9 | 21 | 22 | 23 | 0 | 0 | 9 | 24 | 26 | 27 | 0 | 1 | 28 | 29 | 30 | T | 31 | 0 | 32

18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | N | 24 | N | 25 | N | 0 | 1 | 5 | 26

33 34 35 36 37 40 41 42 43 44 47

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The switches were unqualified because this indication equipment is non-safety related.

1 1 | Therefore no requirement for obtaining an environmentally qualified switch existed when

1 2 | units 2 and 3 were built. Since environment effects on these switches would not render

1 3 | the system inoperable no further corrective action is required.

1 5 | E | 28 | 0 | 8 | 2 | 29 | NA | 30 | C | 31 | Tech Staff Observation | 32

7 8 9 10 12 13 44 45 46 80

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 44 45 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 11 12 13 80

PERSONNEL EXPOSURES NUMP'R TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 11 12 80

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43

7 8 9 10 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45

7 8 9 10 80

ISSUED DESCRIPTION PUBLICITY

NAME OF PREPARER J. Brunner

PHONE: X-472

7905300588

ATTACHMENT TO LICENSEE EVENT REPORT 79-009/01T-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT (ILDRS3)
DOCKET # 050-249

During review required by I.E. Bulletin 79-01 it was noted that limit switches on the core spray system testable check valves 1402-9A and 1402-9B were not qualified for use in a LOCA environment. The switches are Namco model SL2-C-11 and have been in use as original equipment since the construction of both Units 2&3. Although the switches are unqualified, the effect on safety is minimal because they are used for valve position indication only. Also any environmental effect on these switches will not render the core spray system inoperable. Since the position indication is not mandatory for proper system operation or operator action, no corrective action is required.