

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: I L D R S 2 0 0 - 0 0 0 0 0 0 - 0 0 0 4 1 1 1 1 (4) (5)

REPORT SOURCE: (6) 0 5 0 0 0 2 3 7 (7) 0 6 0 8 7 9 (8) 0 7 0 2 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 While performing instrum surv., HPCI steam line high flow switch DPIS 2353 was found
0 3 to trip at 151.5 inches of water. T.S. Table 3.2.1 limit is less than or equal to 150
0 4 inches of water. Redundant switch would have isolated the HPCI steam line in event of
0 5 a break. Minimal safety significance event because switch would have isolated the
0 6 HPCI steam line in the event of a break. Similar occurrence reported by LER 50-237/
0 7 75-15.

SYSTEM CODE: S F (11) CAUSE CODE: E (12) CAUSE SUBCODE: E (13) COMPONENT CODE: I N S T R U (14) COMP. SUBCODE: E (15) VALVE SUBCODE: Z (16)

EVENT YEAR: 7 9 (17) SEQUENTIAL REPORT NO.: 0 4 2 OCCURRENCE CODE: 0 3 REPORT TYPE: L REVISION NO.: 0

ACTION TAKEN: E (18) Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: Y (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: B 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 The cause is attributed to instrument drift. The switch was inspected for abnormali-
1 1 ties and none were found. The switch was reset to 145.0 inches of water. HPCI steam
1 2 line flow switches will continue to be tested monthly.
1 3
1 4

FACILITY STATUS: E (28) % POWER: 0 9 6 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION: Surveillance test (32)

ACTIVITY CONTENT: Z (33) Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)

PERSONNEL EXPOSURES: 0 0 0 (37) Z (38) DESCRIPTION: N/A (39)

PERSONNEL INJURIES: 0 0 0 (40) DESCRIPTION: N/A (41)

LOSS OF OR DAMAGE TO FACILITY: Z (42) DESCRIPTION: N/A (43)

PUBLICITY ISSUED: N (44) DESCRIPTION: N/A (45)

7907110 443 S