

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I | L | D | R | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CONT
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 7 | 1 | 0 | 0 | 1 | 7 | 9 | 8 | 1 | 0 | 1 | 8 | 7 | 9 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | While performing a modification on the fire system, fire water accumulated on
03 | the mezzanine floor which then ran down into the U2 D/G control cabinet via the D/G
04 | room vent ductwork, causing the diesel auto start block alarm. The operating engr.
05 | declared the D/G inoperable and electrical maintenance was called upon to determine
06 | the cause. The health and safety of the public was not affected because redundant
07 | systems were verified operable by required testing. This event is the first of its
08 | kind.

09 | SYSTEM CODE | E | E | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | F | 13 | COMPONENT CODE | R | E | L | A | Y | X | 14 | COMP. SUBCODE | X | 15 | VALVE SUBCODE | Z | 16 |
17 | LER/RO REPORT NUMBER | 7 | 9 | 21 22 | SEQUENTIAL REPORT NO. | 0 | 5 | 2 | 24 26 | OCCURRENCE CODE | 0 | 3 | 28 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |
ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NPRO-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | G | 0 | 8 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Water in control cabinet shorted the auto start relay contact causing auto start
11 | block alarm. The water was removed and the cabinet dried. Required surveillance
12 | was completed satisfactorily and the D/G demonstrated operable. The seams between
13 | ceiling and U2 & U3 DG room vent. ductwork which penetrates the ceiling, have been
14 | sealed with RTV to prevent recurrence.

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 9 | 8 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator observation | 32

16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

17 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

18 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | TYPE | NA | 43

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

7910290240 NRC USE ONLY

NAME OF PREPARER Atif A. Ammar

PHONE: 265