

Common Balth Edison Dresden Nuclear Power Station R.R. #1 Morris, Illinois 60450 Telephone 815/942-2920

January 10, 1994

GFS PMLTR 94-0012

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Licensee Event Report 93-022, Docket 50-237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10CFR50.73(a)(z)(ii)B.

allua 1-10-94

Gary F. Spedl Station Manager Dresden Station

GFS/MP/maf

Enclosure

J. Martin, Regional Administrator, Region III cc: NRC Resident Inspector's Office File/NRC File/Numerical



S

IEDD 1/1

											LICE	NSEE E	EVENT	REPO	DRT (L	ER)		()								Fo	orm F	Rev 3	2.0	
Facility N	ame	(1)				-							C	Docke	t Num	ber	(2)					,	· · · · ·	Pa	ge (3)				<u></u>		
Dresden Nuclear Power Station, Unit 2							0 5	5 0	0 0	2	3	7			1		ŀ	of	Τ		- <u> </u>			3								
Title (4)	Floc	or Dra	ins in th	he	RCA Ha	ve Po	ten	tiat Inpu	uts in	to Non-C	Contan	inated	Proces	sina	Syste	ms (Contu	ary to	FSA	NR 9	1 na	ae	910-	3			-					
Ev	ent D	ate (5	5)	T					LER	Number	(6)						R	eport	Date	(7)		Ţ		Oth	ar Fa	ciliti		nvolv		31		
Month		Day	Year	t	Ye	ar				Sequent Numbe	ial .		Re	visio umbe	n	Mor	ith	Da	IV .	Ý	ear _		Facili Nam	ity es		Do	ocke	t Nun	nber	(8)		
			-	Т			Τ		•			Γ		T					·			Τ	N/A	1	Π		Τ				Γ	
1 2	1	6	9 3	3	9	3			0	2	2		0		0	0	1	1	0	9	4		N/A	<u> </u>					L			
OPER MOI	ATIN DE (9	G)	N	T	THIS REI	ORT	IS :	SUBMIT	TED	PURSUA	ANT TO	O THE	REQUI	RMEN	NTS O	F 10	CFR				•											
		Τ		<u> </u>					2	0.402(b))		Τ		20.40	5(c)				50	73	a)(2	 2)(iv)			Γ	٦	73.71	(Ь)			
POW	ER El		• .				•		2	0.405(a)	(1)()	• .			50.36	(c)(1)			50	.73(a)(2	2)(v)					73.71	/1(c)			
. (10)					•		<u> </u>	2	0.405(a)	(1)(ii)				50.36	(c)(2)	Γ		50	.73(a)(2	2) (vii)					Other	(Sp	ecify in		
			0		9	5			2	0.405(a))(1)(iii)				50,73	(a)(2)(i)		_	_50	.73(a)(2	2)(viii)	(A)		Γ		Abstr and ir	act b i Tex	oelov kt)	N	
	, An thuật				antor de la ca		25.55		2	0.405(a)	(1)(iv)		>	$\langle $	50.73	(a)(2)(ii)			50	.73(a)(2	2){viii){	B)					• *			
					t di padi perten Tanananan		 		2	0.405(a)	(1)(v)	•			50.73	(a)(2)(iii)			50	.73(a)(2	2)(x)	_								
			•							LI	CENSE		ACT F	OR T	HIS LI	ER (1	2)						_			_						
NAME					•.											,							TE	ELEF	HON		UME	ER				
																		-`	·		AREA CODI	A E		1	I	1	1	1			4	
	Rob	ert L.	Holmar	<u>n, s</u>	System	Engin	eer										Ext	t. 2554	4	8	1	5	9	4	2	<u> </u>	Ŀ	2	9	2	0	
			r			CON	IPL	ETE ON	IE LIN	E FOR E	ACH	COMPC	NENT	FAIL	URE D	ESC	RIBE	DIN	THIS T	REP	ORT	<u>(1:</u> 1	3)	_			1998					
CAUSE	SYS	TEM	CO	MP	ONENT		MA		с- Т	REPORT	ABLE	CA	USE	SYS	атем Т	со	мрс		г м		FAC- ER	-	REPO	RTA NPR	BLE DS	то						
			┝─┼	÷	┝╌┼╴	+	┢	+	$\left\{ \cdot \right\}$				-+			+			┢	+		╉			.							
		SUP	LEMEN	ITA	AL REPO	RT E	(PE	CTED (14)	• .					•				E	xpec	ted	1	Mor	nth	Τ		Day	•	Γ	Yea	r	
				•						•									SI	ubmi)ate	ssion (15)	ŗĻ						-	Γ			
	Yes	(If yes	, comp	let	e EXPEC	TED	SUE	MISSI	ON D	ATE)			N	10				-	Γ]	·			•						

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On December 16, 1993, at 1645 hours, with Unit 2 at 95% power and Unit 3 at 84% power, an engineering review of turbine building floor drain paths found several floor drains within the Radiation Control Area (RCA) input into non-contaminated processing systems contrary to FSAR 9.1. page 9.1.0-3. An action plan was immediately formed to identify all floor drains that had input into non-contaminated processing systems and place labels and/or signs above and around the drains to administratively control inputs. An enhanced sampling program was immediately initiated by the chemistry department. The operations department put all control switches from the 2/3 floor drain oil separator and the unit 1 oil separator to pull-to-lock (PTL). Before pumping out of either of these pits, chemistry analyzed the water to determine if any contamination existed. No contamination was found in any of the samples. Plans were formulated to pump the water if future analysis indicated activity, to lined containers thereby preventing any unmonitored releases. During the construction of the plant, several floor drains were designed to have their inputs go to non-contaminated processing systems. Routine sampling of these areas over the years saw no contamination in any of the samples.

	LICENSEE EVENT REPORT (LI	ER) TEXT (ONTIN	UATIC							Fo	rm Re	sv. 2.0
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUM	BER (6))		•		·]	Page (3)	
		Ycar		Sequen	atial Number		Revi Num	ision nber					
Dresden Nuclear Power Station	0 5 0 0 0 2 3 7	9 3		0	2 2		0	0	0	2	OF	0	3

TEXT Energy Industry Identification System (EIIS) codes are identified in the text as [XX]

PLANT AND SYSTEM IDENTIFICATION:

General Electric-Boiling Water Reactor-2527 MWt rated core thermal power.

Nuclear Tracking System (NTS) tracking code numbers are identified in the text as (XXX-XXX-XX-XXXXX)

EVENT IDENTIFICATION:

Floor Drains in the RCA Have Potential Inputs Into Non-Contaminated Processing Systems Contrary to FSAR 9.1 page 9.1.0-3

A. CONDITIONS PRIOR TO EVENT:

Unit: All	Event Date: 12-16-93	Event	Time:	1645	hours
Reactor Mode: N/A	Mode Name: N/A	Power	Level:	N/A	•
Reactor Coolant System	(RCS) Pressure: N/A				

B. DESCRIPTION OF EVENT:

On December 16, 1993, at 1645 hours with unit 2 at 95% power and unit 3 at 84% power, an engineering review of turbine building floor drain paths found several floor drains within the Radiation Control Area (RCA) draining into the non-contaminated processing systems contrary to FSAR 9.1 page 9.1.0-3. The majority of these turbine floor drains drain into the 2/3 floor drain oil separator which flows to the Waste Water Treatment (WWT) system for treatment. The 2/3 diesel generator day tank room floor drain building diagram indicates that this drain goes to the transformer oil separator. These drains all have the potential for an unmonitored release if not properly controlled.

C. APPARENT CAUSE OF EVENT:

The subsequent engineering review revealed that some drains in the turbine building input to non-contaminated processing systems. Upon further investigation, other drains within the turbine building on the 517' elev. and the 538' elev. were discovered to have inputs to non-contaminated processing systems.

SAFETY ANALYSIS OF EVENT:

Radiation Protection surveys of the various drains indicate that no contamination was present in these drains. Chemistry sampling of the effluent of the Waste Water Treatment(WWT) plant indicates that there has not been any unmonitored release. Based on the surveys and sampling there were no effects on the public health or safety. Therefore, this event had no safety significance.

CORRECTIVE ACTIONS:

Immediate corrective actions were to put all control switches from the 2/3 floor drain oil separator ejector pit, and the unit 1 oil separator pit in pull-to-lock and sample for radioactivity prior to pumping the pits to WWT. A composite sample of WWT is also obtained to verify the final effluent is not contaminated.

D.

Ε.

		LICENSEE EVENT REPORT (LI	ER) TEXT CONTINUATIO
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) Page (3)
•			Year Sequential Number Revision Number
!	Dreaden Nuclear Power Station	0 5 0 0 0 2 3 7	9 3 0 2 2 0 0 0 3 OF 0 3

TEXT Energy Industry Identification System (EIIS) codes are identified in the text as [XX]

All floor drains in the turbine building that have inputs to noncontaminated processing systems have been identified. Labels or signs have been placed at each drain indicating that unauthorized dumping of liquids in these drains is not permitted.

Long term corrective action is to administratively (DAP) control all turbine building floor drain inputs thus reducing the possibility of contaminated liquids in the non-contaminated processing systems.

Changes are to be submitted to the FSAR as stated on DAP form 02-06A attached.

Increase the sampling frequency of the WWT and tr oil Separator discharges.

÷

PREVIOUS OCCURRENCES:

No previous occurrences of this nature were previously identified.

COMPONENT FAILURE DATA:

N/A

F.

G.

L:\8360\8301\237\180\93\022