



**Commonwealth Edison**  
Dresden Nuclear Power Station  
6500 North Dresden Road  
Morris, Illinois 60450  
Telephone 815/942-2920

June 21, 1994

GFSLTR 94-0196

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Licensee Event Report 94-014, Docket 50-237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10CFR50.36(c)(2) and 10CFR50.73(a)(2)(i).

Sincerely,

Gary F. Spedl  
Station Manager  
Dresden Station

GFS/IR:cfq

Enclosure

cc: J. Martin, Regional Administrator, Region III  
NRC Resident Inspector's Office  
File/NRC  
File/Numerical

gfs94\0196.94

9406290017 940621  
PDR ADDCK 05000237  
S PDR

JEZ

**LICENSEE EVENT REPORT (LER)**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  
Dresden Nuclear Power Station, Unit 2

DOCKET NUMBER (2)  
05000237

PAGE (3)  
1 OF 4

TITLE (4)  
Tech Spec LCO Not Met Due to Inoperable Redundant EDGs

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	23	94	94	-- 014 --	00	06	21	94	Dresden 2	05000237
									FACILITY NAME	DOCKET NUMBER

OPERATING MODE (9)	N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)				
		20.2201(b)		20.2203(a)(3)(i)	50.73(a)(2)(iii)	73.71(b)
		20.2203(a)(1)		20.2203(a)(3)(ii)	50.73(a)(2)(iv)	73.71(c)
POWER LEVEL (10)	092	20.2203(a)(2)(i)		20.2203(a)(4)	50.73(a)(2)(v)	OTHER
		20.2203(a)(2)(ii)		50.36(c)(1)	50.73(a)(2)(vii)	(Specify in Abstract below and in Text, NRC Form 366A)
		20.2203(a)(2)(iii)	X	50.36(c)(2)	50.73(a)(2)(viii)(A)	
		20.2203(a)(2)(iv)	X	50.73(a)(2)(i)	50.73(a)(2)(viii)(B)	
		20.2203(a)(2)(v)		50.73(a)(2)(ii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: Ismael Rivera Jr. Ext. 2549

TELEPHONE NUMBER (Include Area Code): (815) 942-2920

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	EK	65	W290	Y						

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).

NO

EXPECTED SUBMISSION DATE (15)

MONTH: 04 DAY: 30 YEAR: 95

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On May 23, 1994, the Unit 2/3 Emergency Diesel Generator (EDG) [EK] had been made administratively inoperable due to the service water temperatures rising above 82 degrees. During the performance of a Tech Spec required operability demonstration of the Unit 2 EDG due to the Unit 2/3 EDG being administratively inoperable, the Unit 2 EDG tripped on overspeed. The Unit 2 EDG was declared inoperable and Dresden Unit 2 entered a 24 hour Limiting Condition for Operation (LCO). System Engineering was requested to assist in the overspeed trip investigation. Operations monitored the service water temperature and once they were verified to have dropped below 83 degrees, the 2/3 EDG was demonstrated operable. Unit 2 was removed from the 24 hour LCO and continued on a 7 day LCO.

The root cause of the governor failure is currently unknown, pending the results of a vendor failure analysis of the component. The governor was replaced under work request 26179 and the Unit 2 EDG was successfully demonstrated operable on May 25, 1994 at 2237 hours.

NRC FORM 366A (5-92)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95		
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.		
FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)		PAGE (3)
Dresden Nuclear Power Station, Unit 2		05000237		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
				94	-- 014 --	00
						2 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A). (17)

PLANT AND SYSTEM IDENTIFICATION:

General Electric-Boiling Water Reactor-2527 MWT rated core thermal power.

EVENT IDENTIFICATION:

Tech Spec LCO Not Met Due to Inoperable Redundant EDGs

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit: 2                                      Event Date: May 23, 1994                      Event Time: 1828  
 Reactor Mode: N                              Mode Name: Run                              Power Level: 92%  
 Reactor Coolant System Pressure: 996 psig

B. DESCRIPTION OF EVENT:

On May 23, 1994, at 1828 hours, with Unit 2, at 92% rated core power, the Unit 2 Emergency Diesel Generator (EDG) [EK] tripped on overspeed due to a governor failure. The governor failed to return the fuel rack to its normal position following a start up. The governor maintained the fuel rack in the full open position, causing the EDG to trip on overspeed. The Unit 2 EDG was being demonstrated operable per Technical Specification 3.9.D. due to the Unit 2/3 EDG being administratively inoperable. The 2/3 EDG was administratively inoperable due to the service water intake temperatures exceeding 82 degrees. This temperature limit on the 2/3 EDG was a result of calculations performed following an August 27, 1993 incident in which plant conditions were such that the cooling water flow to the 2/3 EDG was restricted. This incident was reported under LER 2-93-018. Dresden Unit 2 entered a 24 hour Limiting Condition for Operation (LCO).

System Engineering was notified and requested to assist into the investigation of the Unit 2 EDG overspeed trip. Operations verified that the service water intake temperatures had dropped below 83 degrees and performed an operability run on the 2/3 EDG. Upon completion of the 2/3 EDG operability run, Dresden Unit 2 terminated a 24 hour Limiting Condition for Operation (LCO) at 2113 hours and remained on a 7 day LCO due to the Unit 2 EDG.

C. CAUSE OF EVENT:

This report is submitted in accordance with 10CFR50.36(c)(2), which requires notification when a limiting condition for operation is not met, and 10CFR50.73(a)(2)(i), which requires reporting of a condition prohibited by the plants Technical Specifications.

The cause of the Unit 2/3 EDG being declared inoperable was the service water intake temperatures rising above 82 degrees. Once the service water temperature dropped, the Unit 2/3 EDG was demonstrated operable and removed from the degraded equipment log at 2113 hours on May 23, 1994.

The apparent cause of the Unit 2 EDG overspeed trip is attributed to failure of the governor, due to unknown causes. Upon the fast start of the EDG, the

NRC FORM 366A (5-92)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)
Dresden Nuclear Power Station, Unit 2		05000237	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
			94	-- 014 --	00
					3 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

governor failed to properly respond by not returning the fuel rack to its normal operating position. As a result of the fuel rack maintaining a full open position, the engine speed continued to increase exceeding the overspeed trip setting of 1035 RPMs.

D. SAFETY ANALYSIS:

The safety significant of this event is considered minimal for the following reasons:

The Unit 2/3 EDG had been administratively declared inoperable due to the service water intake temperature rising above 83 degrees. However, this temperature only presents a degraded condition if the cooling water flow is degraded as well. The cooling water flow is degraded when four Unit 2 Containment Cooling Service Water (CCSW) pumps are operating concurrently with the Unit 2/3 EDG operating in a loaded condition. This scenario would only be possible with a loss of offsite power (LOOP) occurring concurrently with a loss of coolant accident (LOCA). The likelihood of this scenario is extremely unlikely. Furthermore, once the temperature was verified to be below 83 degrees, the Unit 2/3 EDG was successfully demonstrated operable as required by Tech Spec 3.9.

E. CORRECTIVE ACTIONS:

Immediately following the Unit 2 EDG trip, the System Engineer was contacted to assist with the investigation into the Unit 2 EDG overspeed trip. A review of the alarms received was conducted. A mechanical overspeed trip was verified to have had occurred, eliminating the possibility of this being a spurious actuation. The generator was verified to be intact through a bridge and megger. The overspeed trip setting was verified to be at the 1035 to 1050 RPM range. After discussing the findings thus far with MKW/Power Systems, the focus was next directed at the governor. The injector control lever was inspected and found to be intermittently sticking when taken to full open and released. The injector control arms were disconnected to determine the cause of the injector control lever sticking. The injector control arms operated as designed, therefore, the cause was determined to be the governor. The governor was replaced and the Unit 2 EDG was successfully demonstrated operable at 1828 hours on May 26, 1994.

During the initial investigation into the Unit 2 EDG trip, the service water intake temperatures were being monitored to ensure that the temperature was within the operable range of the Unit 2/3 EDG. Site Engineering had been contacted earlier to issue the final operability evaluation pertaining to the Unit 2/3 EDG cooling water flow requirements. Once the water temperature was verified to have dropped below 83 degrees, the 2/3 EDG was demonstrated operable at 2113 hours on May 23, 1994. Site Engineering issued an operability determination closeout (CHRON # 0301242) which states that the 2/3 EDG is operable with the service water temperature in the 83 to 95 degrees range provided that CCSW is limited to a maximum of two pump operation. The daily operating orders were revised accordingly to incorporate the Site Engineering findings. Dresden Operating Procedures (DOP) 1500-02, 1500-03, and 6600-03 have been revised to restrict the number of CCSW pumps operating to three for a service water temperature range of 82-91 degrees and to two for a service water

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Dresden Nuclear Power Station, Unit 2	05000237	94	-- 014 --	00	4 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

temperature range of 91-95 degrees during required 2/3 EDG operation. In addition, the Updated Final Safety Analysis Report (UFSAR) has been revised to reflect the current cooling water flow rates of 800 gal/minute at 95 degrees for the 2/3 EDG and 900 gal/minute at 95 degrees for the Unit 2 & 3 EDGS.

F. PREVIOUS OCCURRENCES:

There are no similar previous licensee events reports of these occurrences.

G. COMPONENT FAILURE DATA:

Manufacturer	Nomenclature	Model Number	Mfg. Part Number
Woodward Governor Co	Governor	UG 8	N/A

An NPRDS search identified 4 occurrences in which the governor was the root cause of an overspeed trip.