

June 23, 1994

Docket Nos. 50-249  
and 50-254

Mr. D. L. Farrar, Manager  
Nuclear Regulatory Services  
Commonwealth Edison Company  
Executive Towers West III, Suite 500  
1400 OPUS Place  
Downers Grove, Illinois 60515

Dear Mr. Farrar:

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION CONCERNING CORE SHROUD CRACKING  
AT DRESDEN, UNIT 3, AND QUAD CITIES, UNIT 1

By letters dated June 6, 1994, June 13, 1994, and June 14, 1994, the Commonwealth Edison Company (CECo) provided additional information concerning the cracking of the core shroud and justification for the operation of Dresden, Unit 3, and Quad Cities, Unit 1, with the degraded shrouds. Based on the NRC staff review of the information, the staff finds that the additional information is required to allow the staff to justify restart of Dresden, Unit 3, and Quad Cities, Unit 1, with the degraded core shrouds. Please provide a response in writing by Monday, June 27, 1994. This schedule is based on the NRC staff review of the information and providing a safety evaluation prior to restart of Dresden, Unit 3, on July 10, 1994.

The reporting and/or recordkeeping requirements contained in this letter affect fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

If you have any questions concerning this action, please contact me at (301) 504-1345.

Sincerely,  
Original signed by Chandu Patel for  
John F. Stang, Project Manager  
Project Directorate III-2  
Division of Reactor Projects - III/IV  
Office of Nuclear Reactor Regulation

9406300047 940623  
PDR ADOCK 05000249  
P PDR

Enclosure:  
Request for Additional Information

cc w/enclosure:  
See next page

DISTRIBUTION:

~~Docket File~~  
F. Miraglia  
R. Capra  
B. Sheron  
R. C. Jones  
OGC

PDIII-2 r/f  
R. Zimmerman  
C. Moore  
B. D. Liaw  
T. Collins  
ACRS (10)

NRC & Local PDRs  
J. Roe  
J. Stang  
J. Strosnider  
E. Butcher  
C. Patel

W. Russell  
J. Zwolinski  
A. Thadani  
M. Virglio  
B. Clayton RIII

**NRC FILE CENTER COPY**

AA3

DF01

OFC	LA:PDIII-2	PM:PDIII-2	PM:PDIII-2	D:PDIII-2		
NAME	CMOORE <i>JS</i>	JSTANG <i>CP</i>	CPATEL <i>opt</i>	RCAPRA <i>JS</i>		
DATE	6/23/94	6/23/94	6/23/94	6/23/94	/ /94	/ /94
COPY	<u>YES</u> /NO	YES/NO	YES/NO	<u>YES</u> /NO	YES/NO	YES/NO

Mr. D. L. Farrar  
Commonwealth Edison Company

Dresden Nuclear Power Station  
Unit No. 3

cc:

Michael I. Miller, Esquire  
Sidley and Austin  
One First National Plaza  
Chicago, Illinois 60690

Mr. G. Spedl  
Plant Manager  
Dresden Nuclear Power Station  
6500 North Dresden Road  
Morris, Illinois 60450-9765

U. S. Nuclear Regulatory Commission  
Resident Inspectors Office  
Dresden Station  
6500 North Dresden Road  
Morris, Illinois 60450-9766

Chairman  
Board of Supervisors of  
Grundy County  
Grundy County Courthouse  
Morris, Illinois 60450

Regional Administrator  
U.S. NRC, Region III  
801 Warrenville Road  
Lisle, Illinois 60532-4351

Illinois Department of Nuclear Safety  
Office of Nuclear Facility Safety  
1035 Outer Park Drive  
Springfield, Illinois 62704

Mr. D. L. Farrar  
Commonwealth Edison Company

Quad Cities Nuclear Power Station  
Unit No. 1

cc:

Mr. Stephen E. Shelton  
Vice President  
Iowa-Illinois Gas and  
Electric Company  
P. O. Box 4350  
Davenport, Iowa 52808

Michael I. Miller, Esquire  
Sidley and Austin  
One First National Plaza  
Chicago, Illinois 60690

Station Manager  
Quad Cities Nuclear Power Station  
22710 206th Avenue North  
Cordova, Illinois 61242

Quad Cities Resident Inspectors Office  
U. S. Nuclear Regulatory Commission  
22712 206th Avenue North  
Cordova, Illinois 61242

Chairman  
Rock Island County Board  
of Supervisors  
1504 3rd Avenue  
Rock Island County Office Bldg.  
Rock Island, Illinois 61201

Illinois Department of Nuclear Safety  
Office of Nuclear Facility Safety  
1035 Outer Park Drive  
Springfield, Illinois 62704

Regional Administrator  
U. S. NRC, Region III  
801 Warrenville Road  
Lisle, Illinois 60532-4351

REQUEST FOR ADDITIONAL INFORMATION  
CONCERNING CORE SHROUD CRACKING AT  
DRESDEN, UNIT 3, AND QUAD CITIES, UNIT 1  
DOCKET NOS. 50-249 AND 50-254

MATERIALS QUESTIONS

1. Provide for both Dresden, Unit 3, and Quad Cities, Unit 1, the number of effective full power years of operation.
2. Provide information concerning the reactor coolant water chemistry for both units from the time of startup to the present and its effect on the core shroud cracking.
3. Provide justification that the 45 degree Ultra Sonic (UT) transducer would reliably detect all cracks in the core shroud if the cracking is tight or geometry is unfavorable. In addition, the justification should provide a detailed explanation of why bounding flow depth at the H<sub>5</sub> weld is 1.241 inches.
4. Provide justification to rule out cracking coming from the inside of shroud at the H<sub>5</sub> weld from the toe of the fillet weld.
5. Provide a map of the UT measurements on the H<sub>5</sub> weld.
6. Provide a comparison of the Boiling Water Reactor Owners Group core shroud screening criteria to that used for the Dresden and Quad Cities core shroud inspection.
7. Is the Dresden and Quad Cities H<sub>5</sub> fabrication similar to that of Brunswick (i.e., double V grooved, backgouged)?
8. Provide verification of the dimension of the fillet weld.
9. Provide justification that the crack growth rate in your June 13, 1994, submittal is bounded based on the water chemistry during the early years of operation at Dresden and Quad Cities. Could deeper cracks be expected based on water chemistry?
10. Provide justification that crack propagation path predictions have correctly incorporated the effects of residual stresses. Could the crack propagate through an alternate path (i.e., up through the cylinder)?
11. Provide stress distribution profile information across the H<sub>5</sub> weld.
12. What is the status of the use of hydrogen addition to the reactor coolant at Dresden and Quad Cities.

13. Provide the detailed results of the Dresden and Quad Cities boat sample metallurgical analyses.
14. Provide a detailed justification and clarification for the bases of crack depth sizing on the H<sub>5</sub> weld geometry using only UT detection capability.
15. What are the fracture toughness properties in the short transverse direction for the heavy stainless steel plate of the top guide support ring and the core plate support ring?
16. Justify why limit load analysis is appropriate for the stress distributions associated with the H<sub>5</sub> weld and fillet finite element analysis. Is bending appropriately considered?
17. What is the predicted/measured reduction in residual stresses with the cracking at the H<sub>5</sub> weld?
18. Provide an assessment of the operating margin against uncertainties in the approach used to size the H<sub>5</sub> weld crack by UT.

#### Probabilistic Questions

1. Provide the probabilities and bases of the design basis events as well as the data sources for the postulated event frequency. Also, provide the contribution to the core damage frequency and release frequency for these events.
2. Are the shroud cracks in conjunction with the steamline break or recirculation pipe break events incorporated in the IPE study? If so, provide the information.

#### Mechanical Engineering Questions

1. Provide complete structural/mechanical analysis of the core shroud, assuming worst-case degradation of the H<sub>5</sub> weld up to and including a 360-degree thru wall crack at H<sub>5</sub> for upset, emergency and faulted plant conditions (e.g., main steam line break (MSLB), recirculation line break (RCLB), SSE and most severe load combinations). Evaluate the effect of three-dimensional shroud movement (e.g., uplift/tilting and subsequent dropping, tilting, lateral motion, etc.) on the structural integrity and functionality of reactor internal components, equipment and support structures.

Analysis package should fully describe all analytical assumptions with justifications, conservatisms, methodology (e.g., analytical models and boundary constraints, development and application of loads, stress and deflection calculations), and conclusions. Also provide information to verify that any computer codes used in the analysis have been properly benchmarked.

### Reactor Systems Questions

1. What is the total flow value of the LPCI system under accident conditions (i.e., LOCA, large break and steamline break) with postulated worst-case single failure, and what are the limiting single failure assumptions applied and their impacts on injection flow?
2. What is the minimum core water level needed to assure adequate cooling following a DBA LOCA?
3. Provide the operating and design basis faulted condition loads for the H<sub>5</sub> weld. Identify the methodologies for determining the faulted condition loads and justify why the methodologies are appropriate (e.g., WHAM, RETRAN, approximate 3-D blowdown flow analysis). Provide all assumptions with justification conservatisms and initial and final conditions. In addition, provide all benchmarking and experimental data to justify the use of all codes.
4. Provide unavailability data for the following ECCS scenarios: 1 core spray out; 1 LPCI out; both core sprays out; 1 LPCI injection valve unavailable; and common mode LPCI loop-select logic unavailable.

### Reanalyses Question

1. In the May 26, 1994, meeting between the NRC and CECo concerning the core shroud, CECo indicated it would reevaluate continued operation after 6 months if the unit restarted without repairing the H<sub>5</sub> weld. Please provide the details of the proposed reevaluation and all other actions to be taken by CECo.