Commonwealth Edison ppany Dresden Generating Statur 6500 North Dresden Road Morris. IL 60450 Tel 815-942-2920

ComEd

December 29, 1994

TPJLTR 94-0001

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Supplemental Report Number 1 to Licensee Event Report 94-018, Docket 50-237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10CFR50.73(a)(2)(ii) and 10CFR50.73(a)(2)(iv).

Sincerely,

for Thomas P. (Joyce

Site Vice President

TPJ/GCEII:cfq

Enclosure

cc: J. Martin, Regional Administrator, Region III NRC Resident Inspector's Office File/NRC File/Numerical

TJP94\0001.94

9501050189 940707 PDR ADOCK 05000237 S PDR

A Unicom Company

Sk. 20



DAP FORM 02-08C SUPPLEMENTAL REPORT TO LER

DVR NO.	SYSTEM AFFECTE	ED
STA UNIT YEAR NO.	、	
D - 12 - 2 - 94 - 018	7300	· .
PART 1 TITLE OF EVENT	OCCURRED	
Potential Trip of Motor Control Centers Due		
to Improper Feed Breaker Settings	06/08/94	1913
	DATE	TIME
REASON FOR SUPPLEMENTAL REPORT		
Investigation by Electrical/I&C Group determined m	ore information regarding the cause of eve	ent and
Corrective Actions regarding the event.		· · ·
PART 2	~	
ACCEPTANCE BY STATION REVIEW	Permanter Dalpens	R. Staching
DATE	12-22-94	12/23/94
SUPPLEMENTAL REPORT APPROVED AND		
AUTHORIZED FOR DISTRIBUTION	Dening	12-29-44
· · · · · · · · · · · · · · · · · · ·	STATION MANAGER	DATE

4

											_						
NRC FORM	M 366				U.S.	NUCLE	AR I	REGULATO	RY CONN	ISSION			APPROVED BY EXPI	(ONB NO. (RES 5/31)	315 /95	0-0104	
	LICENSEE EVENT REPORT (LER)								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.								
FACILITY	Y NAME Dres	(1) den N	uclea	r F	ower Stati	.on, t	Jni	.t 2			DOCI	KET	NUMBER (2) 05000237			1 0	PAGE (3) DF 7
TITLE (4	4) Pote	ntial	Trip	of	Motor Con	trol	Ce	nters	Due	to Im	prop	per	Feed Brea	aker Se	tt:	ings	
EVEN	T DATE	(5)			LER NUMBER (6)			REPO	RT DATE	(7)			OTHER FACIL	ITIES INV	OL V	ED (8)	
MONTH	DAY	YEAR	YEAR		SEQUENTIAL NUMBER	REVIS NUMB	ION ER	MONTH	DAY	YEAR	FACI Dre	ILITY NAME Søden, Unit 3			DOCKET NUMBER 05000249		
06	08	94	94		018	01		07	Q7	94	FACI	LIT	Y NAME		DO	CKET N	JMBER
OPERA	TING		THIS	REPO	RT IS SUBMITTE	D PURSL	JANT	TO THE	REQUIR	EMENTS	OF 10) CF	R§: (Check (one or moi	re)	(11)	
MODE	(9)		20	.220	1(b)			20.2203	(a)(3)	(i)			50.73(a)(2)(i	iii)		73.71	(b)
POL	FR		20	.220	3(a)(1)			20.2203	(a)(3)	(ii)		X	50.73(a)(2)(i	iv)		73.71	(c)
LEVEL	(10)	000	20	.220	3(a)(2)(i)			20.2203(a)(4)					50.73(a)(2)(v)			OTHER	
			20	.220	203(a)(2)(ii)			50.36(c)(1)				50.73(a)(2)(vii)			(Specify in		
			20	.220	3(a)(2)(iii)			50.36(c)(2)					50.73(a)(2)(viii)(A)			stract	below
			20	.220	3(a)(2)(iv)			50.73(a)(2)(i))			50.73(a)(2)(v	/iii)(B)	NRO	C Form	366A)
			20	.220	3(a)(2)(v)		X	50.73(a)(2)(ii)			50.73(a)(2)()	()			•
			<u> </u>			LICENS	EE (CONTACT	FOR THI	S LER	(12)						
NAME											<u> </u>		TELEPHONE NUN	IBER (Incl	ude	Area	Code)
	Geor	ge C.	Ecke	rt	II, Plant	Suppo	ort	Engir	neer	Ext.	27	96	(81	5) 942-	-29	20	
				HPLE	TE ONE LINE FO	R EACH	CO	(PONENT	FAILURE	DESCR	BED	IN T	HIS REPORT (1	3)			
CAUSE	SYST	EM C	OMPONEN	т	MANUFACTURER	REPOR TO N	TABL PRDS	LE S	C	AUSE	SYS	TEM	COMPONENT	MANUFAC		ER R	EPORTABLE
			SUPPLE	ENT/	AL REPORT EXPEC	TED (1	4)				[F		MONTH	Т	DAY	YEAR
X YES (1f)	/es, co	mplete	EXPECTE	D SL	JBMISSION DATE)	·•		•	0			SUI Da	BMISSION TE (15)				

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

With Unit 3 in Refuel, while performing a 24 hour endurance run of the Unit 3 Emergency Diesel Generator, motor control center (MCC) 39-2 tripped. The trip of MCC 39-2 caused a trip of the Unit 3 Emergency Diesel Generator Cooling Water Pump and consequently a trip of the Unit 3 Emergency Diesel Generator on high temperature. Loss of MCC 39-2 also caused a loss of the 3B Reactor Protection System (RPS) MG-Set, the "B" Standby Gas Treatment (SBGT) Train, the 125VDC Charger #3 and the 250VDC Charger #2/3. The loss of the RPS MG-Set caused a Unit 3 half scram, and the loss of the "B" SBGT train caused a start of the "A" SBGT train, which is considered an ESF actuation. An operability determination was made which stated that the MCC trip was due to an improperly set feed breaker. It also stated that the MCC was operable provided the compensatory action of controlling running load on the MCC was implemented. Station Operations department controlled the loading on the MCC until trip settings could be revised. A review of the MCC loading indicated that the original setting of the breaker was adequate but that load additions over time had created an overload situation. This event initiated a review of all safety related MCC feed breakers. The review indicated that MCCs 28-3 and 38-3 also had improperly set feed breakers. A separate operability assessment was performed on these two MCCs, which included immediate compensatory actions of controlling running loads to below the breakers' trip settings. The loading restrictions remained in place until the breakers could be properly set.

4

NRC FORM 366A (5-92)	U.S. NUCLEAR RI	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				TED BURDEN PER NFORMATION COLLI COMMENTS REGA FORMATION AND I 7714), U.S. NUCLI STON, DC 20555-0 ION PROJECT TENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH 'ORY COMMISSION, O THE PAPERWORK O, DFFICE OF J, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	<u> </u>	PAGE (3)
Dresden Nuclear Power Station, Unit 2	Loop Deven Station Whit 2	0500000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
	05000237	94	018	01	2 OF /	

EVENT IDENTIFICATION:

Potential Trip of Motor Control Centers Due to Improper Feed Breaker Settings

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit: 2(3)Event Date: 06/08/94Event Time: 1913 hrsReactor Mode: N(N)Mode Name: Run (Refuel)Power Level: 99% (00%)Reactor Coolant System Pressure: 1005 (00) psig

B. DESCRIPTION OF EVENT:

On June 8, 1994 with Unit 3 in Refuel Mode, MCC 39-2 inadvertently tripped at 1913. The trip occurred concurrently with a 24 hour endurance run of the Unit 3 Emergency Diesel Generator [EK], during operation of the Unit 2/3 SBGT System [BH] "B" train, and during a Unit 2 High Pressure Coolant Injection (HPCI) [BJ] surveillance. There were no failed components which contributed to this event. The following equipment is fed by MCC 39-2 and consequently became unavailable when the MCC tripped:

Unit 3 Emergency Diesel Generator Cooling Water Pump [LB] Unit 3 Emergency Diesel Generator Vent Fan [EK] Unit 3 Emergency Diesel Generator Starting Air Compressor 3B [LC] Unit 3 Emergency Diesel Generator Fuel Transfer Pump [EK] CCSW Pump Cubicle Cooler C Fans 1 and 2 [BO] CCSW Pump Cubicle Cooler D Fans 1 and 2 [BO] SBGT Inlet Damper 2/3B [BH] SBGT Air Heater 2/3B [BH] SBGT Fan Discharge Damper 2/3B [BH] SBGT Fan 2/3B [BH] SBGT Outside Air Damper 2/3B [BH] Reactor Building Vent to SBGT Damper 2/3B [BH] RPS Motor-Generator Set 3B [JC] 125VDC Battery Charger 3 [EJ] 250VDC Battery Charger 2/3 [EJ] Turbine Building Emergency Lighting [FG] Condensate Transfer Pump 3B [KA]

Trips of these services caused the following system events to occur:

Loss of the SBGT [BH] "B" train caused an automatic initiation of the "A" train at 1913. This is considered an ESF actuation and an ENS notification was made at 2235 EST on June 8, 1994.

Loss of the Emergency Diesel Generator Cooling Water Pump [LB] and Vent Fan [EK] caused a trip of the Emergency Diesel Generator [EK] due to high temperature at 1914.

Loss of the RPS Motor-Generator Set [JC] caused a loss of power to the RPS and, consequently, a Unit 3 half scram.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	GULATORY COMMISSION		APPROVED BY O EXPIRE	MB NO. 315 S 5/31/95	0-0104
	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	R)	ESTIMAT THIS II FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEM	TED BURDEN PER NFORMATION COLLE COMMENTS REGA FORMATION AND F FORMATION AND F FOR, DC 20555-0 ION PROJECT IENT AND BUDGET,	RESPONSE ECTION REQUENT REDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. IEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, 0FFICE OF 1, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6))	PAGE (3)
	aleen Deven Station Unit 2	05000237	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 05 7
Dresden Nu	clear Power Station, Unit 2		94	018	01	3 OF 7

Loss of the 125VDC charger #3 required that operators realign the Unit 3 125VDC system [EJ] to the available 125VDC charger #3A. Loss of the 250VDC charger 2/3 required that operators realign the Unit 3 250VDC battery system [EJ] to the available 250VDC charger #3. Both battery systems were realigned by 1928.

The next actions were to strip the MCC of all its loads and reclose the feed breaker at switchgear 39 which was completed at 1935. The SBGT "B" train was placed in off and then reenergized at 1937. The Emergency Diesel Generator Cooling Water Pump and Vent Fan were energized from MCC 39-2 and started. All remaining loads on MCC 39-2 were restored by 1942.

Due to existing plant conditions, the MCC trip was not believed to be a result of a fault condition. The trip was believed to be due to an overcurrent condition in the long time range of the feed breaker. Per discussions with operating personnel, the HPCI Auxiliary Oil Pump had been recently started when the breaker tripped. Starting the pump would cause the Unit 2/3 250VDC battery charger to go into a current limiting condition meaning that it would draw its maximum current rating from its AC source. This large load in conjunction with the other loads already running on the MCC caused a current of approximately 405 Amps to be drawn. This is in excess of the feed breakers 400 Amp trip setting. The trip of the breaker is not considered an equipment failure because it tripped as designed.

A review of the loads fed from MCC 39-2 indicated that the loads energized during the event may also be energized under certain accident conditions. This implied that the MCC and therefore the loads would not be available for accident mitigation under all scenarios. Because a basis for the existing feed breaker setpoint could not be immediately established, an operability determination was begun by Site Engineering to determine the worst case accident load scenario. The results indicated that the breaker was set too low for a postulated LOCA condition without loss of offsite power; a loading condition similar to the recent event. Immediate compensatory actions were directed to the station Operations Department. The compensatory actions included realigning the AC feed of the Unit 2/3 250VDC charger to MCC 29-2 and to consider the Condensate Transfer Pump 3B out of service. This would ensure the connected load would not trip the feed breaker under accident conditions.

The overcurrent trip device in MCC 39-2 is a General Electric dashpot type EC-2A device which is original plant equipment. Because a basis could not be established for the existing setting, all other MCCs using the original EC-2A devices were also suspect. A review was performed which determined that the remaining MCC feed breakers using EC-2A devices would not suffer from a similar overcurrent problem.

A review of all safety related MCC feed breakers, including those which used newer RMS-9 trip devices, was also performed. The review accounted for all accident conditions to determine the worst case loading and voltage conditions on the safety related switchgear and MCCs. The review indicated that the feed breakers for MCCs 28-3 and 38-3 were also set too low for all postulated conditions. Because the breakers to these MCCs were set too low for all postulated events, the emergency AC power system was believed to be outside of its design basis and an ENS notification was made at 1312 EST on June 13, 1994.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	GULATORY COMMISSION		APPROVED BY C	MB NO. 315 S 5/31/95	0-0104
	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	R)	ESTIMA THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLLE COMMENTS REGA FORMATION AND F 7714), U.S. NUCLI STON, DC 20555-0 TON, DC 20555-0 TON PROJECT MENT AND BUDGET,	RESPONSE ECTION REQU REDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. JEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, OFFICE OF 1, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	>	PAGE (3)
Drogdon Nu	along Bouer Station Unit 2	05000227	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Dresden Nu	Diesden Muclear Fower Station, Unit 2	05000237	94	018	01	4 ÚF /

A second operability assessment was performed to address MCCs 28-3 and 38-3. Immediate compensatory actions similar to those for the previous operability determination were again directed to the station Operations Department. The actions included considering the Turbine Bearing Lift Pumps out of service on MCC 28-3 and considering the Turbine Turning Gear out of service on MCC 38-3. These actions would ensure the connected loads would not trip the respective feed breakers.

C. CAUSE OF EVENT:

This report is being submitted in accordance with 10CFR50.73(a)(2)(ii), which requires the reporting of any event or condition that results in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded, or results in the nuclear power plant being in a condition that is outside the design basis of the plant; and in accordance with 10CFR50.73(a)(2)(iv), which requires the reporting of any event or condition that results in manual or automatic actuation of any Engineered Safety Feature.

The trip of MCC 39-2 was due to an incorrectly set feed breaker. The feed breaker for this MCC had a General Electric dashpot type EC-2A overcurrent trip device which was original equipment. The setting for this breaker was 400 amps +/-10% due to tolerance of the EC-2A device. A review of the original loading on the MCC indicates that the 400 Amp setting was adequate based on protective device setting standards at the time of original design. Load additions made to the MCC over time however, increased the available running load current above the 400 Amp setting. Therefore, the cause of the overload condition was a failure to assure that additions of plant loads were reviewed for impact on breaker settings.

The feed breakers to MCCs 28-3 and 38-3 have had their EC-2A trip devices replaced with General Electric solid state type RMS-9 trip devices. The new RMS-9 devices provide enhanced trip selectivity to allow 480VAC breaker coordination. The RMS-9 devices were installed in November 1991 for MCC 38-3 and March 1993 for MCC 28-3. Both of these feed breakers were set at 400 amps. Because the new devices were installed after implementation of the ELMS program, an investigation was performed by the Electrical / I&C department in Downers Grove to determine the cause of the protective device settings for MCCs 28-3 and 38-3 not reflecting all postulated load conditions. This department performed the investigation because it was responsible for control of 480 Vac Switchgear protective device settings at the time of the event.

The investigation determined that the new setting for MCC 38-3 was chosen to be identical to the original setting based on the assumption that the MCC loading had not changed over time. This was determined by interviews with the personnel involved with the setting calculations. Also, letter #173174 dated September 18, 1991, which transmitted the revised device setting, gave no basis for the setting and did not identify the potential for an overloaded protective device. However, since loading had changed, the total connected load was greater than the protective device setting. The cause of the overloaded condition is therefore a failure to assure that the addition of plant loads over time were reviewed for impact on breaker settings, and a failure to review plant conditions during the calculation of the protective device setting.

NRC FORM 366A (5-92)	U.S. NUCLEAR F	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCI (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWORI REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.				
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)		
	and Deven Station Hait 2	05000337	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	É OF 7		
Dreaden MdC1	ear Power Station, Unit 2	05000237	94	018	01	5 OF /		

At the time the setting for MCC 28-3 was issued, it was recognized that the protective device setting was lower than the total connected load. That information is documented in letter #197606 dated February 2, 1993. However, since the new protective device setting was identical to the original setting, it was assumed that the running load during accident conditions would be within the setting of the protective device. The significance of the potential for an overloaded protective device was not understood by those receiving it or by its authors. The actual running load during a design basis accident was not considered during the device setting calculation. The cause of the overloaded condition on MCC 28-3 therefore, is the same as that for MCC 38-3.

D. SAFETY ANALYSIS:

The following discussion makes reference to the equipment fed by MCCs 28-3 and 38-3; the loads are printed here for ease of discussion.

<u>28-3</u>

Turning Gear Oil Pump Piggy Back Motor Fire Protection Panel FP-2 Unit 2 EDG Circ Lube Oil Pump Unit 2 EDG Immersion Heater Turning Gear Turbine Bearing Lift Pumps Unit 2 250VDC Charger Unit 2 EDG Turbo Lube Oil Pump Unit 2/3 EDG Cooling Water Pump

<u>38-3</u>

Turning Gear Oil Pump Piggy Back Motor Fire Protection Panel FP-3 RPS MG-Set 3A Unit 3 EDG Circ Lube Oil Pump Unit 3 EDG Immersion Heater Distribution Panel 2253-85 Turning Gear Turbine Bearing Lift Pumps CCSW Cubicle Cooler A Fans 1&2 CCSW Cubicle Cooler B Fans 1&2 Unit 3 EDG Turbo Lube Oil Pump Unit 2/3 EDG Cooling Water Pump

The auxiliary power system is designed using safety related and balance of plant switchgear and MCCs to provide AC power to normal and emergency plant loads. The safety related equipment is divided into two separate divisions to provide diversity and redundancy. Under accident conditions, the safety related equipment is designed to have power supplied from the safety related Emergency Diesel Generators of the same division. There are two accident scenarios which are considered to present the worst case loading conditions for the safety related equipment; 1) a Loss of Coolant Accident with a Loss of Offsite Power (LOCA/LOOP) and, 2) a Loss of Coolant Accident with offsite power available (LOCA).

During a LOCA/LOOP condition, some loads on MCCs 28-3, 38-3 and 39-2 will trip and not reenergize when the Emergency Diesel Generators start and provide power to the emergency buses. As such, the loading on the MCCs is significantly reduced and the voltage levels are greatly improved thereby reducing the current draw. Preliminary analysis has been performed which indicates that under LOCA/LOOP conditions, MCC 28-3 may trip due to current levels above the feed breaker's setting. The other MCCs will not trip due to excessive current.

NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET WASHINGTON DC 20503.				
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6		PAGE (3)		
Dresden Nuclea	r Power Station, Unit 2	05000237	YEAR 94	SEQUENTIAL NUMBER	REVISION NUMBER 01	6 OF 7		

Loss of MCC 28-3 would cause a loss of the Unit 2/3 Emergency Diesel Generator Cooling Water Pump. Although this pump has a backup source of power from MCC 38-3, it is assumed that under Unit 2 LOCA and full site LOOP conditions, MCC 38-3 would not have a source of power. Therefore, the Unit 2/3 Emergency Diesel Generator would not have cooling water and is assumed to be unavailable. Assuming a single failure on the Unit 2 Emergency Diesel Generator would render all Unit 2 emergency AC power sources unavailable. However, the Division I crosstie between buses 34-1 and 24-1 would be available to provide AC power. The remaining loads on MCC 28-3 are not required to mitigate the consequences of an accident or to ensure operability of safety related equipment.

Under the second condition of LOCA with offsite power available, it is conservatively assumed that the offsite power is degraded to a level slightly above the second level degraded voltage relay setpoint so that the Emergency Diesel Generator has started on the LOCA signal but is not connected to the bus, thereby forcing onsite power to its lowest postulated value. Under this condition, preliminary analysis has shown that MCCS 28-3, 38-3 and 39-2 will trip due to current levels above the feed breakers' settings thereby causing all loads on the MCCs to become deenergized. The Unit 2/3 and Unit 3 Emergency Diesel Generator Cooling Water Pumps would be lost causing the Emergency Diesel Generators to fail or require manual operator action to be taken to restore cooling. An assumed single failure of the Unit 2 Emergency Diesel Generator would cause all on site emergency AC power to be unavailable. However, in the assumed scenario, offsite power is available to mitigate the consequences of the LOCA.

£.

Another significant load is the feed to the SBGT "B" train. This event could have resulted in the "B" train being unavailable to maintain releases within 10CFR100 limits. However, the "A" train was not affected by this event. Also, loss of the CCSW cubicle cooler fans may cause a loss of the vaulted CCSW pumps and therefore inhibit long term cooling ability. This would again require operator action to mitigate the consequences of this loss. However, the CCSW motors are manually started loads and therefore operator action is already required. Loss of the remaining loads on the MCCs would not cause the inability to mitigate the consequences of an accident.

E. CORRECTIVE ACTIONS:

Immediate corrective actions during the loss of MCC 39-2 included reenergizing the tripped loads. Intermediate corrective actions included operability assessments performed by Site Engineering. The compensatory actions associated with the operability assessments included limiting the loads connected to the affected MCCs. Long term corrective actions of replacing the existing feed breakers to the affected MCCs with properly set breakers is complete. The feed breaker to MCC 39-2 has been replaced with a breaker that contains an RMS-9 trip device. All trip device settings have been reviewed and, where necessary, reset at levels that account for breaker coordination and worst case current levels expected at the individual MCCs.

Long term corrective actions also included reviewing various historical loading conditions on the auxiliary power system. The review considered the modifications to the auxiliary power system over the years including those due to degraded voltage considerations, addition of new MCCs, and other system

NRC FORM 366A U. (5-92)	.S. NUCLEAR R	EGULATORY COMMISSION		APPROVED BY C EXPIRE	MB NO. 315 S 5/31/95	0-0104
LICENSEE EVENT RE TEXT CONTINU	PORT (LE ATION	ER)	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLL D COMMENTS REGA IFORMATION AND 7714), U.S. NUCL GTON, DC 20555-C GTON, DC 20555-C ION PROJECT MENT AND BUDGET,	RESPONSE ECTION REQU REDING BURD RECORDS MA EAR REGULAT 1001, AND T (3150-0104) WASHINGTON	TO COMPLY WIT JEST: 50.0 HRS JEN ESTIMATE TO NAGEMENT BRANCI TORY COMMISSION O THE PAPERWORI O, OFFICE O J, DC 20503.
FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6	>	PAGE (3)
Drogdon Nuclear Bower Station		05000007	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7 05 7
		05000237	94	018	01	, OF /

changes. The review determined that loads were added which caused an overcurrent condition on these MCCs. However, long term corrective actions with regard to the modification process are not believed necessary due to this event. The load additions which created the overcurrent conditions were made prior to modification enhancements. The heightened level of awareness regarding the auxiliary power system design and the modification process in general have resulted in substantial required reviews during the process of adding loads. The modification process now requires a load analysis by the Electrical Load Monitoring System as well as breaker coordination and protective device setting calculations when a new load is added.

With regard to the improper review of plant loading conditions during device setpoint calculation, the investigation determined that Technical Information Document TID-E/I&C-13, 480 Volt Switchgear Trip Device Selection And Setting, was not issued until May 21, 1993. This TID gives guidance as to how a protective device for an MCC feed breaker is to be sized. Prior to issuing the TID, protective device setpoints were determined in accordance with procedure ENC-QE-59. However, the guidance in QE-59 is directed toward new design as opposed to modification of an older plant. In calculation of the device setpoints for Dresden, it was believed that the existing setpoints were adequate and that review of the running loads was not required. The personnel involved with the calculations recognize and acknowledge the error of this methodology, and understand the importance of reviewing plant conditions prior to calculating protective device settings. These personnel were responsible for the investigation into the event, the determination of the affected MCCs, and the corrective actions.

As an added action to prevent recurrence, additional controls have been placed on load changes and the resulting impact on the electrical distribution system trip device settings. The ELMS-AC+ program, used to evaluate the system load flow, has been revised to flag conditions in which the additional load current will exceed the ampacity of the connection. Through the load addition process, both the ELMS program and Relay Setting Program are updated. The ELMS program will flag cases in which the running load is higher than the cable ampacity, therefore requiring further evaluation to avoid nuisance tripping. The protective device settings are currently and will continue to be checked to ensure coordination. This action will preclude recurrence and assure proper review for protection and coordination within the electrical distribution system.

In cases where the connection ampacity is higher than the protective device setting, the device setting will be revised through the relay setting program. The new setting will reflect the additional load condition and thereby also avoid nuisance tripping. The current modification process requires a review of both the ELMS database and protective device settings when a new load is added or a current load is modified.

F. PREVIOUS OCCURRENCES:

There have been no previous occurrences in which a MCC spuriously tripped due to an incorrect breaker setting.

G. COMPONENT FAILURE DATA:

N/A