

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920

**ComEd**

June 26, 1995

TPJLTR 95-0068

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Licensee Event Report 95-011, Docket 50-249 is being submitted as required by Technical Specification 6.6, 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(ii).

Sincerely,



Thomas P. Joyce  
Site Vice President

TPJ/MM:pt

Enclosure

cc: J. Martin, Regional Administrator, Region III  
NRC Resident Inspector's Office  
File/NRC  
File/Numerical

TPJ95\0068.95

9507030094 950628  
PDR ADOCK 05000249  
S PDR

A Unicom Company

*Handwritten initials/signature*

NRC FORM 366 (5-92)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95									
<b>LICENSEE EVENT REPORT (LER)</b>										ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.				
FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3					DOCKET NUMBER (2) 05000249			PAGE (3) 1 OF 3						
TITLE (4) Type B and C Leakage Limit Exceeded Due to Excessive Leakage Past HPCI Check Valve														
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)				
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER				
05	29	95	95	-- 011 --	00	06	28	95	None					
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)												
N		20.2201(b)		20.2203(a)(3)(i)		50.73(a)(2)(iii)		73.71(b)						
POWER LEVEL (10)		20.2203(a)(1)		20.2203(a)(3)(ii)		50.73(a)(2)(iv)		73.71(c)						
000		20.2203(a)(2)(i)		20.2203(a)(4)		50.73(a)(2)(v)		OTHER						
		20.2203(a)(2)(ii)		50.36(c)(1)		50.73(a)(2)(vii)		(Specify in Abstract below and in Text, NRC Form 366A)						
		20.2203(a)(2)(iii)		50.36(c)(2)		50.73(a)(2)(viii)(A)								
		20.2203(a)(2)(iv)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(B)								
		20.2203(a)(2)(v)		X 50.73(a)(2)(ii)		50.73(a)(2)(x)								
LICENSEE CONTACT FOR THIS LER (12)														
NAME M. McGivern, Local Leak Rate Test Coordinator Ext. 2526							TELEPHONE NUMBER (Include Area Code) (815) 942-2920							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)														
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS				
X	BJ	ISV	C283	Yes										
SUPPLEMENTAL REPORT EXPECTED (14)														
X	YES (If yes, complete EXPECTED SUBMISSION DATE).			NO	EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR					
							11	13	95					

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

At approximately 1600, on May 29, 1995 with Unit 3 shutdown for maintenance, the performance of Dresden Technical Surveillance (DTS) 1600-01, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the High Pressure Coolant Injection (HPCI) System [BJ] Turbine Exhaust to Suppression Pool Check Valve 3-2301-45 to be leaking more than the test equipment could measure. When the valve's leakage was added to the existing maximum pathway leakage rate, the maximum pathway leakage rate limit for Type B and C primary containment leakage, 488.452 standard cubic feet per hour (scfh) (0.6L<sub>4</sub>), as listed in Technical Specification 3.7.A.2.b.(2) (a) was exceeded. The safety significance of the leakage past the 3-2301-45 was considered to be minimal since the additional leakage out of containment, on a minimum pathway basis, was 14.39 scfh from the inboard isolation Stop Check Valve 3-2301-74 (LLRT performed on 9/2/94) and would not cause the maximum off-site dose rates established in 10 CFR 100 to be exceeded. The check valve will be removed, inspected, replaced and Local Leak Rate Tested prior to unit startup. A supplement will be submitted to report the reason for valve failure and the corrective actions taken.

NRC FORM 366A (5-92)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)
Dresden Nuclear Power Station, Unit 3		05000249	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
			95	-- 011 --	00
					2 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT IDENTIFICATION:

Type B and C Leakage Limit Exceeded Due to Excessive Leakage Past HPCI Check Valve

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit: 3                                      Event Date: 05/29/95                                      Event Time: 1600 hrs.  
 Reactor Mode: N                                      Mode Name: Shutdown                                      Power Level: 0%  
 Reactor Coolant System Pressure: 0 psig

B. DESCRIPTION OF EVENT:

At approximately 1600, on May 29, 1995 with Unit 3 shutdown for maintenance, the performance of Dresden Technical Surveillance (DTS) 1600-01, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the HPCI Turbine Exhaust to Suppression Pool Check Valve 3-2301-45 to be leaking more than the test equipment could measure. When the valve's leakage was added to the existing maximum pathway leakage rate, the maximum pathway leakage rate limit for Type B and C primary containment leakage, 488.452 scfh (0.6L<sub>4</sub>), as listed in Technical Specification 3.7.A.2.b.(2)(a) was exceeded.

To verify that corrective actions previously undertaken to prevent LLRT failures were sufficient, leak rate tests were to be performed on an accelerated schedule of every six months. This first six month leak rate test resulted in an LLRT failure.

The Unit Supervisor was notified of the event and a Performance Improvement Form (PIF) was written to report a condition prohibited by the plant's Technical Specifications.

C. CAUSE OF EVENT:

This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i) which requires the reporting of any operation or condition prohibited by the plant's Technical Specifications.

This LER is also submitted pursuant to 10 CFR 50.73(a)(2)(ii) which requires reporting any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded.

The dual-disk HPCI Turbine Exhaust Check Valve 3-2301-45 will be removed, inspected, replaced and Local Leak Rate Tested prior to unit startup.

The root cause of the valve failure, and corrective actions to prevent future recurrence of failures, will be thoroughly reviewed prior to startup.

A supplement to this LER will be submitted to document the cause of the check valve's LLRT failure.

NRC FORM 366A (5-92)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)
Dresden Nuclear Power Station, Unit 3		05000249	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
			95	-- 011 --	00
					3 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

D. SAFETY ANALYSIS:

The safety significance of the leakage past the 3-2301-45 was considered to be minimal since the additional leakage out of containment, on a minimum pathway basis, was 14.39 scfh from the inboard isolation Stop Check Valve 3-2301-74 (LLRT performed on 9/2/94) and would not cause the maximum off-site dose rates established in 10 CFR 100 to be exceeded.

E. CORRECTIVE ACTIONS:

Nuclear Tracking System (NTS) tracking code numbers are identified in the text as (XXX-XXX-XX-XXXXX).

The HPCI Turbine Exhaust Check Valve 3-2301-45 will be replaced and Local Leak Rate Tested prior to startup. (NTS #249-180-95-01101)

An LER supplement will be submitted which contains the repairs performed and the results of the as-left LLRT. (NTS #249-180-95-01102)

The root cause of the valve failure, and corrective actions to prevent future recurrence of failures, will be thoroughly reviewed prior to startup. (NTS #249-180-95-01103)

F. PREVIOUS OCCURRENCES:

<u>LER/Docket Numbers</u>	<u>Title</u>
94-022/0500237	Type B and C Leakage Limit Exceeded Due to Worn Seating Surface of HPCI Check Valve
91-007/0500249	Type B and C Containment Local Leak Rate Testing Limit Exceeded Due to HPCI Turbine Exhaust Check Valve Leakage
89-009/0500249	Local Leak Rate Testing "As Found" limit Exceeded Due to leakage From Primary Containment Valves

G. COMPONENT FAILURE DATA:

An LER supplement will be submitted with the results of an industry wide Nuclear Plant Reliability Data System (NPRDS) data base search of similar valve failures along with specific failure information for the check valve obtained from valve disassembly.