Commonwealth Edison ppany Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920

Χ.,



July 21, 1995

TPJLTR 95-0082

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 94-022, Docket 50-237 is being submitted as required by Technical Specification 6.6 and 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(ii).

This revised report is submitted to describe the corrective actions taken for the HPCI Check Valve Local Leak Rate Test (LLRT) Failure and the results of the NPRDS search.

Sincerely,

Thomas/P. Joyce Site Vice President

TPJ/MG:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III NRC Resident Inspector's Office File/NRC File/Numerical

250130



TPJ95\0082.95

1622 11

														·	
NRC FORM	M 366			U.S	. NUCLE	AR S	REGULATO	RY COMM	ISSION	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT REPORT (LER)								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
FACILIT	Y NAME Dres	(1) den N	uclear	Power Stati	Lon, 1	Uni	t 2			DOCKET	NUMBER (2) 05000237			1 C	AGE (3) DF 5
TITLE (4	4) Type	B an	d C Le	eakage Limit	Exce	ede	d Due	to Wo	orn S	eatin	g Surface	of HPCI	Ch	eck	Valve
EVEN	T DATE	(5)		LER NUMBER (6))		REPO	RT DATE	(7)		OTHER FACIL	LITIES INV	OL VE	D (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVIS	ION ER	MONTH	DAY	YEAR	FACILITY NAME None			DOCKET NUMBER		
08	08	94	94	022	01		07	21	95	FACILI	TY NAME	·	DOC	KET NL	IMBER
OPERA	TING		THIS R	EPORT IS SUBMITTE	D PURS	JANT	TO THE	REQUIRE	MENTS	OF 10 C	FR §: (Check	one or mor	re)	(11)	
NODE	(9)	N	20.	2201(b)			20.2203	(a)(3)(i)		50.73(a)(2)(iii)		73.71	(b)
POM	ER		20.	2203(a)(1)		Î	20.2203(a)(3)(ii)				50.73(a)(2)(iv)		73.71	(c)
LEVEL	(10)	099	20.	2203(a)(2)(i)			20.2203(a)(4)				50.73(a)(2)(v)		OTHER		
			20.	2203(a)(2)(ii)			50.36(c)(1)				50.73(a)(2)(vii)		(Specify in		
			20.	2203(a)(2)(iii)			50.36(c)(2)			50.73(a)(2)(viii)(A)		Abstract below			
			20.	2203(a)(2)(iv)	<u> </u>	X	50.73(a)(2)(i)		50.73(a)(2)(viii)(B) NRC Form		366A)			
			20.	2203(a)(2)(v)		x	50.73(a)(2)(ii)		50.73(a)(2)(x) ·			
					LICENS	FF (CONTACT I	OR THI	S LER	(12)	<u> </u>				
NAME						、					TELEPHONE NU	MBER (Incl	ude	Area	Code)
	м. м	cGive	rn, Lo	ocal Leak Rat	e Te	st	Coordi	nator	Ext.	2526	(81	5) 942-	-292	20	
			CO	PLETE ONE LINE FO	OR EACH	COP	PONENT I	AILURE	DESCR	BED IN	THIS REPORT (1	3)		• •	
CAUSE	SYST	EM C	OMPONENT	MANUFACTURER	REPOR TO N	TABL PRDS	.E 5	C	AUSE	SYSTER	COMPONENT	MANUFAC	TURE	R	EPORTABLE
x	BJ		ISV	M358	YI	ES									
х	BJ		ISV	R340	YI	ES									
			SUPPLEM	INTAL REPORT EXPE	CTED (1	4)					EXPECTED	MONTH	T	DAY	YEAR
YES (lf)	YES (If yes, complete EXPECTED SUBMISSION DATE).					S I	UBMISSION ATE (15)								

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

At approximately 0600, on August 8, 1994, with Unit 2 operating at 99% power, the performance of Dresden Technical Surveillance (DTS) 1600-01, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the High Pressure Coolant Injection (HPCI) System Turbine Exhaust to Suppression Pool Check Valve 2-2301-45 and Stop Check Valve 2-2301-74 to be leaking 234.7 standard cubic feet per hour (scfh). This value when added to the existing maximum pathway leakage rate resulted in the maximum pathway leakage rate limit for Type B and C primary containment leakage, 488.452 scfh (0.6L), as listed in Technical Specification 3.7.A.2.b.(2)(a) being exceeded. The safety significance of the leakage past the 2-2301-45 was considered to be minimal since the additional leakage out of containment, on a minimum pathway basis, was 87.6 scfh from the outboard isolation Check Valve 2-2301-45 and would not cause the maximum off-site dose rates established in 10 CFR 100 to be exceeded. The cause of the excessive leakage was due to a worn seating surface which allowed leakage between the valve seat and the plate-type disks. This valve was replaced and the as-left LLRT yielded a leakage rate of 1.06 scfh. This supplement is submitted to report the corrective actions taken for this check valve failure as well as the results of an NPRDS search.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY CHE NO. 3150-0104 EXPIRES 5/31/95						
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			ESTIMATED BURDEN PER RESPONSE TO COMPLY I THIS INFORMATION COLLECTION REQUEST: 50.0 FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BR/ (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISS WASHINGTON, DC 20555-0001, AND TO THE PAPER REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BURGET WASHINGTON DC 20503				
	FACILITY NAME (1)	DOCKET NUMBER (2)	[LER NUMBER (6)	PAGE (3)			
Dresden Nuc	lear Power Station, Unit 2	05000237	YEAR	SEQUENTIAL REVISION NUMBER NUMBER	2 OF 5			
			94	022 01				

EVENT IDENTIFICATION:

Type B and C Leakage Limit Exceeded Due to Worn Seating Surface of HPCI Check Valve

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit:2Event Date:08/08/94Event Time:0600 hrs.Reactor Mode:NMode Name:RunPower Level:99%Reactor Coolant System Pressure:1000 psig

B. DESCRIPTION OF EVENT:

At approximately 1935, on August 7, 1994, with Unit 2 operating at 99% power, high and increasing HPCI (High Pressure Coolant Injection) [BJ] Turbine Exhaust pressure was observed during Dresden Operating Surveillance (DOS) 2300-03, High Pressure Coolant Injection (HPCI) Operability Verification. Upon stopping the surveillance, the HPCI Turbine Exhaust to Suppression Pool Valves (2-2301-45 and 2-2301-74) were declared inoperable. Technical Specification 3.7.D.1. states:

During reactor power operation conditions, all primary containment isolation valves and all instrument line flow check valves shall be operable except as specified in 3.7.D.2.

Technical Specification 3.7.D.2. states:

In the event any primary containment isolation valve becomes inoperable, reactor power may continue provided at least one valve in each line having an inoperable valve is in the mode corresponding to the isolated condition.

Therefore, the HPCI Turbine Exhaust Stop Check Valve 2-2301-74 was locked closed. This stopped the clock for the Limiting Condition for Operation described in Technical Specification 3.7.D.3. which states:

If specification 3.7.D.1 and 3.7.D.2 cannot be met, an orderly shutdown shall be initiated and the reactor shall be in the cold shutdown condition within 24 hours...

At approximately 0600, on August 8, 1994 with Unit 2 operating at 99% power, the performance of Dresden Technical Surveillance (DTS) 1600-01, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the HPCI Turbine Exhaust to Suppression Pool Check Valve 2-2301-45 and Stop Check Valve 2-2301-74 to be leaking 234.7 scfh. This value when added to the existing maximum pathway leakage rate resulted in the maximum pathway leakage rate limit for Type B and C primary containment leakage, 488.452 scfh (0.6L₀), as listed in Technical Specification 3.7.A.2.b.(2)(a) being exceeded.

This Local Leak Rate Test (LLRT) is performed by first shutting the HPCI Turbine Exhaust Stop Check Valve 2-2302-74 and then pressurizing the volume between the Check Valve 2-2301-45 and the 2-2301-74. Since the Stop Check Valve is closed,

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			TED BURDEN PER NFORMATION COLLE COMMENTS REGAL FORMATION AND F 7714), U.S. NUCLE STON, DC 20555-0 ION PROJECT (MENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK , OFFICE OF J, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)		PAGE (3)
Drandon N		05000037	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Dresden Nuclear Power Station, Unit 2 050002			94	022	01	3 OF 5

this allows pressure to build up for testing the integrity of the dual-disk HPCI Turbine Exhaust Check Valve 2-2301-45. All of the leakage is conservatively attributed to the Check Valve 2-2301-45. This volume was considered a single valve pathway since the HPCI Turbine Exhaust Stop Check Valve could not be tested in the proper accident configuration.

The Shift Control Room Engineer (SCRE) was notified of the event, and an ENS phone notification was then made at 0730 Eastern Standard Time on Monday, August 8, 1994 to report a degraded condition while operating.

Since there had been no history of failure of the Stop Check Valve and occasional failures of the dual-disk Check Valve, a test was needed to determine the leakage solely for one of the two valves. Trouble-shooting was performed by slipping a pancake flange between the 2-2301-45 and the 2-2301-74. This test, which pressurized only the Stop Check Valve 2-2301-74, found the 2-2301-74 to be leaking 147.1 scfh. Therefore, the leakage attributed to the Check Valve 2-2301-45 was 87.6 scfh

Since the HPCI Turbine Exhaust to Suppression Pool valves could not be repaired on-line, the Dresden Unit 2 reactor was shut down. An ENS phone notification was made at 0848 Eastern Standard Time on Monday August 8, 1994 to report the initiation of a Technical Specification required reactor shutdown.

C. CAUSE OF EVENT:

This LER is submitted pursuant to 10 CFR 50.73(a)(2)(i) which requires the reporting of any operation or condition prohibited by the plant's Technical Specifications.

This LER is also submitted pursuant to 10 CFR 50.73(a)(2)(ii) which requires the reporting of any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded.

The dual-disk HPCI Turbine Exhaust Check Valve 2-2301-45 was removed from the system under Work Request D26915 and found to have a worn seating surface which allowed a path for leakage between the valve seat and the plate-type disks. The Check Valve was last replaced in 1989, thus, this valve was in operation for approximately 3 full cycles. This is the only known failure of this valve. The rubber valve seat was worn in some areas as much as .006". It is believed that the worn seat is due to normal wear experienced during HPCI system operability verification surveillances.

The lift-type HPCI Turbine Exhaust Stop Check Valve 2-2301-74 was disassembled and inspected under Work Request D26919. The valve disk was found not attached to the valve guide piston. Further inspection revealed that the four tack welds, which prevent the assembly from rotating and coming apart, had broken due to fatigue. For detailed information concerning the failure of the Stop Check Valve 2-2301-74, see LER/Docket 94-021/0500237.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			TED BURDEN PER NFORMATION COLLE COMMENTS REGA IFORMATION AND F 7714), U.S. NUCLI GTON, DC 20555-0 ION PROJECT MENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. DEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, 0FFICE OF 1, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	>	PAGE (3)
Drosdon Nu	aloon Deven Station Unit 2	05000227	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
bresden Nu	crear power scation, unit 2	05000237	94	022	01	* OF 5

D. SAFETY ANALYSIS:

The safety significance of the leakage past the 2-2301-45 was considered to be minimal since the additional leakage out of containment, on a minimum pathway basis, was 87.6 scfh from the outboard isolation Check Valve 2-2301-45 and would not cause the maximum off-site dose rates established in 10 CFR 100 to be exceeded.

E. CORRECTIVE ACTIONS:

Nuclear Tracking System (NTS) tracking code numbers are identified in the text as (XXX-XXX-XX-XX-XXXX).

The HPCI Turbine Exhaust Check Valve 2-2301-45 was replaced with a dual-disk type check valve made by C & S Valve Company. The as-left LLRT yielded a leakage rate of 1.06 scfh. No inspections were performed on the Dresden Unit 3 Check Valve 3-2301-45 since it was replaced during the 1994 Refuel Outage D3R13.

The long-term corrective action was to replace the valve for both units, after two operating cycles. In addition, the performance of a leak rate test to verify the check valve's integrity was to be undertaken on a six month interval. This first 6 month leak rate test on March 7, 1995 found the leakage past the 2-2301-45 check valve to be 7.54 scfh. The check valve was then tested at the beginning of Refuel Outage D2R14 and its leakage could not be measured by the test equipment (See LER/Docket 95-018/0500237). The first 6 month leak rate test of 3-2301-45 was performed on May 29, 1995 and the leakage rate could not be measured by the test equipment (See LER/Docket 95-011/0500249). Evaluation of short term and long term corrective actions is ongoing and these results will be reported in LER/Docket 95-018/05500237 and 95-011/0500249. (NTS $\sharp 237-180-94-022005101$)

The HPCI Turbine Exhaust Stop Check Valve 2-2301-74 internals were cleaned and the seat was lapped. A new valve disk and guide piston assembly was installed. Since the HPCI Turbine exhaust piping is flanged between the Stop Check Valve and the Suppression Pool, a blank flange was installed and an as-left LLRT was performed in the proper accident configuration which yielded a leakage rate of 1.21 scfh. In response to the problem found on Unit 2, the Dresden Unit 3 Stop Check Valve 3-2301-74 was disassembled, inspected and reassembled with no problems found. The as-left LLRT yielded a leakage rate of 14.39 scfh.

The HPCI Turbine Exhaust Check Valve has been in the Dresden Station Check Valve Program since its inception, however, the Stop Check Valve was recently added and had not yet been initially inspected.

F. PREVIOUS OCCURRENCES:

LER/Docket Numbers	Title
91-007/0500249	Type B and C Containment Local Leak Rate Testing Limit Exceeded Due to HPCI Turbine Exhaust Check Valve Leakage
89-009/0500249	Local Leak Rate Testing "As Found" limit Exceeded Due to leakage From Primary Containment Valves

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			TED BURDEN PER NFORMATION COLLE COMMENTS REGA FORMATION AND F 7714), U.S. NUCLI STON, DC 20555-0 ION PROJECT IENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY JEST: 50.0 JEN ESTIMATE NAGEMENT BR TORY COMMISS O THE PAPER), OFFICE 1, DC 20503.	WITH HRS. E TO ANCH SION, WORK OF	
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)		PAGE (3	\mathbf{b}	
Drogdon Nu	aloan Boyon Station Unit 2	05000337	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	E OF	F	
Dresden Nuclear Power Station, Unit 2		05000237	94	022	01		5	

G. COMPONENT FAILURE DATA:

<u>Manufacturer</u>	Nomenclature	<u>Model Number</u> <u>Number</u>	<u>Mfg. Part</u>
Mission Valve	HPCI Turbine Exhaust to Suppression Pool Check Valve 2-2301-45	15SMF-402B	N/A

An industry - wide data base search revealed sixteen failures for the Mission Model 15SMF dual-disk check valve. Seven failures were attributed to wear of seats and valve internals.

Rockwell Int.	HPCI Turbine Exhaust	6504Y	N/A
	to Suppression Pool		•
	Stop Check Valve		
	2-2301-74		

An industry - wide data base search revealed no failures for the Rockwell International Model 6504Y lift-type stop check valve.