NRC FORM	4 366	<u></u>				U.S.	NUCLE	AR I	EGULATO	RY COM	MISSION			APPROVED B	Y OMB NO. IRES 5/31,	31! /95	50-01	04
		LIC	EN	SEE	: E	VENT REP	ORT	(L	ER)			ESTIM THIS FORWAI THE I (MNBB WASHII REDUC MANAG	AT IN RD NI NG TI EM	ED BURDEN PE NFORMATION CO COMMENTS RE FORMATION AND 714), U.S. NU TTON, DC 20555 ON PROJECT IENT AND BUDGE	R RESPON LLECTION GARDING RECORDS CLEAR REG 5-0001, AU (3150-0 T, WASHIN	SE REG BUR ULA ULA 104 GTO	TO IUEST DEN NAGE TORY TO TH ), N, DO	COMPLY WITH 50.0 HRS. ESTIMATE TO MENT BRANCH COMMISSION, E PAPERWORK OFFICE OF 20503.
FACILITY	Dres	(1) den N	uc:	lear	c P	ower Stati	.on,	Uni	t 3			DOCKE	r	NUMBER (2) 05000249			1	PAGE (3) OF 14
TITLE (4	<b>)</b> Туре	B an	d	C Le	ak	age Limit	Exce	ede	d Due	to 1	/alve	3-130	1	-3 Not Fu	lly Clo	se	d	
EVEN	T DATE	(5)				LER NUMBER (6)	)		REPO	RT DAT	E (7)			OTHER FACIL	ITIES IN	OL V	ED (	8)
MONTH	DAY	YEAR	Y	EAR		SEQUENTIAL NUMBER	REVIS NUMB	ION ER	MONTH	DAY	YEAR	FACILI None	T١	YNAME		DO	CKET	NUMBER
03	12	94		94		009	01		07	24	95	FACILI	T	YNAME		DO	CKET	NUMBER
OPERAT	TING		TI	HIS R	EPOF	T IS SUBMITTE	D PURS	UANT	TO THE	REQUI	REMENTS	OF 10 0	:FI	R§: (Check	one or mo	re)	(11)	
NODE	(9)	N		20.	2201	(b)			20.2203	(a)(3)	)(i)			50.73(a)(2)(	iii)		73.7	71(b)
001	<b></b>		╣	20.	2203	S(a)(1)			20,2203	(a)(3)	)(ii)		1	50.73(a)(2)(	(2)(iv) 73.71(c)			(1(c)
LEVEL	LK (10)	000		20	2203	(a)(2)(i)		$\vdash$	20,2203	(a)(4)	)		┥	50.73(a)(2)(	-73(a)(2)(v)			8
		L	╣╌	20	2207	(a)(2)(ii)		<del> </del>	50.360	0(1)			┥	50.73(A)(2)(	<u>(ii)</u>	(S	Decif	v in
			╟─	20	2207	(a)(2)(iji)		<del> </del> —	50.36(	2(2)			┥	50.73(a)(2)(	(iii)(A)	Ab	strac	t below
			⊩	20	2207	(a)(2)(iv)		1 x	50.73(	1(2)(	i)		+	50.73(a)(2)(	viii)(R)	an	d in	Text,
			⊩	20	2207	(a)(2)(v)		Ê	50 73(8	3(2)(3	·//		1	50.73(a)(2)()	0	NK	C FOF	
				1.0.										50.75(0/(2/(				
NAME							LICENS	<u>c</u> (	UNTACT	TUK IH	15 LEK	(12)	٦	TELEPHONE NUR	BER (Inc	lude	е Аге	a Code)
	м. м	cGive	rn	, Lo	oca	l Leak Rat	e Te	st	Coordi	inato	r Ext	2520	5	(81	5) 942-	-29	20	
				COP	PLE	TE ONE LINE FO	REACH	CO	PONENT	FAILUR	E DESCR	IBED IN	T	HIS REPORT (1	3)			
CAUSE	SYST	ем с	OMP	ONENT		MANUFACTURER	REPOR TO N		.E 5		CAUSE	SYSTE	4	COMPONENT	MANUFAC	TUR	ER	REPORTABLE TO NPRDS
x	во		I	sv		C665	Y	89			x	во		ISV	мзя	58		Yes
x	SJ		I	sv		C665	· Y	88			x	BR		ISV	C66	55		Yes
			SUP	PLEN	ENTA	L REPORT EXPE	CTED (	4)					Ð	<b>CPECTED</b>	MONTH	T	DAY	YEAR
YES (If y	/es, co	mplete	EXP	ECTED	ວ ຣບ	BMISSION DATE)	).		X I	10		S I		BMISSION TE (15)				

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

At approximately 1800, on March 12, 1994, with Unit 3 in Refuel Outage D3R13, the performance of Dresden Technical Surveillance, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the Isolation Condenser System Condensate Return Throttling Valve 3-1301-3 to be leaking an undetermined amount. This value when added to the existing maximum pathway leakage rate resulted in the maximum pathway leakage rate limit for Type B and C primary containment leakage being exceeded. Trouble-shooting determined that the Motor Operated Valve had not closed completely when stroked for draining the system. After the valve was closed using primary containment isolation logic another LLRT was performed and leakage was determined to be 5.3 scfh. The safety significance of not fully closing the 3-1301-3 valve for the LLRT is considered minimal since when the valve was fully closed with primary containment isolation logic an acceptable LLRT was obtained. This supplement contains the root cause, corrective actions taken and results of an NPRDS search for all test volumes that exceeded administrative local leakage limits during Refuel Outage D3R13.

9507270184 950724 PDR ADDCK 05000249 S PDR

NRC FORM	3668		U.S.	NUCLEAR REGU	LATORY C	OMMISSION		APPROVED BY	OHB NO. 3150-0	0104
(5-92)	L	ICENSEE FAILUR	E <b>VENT REP</b> E CONTINU	ORT (LER UATION	)		ESTIMATE THIS INF FORWARD THE INFC (MNBB 77 WASHINGT REDUCTIO MANAGEME	EXPI D BURDEN PE ORMATION CON COMMENTS RE DRMATION AND 14), U.S. NU CN, DC 20555 N PROJECT N AND BUDGET	IRES 5/31/95 R RESPONSE TO LECTION REQUES GARDING BURDEN RECORDS MANAG CLEAR REGULATOR -0001, AND TO (3150-0104), L WASHINGTON,	COMPLY WITH IT: 50.0 HRS. ESTIMATE TO EMENT BRANCH Y COMMISSION, THE PAPERWORK OFFICE OF DC 20503.
		FACILITY N	NGE (1)		DOCKET	I NUMBER		LER MUMBER	(6)	PAGE (3)
Dre	sden Nu	clear Powe	r Station,	Unit 3	0500	00249	YEAR 94	NUMBER	01	2 OF 14
<u> </u>		COMPL	ETE ONE LINE F	OR EACH COMPON	ENT FAIL	URE DESCR	IBED IN TH	IS REPORT (1	3)	<u>L</u>
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
x	BO	ISV	A585	Yes						
х	WK	ISV	C665	Yes		. <u>.</u>				
x	BJ	ISV	M358	Yes		,,				
X	IP	ISV	R340	Yes						
x	BB	ISV	H037	Yes					·	
x	IK	ISV	F052	Yes						
x	КС	ISV	C665	Yes						
		·								
		· 								
										··
										<u></u>
	. <u></u>			·						
										r

.

÷

.

.

۲

NRC FORM 3668 (5-92)

NRC FORM 366A (5-92)	RC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION 5-92)			APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (L) TEXT CONTINUATION	ER)	ESTIMA THIS I FORWARI THE IN (MNBB WASHING REDUCTI MANAGE	TED BURDEN PER NFORMATION COLLE COMMENTS REGAU FORMATION AND F 7714), U.S. NUCLI GTON, DC 20555-0 ION PROJECT ( MENT AND BUDGET,	RESPONSE ECTION REQU REDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. IEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, 0FFICE OF 1, DC 20503.		
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	>	PAGE (3)		
Durandan Nu		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 07 14		
Dresden Nu	clear Power Station, Unit 3	05000249	94	009	01	3 OF 14		

PLANT AND SYSTEM IDENTIFICATION:

General Electric-Boiling Water Reactor-2527 MWt rated core thermal power.

Nuclear Tracking System (NTS) tracking code numbers are identified in the text as (XXX-XXX-XX-XX-XXXXX).

EVENT IDENTIFICATION:

Type B and C Leakage Limit Exceeded Due to Valve 3-1301-3 Not Fully Closed

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit:	3		Event Date:	03/12/94	Event	Time:	1800	hrs
Reactor	Mode:	N	Mode Name:	Refuel	Power	Level:	0%	
Reactor	Coolan	t System 1	Pressure: 0	psig				

- B. DESCRIPTION OF EVENT:
  - At approximately 1800, on March 12, 1994, with Unit 3 in Refuel Outage D3R13, the performance of Dresden Technical Surveillance (DTS) 1600-01, Local Leak Rate Testing Of Primary Containment Isolation Valves, identified the Isolation Condenser System [BL] Condensate Return Throttling Valve 3-1301-3 to be leaking an undetermined amount. This value when added to the existing maximum pathway leakage rate resulted in the maximum pathway leakage rate limit for Type B and C primary containment leakage, 488.452 scfh (0.6L), as listed in Technical Specification 3.7.A.2.b.(2)(a) being exceeded. The Shift Control Room Engineer (SCRE) was notified of the event.

In order to quantify minimum pathway leakage (leakage through the 3-1301-4), the throttling valve's motor was disengaged and the valve was closed manually. Approximately 8 turns with the handwheel were needed in order to shut the valve. Leakage promptly dropped to 18.81 scfh.

Due to the configuration of the system piping, the 3-1301-3 throttling valve had been opened to facilitate draining of the system prior to performing the Local Leak Rate Test (LLRT). The 3-1301-3 was then closed from the Control Room by its control switch (normal means).

To determine why the valve did not fully close, a Motor Operated Valve (MOV) diagnostic test was performed in order to verify that the torque switch setting had not changed since April 1993 when the valve had been last tested. Thrust values were essentially the same. Upon completion of the diagnostic testing, the valve was closed using the Primary Containment Group V [JM] logic circuitry. The valve was then given another LLRT which resulted in the volume leaking 5.3 scfh.

A Problem Identification Form (PIF) was initiated per Dresden Administrative Procedure (DAP) 02-27, Integrated Reporting Process.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	GULATORY COMMISSION		APPROVED BY O EXPIRE	MB NO. 315 S 5/31/95	0-0104
-	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	2R)	ESTIMAT THIS I FORWARD THE IN (MNBB WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLLE COMMENTS REGAL FORMATION AND F 7714), U.S. NUCLI GTON, DC 20555-0 ION PROJECT ( MENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WIT JEST: 50.0 HRS EN ESTIMATE 1 NAGEMENT BRANG ORY COMMISSION O THE PAPERWOR O THE PAPERWOR O FFICE C , DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	)	PAGE (3)
Duesden Nu	-leen Deven Chaties Unit 2	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OR 14
Dresden Nuc	clear Power Station, Unit's	05000249	94	009	01	4 OF 14

The total as-found minimum pathway leakage (Type A test) for D3R13 was 1.2233 wt%/day which exceeded the Technical Specification limit of 1.2 wt%/day. Calculations have been performed to validate that this leakage did not exceed 10 CFR 100 limits.

A list of additional valves which failed the administrative leakage limit during the outage is provided below. The test volumes which required repairs or adjustments and the as-found maximum pathway and minimum pathway leakage rates are included in the table. The minimum pathway leakage rate reflects the actual leakage which would occur under design basis accident conditions.

VOLUME	<u>System</u>	(Maximum Pathway) <u>LEAKAGE RATE</u>	(Minimum Pathway) <u>LEAKAGE RATE</u>
3-205-24 & Flange	Head Cooling	35.3 scfh	29.40 scfh
3-205-27 & Flange	Head Cooling	.35.3 scfh	29.40 scfh
3-220-1 & 2	Main Steam	Undetermined	0.10 scfh
	Lines Drain		
3-220-57A & 58A	Feedwater	Undetermined	2.00 scfh
3-220-57B & 58B	Feedwater	Undetermined	18.50 scfh
3-1101-1 & 15	SBLC	21.56 scfh	10.21 scfh
3-1101-1 & 16	SBLC	21.56 scfh	10.21 scfh
3-1501-25A & 26A	LPCI	81.47 scfh	2.90 scfh
3-2001-5 & 6	DW Equip.	Undetermined	0.10 scfh
	Drain Sumps		
3-2301-45 & 74	HPCI -	Undetermined	84.00 scfh
3-2499-28B & 29B	CAM	211 scfh	0.10 scfh
3-2599-2A & 23A	ACAD	Undetermined	1.40 scfh
3-2599-2B & 23B	ACAD	18.30 scfh	0.80 scfh
3-9208A	DW Air Sample	Undetermined	17.40 scfh
3-9208в	DW Air Sample	Undetermined	17.40 scfh
3-4327-502	Demin Water	102.12 scfh	102.12 scfh
Elec Pen X-202F	Thermocouples	15.64 scfh	7.82 scfh
Bellows X-111A	Shutdown	1.42 scfh	0.71 scfh
	Cooling	<b>-</b> · · <b>-</b> · · · · · ·	
Bellows X-138	SBLC	0.90 scfh	0.45 scfh
Bellows X-149B	LPCI	5.70 scfh	2.85 scfh

## c. CAUSE OF EVENT:

This report is being submitted in accordance with 10 CFR 50.73(a)(2)(i) which requires the reporting of any operation or condition prohibited by the Technical Specifications.

The closing logic for throttling valve 3-1301-3 is designed such that the control switch could be released (spring return to normal) any time during valve travel, prior to reaching closed torque switch trip, and the valve would stop in the open position. The Operator also has the option of using a Pull-to-Lock feature of the control switch which would maintain the control switch closed signal and the valve would stop on achieving closed torque switch trip. Also, a Primary Containment Group V isolation signal would provide a close signal, regardless of control switch position, and the valve would stop on achieving

NRC FORM 366A (5-92)	U.S. WUCLE/	APPROVED BY CHE NO. 3150-0104 Expires 5/31/95				
	LICENSEE EVENT REPORT TEXT CONTINUATION	(LER)	ESTIMA THIS I FORWARI THE IN (MNBB WASHIN REDUCT MANAGE	TED BURDEN PER INFORMATION COLI D COMMENTS REG NFORMATION AND 7714), U.S. NUCI IGTON, DC 20555- ION PROJECT MENT AND BUDGET	RESPONSE ECTION REQU ARDING BURD RECORDS MA EAR REGULAT 0001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH UEST: 50.0 HRS. DEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, O THE PAPERWORK O, OFFICE OF N, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
D		05000040	YEAR	SEQUENTIAL	REVISION	5 07 14
Dresden Nud	clear power Station, Unit 3	05000249	94	009	01	5 UF 14

closed torque switch trip. See attached Figure 1, MOV 3-1301-3 Simplified Schematic.

The logic for MOV 3-1301-3 includes an interlock (MO/NC) between the open and close contactors that prevents energizing the close contactor (MC) if the open contactor (MO) is energized. When a close signal is received from either the control switch or the Group V isolation logic and the valve is in the full open position (LS/O) or the intermediate open position (LS/IO), the throttling valve will start to go closed, as the close contactor (MC) is energized. Upon energization of the closing contactor (MC), auxiliary contact (MC/NO) will close bringing the close torque switch into the circuit. The close torque switch contacts (CTS) are normally closed and open upon the close torque switch setting being reached (valve full closure).

The Operator's normal action to full close this valve is to move the control switch to the CLOSE position (closing contact CS/CLOSE) and to hold it there until 5 seconds after full close indication is received. The Operator can stop the valve anywhere in its closing cycle by releasing the control switch and allowing it to spring return to the AUTO position (opening contact CS/CLOSE). The valve can be given a close signal again through either the control switch or the Group V isolation logic and the valve would close as long as the valve was in the intermediate position (limit switch contact LS/IO is closed).

The closing logic is designed with close contactor auxiliary contact (MC/NO) in series with the close torque switch (CTS) since this valve has non-locking actuator gears. Once the actuator stops, the gear engagement relaxes slightly, allowing relaxation of the spring pack, thus resulting in reclosure of the close torque switch contact (CTS). The close contactor auxiliary contact (MC/NO) prevents anti-hammering of the valve by opening on initial deenergization of the close contactor (MC) and eliminating circuit continuity through the close torque switch (CTS) despite its reclosure.

As with any MOV, when the close signal is removed, the valve momentarily continues to move in the close direction due to close contactor drop out time and MOV inertia. For this valve, this creates a condition in which the control switch could be released while the valve is in the intermediate position (LS/IO closed) and the valve could coast into the closed indication region (LS/IO open) but not be fully seated (achieve close torque switch trip). In order to fully seat the valve, the valve would first have to be opened to at least the intermediate position and then reclosed. This condition has been recognized and is explained to the Operators in step F.9 of Dresden Operating Surveillance DOS 1300-3, Manual Operation of the Isolation Condenser:

<u>IF</u> MO 2(3)-1301-3, RX INLET ISOL valve is determined to be <u>NOT</u> full closed, <u>AND</u> only the CLOSE indication is lit, <u>THEN</u> the valve must be reopened to obtain a dual <u>OR</u> OPEN indication before an attempt to close the valve can be made.

NRC FORM 366A	U.S. NUCLEAR RE	GULATORY COMMISSION		APPROVED BY O EXPIRE	MB NO. 315 S 5/31/95	0-0104
	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	R)	ESTIMAT THIS I FORWARD THE IN (MNBB WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLLE COMMENTS REGAU FORMATION AND F 7714), U.S. NUCLE STON, DC 20555-0 ION PROJECT ( MENT AND BUDGET,	RESPONSE ECTION REQU RDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. JEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, O THE PAPERWORK O, OFFICE OF J, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	)	PAGE (3)
		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6 07 14
Dresden Nu	clear Power Station, Unit 3	05000249	94	009	01	6 OF 14

The Operators are also instructed to hold the control switch in the closed position beyond full close indication to ensure valve full closure in DOS 1300-3, step F.8:

When closing the MO 2(3)-1301-3, RX INLET ISOL value the control switch should be held in the CLOSE position for a minimum of five (5) seconds to ensure full closure.

MOV 3-1301-3 is a 14 inch gate valve that is set for a total stroke of approximately 1-3/4 inches. The stroke time of the valve is about six seconds. The LLRT volume for the Isolation Condenser condensate return line includes the outboard isolation MOV, 3-1301-3, and the inboard isolation MOV, 3-1301-4. The 3-1301-4 is located at an elevation lower than the 3-1301-3, and a drain valve is located adjacent to the 3-1301-4 to support volume draining. In order to perform the LLRT the 3-1301-3 was cycled several times to support draining of the system. The Operator was instructed to close the 3-1301-3 valve for the LLRT and he proceeded to hold the control switch in the closed position and continued that for at least 5 seconds after receipt of full closed indication. The exact root cause for this event is unknown but it is speculated that the control switch was engaged for valve closure but then was unknowingly relaxed prior to reaching full closure (torque switch trip), but the valve travelled far enough to achieve closed indication. Due to the control logic for the valve, as previously explained, the Operator's action of continuing to hold the control switch would not continue to close the valve. This appears to be the cause as the MOV diagnostic test did not indicate any differences from the previous test (April, 1993) and when the valve was closed with the primary containment isolation logic a successful LLRT was obtained.

A summary describing the cause and corrective actions for the remaining volumes which leaked in excess of Station administrative leakage limits during Refuel Outage D2R13 are contained in Section E of this report.

## D. SAFETY ANALYSIS:

The safety significance of not fully closing the 3-1301-3 valve for the LLRT is considered minimal since when the valve was fully closed with primary containment isolation logic an acceptable LLRT was obtained.

The calculated as-found leakage rate for Refuel Outage D3R13 of 1.2233 wt%/day exceeds the Technical Specification limit of 1.2 wt%/day. Calculations which were performed and reported in LER/Docket 90-018-1/0500237, Leakage Path Discovered During Primary Containment ILRT due to Management Deficiency, dated August 6, 1991, indicate that a leakage rate of approximately 31 wt%/day would not exceed the off-site and Control Room dose rates specified by the limits of 10 CFR 100 and General Design Criteria 19 with Standby Gas Treatment System operable. The safety significance is mitigated by the integrity of the Secondary Containment and the function of the Standby Gas Treatment System, which is used to maintain a slight negative pressure in the Reactor Building during accident conditions. Filters are provided in the system to remove radioactive particles and charcoal absorbers are provided to remove radioactive halogens which may be present in concentrations significant to environmental dose criteria. The Refuel Outage D3R13 as-found leakage rate of 1.2233 wt%/day is approximately 3.9% of the 31 wt%/day previously analyzed condition.

. . .

1.1

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95				
<b>Licensee ev</b> Text Co	ENT REPORT (LE ONTINUATION	(R)	ESTIMATED BURDEN PER RESPONSE TO COMPLY W THIS INFORMATION COLLECTION REQUEST: 50.0 H FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRA (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSI WASHINGTON, DC 20555-0001, AND TO THE PAPERW REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
FACILITY NAME (	1)	DOCKET NUMBER (2)	LER NUMBER (6)		)	PAGE (3)			
Decider Nuclear Deven Cha		05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Diesden Muciear Power Sta	cion, onit 3	05000249	94	009	01	/ UF 14			

Therefore, the safety significance of this as-found minimum pathway leakage is considered minimal.

Ε. CORRECTIVE ACTIONS:

> Nuclear Tracking System (NTS) tracking code numbers are identified in the text as (XXX-XXX-XX-XXXXX).

During a feedwater transient in 1987, the reactor operators observed that small changes in 3-1301-3 valve position were difficult to perform due to the rapid speed of valve movement. A modification request form was submitted to consider providing a slower speed gearing ratio for the 3-1301-3 valve in order to facilitate fine adjustment of 3-1301-3 valve position. This has been accomplished through installation of modification M12-3-92-001 which increased the gear ratio for the 3-1301-3 valve to support commitments to NRC Generic Letter 89-10. In addition, the closing limit switches have been repositioned closer to valve seat contact. These changes have improved the thrust capability and valve controllability.

This LER was incorporated into the required reading list for Reactor Operators. (NTS 249-180-94-00901)

A search of similar valve operation problems will be performed to determine if additional Operator training is needed. (NTS 249-180-94-00900S01)

A summary of the root cause, repairs, adjustments, and as-left leak rate testing results for volumes which exceeded Station administrative leakage limits are listed below:

- 3-205-24 Reactor Head Cooling Inlet Valve 3-205-24, a Crane gate valve, was cut out under Work Request D01831 and an Anchor Darling dual disk gate valve was installed. The cause of the leakage was determined to be an inadequate application of the valve resulting in changing to the dual disk gate valve. An as-left LLRT was performed which yielded a leakage rate of 3.70 scfh. LLRT records dating back to 1980 indicates 5 previous failures of this valve of which only one failure resulted (January, 1990) in the performance of maintenance to the valve.
- 3-205-27 Reactor Head Cooling Inlet Check Valve 3-205-27 was disassembled and inspected under Work Request D07178. Cause of the excessive leakage was determined to be corrosion deposits on the valve seat. The valve was replaced due to poor leak rate performance. An as-left LLRT was performed which yielded a leakage rate of 15.74 scfh. LLRT records dating back to 1980 indicate 1 previous failure of this valve. Valve replacement is considered adequate corrective action based on the historical leakage data.
- 3-220-1 During power operation, the motor for Main Steam Line Drain To Condenser Valve MOV 3-220-2 had developed a ground and could not be 3-220-2 operated. Since the 3-220-2 is at the test volume's low point, the valve had to be manually opened to drain possible water from the main steam line drain piping. The valve was then closed manually.

NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY CHE NO. 3150-0104 EXPIRES 5/31/95					
·	LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE T THE INFORMATION AND RECORDS MANAGEMENT BRANC (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), OFFICE 0 MANAGEMENT AND RUDCET WASHINGTON DC 20503				
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	>	PAGE (3)	
<b>D</b>		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	0 07 14	
Dresden Nu	clear power station, Unit 3	05000249	94	009	01	5 OF 14	

The leakage rate was conservatively assigned as undetermined since the valve was not closed by normal means prior to testing even though the test yielded no leakage. The cause of the leakage was determined to be an inadequate application of the valve. Main Steam Line Drain To Condenser Valves 3-220-1 and 3-220-2, Crane gate valves, were cut out and Anchor Darling dual disk gate valves were installed under Work Requests D17980 and D19887, respectively. LLRT records dating back to 1980 indicate 2 previous failures (December, 1989 and September, 1991) for 3-220-1 and 3 previous failures (last failure in September, 1991) for 3-220-2. An as-left LLRT was performed which yielded a leakage rate of 4.81 scfh. There have been LLRT failures of the Anchor Darling dual disk gate valves subsequent to Refuel Outage D3R13. See LER/Docket 95-007/0500249.

- Feedwater Inboard Check Valve 3-220-58A was disassembled and 3-220-58A inspected under Work Request D20566. A seat/disk assembly to valve body hold down bolt was discovered to be loose. Valve leakage was determined to be caused by this loose bolt allowing the seat/disk assembly to distort. This loose hold down bolt allowed the seat/disk assembly to distort, therefore, the disk could not fully close leaving a gap for leakage. As part of the materiel condition improvement initiative, the valve internals were modified to eliminate this problem of leakage between the seat/disk assembly and the valve body. This modification included grinding out part of the valve body for the introduction of a bolting ring, the use of a flexatallic gasket and a seat/disk assembly with more hold down bolts. An as-left LLRT was performed which yielded a leakage rate of 34.10 scfh. LLRT records dating back to 1980 indicate 6 previous failures of this valve.
- 3-220-58B Feedwater Inboard Check Valve 3-220-58B was disassembled and inspected under Work Request D20425. Reddish debris was found on the seat. Valve internals showed indication of leakage between the valve body and the seat/disk assembly. The "O" ring between the seat/disk assembly and the valve body was in poor condition. Inadequate valve design was determined to be the cause of the degradation of the "O" ring which allowed leakage between the valve body and the seat/disk assembly. As part of the materiel condition improvement initiative, the valve internals were modified to eliminate the leakage between the seat/disk assembly and the valve This modification included grinding out part of the valve body. body for the introduction of a bolting ring, the use of a flexatallic gasket and a seat/disk assembly with more hold down bolts. An as-left LLRT was performed which yielded a leakage rate of 12.07 scfh. LLRT records dating back to 1980 indicate 2 previous failures of this valve.
- 3-1101-15 SBLC Inboard Isolation Check Valve 3-1101-15 was disassembled and 3-1101-16 inspected under Work Request D20152. The inspection revealed reddish debris on the seat which caused it not to seat properly. The seat was cleaned and lapped while the plug was cleaned and skim cut. The as-left LLRT yielded a leakage rate of 0.60 scfh.

NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY ONB NO. 3150-0104 Expires 5/31/95				
	LICENSEE EVENT REPORT (L) TEXT CONTINUATION	ER)	ESTIMAT THIS I FORWARD THE IN (MNBB T WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLLE D COMMENTS REGAR FORMATION AND R 7714), U.S. NUCLE GTON, DC 20555-00 ION PROJECT ( MENT AND BUDGET,	RESPONSE CTION REQU DING BURD ECORDS MAN AR REGULAT 001, AND TO 3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO JAGEMENT BRANCH ORY COMMISSION, D THE PAPERWORK , OFFICE OF , DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Dana dan Nu		05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	0.07.14
Dresden Nu	clear power station, unit 3	05000249	94	009	01	9 01 14

SBLC Outboard Isolation Check Valve 3-1101-16 was disassembled and inspected under Work Request D20099. The inspection revealed a slight raise in the seating material of the piston. Reddish debris on the seat caused it to not seat properly. The seat and plug were cleaned. An as-left LLRT was performed which yielded a leakage rate of 0.10 scfh.

LLRT records dating back to 1980 indicate 2 previous failures (Fall of 1983 and September, 1992) for 3-1101-15 and 2 previous failures (last failure in Spring of 1988) for 3-1101-16. Corrective actions of cleaning and refurbishing are considered adequate corrective actions for both failures because of the low failure history.

- 3-1501-25A LPCI Inboard Isolation Check Valve 3-1501-25A was disassembled and inspected under Work Request D24990. The inspection revealed slight corrosion and a nick on the seating surfaces. The seating surfaces were cleaned and lapped. An as-left LLRT was performed which yielded a leakage rate of 3.10 scfh. LLRT records dating back to 1980 indicate no previous failures of this valve.
- 3-2001-5 Drywell Equipment Drain Sump Valves 3-2001-5 and 3-2001-6, Crane 3-2001-6 gate valves, were cut out under Work Request D16245 and ITT Grinell diaphragm valves were installed. These gate valves are susceptible to damage caused by the pumping of dirt and grit that accumulates in the sump. The cause of the valve leakage is thus an inadequate application of the valve. To correct this, diaphragm valves, which are less susceptible to damage, were installed. An as-left LLRT was performed which yielded a leakage rate of 0.10 scfh. LLRT records dating back to 1980 indicate 1 previous failure (October, 1991) of each valve.
- 3-2301-45 HPCI Turbine Exhaust Check Valve 3-2301-45, a Marlin duo-check valve, was removed from the system and inspected under Work Request D20134. The rubber seat was found to be worn and is attributed to erosion during low flow conditions. Corrective actions include installation of a C & S dual disk check valve with a lighter spring. This change will allow the valve to open fully against low steam flow. A revision to Operations Department procedures, which includes minimizing operating time within this low flow condition, has been completed. An as-left LLRT was performed which yielded a leakage rate of 0.10 scfh. LLRT records dating back to 1980 indicate 3 previous failures of this valve. Dresden station has experienced an additional LLRT failure of the 3-2301-45 valve after the completion of the D3R13 Refuel Outage. See LER/Docket 95-011/0500249.
- 3-2499-28B  $H_2/O_2$  Analyzer Discharge Check Valve 3-2499-28B was disassembled and inspected under Work Request D24571. The inspection revealed moisture in the valve, light grayish corrosion and a small piece of debris on the piston seat. These conditions result from the moist drywell atmosphere condensing in the cooler  $H_2/O_2$  Analyzer return piping. The cause of the valve failure is an inadequate application of the valve. The lift-type check valve was cut out and replaced

NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY ONE NO. 3150-0104 Expires 5/31/95					
-	LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE T THE INFORMATION AND RECORDS MANAGEMENT BRANC (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), DFICE ( MANAGEMENT AND REDUCT (3150-0104), DFICE (				
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
Durandan Nat		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	10 07 14	
Dresden Nu	clear Power Station, Unit 3	05000249	94	009	01	10 OF 14	

with an Anchor Darling swing-type check valve which is less susceptible to corrosion and fouling of seating surfaces. An as-left LLRT was performed which yielded a leakage rate of 5.90 scfh. LLRT records dating back to 1980 indicate 2 previous failures (January, 1992 and February, 1994) of this valve.

- 3-2599-23A ACAD Inlet To Drywell Check Valve 3-2599-23A, a Hancock lift-type check valve, was disassembled and inspected under Work Request D24403. The inspection revealed that the piston was corroded to the disc guide. The cause of the valve failure is an inadequate application of the valve. The lift-type check valve was cut out and replaced with an Anchor Darling swing-type check valve which is less susceptible to corrosion and fouling of seating surfaces. An as-left LLRT was performed which yielded a leakage rate of 1.20 scfh. LLRT records dating back to 1980 indicate one previous failure (September, 1993) of this valve.
- 3-2599-23B ACAD Inlet To Drywell Check Valve 3-2599-23B, a Hancock lift-type check valve, was disassembled and inspected under Work Request D20131. The inspection revealed that the piston was corroded to the disc guide. The cause of this failure is an inadequate application of the valve. The lift-type check valve was cut out and replaced with an Anchor Darling swing-type check valve which is less susceptible to corrosion and fouling of seating surfaces. An as-left LLRT was performed which yielded a leakage rate of 0.10 scfh. LLRT records dating back to 1980 indicate 2 previous failures (Fall of 1985 and Spring of 1988) of this valve.
- 3-9208A Drywell Air Sample Valve 3-9208A was disassembled and inspected under Work Request D24610. An inspection revealed that the valve internals were in good condition resulting in an inability to determine the root cause of the failure of the valve to meet the administrative leakage limit. Work Request D24610 reassembled the valve with no change to the internals since LLRT records dating back to 1980 indicate no previous failure of this valve. An as-left LLRT was performed which yielded a leakage rate of 2.72 scfh. The maintenance inspection activity is considered adequate for corrective action because of the historical ability of the valve to perform satisfactorily.
- 3-9208B Drywell Air Sample Valve 3-9208B was disassembled and inspected under Work Request D24608. Valve leakage was caused by a badly worn valve seating surface due to erosion. The valve internals were replaced. An as-left LLRT was performed which yielded a leakage rate of 0.35 scfh. LLRT records dating back to 1980 indicate no previous failure of this valve.
- 3-4327-502 Clean Demineralized Water Stop Valve 3-4327-502 was cut out and replaced under Work Request D26498. An as-left LLRT was performed which yielded a leakage rate of 0.10 scfh. LLRT records dating back to 1980 indicate no previous failure of this valve. Valve replacement is considered satisfactory corrective action based on failure records.

NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
-	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY W THIS INFORMATION COLLECTION REQUEST: 50.0 H FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRA (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSI WASHINGTON, DC 20555-0001, AND TO THE PAPERW REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND RUDGET WASHINGTON DC 20503		
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
Drogdon Nu	along Devez Station Unit 2	05000240	YEAR	SEQUENTIAL I	REVISION NUMBER	11 07 14	
Diesden Nu	clear Power Station, Unit 3	05000249	94	009	01	11 05 14	

- Elec Pen Electrical Penetration X-202F was disassembled and inspected under X-202F Work Request D20020. Cause of the leakage was a torn pliable inner inboard seal. The tear was repaired and an as-left LLRT yielded a leakage rate of 0.10 scfh.
- Bellows Shutdown Cooling Piping Expansion Bellows X-111A was cut out under X-111A Work Request D08405. As part of the bellows replacement upgrade initiative, this bellow was replaced by a single ply expansion bellow and was welded in place. A Bellows Test Enclosure was then installed. This Bellows Test Enclosure is a removable outer cover which performs as the outboard primary containment boundary. The as-left LLRT yielded a leakage rate of 1.10 scfh.
- Bellows Standby Liquid Control Piping Expansion Bellows X-138 was cut out X-138 under Work Request D08407. As part of the bellows replacement upgrade initiative, this bellow was replaced by a single ply expansion bellow and was welded in place. A Bellows Test Enclosure was then installed. This Bellows Test Enclosure is a removable outer cover which performs as the outboard primary containment boundary. The as-left LLRT yielded a leakage rate of 14.04 scfh.
- Bellows X-149B Core Spray "A" Loop Piping Expansion Bellows X-149B was cut out under Work Request D08408. As part of the bellows replacement upgrade initiative, this bellow was replaced by a single ply expansion bellow and was welded in place. A Bellows Test Enclosure was then installed. This Bellows Test Enclosure is a removable outer cover which performs as the outboard primary containment boundary. The as-left LLRT yielded a leakage rate of 1.00 scfh.

A valve team has been established at Dresden Station in order to increase valve performance. This is to be done through the use of diagnostic testing and preventive maintenance so as to minimize the amount of corrective maintenance needed to be performed. The Valve Team consists of Program Engineers who are tasked with developing and implementing plans for increasing the performance of a specific type of valve; motor-operated valves, air-operated valves, check valves and manual and relief valves. This focused attention will allow Dresden to continue the trend of decreasing as-left maximum pathway leakage experienced over the last 3 refuel outages.

## F. PREVIOUS OCCURRENCES:

LER/Docket Number	Title
91-007/0500249	Type B and C Containment Local Leak Rate Testing Limit Exceeded Due to HPCI Turbine Exhaust Check Valve Leakage.
93-002/0500237	Type B and C Primary Containment Local Leak Rate Testing Limit Exceeded Due to Leakage Past Head Cooling Inlet Isolation Valve 2-205-2-4.

C FORM 366A U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY CHB NO. 3150-0104 EXPIRES 5/31/95			
<b>LICENSEE EVENT REPORT (LER)</b> TEXT CONTINUATION			ESTIMATED BURDEN PER RESPONSE TO COMPLY W THIS INFORMATION COLLECTION REQUEST: 50.0 H FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRA' (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSI WASHINGTON, DC 20555-0001, AND TO THE PAPERW REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND RUDGET WASHINGTON DC 20503.			TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO HAGEMENT BRANCI ORY COMMISSION D THE PAPERWORN O THE PAPERWORN OFFICE OI , DC 20503.	
FACILITY NAME	(1)	DOCKET NUMBER (2)		LER NUMBER (6	>	PAGE (3)	
		05000040	YEAR	SEQUENTIAL	REVISION NUMBER	10 07 14	
presden Mucrear Power St	acion, onit 3	05000249	94	009	01	12 05 14	

G. COMPONENT FAILURE DATA:

MANUFACTURER	NOMENCLATURE	MODEL NUMBER	MFG. PART #
Crane Valve Co.	Reactor Head Cooling Inlet Valve 3-0205-24	787-UL	N/A

An industry-wide data base search revealed 1 failure for the Crane Model 787-UL valve. The failure was caused by steam erosion damage to the seating surface.

Mission Valve Co. Reactor Head Cooling Inlet 90 CPF-403 N/A Check Valve 3-0204-27

An industry-wide data base search revealed 1 failure for the Mission Crane Model 90 CPF-403 check valve. This failure was caused by slippage of the flange bolting which caused the gasket to tear.

Crane Valve Co. "A" Feedwater Line Inboard 973 N/A Check Valve 3-220-58A

> "B" Feedwater Line Inboard Check Valve 3-220-58B

An industry-wide data base search revealed 91 failures for the Crane Model 973 tilting disc check valve. Twenty six failures were attributed to failures of the "O" ring between the valve body and seat ring assembly and thirteen failures were due to normal wear to the tilting disc hinge pin and bushings. Most of the failures were in high temperature, high flow feedwater systems.

Crane	Valve	Co.	Standby	Liquid Control	3888-U	N/A
			Inboard	Injection Check		
			Valve 3-	1101-15		

Standby Liquid Control Outboard Injection Check Valve 3-1101-16

An industry-wide data base search revealed 4 failures for the Crane Model 3888-U lift-type check valve. All four failures were due to general corrosion of seating surfaces not allowing proper seat-plug contact.

Atwood & Morrill LPCI Loop "A" Injection Check 20746-H N/A 3-1501-25A

An industry-wide data base search revealed 3 failures for the Atwood & Morrill Model 20746-H testable swing check valve. One failure was due to seat deformation from the system environmental conditions.

 $\sigma \to 1, 0$ 

NRC FORM 366A (5-92)	U.S. NUCLEAR F	REGULATORY COMMISSION APPROVED BY ONE NO. 3150-01 EXPIRES 5/31/95			0-0104		
-	LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WI THIS INFORMATION COLLECTION REQUEST: 50.0 HR FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRAN (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSIO WASHINGTON, DC 20555-0001, AND TO THE PAPERWO REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.				
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (C	)	PAGE (3)	
			YEAR	SEQUENTIAL	REVISION		
Dresden Nu	clear power Station, Unit 3	05000249	94 009	009	01	13 OF 14	

.

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

	MANUFACTURER	NOMENCLATURE	MODEL NUMBER	MFG. PART #
	Crane Valve Co.	Drywell Equipment Drain Sump Valves 3-2001-5 & 3-2001-6	47-1/2LU	N/A
	An industry-wide gate valves due to grit from drain s	data base search revealed 45 f o wear and poor seat condition ystems.	ailures of Crane M s. Twelve failure	odel 47-1/2LU s were due to
	Mission Mfg. Co.	HPCI Turbine Exhaust To Suppression Chamber Check Valve 3-2301-45	15smF402	N/A
	An industry-wide 15SMF duo check v	data base search revealed 6 fa alves. Three failures were du	ilures of Mission e to worn seating	Mfg. Co. Model surfaces.
	Rockwell Edwards	"B" H <sub>2</sub> /O <sub>2</sub> Analyzer Discharge Check Valve 3-2499-28B	36174JTZ	N/A
	An industry-wide lift-type check v internals not all	data base search revealed 1 fa alve. This failure was also d owing the valve to close.	ilure for the Rock ue to debris trapp	well Edwards ed inside valve
	Hancock Co.	ACAD Inlet To Drywell Check Valve 3-2599-23A	H037	N/A
		ACAD Inlet To Drywell Check Valve 3-2599-23B		
	An industry-wide check valve. Six	data base search revealed 36 f teen failures were due to debr	ailures of the Han is fouling seating	cock lift-type surfaces.
	Fisher	Drywell Air Sample Valve 3-9208A	667ES	N/A
		Drywell Air Sample Valve 3-9208B		
•	An industry-wide ( 667ES globe valve	data base search revealed 16 f due to normal wear.	ailures of the Fis	cher Model
	Crane Valve Co.	Clean Demineralized Water Stop Valve 3-4327-502	143-1/20	N/A

An industry-wide data base search revealed 8 failures of Crane Model 143-1/2U gate valves.

· ••

-

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY CHB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION			TED BURDEN PER NFORMATION COLLE COMMENTS REGAU FORMATION AND R 7714), U.S. NUCLE GTON, DC 20555-0 ION PROJECT ( MENT AND BUDGET,	RESPONSE CTION REQ RDING BURD RECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. JEN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, 0FFICE OF 1, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	•	PAGE (3)
		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	14 07 14
Dresden Nu	clear Power Station, Unit 3	05000249	94	009	01	14 OF 14

.

.

FIGURE 1 MOV 3-1301-3 Simplified Schematic

