Commonwealth Edison (pa Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



1422

December 5, 1995

PGHLTR 95-0035

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 95-021, Docket 50-249, is being submitted pursuant to 10CFR50.73(a)(2)(vii), any operation or condition prohibited by the plant's Technical Specifications.

This report provides clarification to corrective actions for previous events and does not include any new commitments specifically related to LER 95-021.

Sincerely,

Eter D. Holland

Peter G. Holland Regulatory Assurance Supervisor

PGH/BC:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III NRC Resident Inspector's Office

110032

L:\8360\8301\pghltr.95\0035.95



			- .				•						• •			- 1
NRC FOR (5-92)	M 366			U.S	NUCLE/	AR R	REGULATO	RY COP	MISSION			APPROVED B EXP	Y ONE NO. IRES 5/31	315 /95	0-010	6
	•	LIC	ensee	EVENT REPO	ORT (LE	R)		-	ES TH FOI THI (MI WA REI MAI	TIMA IS I RWARD E IN NBB 7 SHING DUCTI NAGEM	TED BURDEN PE NFORMATION CO COMMENTS RE FORMATION AND FORMATION AND STON, DC 20555 ION PROJECT (ENT AND BUDGE	ER RESPON LLECTION GARDING RECORDS CLEAR REG -0001, A (3150-0 T, WASHIN	ISE REQU BURD BURD IND T DID4) IGTON	TO CO JEST: EN ES NAGEME ORY C O THE O, O I, DC	MPLY WIT 50.0 HRS TIMATE TO NT BRANC OMMISSION PAPERWOR FFICE O 20503.
FACILIT	Y NAME Dres	(1) den N	uclear	Power Stati	lon, U	Jni	t 3			DO	CKET	NUMBER (2) 05000249			1	PAGE (3) OF 5
TITLE (4	4) Yarw	ay`Re	actor	Water Level	Switc	h	Failur	e	•							
EVEN	T DATE	(5)		LER NUMBER (6))		REPO	RT DAT	E (7)			OTHER FACIL	ITIES IN	VOL VE	ED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISI NUMBE	ION R	MONTH	DAY	YEAR	FAC No	ne	Y NAME		DOC	KET N	UMBER
11	09	.95	95	021	00		12	05	95	FAC	ILIT	Y NAME		DOC	KET NI	MBER
OPERA	TING		THIS RE	PORT IS SUBMITTE	D PURSU	ANT	TO THE	REQUI	REMENTS	OF 1	IO CF	R§: (Check d	one or mo	re)	(11)	
NODE	(9)	N	20.2	2201(b)			20.2203	(a)(3)(1)			50.73(a)(2)(i	11)		73.71	(b)
POLI	FR		20.2	203(a)(1)			20.2203	(a)(3))(ii)			50.73(a)(2)(iv)	П	73.71	(c)
LEVEL	(10)	089	20.2	203(a)(2)(i)			20.2203	(a)(4))		50.73(a)(2)(v) OTHER					
			20.2	203(a)(2)(ii)	· .		50.36(c)(1)		X 50.73(a)(2)(vii) (Specify in			in			
			20.2	203(a)(2)(iii)	• •		50.36(c)(2)		_		50.73(a)(2)(viii)(A) Abstract b		Delow		
			20.2	203(a)(2)(iv)	•		50.73(a)(2)(i)		50.73(a)(2)(viii)(B) NRC Form 366			366A)		
			20.2	203(a)(2)(v)			50.73(a)(2)(ii)			50.73(a)(2)(x	() /	1		
	_		*****	·····	LICENSE	E C	ONTACT F	OR TH	IS LER	12)						
NAME												TELEPHONE NUM	BER (Inc	lude	Агеа	Code)
	Bob	Carro	11, Si	te Engineeri	ng				Ext.	23	335	(81	5) 942-	-292	20	
			COM	PLETE ONE LINE FO	REACH	CON	PONENT F	AILUR	E DESCR	BED	IN T	HIS REPORT (1	3)			·
CAUSE	SYST	EM C	OMPONENT	MANUFACTURER	REPORT TO NP	RDS	E		CAUSE	SY:	STEM	COMPONENT	MANUFAC	TURE	RR	EPORTABLE
В -	JE		LS	¥005	Ye	S										
														-		-
			SUPPLEME	NTAL REPORT EXPE	CTED (14	\$					E	KPECTED	HONTH	T	DAY	YEAR
YES (If)	yes, co	mplete	EXPECTED	SUBMISSION DATE)		X	0			SUI DA	BMISSION TE (15)				

BSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On November 9, 1995, at 1330 hours, with Unit 3 at 83% rated core thermal power, while performing Dresden Instrument Surveillance (DIS) 0500-03, Reactor Water Level ECCS Initiation Indicating Switch Calibration, level switch 3-263-72B contact 7-8 tripped outside of the Technical Specification (TS) limit. Level Indicating Switch (LIS) 3-263-72B is part of the Core Spray II and Auto Blowdown, -59" Reactor Water Level initiation one-out-of-two twice logic. The TS limit is 159.395" water column (WC), however, the switch was actuated to close at 170.0" WC. The switch was adjusted to an acceptable value of 155.1" WC. The necessary redundant switches were available during the event allowing both the Core spray and Auto Blowdown systems to remain operable. Previous events involving the failure of similar Yarway configurations are documented in the Operability Assessment dated February 17, 1994, (Chron 0124505) that was written in response to LERS 93-031/050237 and 94-007/050249. Input to the Operability Assessment included two years of calibration data for the Yarway instruments. Additionally LER 3-94-002 documents a similar event for the same instrument.

		· · · · · · · · · · · · · · · · ·				
NRC FORM 366A (5-92)	U.S. NUCLEAR R	APPROVED BY CMB NO. 3150-0104 EXPIRES 5/31/95				
	LICENSEE EVENT REPORT (LEI TEXT CONTINUATION	R)	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCT) MANAGEP	TED BURDEN PER NFORMATION COLLI COMMENTS REGA FORMATION AND I 7714), U.S. NUCLI GTON, DC 20555-0 ION PROJECT <u>TENT AND BUDGET.</u>	RESPONSE ECTION REOR RDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) MASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO VAGEMENT BRANCH ORY COMMISSION, 0 THE PAPERWORK 0, OFFICE OF 1, DC 20503.
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	>	PAGE (3)
Deceder No.		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 07 5
Jresden Nu	ciear Power Station, Unit 3	05000249	95	021	00	2 UF 5

EVENT IDENTIFICATION:

Yarway Reactor Water Level Switch Failure

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit: 3	Event Date: 11/09/95	Event	Time:	1330 hrs
Reactor Mode: N	Mode Name: Run	Power	Level:	838
Reactor Coolant System	Pressure: 982 psig			

B. DESCRIPTION OF EVENT:

On November 9, 1995, at 1330 hours, with Unit 3 at 83% rated core thermal power, while performing Dresden Instrument Surveillance (DIS) 0500-03, Reactor Water Level ECCS Initiation Indicating Switch Calibration, level switch 3-263-72B contact 7-8 tripped outside of the Technical Specification (TS) limit. Level Indicating Switch (LIS) 3-263-72B is part of the Core Spray II and Auto Blowdown, -59" Reactor Water Level initiation one-out-of-two twice logic. The TS limit is 159.395" water column (WC), however, the switch was actuated to close at 170.0" WC which correlates to -74.04" Reactor Water Level. The switch was adjusted to an acceptable value of 155.1" WC. The necessary redundant switches were available during the event allowing both the Core Spray and Auto Blowdown systems to remain operable.

C. CAUSE OF EVENT:

This report is being submitted in accordance with 10CFR50.73(a)(2)(vii) which requires the reporting of any event or condition that caused at least one independent train or channel to become inoperable in multiple systems or two independent trains or channels to become inoperable in a single system designed to mitigate the consequences of an accident. It has been determined that this failure is one point of an unfavorable trend history that has developed on these switches. A thorough review of the past two years of Yarway performance has been performed. Unit 3 Yarway contacts have been found at or out of tolerance 15 times out of a possible 220 calibrations. The 15 out of tolerances resulted in 3 Tech Spec violations.

Contacts for the 3-263-72B instrument were found out of tolerance 5 of 14 times during 1993 (36%). For 1994/95 the instrument's contacts have been found out of tolerance 4 out of 22 calibrations (18%). The continued out of tolerance events of Yarway setpoints have received heightened station attention.

The Yarway reactor water level instruments have not been able to maintain setpoints within the Technical Specifications and administrative limits as documented in DIS 0500-3. A root cause analysis was performed which identified the following i) Technical Specifications and procedural limits were more restrictive than instrument capabilities, ii) sub-component failures (Mercoid switch), and iii) excessive drift. Probable causal factors attributed to excessive drift include Mercoid switch aging (spring force degradation), mounting of the Mercoid switch, alignment of switch to actuating magnets, and/or defective jewelled bearings. However, the average "drifts" experienced during the past two years have been within the statistical 2 sigma failure values

NRC FORM 366A (5-92)		U.S. NUCLEAR RE	GULATORY COMMISSION		APPROVED BY EXPIRE	DHB NO. 315 S 5/31/95	0-0104
	LICENSEE EVENT RI TEXT CONTIN	EPORT (LEF IUATION	8)	ESTIMAT THIS IN FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEM	TED BURDEN PER NFORMATION COLL COMMENTS REGA FORMATION AND FORMATION AND T714), U.S. NUCL STON, DC 20555-C ON PROJECT TENT ANC BUDGET,	RESPONSE ECTION REQUER RDING BURD RECORDS MAI EAR REGULAT 0001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK O, OFFICE OF J, DC 20503.
	FACILITY NAME (1)	19 T	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)
Dreader No	alaan Dawan Chatian	The is a	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 5
Dresden Nuclear Power Station, Unit 3		UNIC 3	05000249	95.	021	00	3 UF 5

(+/- 6.42" Reactor Water Level) documented in calculation NED-I-EIC-0100 Revision 2.

Performance of the 3-263-72B switch has been evaluated and is summarized below.

3-263-728 (7-8)	Jan 3, 1995 thru Nov. 9, 1995
Found Out of Tolerance/Calibrations	2/12 or 16.68
Avg. Drift/Calibration (% Span)	1.82%

Instrument 3-263-72B (7-8) performance has improved from 1993 thru November 1995. In 1993, switch 72B (7-8) was found to be out of tolerance during 5 of 14 surveillances (i.e. 36%). Since January 3, 1995, the switch was found within tolerance for the ten consecutive months before the November 9 surveillance which identified another out of tolerance of 10.6" WC with respect to the surveillance procedure tolerance. The presence of the consecutive acceptable "as founds" represent an improvement in instrument operation. This improvement occurred after changing the setpoint to implement a technical specification change. The present calculated out-of-tolerance occurrences yield a 16% out of tolerance occurrence rate for a rolling 12-month period. This represents an improvement over the 36% for the year 1993.

D. SAFETY ANALYSIS:

The safety significance of this event is minimal even though the failure occurred in the non-conservative direction. ECCS is initiated on low low reactor water level by 4 level switches. These switches are arranged in oneout-of-two-twice logic format such that failure of one instrument will not prevent the function of Core Spray and Auto Blowdown. The actuation logic was operable because only one switch was affected.

A review of the safety significance of non-conservative drifts was performed as part of an Operability Assessment dated February 17, 1994, (Chron 0124505). A bounding PRA analysis, assuming one complete logic system failure with a duration of 10 days during the two year period resulted in a change to core damage frequency of only 1%.

E. CORRECTIVE ACTIONS:

Nuclear Tracking System (NTS) tracking code numbers are identified in the text as XXX-XXX-XXX-XXXXXX.

There was no discernible reason for the instrument setpoint drift beyond the 2 sigma range. The immediate corrective action was to recalibrate the switch within its tolerance limits and to return the instrument to service. Also, several long term corrective actions have been previously proposed and are in progress at this time. The following NTS items (partial listing) identify actions which have been taken or are in progress by the station to eliminate the continued performance deficiencies with the Yarway instruments:

NRC FORM 366A (5-92)	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (5-92)			APPROVED BY ONE NO. 3150-0104 EXPIRES 5/31/95			
	LICENSEE EVENT REPORT (LEI TEXT CONTINUATION	۶)	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLLI COMMENTS REGA FORMATION AND (7714), U.S. NUCL STON, DC 20555-0 ION PROJECT TENT AND BUDGET.	RESPONSE ECTION REQU RDING BURD RECORDS MAJ EAR REGULAT 1001, AND TI (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO VAGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK O THE PAPERWORK OFFICE OF DC 20503.	
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	<u> </u>	PAGE (3)	
Dreeden Nu	-lean Deven Chaties Unit 3	05000240	YEAR SEQUENTIAL REVISION NUMBER NUMBER		4.07.5		
Dresden Nuc	crear rower station, Unit 3	05000249	95	021	00	4 01 3	

Proposed "Corrective Actions" have been previously documented in the LERs and Operability Assessment referenced in the abstract and are being tracked by NTS as the following items:

	237-200-91-11901	Yarways are scheduled to be replaced during D2R14 and D3R14. Unit 2 modification is installed and testing is in progress. Unit 3 design is approved and awaiting installation.
	237-180-93-03101	Develop an action plan for the chronic failures of Yarway switches (action plan developed, increased engineering assistance and data tracking in progress.)
	237-180-93-03103	DIS 500-03 has been revised. The tolerances have been expanded and setpoint moved conservatively away from the TS limit.
	249-180-94-00301	An Operability assessment for Yarways has been performed in accordance with QE 40.1 in response to LER 94-003/0500249 corrective action (action completed February 17, 1994, Chron 0124505).
	237-225-94-R12-94018A	DIS 500-03 has been revised to incorporate drift optimization actions.
	237-225-94-R12-94018B	As-found calibration data is being trended per Dresden Yarway Administrative Action Plan (actions on going until replacement).
,	237-225-94-R12-94018C	Obtain setpoint tolerance Technical Specification change approval from NRC (action completed).
	249-225-94-R12-94018D	Implement a setpoint change on Unit 3 Yarways and revise Administrative Action Plan (action completed).
	237-225-94-R12-94018E	Implement setpoint change on Unit 2 Yarways (action completed).
	237-225-94-R12-94019A	A characterization program has been developed for Yarways. Information from this program was used to develop a wider tolerance band. (action completed).
	237-225-94-R12-94019B	A Yarway Administrative Action Plan has been developed with the objective of achieving Yarway contact failure rates of lx10E-5 per operating hour or better (action complete)
	237-225-94-R12-94019I	The Operating Department has been informed of the necessity to maintain a heightened awareness regarding the excessive non-conservative drift and failure history.

; J·

· · · · ·							
NRC FORM 366A (5-92)	U.S. NUCLEAR R	EGULATORY COMMISSION		APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95			
	LICENSEE EVENT REPORT (LE TEXT CONTINUATION	R)	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEN	TED BURDEN PER NFORMATION COLL COMMENTS REGA FORMATION AND FORMATION AND TON, DC 20555-C ION PROJECT TENT AND BUDGET,	RESPONSE ECTION REGU RDING BURD RECORDS MAI EAR REGULAT 0001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH ORY COMMISSION, 0 THE PAPERWORK 0, 0FFICE OF 1, DC 20503.	
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	>	PAGE (3)	
Duesden Nu	aloan Deven Station Unit 2	05000249	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5	
Dresden Nu	crear rower Station, Unit 3	05000249	95	021	00	5015	

F. PREVIOUS OCCURRENCES:

5]

Numerous occurrences of similar events have been documented. A detailed calibration history is contained in the Operability Assessment dated February 17, 1994, which provides a chronology of all calibrations during the past two years with as-found and as-left setpoints. Reportable Occurrences since 1993 are as follows:

UNIT	2/0500237	LER 2-93-019 LER 2-94-008 LER 2-94-016	LER 2-93-031 LER 2-94-015
UNIT	3/0500249	LER 3-93-001 LER 3-94-002	LER 3-93-018 LER 3-94-007

G. COMPONENT FAILURE DATA:

L:\8360\8301\249\180\95\021

Manufacturer	Nomenclature	Model Number	Mfg. Part Number
Yarway	Level Switch	4418C	DS551