Commonwealth Ediso Smpany Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920

**ComEd** 

December 12, 1995

PGHLTR 95-0037

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Subject:

Dresden Nuclear Power Station Unit 3,

30 Day Special Report;

Both Off Gas Recombiners Inoperable During an Off Gas Fire;

NRC Docket Number 50-249.

This letter is provided pursuant to Dresden Technical Specification 3.8.A.6 which requires submittal of a special report within 30 days when either recombiners have been inoperable. Unit 3 Recombiners (3A and 3B) were inoperable when Unit 3 experienced fires of short duration within the Off Gas system on November 12 and November 18, 1995.

This correspondence contains the following commitment:

Investigation of the causes of the Off Gas fires and determination of any additic: 1 corrective action is in progress. Upon completion of the investigation the results will be communicated to the NRC. (Station Commitment Number 249132950010001)

Any questions pertaining to this correspondence should be directed to the Dresden Engineering Manager, Frank Spangenberg at (815) 942-2920, Ext 3800.

Sincerely,

Peter 6. Holland

Regulatory Assurance Supervisor

PGH/JZ:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III

NRC Resident Inspector's Office

File/NRC

File/Numerical

9512180036 951212 PDR ADDCK 05000249 S PDR

A Unicom Company

Tess.

# Dresden Nuclear Power Station Unit 3

30 Day Special NRC Report

Both Off Gas Recombiners Inoperable During an Off Gas Fire NRC Docket Number 50-249.

December 11, 1995

Prepared by: P. Garrett

H. Shaffer

### INTRODUCTION

This letter report is provided pursuant to Dresden Technical Specification 3.8.A.6 which requires submittal of a special report within 30 days when either recombiners have been inoperable. Unit 3 Recombiners (3A and 3B) were inoperable when Unit 3 experienced fires of short duration within the Off Gas system on November 12, and November 18, 1995.

On November 12, 1995, with the Unit 3 reactor in run mode, increasing power to 805 MWe, pressure at 1003 psi, both the 3A and 3B Off Gas Recombiners were inoperable for 5 hours and 32 minutes. Again on November 18, 1995, with the Unit 3 reactor in run mode and reactor power steady at 600 MWe, pressure at 970 psi, both the 3A and 3B Off Gas Recombiners were inoperable for 45 minutes. The 3A Recombiner was inoperable due to a Hydrogen fire within its train and the 3B Recombiner was inoperable due to condensate blockage. An Additional fire was experienced within the 3B Recombiner on November 20, 1995, however, the 3A Recombiner was available during this period.

The fires were extinguished by injecting service air per station procedure. The condensate was evaporated from the 3B Recombiner using the normal startup configuration. No Off Gas system damage was experienced. The fires occurred within the Unit 3, 3A Recombiner train while utilizing the 3A Steam Jet Air Ejectors (SJAE) train.

No increase in the volume and curie content of the effluent were observed.

# **DESCRIPTION OF EVENT**

On November 12, 1995, when the reactor reached 805 MWe, operations personnel observed indication of an Off Gas fire in the 3A Recombiner train. The symptoms of the fire included reduced SJAE flow and greatly reduced recombiner temperatures. After identification, the fire was extinguished by reducing load to 600 MWe and injecting service air at the SJAE common suction per station procedures. Plant load remained at 600 MWe while an investigation was conducted per station procedure. The investigation found that there was no damage to the Off Gas system and that the fire was most likely the result of recombiner fines traveling upstream of the recombiner, igniting the hydrogen in the system. Thus, a power level of 600 MWe was maintained until a transfer to the stand-by 3B Recombiner could be performed.

On November 14, 1995, during an attempt to place the 3B Recombiner into service, it was found to be blocked with condensate due to the drain lines being plugged. On November 16, 1995, the 3B Recombiner train was placed into the startup configuration to allow steam to enter the train and heat the Recombiner to evaporate the condensate. Upon the completion of the condensate removal on November 20, 1995, the 3B Recombiner train was ready for use.

On November 18, 1995, the second Off Gas fire occurred within the 3A Recombiner train when the Main Condenser's Circulating Water flow was reversed. This fire was promptly extinguished with service air per procedure. A preliminary investigation concluded that the fire was caused by an instantaneous increase in hydrogen and oxygen in the SJAE discharge, which was created by the very short interruption in gas flow that occurs when the SJAE supply suction transfers from one end of the Main Condenser to the other. This transfer takes place automatically as part of the Circulating Water flow reversal, and results in a slight build up of gas in the Main Condenser. When this volume of gas was drawn into the system by the SJAEs, the fire occurred immediately as shown by the SJAE flow recorder. Plant operation continued at 600 MWe with Off Gas lined up to the 3A SJAE and the 3A Recombiner. This fire was also attributed to catalyst fines in the system.

The plant shifted to the 3B Recombiner while at 600 MWe, on November 20, 1995, in order to bypass the suspected train and to achieve full power. Approximately three hours after shifting, another fire occurred, also attributed to catalyst fines. This fire was put out with Service Air while the plant remained at 600 MWe. The plant remained at 600 MWe and shifted to the 3B SJAEs, on November 22, 1995, then reversed Circulating Water flow again and ascended to full power with no further fires. The combination of the 3B SJAE and 3B Recombiner has been used for many years with no fires.

## **ANALYSIS**

The fires are believed to have been initiated by recombiner catalyst fines that migrated upstream of the booster jet for the recombiners. Off Gas fires are not a new phenomena in BWRs and have been extensively analyzed at Dresden and elsewhere. The catalyst fines, in a combustible mixture of hydrogen and oxygen, heat up to the point of gas ignition. The hydrogen and oxygen then burn back to the point where a combustible mixture begins to exist, after the second stage air ejector, which is in the After Condenser. The fire continues to burn there until extinguished. This is proven by the characteristic decrease in SJAE flow, and the drop in recombiner temperature.

### SAFETY SIGNIFICANCE

There is no reactor safety impact due to an Off Gas fire. There is no known short term harmful effect from Off Gas fires. The most limiting long term effect is thought to be possible damage to the After Condenser tubes causing leaks or to the Off Gas condenser shell. The recent Off Gas fires at Dresden have caused no damage to system components. This conclusion is based on previous experience with Off Gas fires on Dresden Unit 2, consultations with the Original Equipment Manufacture (GE) Designer and a review of plant parameters for the November 12 fire that shows no indication of failed components.

# PREVIOUS EVENT HISTORY

Dresden has experienced Off Gas System fires during the mid 1980s which resulted in no damage to the Off Gas system components. As a result of the previous Unit 2 fires, the 2A and 2B trains were modified. The 2A train modification added a fire suppression spray in the SJAE discharge loop. The 2B train modification installed the GE recommendation which provides only two stages of air ejectors and never has a combustible mixture of gas in the Recombiner portion of the system. Unit 2 operation has demonstrated that these modifications have been effective at preventing fires.

# **CORRECTIVE ACTION**

Investigation of the causes of the Off Gas fires and determination of any additional corrective action is in progress. Upon completion of the investigation the results will be communicated to the NRC (Station Commitment Number 249132950010001)