Commonwealth Editorian Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



February 7, 1996

PGHLTR 96-0005

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Licensee Event Report 95-014, Revision 1, Docket 50-249 is being submitted pursuant to 10CFR50.73(a)(2)(iv) any event that results in automatic or manual actuation of any Engineered Safety Feature (ESF).

This supplement is being submitted to modify corrective action E.4. This commitment is modified to state:

Investigate the basis for the vacuum breaker settings and change DMP 1600-01 and DMS 1600-03 to provide greater operating margin to prevent unnecessary valve operations. DAN 902(3)-4 G-14, DAN 902(3)-4 H-14 and DOS 1600-09 will be revised to include field setpoints. (SCN: 249-180-95-01403).

Sincerely,

Peter G. Holland V V Regulatory Assurance Supervisor

PGH/JW:pt

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical

L:\8360\8301\pghltr.96\0005.96

PDR

ADOCK 05000249

150044

A Unicom Company

9602150307 960207

PDR

NRC FO	RM 366				U.S	. NUCLE	AR R	EGULATO	RY COM	HISSION	1	APPROVED B	Y OMB NO.	3150-0	0104		
(5-92)		LIC	EN	SEE	EVENT REPO	DRT ((LE)	R)			ESTIMA THIS I FORWARI THE IN (MNBB WASHINI REDUCT MANAGEI	EXP TED BURDEN P NFORMATION CO COMMENTS R FORMATION ANI (FORMATION ANI (FORMATION ANI STON, DC 2055) GON PROJECT (ENT AND BUDGE	IRES 5/31, ER RESPON EGARDING D RECORDS JCLEAR REG 5-0001, AI (3150-0 T, WASHIN	/95 REQUES BURDEN MANAG ULATOR ND TO 104), GTON, I	COMPLY WITH T: 50.0 HRS ESTIMATE TO EMENT BRANCH Y COMMISSION, THE PAPERWORY OFFICE OI DC_20503.		
FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3								DOCKET	NUMBER (2) 05000249	PAGE (3) 1 OF 4							
TITLE	(4) Unex Due	pecte to In	ed (nade	Opera equat	tion of the e Training	Pres and H	ssur Proc	re Sup cedure	opres e Def	sion icien	Chambe	er To Dryw	ell Vac	uum I	Breakers		
EVE	NT DATE	(5)			LER NUMBER (6)			REPO	RT DAT	(7)	OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	Y	EAR	SEQUENTIAL NUMBER	REVIS	ION ER	MONTH	DAY	YEAR	FACILITY NAME None			DOCKET NUMBER			
09	07	95	9	95 -	- 014	01		02	07	96	FACILITY NAME			DOCKET NUMBER			
OPERATING N MODE (9)		THI		HIS REPORT IS SUBMITTED PURSUANT			TO THE	REQUIR	EMENTS	OF 10 CFR §: (Check one or more			re) (11	e) (11)			
		N		20.22	01(b)			20.2203	(a)(3)	(i)		50.73(a)(2)(iii)	73	.71(b)		
POWER LEVEL (10)		000		20.22	03(a)(1)	2		20.2203(a)(3)(ii)		X	X 50.73(a)(2)(iv)		73	.71(c)			
		000		20.2203(a)(2)(i)				20.2203(a)(4)			50.73(a)(2)(v)			OTHER			
				20.22	03(a)(2)(ii)			50 .36(c)(1)			50.73(a)(2)(vii)	(Speci	fy in		
	20.22			20.2203(a)(2)(iii)			50.36(c)(2)			50.73(a)(2)(viii)(A)		/iii)(A)	and in Text.				
			ŝ.	20.2203(a)(2)(iv) 20.2203(a)(2)(v)				50.73(a)(2)(i) 50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)		NRC Form 366A)			
											50.73(a)(2)(x)		1				
						LICENSE	EE CO	WTACT F	OR THI	S LER ((12)						
NAME		-										TELEPHONE NUR	BER (Incl	ude Ar	ea Code)		
Jesse Williams, System Engineer Ext. 2708 (815) 942-2920																	
				COMPI	ETE ONE LINE FO	R EACH	COMP	ONENT F	AILURE	DESCRI	BED IN T	HIS REPORT (1	3)				
CAUSE	CAUSE SYSTEM COMPONEN		ONENT	MANUFACTURER REPOR		TABLE PRDS	E CAUSE		SYSTEM	COMPONENT	MANUFAC	TURER	REPORTABLE TO NPRDS				
							<u>.</u>								,		
			<u> </u>												<u> </u>		
			SUP	PLEMEN	TAL REPORT EXPEC	TED (1	4)				E	XPECTED	MONTH	DA	YEAR		
YES (If yes, complete EXPECTED SUBMISSION DATE).					- X N	0		SUBMISSION DATE (15)									
STRACT	(Limi)	t to 14	00 s	paces.	i.e. approxim	ately 1	15 si	ngle-sp	aced t	vpeurit	ten line	s) (16)					

On September 9, 1995, at 2233 hours with Unit 3 in startup at 1 percent thermal power, all twelve Pressure Suppression Chamber (Torus) to Drywell Vacuum breakers (3-1601-32A, B, C, D, E, F AND 33A, B, C, D, E, F) opened while relieving negative pressure in the torus per Dresden Operating Procedures (DOP) 1600-1. This constitutes an unexpected actuation of an Engineered Safety Feature. Initial drywell pressure was -0.16 psig, and torus pressure was -0.21 psig. When torus pressure increased to 0 psid all twelve vacuum breakers cycled open. Cause was due to training and procedure deficiencies. Technical Specifications (TS) require Torus to Drywell Vacuum Breakers to open fully with applied force at all valve positions not exceeding the equivalent to 0.5 psi acting on torus face of the valve disk. Operations was aware of the TS requirement but was not aware of actual valve setpoint. DOP 1600-1 instructs operators on how to relieve containment pressure but did not contain a warning that vacuum breakers may open, therefore operators did not expect vacuum breakers to open. Startup continued, however, an administrative heatup rate limit of 25 degrees F per hour was initiated pending an investigation of vacuum breaker set points and an evaluation of startup plans. Setpoints were found to be correct, and administrative heatup limit was removed.

· _							
NRC FORM 366A (5-92)	. U.S. NUCLEAR	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
	LICENSEE EVENT REPORT (LI TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BURDECT WASHINGTON DC 2053.					
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6	PAGE (3)		
Durandan Mu	uclear Power Station, Unit 3	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 05 4	
Dresden Nu		05000249	95	014	01	2 OF 4	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT IDENTIFICATION:

Unexpected Operation of the Pressure Suppression Chamber To Drywell Vacuum Breakers Due to Inadequate Training and Procedure Deficiency

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit:3Event Date:09/09/95Event Time:2233Reactor Mode:NMode Name:StartupPower Level:1%Reactor Coolant System Pressure:90 psig

DESCRIPTION OF EVENT:

Β.

On September 9, 1995, at 2233 hours with Unit 3 in startup at 1 percent power, all twelve Suppression Chamber (Torus) to drywell vacuum breakers [BF] (3-1601-32A, B, C, D, E, F and 33A, B, C, D, E, F) opened while relieving negative pressure in the torus per Dresden Operating Procedures (DOP) 1600-1, Normal Pressure Control of The Drywell or Torus. The initial drywell pressure was -0.16 psig, and the initial Pressure Suppression pressure was -0.21 psig. When the torus pressure increased to 0 psid all twelve vacuum breakers opened. This constitutes an unexpected actuation of an Engineered Safety Feature. The procedural actions taken by the operators caused the ESF actuation. At 0128 hours, an Event Notification System (ENS) telephone call was made to the Nuclear Regulatory Commission to report the event.

The startup continued, however, the Shift Manager initiated a primary coolant administrative heat rate limit of 25 degrees F per hour until the vacuum breaker setpoint issue was resolved, and the startup plans were evaluated. Plant Engineering reviewed the Sequence of Events Printer and verified operation of all twelve vacuum breakers. The Plant Engineering Department also investigated the drywell vacuum breaker actuation and discovered that the valves are set to open at 35 ft-lbs torque as required by Dresden Maintenance procedure (DMP) 1601-1, Torus Vacuum Breaker Valve Maintenance. Plant Engineer Department issued a letter which correlated the torque settings to a valve opening dp. The torque setting correlated to a opening dp of 0.15 PSID. The drywell vacuum breakers opened at 35 ft-lbs plus or minus 4 ft-lbs.

The letter was reviewed and approved, and the administrative heatup rate was removed.

NRC FORM 366A (5-92)	•	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MAYAGEMENT AND BUDGET. WASHINGTON, DC 2053.				
	LICENSEE EVENT TEXT CON	REPORT (LEE					
	FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6) PAGE (PAGE (3)
Duesdan Nu	Welson Deven Station Unit 3	05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 05 4	
Dresden Nud	clear rower Statio	on, unit 3	05000249	95	014	01	S OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

C. CAUSE OF EVENT:

This event is being issued pursuant to 10 CFR50.73 (a)(2)(iv) - any event that results in automatic or manual actuation of any Engineered Safety Feature (ESF).

The cause of the event was due to training and procedure deficiencies. The Technical Specifications (TS) require the Torus to Drywell Vacuum Breakers to open fully with the applied force at all valve positions not exceeding the equivalent to 0.5 psi acting on the Torus face of the valve disk. The Operations Department was aware of the TS requirement but was not aware of the actual valve field setpoint in ft-lbs torque. The section of DOP 1600-01, which provides the method to relieve containment pressure, did not contain a warning that the vacuum breakers may open at the field setpoint of 35 ft-lbs, 0.15 psi, therefore the operators did not expect the vacuum breakers to open.

Dresden Mechanical Surveillance (DMS) 1600-03, Torus To Drywell And Torus To Reactor Building Vacuum Breaker Valve Surveillance, requires the drywell to torus vacuum breaker torque to be set at 35 ft-lbs. Dresden Operating Surveillance (DOS) 1600-9, Pressure Suppression Chamber to Drywell Vacuum Breaker Full Stroke Exercise Test, requires the vacuum breakers to open at less than 58 ft-lbs torque. The procedures do not convert the ft-lbs torque value to an equivalent differential pressure. Because no procedure directly states the opening range for the Drywell Vacuum or the Torus Vacuum breaker, the operators expect the vacuum breakers to open when the DOS 1600-09 limit of 58 ft-lbs, 0.25 psid, is approached.

D. SAFETY ANALYSIS:

After a design basis accident, the drywell vacuum relief valves [BF] open under differential pressure (dp) to allow gas to be drawn from the torus. The torus valves open under dp to allow air to be drawn in from the reactor building. The TS require the drywell vacuum relief valves to open under 0.5 psi dp. This protects the primary containment from collapse by limiting the design basis external to internal dp. Under normal operating conditions the valves must be closed and leak tight. The safety significance of this event was minimal since the Pressure Suppression to Drywell vacuum Breakers operated at the desired setpoint, which is conservative to the TS requirement of 0.5 psid.

···· · · ·

NRC FORM 366A . U.S. NUCLEAR RE	GULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT REPORT (LEI TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND RUDGET WASHINGTON DC 20503.						
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6))	PAGE (3)		
Decider Nuclear Deven Chatien Unit 2	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 05 4		
bresden Nuclear Power Station, Unit 3	05000249	95	014	• 01	4 OF 4		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

- E. CORRECTIVE ACTIONS:
 - Train Operators on the Torus to Drywell and Reactor Building to Torus Vacuum Breaker Setpoints (Station Commitment Number (SCN): 249-180-95-01401).
 - Simulator fidelity for the Torus to Drywell and the Reactor Building to Torus Vacuum Breakers was completed by station work request U06763 and U06777 which adjusted the setpoints for the vacuum breakers. (SCN: 249-180-95-01402).
 - 3. DOP 1600-9 has been changed to warn operators that the Torus to Drywell vacuum breakers may open while performing excess pressure relief of the Drywell and Pressure Suppression chamber.
 - 4. Investigate the basis for the vacuum breaker settings and change DMP 1600-01 and DMS 1600-03 to provide greater operating margin to prevent unnecessary valve operations. DAN 902(3)-4 G-14, DAN 902(3)-4 H-14 and DOS 1600-09 will be revised to include field setpoints. (SCN: 249-180-95-01403).

F. PREVIOUS OCCURRENCES:

Not Applicable.

G. COMPONENT FAILURE DATA:

Not Applicable.

02/09/96:847