Commonwealth Ediscompany Dresden Generating Station 6500 North Dresden Road Morris, IL 60450 Tel 815-942-2920



March 28, 1996

JSP Ltr. #96-0046

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Enclosed is Licensee Event Report 95-014, Docket 50-249, Revision 2, which is being submitted pursuant to 10CFR50.73 (a)(2)(iv), which requires the reporting of any event that results in automatic or manual actuation of any Engineered Safety Feature (ESF). This Supplemental LER is provided to update corrective actions associated with the event.

Sincerely,

J Stephen Perry Vice President BWR Operations

Enclosure

cc: H. Miller, Regional Administrator, Region III

NRC Resident Inspector's Office

JE22 1

NRC FORM 366 (5-92)				U.S. NUCLEAR REGULATORY COMMISSION							APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95						
	LICENSEE EVENT REPORT (LER)										ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND YO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
									DOCKET NUMBER (2) 05000249				PAGE (3) 1 OF 4				
TITLE	TITLE (4)  Unexpected Operation of the Pressure Suppression Chamber To Drywell Vacuum Breakers  Due to Inadequate Training and Procedure Deficiency																
EVE	NT DATE	(5)				LER NUMBER (6)		REPO	RT DATE	(7)	I	-	OTHER FACIL	ITIES INV	VOL V	ÆD (8	)
MONTH	DAY	YE	AR	YEAR		SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY		FAC: Nor	FACILITY NAME None				DOCKET NUMBER	
09	07	9	5	95		- 014	02	03	28	96	FAC	CILITY NAME				DOCKET NUMBER	
OPERATING N		1				SUBMITTED PURSUANT TO THE REQUIREMENTS			OF 10	) CF							
MODE	(9)		`			201(b)		20.2203(a)(3)(i)				50.73(a)(2)(iii)		┖	73.7		
POMER		00		20.2203(a)(1)				20.2203	20.2203(a)(3)(ii) $X = 50.73(a)(2)$			50.73(a)(2)(	iv)		73.7	1(c)	
LEVEL (10)				20.2203(		03(a)(2)(i)		20.2203(a)(4)				50.73(a)(2)(v)		OTHER			
			20.2203(a)(2)(ii)			50.36(c)(1)					50.73(a)(2)(vii)			(Specify in Abstract below			
					03(a)(2)(iii)		50.36(c)(2)				50.73(a)(2)(v	/iii)(A)_	and in Text,				
				20	.220	03(a)(2)(iv)		50.73(a	)(2)(i	)			50.73(a)(2)(v	/iii)(B)			1 366A)
				20.2203(a)(2)(v)				50.73(a)(2)(ii)					50.73(a)(2)(x)				
							LICENSEE C	CONTACT F	OR THI	S LER	(12)						
NAME								•			TELEPHONE NUMBER (Include Area Code)						
	Jesse Williams, System Engineer						-	Ext	. 27	80	(81	5) 942-	-29	20			
	•			CC	MPL	ETE ONE LINE FO	R EACH COM	PONENT F	ALLURE	DESCR	I BED	IN T	HIS REPORT (1	<u></u>			
CAUSE SYSTEM C		co	OMPONENT MANUFACTURER		REPORTABLE TO NPRDS		့် င	AUSE	SYSTEM		COMPONENT	OMPONENT MANUFAC		CTURER REPORTABI			
	SUPPLEMENTAL REPORT EXPECTED (14)								F	KPECTED	MONTH	T	DAY	YEAR			
YES (If						X	ю			SUBMISSION DATE (15)							

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On September 9, 1995, at 2233 hours with Unit 3 in startup at 1 percent thermal power, all twelve Pressure Suppression Chamber (Torus) to Drywell Vacuum breakers (3-1601-32A, B, C, D, E, F AND 33A, B, C, D, E, F) opened while relieving negative pressure in the torus per Dresden Operating Procedures (DOP) 1600-1. This constitutes an unexpected actuation of an Engineered Safety Feature. Initial drywell pressure was -0.16 psig, and torus pressure was -0.21 psig. When torus pressure increased to 0 psid all twelve vacuum breakers cycled open. Cause was due to training and procedure deficiencies. Technical Specifications (TS) require Torus to Drywell Vacuum Breakers to open fully with applied force at all valve positions not exceeding the equivalent to 0.5 psi acting on torus face of the valve disk. Operations was aware of the TS requirement but was not aware of actual valve setpoint. DOP 1600-1 instructs operators on how to relieve containment pressure but did not contain a warning that vacuum breakers may open, therefore operators did not expect vacuum breakers to open. Startup continued, however, an administrative heatup rate limit of 25 degrees F per hour was initiated pending an investigation of vacuum breaker set points and an evaluation of startup plans. Setpoints were found to be correct, and administrative heatup limit was removed. This supplemental report is being provided to update corrective actions associated with the event.

L:\8360\8301\249\180\95\014.R02 03/26/96:1002

NRC FORM 366A (5-92)	U.S. MUCLEAR RE	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95  ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.					
13	VENT REPORT (LEFT CONTINUATION						
FACILITY NAM	E (1)	LER NUMBER (6) PAGE (3)					
Danadas Vivalian Davida G	Variation Provide Charling White 2	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 07 4	
Dresden Nuclear Power S	ctation, unit 3	05000249	95	014	02	2 OF 4	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

## EVENT IDENTIFICATION:

Unexpected Operation of the Pressure Suppression Chamber To Drywell Vacuum Breakers Due to Inadequate Training and Procedure Deficiency

### PLANT CONDITIONS PRIOR TO EVENT: Α.

Unit:

09/09/95 Event Time: 2233 Event Date:

Reactor Mode: N

Mode Name: Startup

Power Level: 1%

Reactor Coolant System Pressure: 90 psig

#### В. DESCRIPTION OF EVENT:

On September 9, 1995, at 2233 hours with Unit 3 in startup at 1 percent power, all twelve Suppression Chamber (Torus) to drywell vacuum breakers [BF] (3-1601-32A, B, C, D, E, F and 33A, B, C, D, E, F) opened while relieving negative pressure in the torus per Dresden Operating Procedures (DOP) 1600-1, Normal Pressure Control of The Drywell or Torus. The initial drywell pressure was -0.16 psig, and the initial Pressure Suppression pressure was -0.21 psig. When the torus pressure increased to 0 psid all twelve vacuum breakers opened. This constitutes an unexpected actuation of an Engineered Safety Feature. The procedural actions taken by the operators caused the ESF actuation. At 0128 hours, an Event Notification System (ENS) telephone call was made to the Nuclear Regulatory Commission to report the event.

The startup continued, however, the Shift Manager initiated a primary coolant administrative heat rate limit of 25 degrees F per hour until the vacuum breaker setpoint issue was resolved, and the startup plans were evaluated. Plant Engineering reviewed the Sequence of Events Printer and verified operation of all twelve vacuum breakers. The Plant Engineering Department also investigated the drywell vacuum breaker actuation and discovered that the valves are set to open at 35 ft-lbs torque as required by Dresden Maintenance procedure (DMP) 1601-1, Torus Vacuum Breaker Valve Maintenance. Plant Engineer Department issued a letter which correlated the torque settings to a valve opening dp. torque setting correlated to a opening dp of 0.15 PSID. The drywell vacuum breakers opened at 35 ft-lbs plus or minus 4 ft-lbs.

The letter was reviewed and approved, and the administrative heatup rate was removed.

03/26/96:1002

NRC FORM 366A (5-92)	U.S. MUCLEAR RE	APPROVED BY CMB NO. 3150-0104 EXPIRES 5/31/95					
	LICENSEE EVENT REPORT (LEF	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.					
	FACILITY NAME (1)		LER NUMBER (6	PAGE (3)			
Dreader Nue	clear Power Station, Unit 3	05000249	YEAR	YEAR SEQUENTIAL REVISION NUMBER 95 014 02		3 05 4	
Dresden Nuc		05000249	95			3 OF 4	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

# C. CAUSE OF EVENT:

This event is being issued pursuant to 10CFR50.73 (a)(2)(iv) - any event that results in automatic or manual actuation of any Engineered Safety Feature (ESF).

The cause of the event was due to training and procedure deficiencies. The Technical Specifications (TS) require the Torus to Drywell Vacuum Breakers to open fully with the applied force at all valve positions not exceeding the equivalent to 0.5 psi acting on the Torus face of the valve disk. The Operations Department was aware of the TS requirement but was not aware of the actual valve field setpoint in ft-lbs torque. The section of DOP 1600-01, which provides the method to relieve containment pressure, did not contain a warning that the vacuum breakers may open at the field setpoint of 35 ft-lbs, 0.15 psi, therefore the operators did not expect the vacuum breakers to open.

Dresden Mechanical Surveillance (DMS) 1600-03, Torus To Drywell And Torus To Reactor Building Vacuum Breaker Valve Surveillance, requires the drywell to torus vacuum breaker torque to be set at 35 ft-lbs. Dresden Operating Surveillance (DOS) 1600-9, Pressure Suppression Chamber to Drywell Vacuum Breaker Full Stroke Exercise Test, requires the vacuum breakers to open at less than 58 ft-lbs torque. The procedures do not convert the ft-lbs torque value to an equivalent differential pressure. Because no procedure directly states the opening range for the Drywell Vacuum or the Torus Vacuum breaker, the operators expect the vacuum breakers to open when the DOS 1600-09 limit of 58 ft-lbs, 0.25 psid, is approached.

## D. SAFETY ANALYSIS:

After a design basis accident, the drywell vacuum relief valves [BF] open under differential pressure (dp) to allow gas to be drawn from the torus. The torus valves open under dp to allow air to be drawn in from the reactor building. The TS require the drywell vacuum relief valves to open under 0.5 psi dp. This protects the primary containment from collapse by limiting the design basis external to internal dp. Under normal operating conditions the valves must be closed and leak tight. The safety significance of this event was minimal since the Pressure Suppression to Drywell vacuum Breakers operated at the desired setpoint, which is conservative to the TS requirement of 0.5 psid.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95						
	LICENSEE EVENT REPORT (LEF	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITHIS INFORMATION COLLECTION REQUEST: 50.0 HE FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRANCHMBB 7714), U.S. NUCLEAR REGULATORY COMMISSION MASHINGTON, DC 20555-0001, AND TO THE PAPERMORE REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
	FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)					
Dungdon Nu	lan Davin Station Wait 2	05000240	YEAR	SECULENTIAL DEVISION		4 05 4		
bresden Nuc	clear Power Station, Unit 3	05000249	95	014	02	4 OF 4		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

### E. CORRECTIVE ACTIONS:

- Train Operators on the Torus to Drywell and Reactor Building to Torus Vacuum Breaker Setpoints (NTS#: 249-180-95-01401).
- Simulator fidelity for the Torus to Drywell and the Reactor Building to Torus Vacuum Breakers was completed by station work request U06763 and U06777 which adjusted the setpoints for the vacuum breakers. (Reference NTS #: 249-180-95-01402).
- 3. DOP 1600-9 has been changed to warn operators that the Torus to Drywell vacuum breakers may open while performing excess pressure relief of the Drywell and Pressure Suppression chamber.
- 4. The basis for the vacuum breaker setting was determined to be as a result of the Plant Unique Analysis Report (Mark I Containment Analysis). No revisions to the maintenance procedures which set the vacuum breaker setpoint setting was performed. Station procedures DAN 902(3)-4 G-14, DAN 902(3)-4 H-14 and DOS 1600-09 have been revised to include field setpoints. (Reference NTS #: 249-180-95-01403).
- F. PREVIOUS OCCURRENCES:

Not Applicable.

G. COMPONENT FAILURE DATA:

Not Applicable.